

ASS. REC. BY:

REF: CS/FCI 19000966/KVD3/12

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Severe for

of

FCI

Date/Time: 6:30pm 15/1/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 6809S

Insured:

SHA 3569G

at Workshop m/s

Hui Yung Motor

Tel:

64515752

of

Blk 176 Sin Ming Drive #04-02

Policy No:

Claim No:

D18009032MESH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/12/18

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

10:21am 16/1/19

Person Contacted:

Belle

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLU 6809S-X
	SHA 3569G-NA/INC13012223/61
	JUN: 6/7/2013
17/1/19	Email preli revised to FCI
24/1	& 1804.83 email & confirmed (Red 3004.80, 6/9)

ASS. REC. BY:

REF: PC21Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hui Yang

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 588k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 680PS Yr Regn: 12, 17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1797Colour: N. Black A/C: Insured / Std / NI / NASp. Reading: 126436 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZVW 50 . 6100319Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 21/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.I. 16/1/19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/1 File pass to Car

RECEIVED 24 JAN 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 24/1 - typistDays Of Repair: 2Resurvey No. of Trlp: 2

Report Format :

CWS

Lump Sum / I.B.I: (\$

1804.83

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

Fixt/ps

Others

TOTAL

135
50
50 + 50
17
302

MOTOR SURVEY ASSIGNMENT

Date	24-12-2018	Our Ref No. D18009032MFSH
Accident Date	21-12-2018	Claim Type. Third Party
Insured Vehicle	SHA3569G	Third Party Vehicle. SLU6809S
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	DIRECT SETTLEMENT: EST. COR - \$4,809.63	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 17 January 2019 1:45 PM
To: SUR; 'CWS Motor Claims'
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D18009032MFSH/1, SLU 6809S
Attachments: SLU 6809S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLU 6809S
Date of survey: 16/1/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 17 January 2019 1:42 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D18009032MFSH/1

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]
Sent: Wednesday, 16 January, 2019 10:23 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18009032MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 15 January 2019 6:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18009032MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18009032MFSH

Our ref: CS/FCI19000966/Kvd3

Date : 17/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 6809S


We thank for your instruction on 15/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/1/2019 at the premises of M/s HUI YANG MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,809.63
Revised Estimate Amount	: S\$1,571.26
"Check" Items Amount	: S\$759.25
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

ms final by
LKK
16/01/19
Wed

21/12/2018

Owner: FAVORIDE PTE LTD

81804.83

Not Authorised
Remy Begam
2 days

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

1pc rear bumper 585.90
1pc rear bumper reinforcement 384.20
1pc rear bumper sponge
1pc rear bumper diffuser
8pcs rear bumper diffuser clip \$5.00
1pc rear bumper towing cover
1pc rear end panel
1pc rear end panel inner garnish

Am \$ 928.35
M \$ 458.00
S \$ 181.00
Pd/Di \$ 379.00
M \$ 40.00
S \$ 61.00
R \$ 970.25
S \$ 381.90

\$ 3,399.50

less 25%

\$ 849.88

\$ 2,549.63

1set rear parking sensor

Ad 1540 s.nett \$ 280.00 2001

tuffkote
wiring
spray painting
labour charges
Total

nn \$ 100.00
\$ 80.00
\$ 900.00
\$ 900.00
\$ 4,809.63



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification allowed
- Supplementary items must be surveyed and is subject to the approval from Insurance Company

Approved by the Repairer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000966/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3569G	Veh. Inspected	SLU 6809S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18009032MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	15/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZVW506100319	Colour	METALLIC BLACK	
Odometer	126436	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	JOURNEY	7 mm	
L/H Front Tyre	195/65 R15	JOURNEY	7 mm	
R/H Rear Tyre	195/65 R15	JOURNEY	5 mm	
L/H Rear Tyre	195/65 R15	JOURNEY	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/12/2018	Inspection Date	16/01/2019	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 6809S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	928.35	585.90
1	REAR BUMPER REINFORCEMENT	BENT	458.00	387.20
1	REAR BUMPER SPONGE	SERVICEABLE	181.00	-
1	REAR BUMPER DIFFUSER	DENTED / DISTORTED	379.00	379.00
8	REAR BUMPER DIFFUSER CLIP @\$5.00	NECESSARY	40.00	40.00
1	REAR BUMPER TOWING COVER	DENTED	61.00	61.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	970.25	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	381.90	-
	LESS 25% DISCOUNT		-849.87	-363.27
			2,549.63	1,089.83
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR PARKING SENSOR (SN)	DENTED / SHORTED	280.00	200.00
			280.00	200.00
	<u>LABOUR</u>			
	TUFFKOTE.	NOT NECESSARY	100.00	-
	WIRING.		80.00	15.00
	SPRAY PAINTING.		900.00	250.00
	LABOUR CHARGES INCLUSIVE OF THE REPAIR OF REAR END PANEL.		900.00	250.00
			1,980.00	515.00
	GRAND TOTAL		4,809.63	1,804.83
RECOMMENDED COST OF REPAIRS				1,804.83

Report Ref No. CS/FC119000966/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.