LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Catherine Thia Date: 21 Jan 2019

Preliminary Advice

Vehicle No : PC7619P **Accident Date** : 12/01/2019

Make : TOYOTA HIACE Policy No.

DMCVSN30670818000

Assignment Date : S\$0.00 : 16/01/2019 **Excess** Date of Inspection : 16/01/2019 : 0.00 Est. Duration of Repair

Inspection At : BEST AUTO K PTE LTD (HQ)

2 KAKI BUKIT AVENUE 2, #01-11 KAKI BUKIT AUTOHUB

SINGAPORE 417921

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 8,795.00 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 5,320.00 |
| Check Items (Estimated) | :S\$ | 1,340.00 |
| Total | :S\$ | 6,660.00 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 68,000.00 COE / PARF Rebate :S\$ 26,848.00

Salvage Value :S\$

Margin for Repair :S\$ 41,152.00

Remarks

| X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|-----|---|
|) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
|) | Other comments : |