

ASS. REC. BY:

REF CS/FCI/9001015/At d3 72

Special Instruction:

Surveyor:

aws

ASSIGNMENT (Office)

From (Person):

Sithera

of

FEI

Date/Time:

5:15pm @ 16/1/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 4401A

Insured:

8HD 8555Y

at Workshop m/s:

MG Solution

Tel:

6744 4165

of

23 Kaki Bukit Ave 4 # 02-03B

Policy No:

Claim No:

D19000363 MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/01/2019

CA / REV / REP. / REV 24 HRS

kup

17/1/19

H.O.D. Endorsement:

Date/Time:

5:44pm @ 16/1/19

Person Contacted:

Jenny

Vehicle:

IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SMD 4401A - X

8HD 8555Y - CS/FCI/17013993/Agbn2

DOA: 6/7/17

18/1-2019- Report email pending estimate.

lump sum \$3000-

(Ref: 5/13.88 / 632)

REF: FCI

ASSIGNMENT

From: _____ Date: **17/01/2019** Vch No: **SMD4401A** Yr Regn: **2018 August**

Estimated Cost: _____ Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or

To inspect Vehicle No: **SMD 4401A** Make: **Honda Shuttle** C/S: **1496**

at Workshop m/s: **MG Solution** Colour: **Black** A/C: Insured / Std / NI / NA

of **23 kaki Bukit Ave 4 # 02-03B** Sp. Reading: **16465** T/Radio: Insured / Std / NI / NA

Insured: _____ Eng/No: _____

Policy No: _____ C/No: **GPT1218436**

Claims No: _____ Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____ Steering: In order / Jammed / Leaked / Burnt or

(Client's Record) Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____ Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition) Tyre Size: F: **205/50R16**

Remark: The veh had commenced its repair at the time of inspection. N/S O/S R: **205/50R16**

Bal. or Market Value: _____ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

IDAC Accident Rpt: Consistent? : Yes or No TOYO / YOKO or **Falken**

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up} Front Rear

Date: _____ Person Contacted: _____ R/Bal. **06** mm R/Bal. **06** mm

Vehicle: IN / OUT L/Bal. **06** mm L/Bal. **06** mm

Survey held at **MG Solution** D.O.I. **17/01/19**

Des. of Damages: Frt / Rear / O/S (N/S) / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.
	RECEIVED 26 FEB 2019

Date/Time, File Pass to? ☐ : Preli. Report

26/2 Typist ☒ : Final Report

Date/Time, File Return to? _____

Report Format: **TP**

Lump Sum / L.B.I: (\$) **3000**

Days Of Repair: **5**

Resurvey No. of Trip: **-**

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: _____

Transportation: _____

Photos: _____

Others: _____

TOTAL: **226**

MOTOR SURVEY ASSIGNMENT

Date	11-01-2019	Our Ref No. D19000363MFSH
Accident Date	10-01-2019	Claim Type. Third Party
Insured Vehicle	SHD8555Y	Third Party Vehicle. SMD4401A
Survey Location	23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE	
Contact Person.	HONG	
Contact No.	67444165/ 0	Fax No. 67444604
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: FIRST CAPITAL	DATE	: 16-Jan-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMD4401A		
MODEL	: HONDA SHUTTLE 1.5G	Denise	
CHASSIS NO	:		
<u>ACCIDENT DETAILS</u>		DATE	: 10-Jan-19
		TIME	: 13:35HR
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH <i>Dented</i>	1	\$ 1,055.30	\$ 1,055.30
2	FRONT DOOR LOCK LH <i>2</i>	1	\$ 299.50	\$ 299.50
3	FRONT DOOR INNER BOARD <i>new</i>	1	\$ 655.30	\$ 655.30
4	FRONT DOOR WEATHERSTRIP	1	\$ 297.30	\$ 297.30
5	FRONT DOOR POWER WINDOW MOTOR <i>new</i>	1	\$ 522.30	\$ 522.30
6	FRONT DOOR WINDOW REGULATION <i>new</i>	1	\$ 388.70	\$ 388.70
7	REAR DOOR LH <i>Dented</i>	1	\$ 1,055.30	\$ 1,055.30
8	REAR DOOR HINGE(UPPER) <i>2</i>	1	\$ 89.00	\$ 89.00
9	REAR DOOR HINGE(LOWER) <i>new</i>	1	\$ 89.00	\$ 89.00
10	REAR DOOR WEATHERSTRIP	1	\$ 297.30	\$ 297.30
11	REAR DOOR STRIP	1	\$ 133.20	\$ 133.20
12	ROCKER PANEL LH <i>Repairs</i>	1	\$ 655.50	\$ 655.50
13	SIDE SKIRT LH <i>Deformed</i>	1	\$ 460.90	\$ 460.90

2571.5
2057.20

TOTAL PRICE \$5,998.60

LESS 20% \$ 1,199.72

SUB TOTAL PRICE \$4,798.88

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR STICKER(SMALL) <i>new</i>	1	\$ 60.00	\$ 60.00

2	FRONT DOOR STICKER(BIG) <i>mu</i>	1	\$ 80.00	\$ 80.00	✓
3	FRONT DOOR INNER BOARD CLIPS(SET) <i>mu</i>	1	\$ 30.00	\$ 30.00	✓
4	REAR DOOR STICKER(BIG) <i>mu</i>	1	\$ 80.00	\$ 80.00	✓
5	SIDE SKIRT CLIPS(SET) <i>mu</i>	1	\$ 25.00	\$ 25.00	✓
6	DOOR RED STRIP <i>lt</i>	1	\$ 180.00	\$ 180.00	✓ 100.

345

TOTAL

\$455.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,200.00	500.	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	700.	
3	TUFF COAT	\$ 100.00	x	
4	REMOVE AND REFIX FRONT REAR MECHANISM	\$ 180.00	80	
5	REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 180.00	80	

1360

TOTAL

\$2,860.00

ESTIMATE REPORT

TOTAL PARTS COST : \$5,253.88
TOTAL LABOUR COST : \$2,860.00
TOTAL REPAIR COST : \$8,113.88

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lj total: 3762.20
1/s 17/01/19 h/s: 3K.
05 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FC119001015/Atd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-02-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8555Y	Veh. Inspected	SMD 4401A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000363MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	16/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71218436	Colour	BLACK	
Odometer	16465	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	FALKEN	6 mm	
L/H Front Tyre	205/50 R16	FALKEN	6 mm	
R/H Rear Tyre	205/50 R16	FALKEN	6 mm	
L/H Rear Tyre	205/50 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/01/2019	Inspection Date	17/01/2019	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 4401A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR LH	DENTED	1,055.30	1,055.30
1	FRONT DOOR LOCK LH	NOT NECESSARY	299.50	-
1	FRONT DOOR INNER BOARD	NOT NECESSARY	655.30	-
1	FRONT DOOR WEATHERSTRIP	NOT NECESSARY	297.30	-
1	FRONT DOOR POWER WINDOW MOTOR	NOT NECESSARY	522.30	-
1	FRONT DOOR WINDOW REGULATION	NOT NECESSARY	388.70	-
1	REAR DOOR LH	DENTED	1,055.30	1,055.30
1	REAR DOOR HINGE (UPPER)	NOT NECESSARY	89.00	-
1	REAR DOOR HINGE (LOWER)	NOT NECESSARY	89.00	-
1	REAR DOOR WEATHERSTRIP	NOT NECESSARY	297.30	-
1	REAR DOOR STRIP	NOT NECESSARY	133.20	-
1	ROCKER PANEL LH	TO REPAIR SEE LABOUR	655.50	-
1	SIDE SKIRT LH	DEFORMED	460.90	460.90
	LESS 20% DISCOUNT		-1,199.72	-514.30
			4,798.88	2,057.20
SPECIAL NETT ITEMS				
1	FRONT DOOR STICKER (SMALL)(SN)	NECESSARY	60.00	60.00
1	FRONT DOOR STICKER (BIG)(SN)	NECESSARY	80.00	80.00
1	SET FRONT DOOR INNER BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR DOOR STICKER (BIG)(SN)	NECESSARY	80.00	80.00
1	SET SIDE SKIRT CLIPS (SN)	NECESSARY	25.00	25.00
1	DOOR RED STRIP (SN)	CUT	180.00	100.00
			455.00	345.00
LABOUR				
	TO PANEL BEAT, REMOVE AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF ROCKER PANEL LH.		1,200.00	500.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	700.00
	TUFF COAT.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX FRONT REAR MECHANISM.		180.00	80.00

Report Ref No. CS/FCI19001015/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX FRONT DOOR MECHANISM.		180.00	80.00
			2,860.00	1,360.00
GRAND TOTAL			8,113.88	3,762.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/FCI19001015/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.