



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2004908  
INV Date 14/07/2020  
Reference CC4/LPC19001016/Uba3n2  
Code LPC2



### PROFESSIONAL SERVICE FEE

Vehicle No. GBG 5111U  
Insured Veh. XD 6513S  
Claim No. 18/19/19/VC05/021321  
Policy No. Z18VC05000790  
Accident Date 12/01/2019  
Inspection Date 16/01/2019

Description	Total
Third Party Express Settlement	450.00
<b>Subtotal</b>	<b>450.00</b>
<b>GST (7%)</b>	<b>31.50</b>
<b>Grand Total</b>	<b>481.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19001016/Uba3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 14-07-2020



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 6513S	Veh. Inspected	GBG 5111U
Policy No.	Z18VC05000790	Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021321	Excess (\$)	0.00
Assign From	GERALD	Assign Date	15/01/2019

### 2. Vehicle Particulars & Condition

Make & Model	KIA K2500 (M)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNCSJX76LH7165902	Colour	BLUE
Odometer	61809	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	5.00 R12 (D)	HANKOOK	6/6 mm
L/H Rear Tyre	5.00 R12 (D)	HANKOOK	6/6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	12/01/2019	Inspection Date	16/01/2019
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 5111U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	BADLY DENTED	1,665.50	1,050.00
3	TAILGATE HINGES @\$78.50	BENT (2 PCS ONLY)	235.50	157.00
2	TAILGATE LOCK HANDLE @\$122.30	NOT NECESSARY	244.60	-
2	TAILGATE SIDE LOCK @\$98.50	O/S BENT	197.00	98.50
2	TAILLAMP ASSY @\$289.50	O/S CRACKED	579.00	289.50
4	REAR STOPPERS @\$12.50	O/S CUT	50.00	12.50
1	REAR END PANEL	BADLY DENTED	589.50	589.50
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	2,458.60	-
1	REAR BUMPER	BENT	425.50	425.50
2	REAR BUMPER BRACKETS @\$95.20	BENT	190.40	190.40
1	REAR NO. PLATE LAMP	BROKEN	98.50	98.50
1	REAR NO. PLATE LAMP BRACKET	BENT	102.50	102.50
	LESS 10% DISCOUNT		-683.66	-301.39
			6,152.94	2,712.51
<b><u>SPECIAL NETT ITEMS</u></b>				
1	TAILGATE STICKER -70KM/H (SN)	NECESSARY	12.00	10.00
1	TAILGATE STICKER-13PAX (SN)	NECESSARY	12.00	10.00
1	TAILGATE INNER ALUMINIUM PLATE (SN)	BENT	500.00	220.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	REAR FLOOR PANEL CHECKER PLATE (SN)	BUCKLED	1,500.00	680.00
2	REAR SIDE CANOPY LOWER RAIL @\$350.00 (SN)	NOT NECESSARY	700.00	-
2	REAR SIDE CANOPY LOWER RAIL BRACKET @\$65.00 (SN)	NOT NECESSARY	130.00	-
1	REAR CRASH BAR (REINFORCEMENT) (SN)	NOT NECESSARY	350.00	-
1	REAR NO.PLATE WITH COVER (SN)	BENT	45.00	40.00
1	REAR NO.PLATE LAMP TOP COVER (ALUMINIUM) (SN)	BENT	100.00	100.00
			3,599.00	1,260.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AD MENTIONED ABOVE ETC.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL .		1,500.00	1,200.00
	TO RESPRAY AFFECTED PART		900.00	800.00
	TO SPPLY UNDERSEAL.		100.00	60.00
	TO CHECK WIRING.		30.00	30.00
			2,530.00	2,090.00
	<b>GRAND TOTAL</b>		<b>12,281.94</b>	<b>6,062.51</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,850.00</b>

Report Ref No. CC4/LPC19001016/Uba3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 5111U

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 5111U

RE-INSPECTION

