

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 12/8/2013

Reference: SLQ506B
OPEL MOKKA X
Make: 1.6 CDTI 6AT

TPAXA.
Vic.

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLQ506B
CHASSIS NO.: W0LJD7EC5HB179333
ENGINE NO.: A1170165GU7X0137

Name of insured : Alpine Car Rental Pte Ltd
Date of accident.: 12/01/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Rear Bumper	\$ 1,800.00
2	1	Rear Bumper Lower	\$ 1,390.00
3	1	Rear Bumper Towing Cover	\$ 90.00
4	1	Rear Bumper Sill Plate	\$ 344.00
5	1	LHF Bumper Reflector	\$ 150.00
6	1	RHF Bumper Reflector	\$ 150.00
7	1	Rear Bumper Reinforcement Bar	\$ 671.00
8	1	Rear End Panel	\$ 1,217.00
9	1	Rear End Panel Trim	\$ 150.00
10	1	Rear Bumper Absorber - RH	\$ 82.00
11	1	Rear Bumper Absorber - LH	\$ 82.00
12	1	LHR Bumper Bracket, Guide	\$ 70.00
13	1	RHR Bumper Bracket, Guide	\$ 70.00
14	1	LHR Bumper Bracket	\$ 65.00
15	1	RHR Bumper Bracket	\$ 65.00
16	1	LHR Lower Bumper Bracket	\$ 80.00
17	1	RHR Lower Bumper Bracket	\$ 80.00

4565
4108.50

Parts Total: \$ 6,556.00
Less 10%: \$ 655.60

Total : \$ 5,900.40

Labour

Labour Description

No.

Price (SGD)

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 1,650.00	550
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 1,350.00	450
3	To conduct anti rust of under carriage tuff coat	\$ 200.00	x
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
5	To remove and refix reverse sensor and conduct test	\$ 80.00	50

1080

Labour Total : \$ 3,310.00

Others

Other Description

No. Qty

Price (SGD)

Rear portion

1	10	Rear bumper upper clip <i>2 per</i>	Rear bumper upper clip	\$ 65.00	30
2	10	Rear bumper lower clip <i>1</i>	Rear bumper lower clip	\$ 65.00	30
3	1	Reverse sensor 1 set <i>not in</i>	Reverse sensor 1 set	\$ 640.00	x

60

Other Total: \$ 770.00

GRAND TOTAL: \$ 9,980.40

VB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Suhaimi O
Suhaimi O

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax:6844 5185

Adrian King
P/P 17/01/19

030 days.

Self: 5248.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: