

Your Ref: 19.26068 PD-O

Date: 01<sup>st</sup> Feb 2019

Our Ref : CS3/ASM18015875/Bqd3e2-1

**M/s AXA Insurance Pte Ltd**

C/O: Seah Ong &amp; Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBE 6696C  
INSURED VEHICLE: GBA 9811M  
ACCIDENT DATE: 27/08/2018**

We thank you for your instruction on 16/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBE 6696C from M/s Prominent Appraiser Services Pte Ltd.
- b) Singapore Accident Statement of Vehicle GBE 6696C and GBA 9811M.
- c) Police Report of Vehicle GBE 6696C.
- d) Final Repair Bill of GBE 6696C from My Car Consultant Pte Ltd.
- e) Colour damaged vehicle photographs of GBE 6696C.

Pre-Repair Inspection Date : 31/08/2018 at M/s My Car Consultant Pte. Ltd, 53 Ubi Avenue 1 #01-33, Paya Ubi Industrial Park, Singapore 408934

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

|                      |                              |
|----------------------|------------------------------|
| Registration Number  | : GBE 6696C                  |
| Make & Model         | : Mercedes Benz Vito 114 CDI |
| Year of Registration | : 2015                       |
| Chassis Number       | : WDF44760323074930          |
| Engine Capacity      | : 2143 cc                    |

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.