

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III19001068/DPS3Q2  
**Date:** 06/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SJG1617J	<b>Insured Vehicle No :</b>	SHB6643A
Date of Loss:	07/01/2019	Nature of Claim:	TP
		Claim No:	MCT19010177

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJG1617J</b>	Engine No:	G4KEFH173739
Make & Model:	KIA OPTIMA, 2.4 (A)	Chassis No:	KNAGN412MF5611300
Reg. Date:	16/06/2015 (Man. Year: 2015)	Odometer:	58880 km
Colour:	Black		
Engine Capacity:	2359 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,581.68	1,960.06	2,621.62	57.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,250.00	960.00	43.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,791.68</b>	<b>3,210.06</b>	<b>3,581.62</b>	<b>52.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,550.00</b>		

(S\$)	6,791.68	2,550.00	4,241.68	62.45
+ GST 7.00/7.00% (S\$)	475.42	178.50	296.92	62.45
Nett Amount (S\$)	7,267.10	2,728.50	4,538.60	62.45
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	16/01/2019		
Date Inspected:	17/01/2019	Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	4.0 days		

Adjuster:	BRYAN TANI	Manager:	CHEW HSIAO TONG
-----------	------------	----------	-----------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2019)
<b>Parts:</b>	143	KIA OPTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJG1617J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	681.50 FL	*- FL
2	1		*REAR BUMPER SIDE RETAINER	Not Necessary	76.50 FL	*- FL
3	1		*REAR RH FENDER	Repair	543.80 FL	*- FL
4	1		*REAR RH SHOCK ABSORBER	Distorted	561.10 FL	*561.10 FL
5	1		*REAR RH KNUCKLE ARM	Distorted	463.30 FL	*463.30 FL
6	1		*REAR RH KNUCKLE ARM BEARING	Damaged	150.88 FL	*150.88 FL
7	1		*REAR RH LOWER ARM	Distorted	335.90 FL	*335.90 FL
8	1		*RIM	Cut	1,200.00 FS	*600.00 FS
9	1		*TYRE	Serviceable	800.00 FS	*- FS
10	1		*SET REAR BUMPER CLIP	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,862.98</b>	<b>2,111.18</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	281.30	151.12
<b>Total Parts (\$\$)</b>	<b>4,581.68</b>	<b>1,960.06</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	0.00
2	CHECK REAR WHEEL ALIGNMENT	New	200.00	60.00
3	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	New	200.00	150.00
4	PANEL BEATING ON AFFECTED AREAS	New	800.00	500.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	500.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>2,210.00</b>	<b>1,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >