

22/03/2002

ASS. REC. BY:

REF: CS/FCI 19001117/ Ds d3n2 Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): Scene for of FCI Date/Time: 5:10pm @ 17/1/19

Estimated Cost: Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHC 8243C Insured: SHA 9589Jat Workshop m/s Chunni Motor Tel: 65425119of AMK Autopoint #01-05/06Policy No: Claim No: D19000428MF84

Sum Insured: Excess:

Make of Veh: D.O.A. 14/1/19
(Client's Record) 18/1/19

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement:

Date/Time: 5:38pm @ 17/1/19 Person Contacted: Jynn Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 8243C - CS / III 18016909 / Ky be 2 DUA: 27/8/18
	SHA 9589J - CS / FCI 18022885 / Aqob DUA: 18/12/18
23/1/19	Email preli revised to FCI

REF:


ASSIGNMENT

CBE March 2023

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 8243C Yr Regn: 2015 March
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai I40 C.C. 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 539431 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDEU41222
 C/No: KMHLB41UMFU065307
 Gen. Cond: 6 / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60 R16
 R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 14/01/2019D.O.I. 18/01/2019Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

W/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SHH 95895

12/02/19 Johny L/S 95895 - with 10 days of work
 (Red. # 7066.04, 43%)

RECEIVED 14 FEB 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

14/2 - typstDays Of Repair: 10Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$) 9200/-

Survey Fee:

Transportation:

) S + RS: \$

) Photos: 800) Others: 14/2/19

TOTAL

6x15=90170+905050+50120530



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000428MFSH

Our ref: CS/FCI19001117/DSd3

Date:23/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 8243C


We thank you for your instruction on 17/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/1/2019 at the premises of M/s CHUNNI MOTOR WORKS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$16,266.04
Revised Estimate Amount	: S\$11,562.36
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	15-01-2019	Our Ref No. D19000428MFSH
Accident Date	14-01-2019	Claim Type. Third Party
Insured Vehicle	SHA9589J	Third Party Vehicle. SHC8243C
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	DIRECT SETTLEMENT: EST. COR - \$16,266.04	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 23 January 2019 10:34 AM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000428MFSH/1, SHC 8243C
Attachments: SHC 8243C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 8243C
Date of survey: 18/1/2019
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 17 January 2019 5:39 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000428MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 17 January 2019 5:10 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000428MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 8243C

DATE : 14.01.2019

MAKE :

TEL : 6542 5119


MODEL : HYUNDAI i40

FAX : 6542 6039

FCE (ChryCab)

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Dented</i>			\$ 553.00	✓
	Rear Bumper Clip 10 pcs <i>Hec</i>			\$ 22.00	✓
	Rear Bumper Bracket, LH <i>SVC</i>			\$ 35.60	X
	Rear Fender With Housing (LH) <i>Dented</i>			\$ 4,736.80	✓
	Rear Fender Inner Lining (LH) <i>distorted</i>			\$ 169.30	✓
	Rear Fender Air-Duct <i>NH</i>			\$ 51.60	X
	Rear Windscreen Moulding <i>Hec</i>			\$ 28.30	✓
	Fuel Tank <i>NH</i>			\$ 962.90	X
	Fuel Tank Sub Hose <i>NH</i>			\$ 78.20	X
	Fuel Tank Upper Neck <i>NH</i>			\$ 221.10	X
	Fuel Lid Cover <i>distorted</i>			\$ 59.40	✓
	Rocker Panel Outer Garnish (LH) <i>NH</i>			\$ 341.40	X
	Rear Door (LH) <i>Dented</i>			\$ 2,201.10	✓
	Rear Tyre Rim (LH) <i>bst</i>			\$ 325.30	✓
	Rear Wheel Hup-Cap (LH) <i>bst</i>			\$ 107.10	✓
	Rear Wheelbearing ING & Hub <i>Done</i>			\$ 362.00	✓
	Rear Trailing Arm (LH) <i>distorted</i>			\$ 192.00	✓
	Rear Assist (LH) <i>distorted</i>			\$ 145.70	✓
	Rear Shock Absorber (LH) <i>distorted</i>			\$ 276.30	✓
	Rear Shock Absorber Mounting (LH) <i>NH</i>			\$ 81.30	X
	Rear Crossmember <i>distorted / bst</i>			\$ 1,021.50	✓
	Stabilizer Bar <i>distorted</i>			\$ 199.60	✓
	Stabilizer Link <i>distorted</i>			\$ 85.90	✓
	Rear Upper Arm (LH) <i>distorted</i>			\$ 335.75	✓
	Rear Lower Arm (LH) <i>distorted</i>			\$ 353.80	✓
	Rear Knuckle Arm (LH) <i>distorted</i>			\$ 545.60	✓
			11720.45		
			9376.36		
	SUB TOTAL			\$ 13,492.55	
	LESS 20%			\$ 2,698.51	
	DISCOUNTED TOTAL			\$ 10,794.04	
	Rear Bumper Advertisement Logo <i>Hec</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>Hec</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>Hec</i>			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (LH) <i>Hec</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Hec</i>			\$ 80.00	Nett ✓
	Rear Tyre (LH) <i>SVC</i>			\$ 216.00	Nett X
			476.00		
				\$ 692.00	

SHC 8243C

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 600/-
	Spray Painting Charge			\$ 1,250.00 600/-
	Wiring Charge			\$ 50.00 H/W
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 H/W
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Remove/Refix Fuel Tank			\$ 120.00 H/W
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System		1710.00	\$ 200.00 H/W
	Trnasfer of Door			\$ 120.00 60/-
	Re-set Rear Power Window System			\$ 200.00 H/W
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 H/W
	TOTAL LABOUR			\$ 4,780.00
	ESTIMATE TOTAL			\$ 16,266.04
	18/01/2019 @ 1100hrs Kia Activa 2 Shm 10 days.  ryan LKK Auto 			
	1156236 4159200/-			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 8243 C

Technician:

Mileage: 539431

Time Printed 18.1.19 12:12 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°26'		-3°00' 3°00'
6°20'		-0°19' 5°41'
0°25'		-1°30' 1°30'
21°31'		
21°05'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°46'		-3°00' 3°00'
6°47'		-0°19' 5°41'
-0°16'		-1°30' 1°30'
17°09'		
16°23'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°20'		-3°00' 3°00'
-0°28'		-3°00' 3°00'
4°22'		-3°00' 3°00'
0°09'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
3°58'		-3°30' 2°30'
7°27'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
1°45'		-3°30' 2°30'
0°37'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
2°12'		-3°00' 3°00'
8°04'		-3°00' 3°00'
3°25'		-3°00' 3°00'

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19001117/Dsd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-02-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9589J	Veh. Inspected	SHC 8243C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000428MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	17/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMFU065307	Colour	BLUE	
Odometer	539431	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/01/2019	Inspection Date	18/01/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8243C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	553.00	553.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET, LH	SERVICEABLE	35.60	-
1	REAR FENDER WITH HOUSING (LH)	DENTED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (LH)	DEFORMED	169.30	169.30
1	REAR FENDER AIR-DUCT	NOT NECESSARY	51.60	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	FUEL TANK	NOT NECESSARY	962.90	-
1	FUEL TANK SUB HOSE	NOT NECESSARY	78.20	-
1	FUEL TANK UPPER NECK	NOT NECESSARY	221.10	-
1	FUEL LID COVER	DISLODGE	59.40	59.40
1	ROCKER PANEL OUTER GARNISH (LH)	NOT NECESSARY	341.40	-
1	REAR DOOR (LH)	DENTED	2,201.10	2,201.10
1	REAR TYRE RIM (LH)	BENT	325.30	325.30
1	REAR WHEEL HUP-CAP (LH)	BENT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	192.00	192.00
1	REAR ASSIST (LH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED / BENT	1,021.50	1,021.50
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-2,698.51	-2,344.09
			10,794.04	9,376.36
SPECIAL NETT ITEMS				
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00

Report Ref No. CS/FCI19001117/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
			692.00	476.00
	LABOUR			
	PANEL BEATING.		1,500.00	600.00
	SPRAY PAINTING CHARGE.		1,250.00	600.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	120.00	-
	REAR WHEEL ALIGNMENT.		120.00	60.00
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	200.00	-
	TRANSFER OF DOOR.		120.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			4,780.00	1,710.00
GRAND TOTAL			16,266.04	11,562.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,200.00

Report Ref No. CS/FCI19001117/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.