

ASS. REC. BY:

REF:

CS/SMO19001163/Dg d3 n2

Special Instruction:

Surveyor:
Merimen

ASSIGNMENT (Office)

From (Person):

Gnoh Pau Loong

of

SMO

Date/Time:

18/1/19 @ 11:54am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM7825Z

Insured:

SDR3733G

at Workshop m/s

SG. 98 Motor

Tel:

64524898

of

Blk 4001, AMK Ind. park 1 #01-21

Policy No:

D18MTPV01017834

Claim No:

CMTD1900406

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

16/01/2019

CA / REV / REP. / REV 24 HRS

lap

21/1/19

H.O.D. Endorsement:

Date/Time:

2:28pm @ 18/1/19

Person Contacted:

Rose

Vehicle-IN/

OUT

Date/Time

Action/Instruction (✓) Estimate

FBM7825Z - X

SDR3733G - CS/SMO19001143/d3

DOA: 16/1/19


28/01/19

@ 15:34 p.m. revised IN to Gnoh Pau Loong via merimen.

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehl: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: FBM 78252 Yr Regn: 2014 Maron
 Type: M.Car / M. Cycle Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Suzuki GSX 1300 RAL4 1340
 Colour: White / Black A/C Insured / Std / NI / NA
 Sp. Reading: 46826 T/Radio: Insured / Std / NI / NA
 Eng/No: X704151108
 C/No: JS1CK131BE0100060
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: 120/70 R17
 R: 190/50 R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Michelin
 Front R/Bal. 3 mm Rear R/Bal. 3 mm
 L/Bal. mm L/Bal. mm
 D.O.A. 16/01/2019 D.O.I. 21/01/2019
 Survey held at SG 98 AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 N/S Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Sompo SDR 3733 G
26/04/19	Insured L/S 1050/- with 4 days of work (F 583.50 Red - 36%)

RECEIVED 26 APR 2019

Date/Time, File Pass to? 26/04/19
 1) : Preli. Report
 : Final Report
 Date/Time, File Return to? Typ. 24

Days Of Repair: 4
 Resurvey No. of Trip: 1

Survey Fee: _____
 Transportation: _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Techn. Invs (\$)
 Weekend (\$)

) S + RS \$
) Photos
) Other

Report Format:
 Lump Sum / I.B.I: (\$) 1,050/- L/S

250
10
TOTAL 260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 28 Jan 2019

Preliminary Advice

Insured Vehicle No	: SDR3733G	Accident Date	: 16/01/2019
TP Vehicle No	: FBM7825Z	Assignment Date	: 18/01/2019
Make	: SUZUKI HAYABUSA 1300	Est. Duration of Repair	: 4 days
Date of Inspection	: 21/01/2019		
Inspection At	: Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,608.50
Revised Amount	:S\$	1,393.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,393.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2019		18 Jan 2019 11:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	LEONG CHEE ONN, ID: S1610093E, Tel: +6590120823, Email: fleong3733@gmail.com		
Main Claimant:	THEEBAN S/O SANDERAN, ID: S9244362J		
Vehicle Reg. No.:	FBM7825Z	Date of Loss:	16/01/2019 08:00 - :59
Claim Type:	TP / CMTD1900406	Policy/Cover Note No.:	D18MTPV01017834 (Comprehensive)
Vehicle Reg. No. (Insured):	SDR3733G	Policy No. (Claimant):	
		Excess:	
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/01/2019]		
Driver/Custodian (Insured):	LEONG CHEE ONN (55 / Male), NRIC: S1610093E, Tel: +6590120823		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 21 January 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel : 97237799

VEHICLE NO : FBM 7825Z

Suzuki Haya Busa 1300

ACCIDENT DATE: 16 January 2019

Description	Qty	Quotation \$
1 Body Frame Slider cut H/S	1 set pc	200.00 ✓ 100.00
2 Magnetic Slider cover broken/cracks	1	250.00 ✓
3 Front LH Centre Fairing cut	1	650.00 ✓
4 Gasket Set Huc	1	65.00 ✓
	1065.00	
	95% 50	
Sub-Total		1,165.00
Less 10%		116.50
Sub-Total		1,048.50

Nett items

1 Towing fee Huc	60.00	30/-
2 Remove & replace parts, align & etc	220.00	150/-
3 Putty & respray paint, supply body sticker	345.00	280.00 150/-
4 Top up engine oil Huc 100.00	25.00	15/-
Sub-Total	560.00	1633.50
Nett Total	560.00	1303.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

21/01/2019 @ 1100hrs

L/S 1050/-

NA Authorized

L/Srm 4 days.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

GT:

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Reparer

Signature: *[Signature]*

Date: *[Signature]*

LKK Auto

[Signature]

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19001163/DSD3N2

Date: 06/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01017834
Claimant Vehicle No :	FBM7825Z	Insured Vehicle No :	SDR3733G
Date of Loss:	16/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900406

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM7825Z	Engine No:	X704151108
Make & Model:	SUZUKI HAYABUSA 1300, 1.3	Chassis No:	JS1CK131BE0100060
Reg. Date:	26/03/2014 (Man. Year: 2013)	Odometer:	46826 km
Colour:	Black/White		
Engine Capacity:	1340 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	190/50 R17
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,073.50	973.50	100.00	9.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	560.00	330.00	230.00	41.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,633.50	1,303.50	330.00	20.20
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	1,633.50	1,050.00	583.50	35.72

INSPECTION

Date of Assignment:	18/01/2019	
Date Inspected:	21/01/2019	Inspected At:
		Sg 98 Motor Pte Ltd (HQ)
		BLK 4001 ANG MO KIO INDUSTRIAL
		PARK 1 #01-21
		Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 May 2019)	
Parts:	N/A	SUZUKI HAYABUSA 1300 1.3 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM7825Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BODY FRAME SLIDER N/S	Cut	200.00 FL	*100.00 FL	
2	1		*MAGNETIC COVER	Broken / Cracked	250.00 FL	*250.00 FL	
3	1		*FRONT LH CENTRE FAIRING	Cut	650.00 FL	*650.00 FL	
4	1		*SET GASKET	Necessary	65.00 FL	*65.00 FL	
5	1		*TOP UP ENGINE OIL	Necessary	25.00 FS	*15.00 FS	
					Sub Total (\$\$)	1,190.00	1,080.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	116.50	106.50
					Total Parts (\$\$)	1,073.50	973.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	60.00	30.00
2	REMOVE & REPLACE PARTS ,ALIGN & ETC	New	220.00	150.00
3	PUTTY & RESPRAY PAINT ,SUPPLY BODY STICKER	New	280.00	150.00
Gross Labour Cost (S\$)			560.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >