



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003150
INV Date 14/04/2020
Reference CC6/CTI19001170/Ada3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SJT 2778C
Insured Veh. GBA 8862Y
Claim No. SNM19D200381C02/2
Policy No. DMCVSN1825291800
Accident Date 16/01/2019
Inspection Date 17/01/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19001170/Ada3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 14-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 8862Y	Veh. Inspected	SJT 2778C
Policy No.	DMCVSN1825291800	Coverage (\$)	0.00
Claim No.	SNM19D200381C02/2	Excess (\$)	0.00
Assign From		Assign Date	17/01/2019

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET CRUZE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KL1JA6961AK534439	Colour	SILVER
Odometer	80742	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/01/2019	Inspection Date	17/01/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 2778C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	833.50	833.50
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	72.50	72.50
1	FRONT FENDER LH	DISTORTED	533.50	533.50
1	FRONT FENDER SIGNAL LAMP LH	CRACKED	60.20	60.20
1	FRONT FENDER INNER COWLING LH	DEFORMED	170.20	170.20
1	FRONT SIDE MIRROR ASSEMBLY LH	MISSING	455.30	455.30
1	FRONT SIDE MIRROR COVER LH	CRACKED	90.50	90.50
1	FRONT DOOR LH	DISTORTED	987.00	987.00
1	FRONT DOOR HINGE (UPPER)	BENT	63.20	63.20
1	FRONT DOOR HINGE (LOWER)	BENT	63.00	63.00
1	FRONT DOOR CHECKER	BENT	128.00	128.00
1	FRONT DOOR LOCK	JAMMED	230.00	230.00
1	FRONT DOOR CATCH	NOT NECESSARY	80.00	-
1	FRONT DOOR WEATHERSTRIP	NOT NECESSARY	188.20	-
1	FRONT DOOR OUTER HANDLE	TO REPAIR SEE LABOUR	98.00	-
1	FRONT DOOR OUTER PILLAR	CUT	140.00	140.00
1	FRONT DOOR OUTER GARNISH	DISTORTED	166.70	166.70
1	FRONT DOOR POWER WINDOW MOTOR	NOT NECESSARY	433.50	-
1	FRONT DOOR POWER REGUALTION	NOT NECESSARY	280.50	-
1	FRONT DOOR GLASS	CUT	380.00	380.00
1	FRONT DOOR GLASS CHANNEL	NOT NECESSARY	188.90	-
1	REAR DOOR LH	TO REPAIR SEE LABOUR	987.00	-
1	REAR DOOR OUTER HANDLE	TO REPAIR SEE LABOUR	98.00	-
1	REAR DOOR OUTER PILLAR	CUT	140.00	140.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	933.50	-
	LESS 10% DISCOUNT		-780.12	-451.36
			7,021.08	4,062.24

Report Ref No. CC6/CTI19001170/Ada3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT FENDER INNER COWLING CLIPS (SN)	NECESSARY	20.00	20.00
			40.00	40.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR OUTER HANDLE ,REAR DOOR LH,REAR DOOR OUTER HANDLE AND REAR FENDER LH.		2,000.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		2,000.00	1,200.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.		120.00	30.00
	TO TRANSFER FRONT DOOR MECHANISM.		120.00	80.00
	TO TRANSFER REAR DOOR MECHANISM.	NOT NECESSARY	120.00	-
			4,610.00	2,110.00
GRAND TOTAL			11,671.08	6,212.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CC6/CT119001170/Ada3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.