7/29/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/FWD19001191/APA3Q2

Date:

29/07/2021

REFERENCE

Date of Loss:

Handling Insurer: FWD Singapore Pte. Ltd. Policy No:

PNPV2018-00001843

Claimant Vehicle No:

SKR6768D 14/01/2019 Insured Vehicle No: Nature of Claim:

ΤP

SLH9964A

Claim No:

1201900002541

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SKR6768D** 

Make & Model: SUZUKI GRAND VITARA, 2.0 5DOOR 2WD ABS AIRBAG (A) Engine No: J20A674336 Chassis No:

Reg. Date: 27/05/2009 (Man. Year: 2009)

Odometer:

JSAJTE54V00520120

155755 km

Colour: Silver

**Engine Capacity:** 1995 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Handbrake (Serviceable):

**Engine Modification:** Yes

No

Pre-accident Condition:

Yes

**CONDITION OF TYRES** 

Front Tyre Size: 225/55 R18 Rear Tyre Size:

225/55 R18

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,509.08	2,104.98	1,404.10	40.01
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,110.00	1,260.00	850.00	40.28
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,619.08	3,364.98	2,254.10	40.12
	Approved Total (Overridden) (S\$)		2,700.00		

Nett Amount (S\$)	5,619.08	2,700.00	2,919.08	51.95
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		_
	Nett Liability (S\$)	3,020.00		

**INSPECTION** 

Date of Assignment: 18/01/2019

TEK SOON MOTOR REPAIR & SPRAY PAINTING (HQ) 1 KAKI BUKIT AVE 6, BLK D #01-93,, AUTOBAY@KAKI BUKIT Date Inspected: Inspected At: 30/01/2019

Singapore 417883

Estimated Period of Repair: 4.0 days

ADRIAN LING Adjuster: Manager: **CHEW HSIAO TONG** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2021)

SUZUKI GRAND VITARA 2.0 5DOOR 2WD ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0) Parts: 192

Repairer's (Price-denominated Standard List) Labour:

(Unsubmitted, no print-code for SKR6768D) **Print Code:** 

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Recommended Parts**

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*REAR TAILGATE	Dented	773.60 FL	*773.60 FL
2 1	*REAR TAILGATE DAMPER	Not Necessary	109.90 FL	*- FL
3 1	*REAR TAILGATE INNER BOARD	Cracked	195.15 FL	*195.15 FL
4 1	*REAR TAILGATE LOCK	Not Necessary	162.35 FL	*- FL
5 1	*REAR TAILGATE RUBBER	Not Necessary	87.10 FL	*- FL
6 1	*REAR TAILGATE VITARA EMBLEM	Necessary	30.25 FL	*30.25 FL
7 1	*REAR TAILLAMP	Not Necessary	186.15 FL	*- FL
8 1	*REAR END PANEL	Repair	188.95 FL	*- FL
9 1	*REAR BUMPER	Deformed	669.10 FL	*669.10 FL
10 1	*REAR BUMPER REFLECTOR	Not Necessary	24.75 FL	*- FL
11 1	*REAR BUMPER SIDE RETAINER	Necessary	18.15 FL	*18.15 FL
12 1	*REAR SPARE TYRE OUTER COVER	Deformed	456.85 FL	*456.85 FL
13 1	*REAR SPARE TYRE INNER COVER	Not Necessary	390.30 FL	*- FL
14 1	*REAR SPARE TYRE COVER SUZUKI EMBLEM	Necessary	98.05 FL	*98.05 FL
15 1	*REAR SPARE WHEEL BRACKET	Not Necessary	196.50 FL	*- FL
16 1	*REAR WINDSCREEN SEAL	Not Necessary	50.00 FS	*- FS
17 1	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
18 1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
19 1	*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
F=Franchise part. S=SpcNe	tt. L=ListItemDisc.			
		Sub Total (S\$)	4,047.15	2,441.15
		- List Item Discount on L Items 15.00/15.00% (S\$)	538.07	336.17
		Total Parts (S\$)	3,509.08	2,104.98

Report was unsubmitted during this print-out.

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	120.00	40.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	50.00
4	TO REMOVE AND REFIT WINDSCREEN GLASS	New	180.00	0.00
5	PANEL BEATING	New	750.00	500.00
6	SPRAY PAINTING	New	750.00	600.00
7	TO UNDERSEAL	New	110.00	40.00
		Gross Labour Cost (S\$)	2,110.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >