



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 4588T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	R/F DOOR MOULDING (CONSISTENT)	TO REPAIR SEE LABOUR	85.00	-
1	R/DOOR MIRROR (CONSISTENT)	CRACKED	680.00	680.00
1	R/ DOOR MIRROR GLASS (CONSISTENT)	SERVICEABLE	50.00	-
1	R/OUT DR MIRROR CVR (CONSISTENT)	SERVICEABLE	80.00	-
1	R/R DOOR (CONSISTENT)	BENT	780.00	780.00
1	R/R UPPER DOOR HINGE (CONSISTENT)	SERVICEABLE	60.00	-
1	R/R LOWER DOOR HINGE(CONSISTENT)	SERVICEABLE	60.00	-
1	R/R DOOR REAR STRIP (CONSISTENT) (NPA)	SERVICEABLE	-	-
1	R/R DOOR FRONT STRIP (CONSISTENT) (NPA)	SERVICEABLE	-	-
1	R/R UPP DOOR STRIPE (CONSISTENT) (NPA)	SERVICEABLE	-	-
1	R/R DOOR MOULDING (CONSISTENT)	CUT	85.00	85.00
1	MIRROR SIGNAL (R) (CONSISTENT)	SCRATCHED	85.00	85.00
1	RIGHT FRONT DOOR (CONSISTENT)	BENT	850.00	850.00
1	R/F UPPER DOOR HINGE (CONSISTENT)	SERVICEABLE	60.00	-
1	R/F LOWER DOOR HINGE (CONSISTENT)	SERVICEABLE	60.00	-
1	R/F OUTER HANDLE (CONSISTENT)	TO REPAIR SEE LABOUR	185.00	-
1	R/F DOOR REAR STRP (CONSISTENT) (NPA)	SERVICEABLE	-	-
1	R/F DOOR STRIPE (CONSISTENT) (NPA)	SERVICEABLE	-	-
1	R/F DOOR FRONT STRIP (CONSISTENT) (NPA)	SERVICEABLE	-	-
			3,120.00	2,480.00
<u>SPECIAL NETT ITEMS</u>				
1	BODY SEALANT BODY SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
			80.00	40.00
<u>LABOUR</u>				
243.0 WU X 45.00 SGD/H.			1,093.50	1,093.50
LABOUR COST 95.0 WU X 45.00 SGD/H.INCLUSIVE OF THE REPAIR OF R/F DOOR MOULDING AND R/F OUTER HANDLE .			427.50	387.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	MATERIAL COST.		144.23	144.23
			1,665.23	1,624.73
	GRAND TOTAL		4,865.23	4,144.73
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CC4/ASM19001197/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.