

Accident Photo



Accident Photo



Accident Photo



Accident Photo



UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Diana Goh Mui Mui

Our ref. : UAM18.06.06-AK-STP-HLA-SLV1167M

Date : 17 Jul 2018

REFERENCE

Assign by	: Diana Goh Mui Mui	Insured	: To be advice
Assign on	: 11 Jun 2018	Policy no.	: To be advice
Inspection on	: 11 Jun 2018	Claim no.	: To be advice
Accident on	: 08 Jun 2018	Sum insured	: To be advice
Workshop name	: Hiap Lek Automobile Trading	Excess	: Not applicable
Inspection at	: 160 Sin Ming Drive	3rd party Veh.	: To be advice
	#05-17 Sin Ming Autocity	3rd party ins.	: To be advice
	Singapore 575722		

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SLV1167M	Odometer	: 6462 km
Make / Model	: KIA Cerato K3 1.6A	Chassis no.	: KNAFX411MJ5755811
Regn. date	: 22 Dec 2017	Engine no.	: G4FGHH688148
Body colour	: Blue	Engine cap.	: 1591 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

TYRE CONDITION ON VEHICLE


	Make	Size	Tread depth	Type of road wheel
Front N/S	: Nexen	265/55R16	80%	Alloy
Front O/S	: Nexen	265/55R16	80%	Alloy
Rear N/S	: Nexen	265/55R16	80%	Alloy
Rear O/S	: Nexen	265/55R16	80%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT

On the rear in the direction from rear to front.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the bootlid, rear bumper, rear end panel, taillamps, rear fender, spare tyre panel and etc...

Please refer to Annex A (Appraisalment Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 13 Jun 2018 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Hiap Lek Automobile Trading as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 13,650.00 to carry out the repairs. Please refer to Annex A (Appraisalment Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 8 (Eight) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,
United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SLV1167M

Our reference : UAM18.06.06-AK-STP-HLA-SLV1167M

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
<u>LIST ITEMS (1 of 2)</u>					
1	1	Bootlid	Buckled	1497.00	1497.00 ✓
2	1	Bootlid logo	Necessary	54.00	54.00 ✓
3	1	Bootlid emblem "CERATO"	Necessary	56.00	56.00 ✓
4	1	Bootlid emblem "K3"	Necessary	55.00	55.00 ✓
5	2	Bootlid reflector @ SGD 595.00 312.30	Cracked	1190.00 624.60	1190.00 ✓
6	2set	Bootlid reflector clips @ SGD 20.00	Necessary	40.00	40.00 NH
7	1	Bootlid lock	Distorted	139.00	139.00 ✓
8	1	Bootlid lock striker	Distorted	61.00	61.00 ✓
9	1	Bootlid lock switch	Shorted	119.00	119.00 NH
10	1	Bootlid lock sensor	Shorted	108.00	108.00 NH
11	1	Bootlid weatherstrip	Cut	198.00	198.00 ✓
12	2	Bootlid hinge @ SGD 99.00	Bend	198.00	198.00 NH
13	2	Bootlid hinge garnish @ SGD 92.00	Re-Used	184.00	184.00 NH
14	1	Bootlid inner trim	Torn	361.00	361.00 ✓
15	1set	Bootlid inner trim clips	Necessary	35.00	35.00 ✓
16	2	Rear number plate lamp @ SGD 79.00	Cracked	158.00	158.00 NH
17	1	Rear bumper	Deformed	798.00 698.10	798.00 ✓
18	1set	Rear bumper clips	Necessary	50.00	50.00 ✓
19	2	Rear bumper side retainer @ SGD 64.00	Cracked	128.00	128.00 ✓
20	1	Rear bumper lower	Deformed	447.00	447.00 ✓
21	2	Rear bumper reflector @ SGD 144.00	Cracked	288.00	288.00 NH
22	1	Rear bumper reinforcement	Cracked	394.00	394.00 ✓
23	2	Reinforcement bracket @ SGD 99.00	Distorted	198.00	198.00 ✓
24	3	Rear bumper lower bracket @ SGD 41.00	Cracked	82.00	82.00 NH
25	1	Rear bumper lower cover	Deformed	122.00	122.00 ✓
26	1	Rear end panel	Dented	428.00	428.00 ✓
27	1	Rear end panel top garnish	Deformed	121.00	121.00 ✓
28	1set	Rear end panel top garnish clips	Necessary	35.00	35.00 ✓
29	1	Spare tyre panel	Buckled	1255.00 607.00	1255.00 ✓
30	1	Spare tyre panel insulator padding	Necessary	339.00	339.00 ✓
31	1	Spare tyre fastener	Bend	35.00	35.00 ✓
32	2	Taillamp @ SGD 852.00 563.20	Cracked	1704.00 1126.40	1704.00 ✓
33	2set	Taillamp clips @ SGD 35.00	Necessary	70.00	70.00 NH
34	2	Taillamp lower bracket @ SGD 129.00	Distorted	258.00	258.00 NH
35	2	Taillamp base panel @ SGD 192.50	O/S Buckled	385.00	192.50 R
36	2	Rear fender @ SGD 1433.00	O/S Buckled	2866.00	1433.00 R
37	2	Rear fender inner trim @ SGD 361.00	Torn	722.00	722.00 NH
38	2set	Rear fender inner trim clips @ SGD 30.00	Necessary	60.00	60.00 NH
39	2	Rear fender inner shield @ SGD 87.00	Re-Used	174.00	0.00 NH
40	2set	Rear fender inner shield clips @ SGD 20.00	Necessary	40.00	40.00 NH
List Item Sub-Total				15452.00	13652.50

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SLV1167M

Our reference : UAM18.06.06-AK-STP-HLA-SLV1167M

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
<u>LIST ITEMS (2 of 2)</u>			Balance C/F	15452.00	13652.50
41	2	Rear fender air vent @ SGD 61.00	O/S Deformed	122.00	122.00 HH
42	1	Rear windscreen moulding	Necessary	89.00	89.00 HH
43	1	Exhaust muffler	Bend	1263.00	1263.00 HH
44	3	Exhaust mounting @ SGD 52.00	Stretched	156.00	156.00 HH
				17082.00	15282.50
Less 0% / 20%				0.00	3056.50
				17082.00	12226.00

SPECIAL NETT ITEMS

1	1	Sundries	Necessary	50.00	30.00 HH
2	2	Bootlid reflector seal @ SGD 40.00	Necessary	80.00	70.00 HH
3	2	Taillamp seal @ SGD 50.00	Necessary	100.00	90.00 HH
4	1	Spare tyre panel sealant	Necessary	80.00	60.00 HH
5	1	Rear end panel sealant	Necessary	80.00	60.00 HH
6	1	Rear fender sealant	Necessary	80.00	60.00 HH
7	1	Rear windscreen primer and cleaner	Necessary	80.00	60.00 HH
8	1	Rear windscreen inner seal	Necessary	80.00	60.00 HH
9	1	Rear windscreen sealant	Necessary	60.00	40.00 HH
10	1	Reverse camera	Shorted	400.00	380.00 HH
11	1	Reverse sensor with control module	Shorted	300.00	280.00 HH
				1390.00	1190.00
TOTAL				18472.00	13416.00

LABOUR & MISC CHARGES (1 of 2)

1	To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	1600.00	1200/- 1400.00
2	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.	80.00	30/- 60.00
3	To remove and refit interior upholstery to facilitate the repair.	200.00	120/- 180.00
Labour Sub-Total		1880.00	1640.00

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SLV1167M

Our reference : UAM18.06.06-AK-STP-HLA-SLV1167M

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Part Balance C/F	18472.00	13416.00
			Labour Balance C/F	1880.00	1640.00
<u>LABOUR & MISC CHARGES (2 of 2)</u>					
4		To remove and refit bootlid component to replace bootlid, check and re-adjust the close gap and alignment and water seepage.		100.00	80.00 60/-
5		To remove and refit rear windscreen to facilitate the repair.		150.00	120.00 NH
6		To remove and refit fuel tank ass'y to facilitate repair.		280.00	250.00 Hw
7		To remove and refit, straighten and readjust exhaust pipe and replace exhaust silencer.		180.00	150.00 60/-
8		To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test on the distance and functions.		80.00	60.00 40/-
9		To apply undercoating on the accident repair and replaced panel for rust protection.	2590/-	200.00	180.00 80/-
10		Supply spray paint material and necessary items to respray bootlid, rear bumper, rear end panel, spare tyre panel, taillamp base panels, rear fenders and other affected area / panel.		1400.00	1200.00 1000/-
TOTAL				4270.00	3680.00
Total Parts and Labour Cost of Repair				22742.00	17096.00
Less (Lumpsum repair adjustment)					3446.00
Adjustment Parts and Labour Cost of Repair					13650.00

8590.00

4156850/-

with 6 days
jrg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		12 Jun 2018 16:15 Edit Adj Rpt	S\$6,850.00 Edit Estimates	S\$6,850.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	DIANA GOH MUI MUI (WU MEIMEI), ID: S7147273F		
Vehicle Reg. No.:	SLV1167M	Date of Loss:	08/06/2018 23:00 - :59 [5 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560871	Policy/Cover Note No.:	28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018
Vehicle Reg. No. (Insured):	SLJ4811E	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 16/01/2019]		
Driver/Custodian (Insured):	GAN CHIN HUAT (), NRIC: S7707993I, Tel: +6591994915		
Adj Asg. Remarks:	on WP. SJE - DISAGREED Please appoint LKK AUTO CONSULTANTS to conduct the survey . Kindly contact Choon Yong @ 6453 1743 to arrange for survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (14/01/2019): Report Send Back Alerts - SLV1167M (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV1167M (560871)

[SLJ4811E]

TP

DIANA GOH MUI MUI (WU MEIMEI)

Jun 8 2018 11:00PM

[SKYWAY MOTOR PTE LTD]

Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter

View View in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 18:03	Rear View Right	 Load JPG	☒
2	18/07/18 18:03	Rear View Left	 Load JPG	☒
3	18/07/18 18:03	General View	 Load JPG	☒
4	18/07/18 18:03	General View	 Load JPG	☒
5	18/07/18 18:03	General View	 Load JPG	☒
6	18/07/18 18:03	General View	 Load JPG	☒
7	18/07/18 18:03	General View	 Load JPG	☒
8	18/07/18 18:03	General View	 Load JPG	☒
9	18/07/18 18:03	General View	 Load JPG	☒
10	18/07/18 18:03	General View	 Load JPG	☒
11	18/07/18 18:03	General View	 Load JPG	☒
12	18/07/18 18:03	General View	 Load JPG	☒
13	18/07/18 18:03	General View	 Load JPG	☒
14	18/07/18 18:03	General View	 Load JPG	☒
15	18/07/18 18:03	General View	 Load JPG	☒
16	18/07/18 18:03	General View	 Load JPG	☒
17	18/07/18 18:03	General View	 Load JPG	☒
18	18/07/18 18:03	General View	 Load JPG	☒
19	18/07/18 18:03	General View	 Load JPG	☒
20	18/07/18 18:03	General View	 Load JPG	☒
21	18/07/18 18:03	General View	 Load JPG	☒
22	18/07/18 18:03	General View	 Load JPG	☒
23	18/07/18 18:03	General View	 Load JPG	☒
24	18/07/18 18:03	General View	 Load JPG	☒
25	18/07/18 18:03	General View	 Load JPG	☒
26	18/07/18 18:03	General View	 Load JPG	☒
27	18/07/18 18:03	General View	 Load JPG	☒
28	18/07/18 18:03	General View	 Load JPG	☒
29	18/07/18 18:03	General View	 Load JPG	☒
30	18/07/18 18:03	General View	 Load JPG	☒
31	18/07/18 18:03	General View	 Load JPG	☒
32	18/07/18 18:03	General View	 Load JPG	☒
33	18/07/18 18:03	General View	 Load JPG	☒
34	18/07/18 18:03	General View	 Load JPG	☒
35	18/07/18 18:03	General View	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	18/07/18 18:03	General View	 Load JPG	✓
37	18/07/18 18:03	General View	 Load JPG	✓
38	18/07/18 18:03	General View	 Load JPG	✓
39	18/07/18 18:03	General View	 Load JPG	✓
40	18/07/18 18:03	General View	 Load JPG	✓
41	18/07/18 18:03	General View	 Load JPG	✓
42	18/07/18 18:03	General View	 Load JPG	✓
43	18/07/18 18:03	General View	 Load JPG	✓
44	18/07/18 18:03	General View	 Load JPG	✓
45	18/07/18 18:03	General View	 Load JPG	✓
46	18/07/18 18:03	General View	 Load JPG	✓
47	18/07/18 18:03	General View	 Load JPG	✓
48	18/07/18 18:03	General View	 Load JPG	✓
49	18/07/18 18:03	Odometer Reading	 Load JPG	✓
50	18/07/18 18:03	Chassis Number	 Load JPG	✓
51	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
52	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
53	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
54	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
55	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
56	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
57	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
58	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
59	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
60	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
61	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
62	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
63	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
64	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
65	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
66	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
67	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
68	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
69	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
70	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
71	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
72	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
73	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
74	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
75	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
76	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
77	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
78	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
79	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
80	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
81	18/07/18 18:04	Reinspection Photo	Load JPG	✓
82	18/07/18 18:04	Reinspection Photo	Load JPG	✓
83	18/07/18 18:04	Reinspection Photo	Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
85	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
86	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
87	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
88	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
89	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
90	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
91	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
92	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
93	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
94	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
95	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
96	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
97	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
98	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
99	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
100	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
101	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
102	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
103	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
104	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
105	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
106	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
107	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
108	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
109	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
110	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
111	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
112	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
113	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
114	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
115	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
116	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
117	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
118	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
119	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
120	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
121	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
122	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
123	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
124	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
125	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
126	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
127	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
128	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
129	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
130	18/07/18 18:04	Reinspection Photo	 Load JPG	✓
131	18/07/18 18:04	Reinspection Photo	Load JPG	✓

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	18/07/18 18:04	Reinspection Photo	Load JPG	☒
133	18/07/18 18:04	Reinspection Photo	Load JPG	☒
134	18/07/18 18:04	Reinspection Photo	Load JPG	☒
135	18/07/18 18:04	Reinspection Photo	Load JPG	☒
136	18/07/18 18:04	Reinspection Photo	Load JPG	☒
137	18/07/18 18:05	Finishing Photo	Load JPG	☒
138	18/07/18 18:05	Finishing Photo	Load JPG	☒
139	18/07/18 18:05	Finishing Photo	Load JPG	☒
140	18/07/18 18:05	Finishing Photo	Load JPG	☒
141	18/07/18 18:05	Finishing Photo	Load JPG	☒
142	18/07/18 18:05	Finishing Photo	Load JPG	☒
143	18/07/18 18:05	Finishing Photo	Load JPG	☒
144	18/07/18 18:05	Finishing Photo	Load JPG	☒
145	18/07/18 18:05	Finishing Photo	Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/06/18 16:34	TPD SLV1167M - PRI	Load PDF	
2	12/06/18 10:57	TPD SLV1167M - SURVEY LISTING	Load PDF	
3	12/06/18 10:57	Reject email to TP Lawyer & appoint LKK AUTO	Load PDF	
4	13/06/18 08:22	OI SLJ4811E GIA REPORT	Load PDF	
5	13/06/18 08:23	TPD SLV1167M GIA REPORT	Load PDF	
6	14/01/19 14:05	3P Survey Report 1/2	Load PDF	
7	14/01/19 14:05	3P Survey Report 2/2	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/19 10:08	PRS INVOICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18010780/DQD3S2-1

Date: 11/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28795104MCX

Claimant Vehicle No : SLV1167M

Insured Vehicle No : SLJ4811E

Date of Loss: 08/06/2018

Nature of Claim: TP

Claim No: 560871

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV1167M

Make & Model: KIA CERATO K3, 1.6 (A)

Engine No: G4FGHH688148

Reg. Date: 22/12/2017 (Man. Year: 2017)

Chassis No: KNAFX411MJ5755811

Colour: Blue

Odometer: 6462 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Nexen 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	18,472.00	6,000.08	12,471.92	67.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	2,590.00	1,680.00	39.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,742.00	8,590.08	14,151.92	62.23
Approved Total (Overridden) (S\$)		6,850.00		
Nett Amount (S\$)	22,742.00	6,850.00	15,892.00	69.88

INSPECTION

Date of Assignment: 12/06/2018

Date Inspected: 13/06/2018 Inspected At:

160 Sin Ming Drive, #05-17 Sin Ming Autocity
Singapore 575722

Repairer: Hiap Lek Automobile Trading

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2019)
Parts: 143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV1167M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	1,497.00 F	*863.00 FL
2	1		*BOOTLID LOGO	Necessary	54.00 F	*54.00 FL
3	1		*BOOTLID EMBLEM CERATO	Necessary	56.00 F	*56.00 FL
4	1		*BOOTLID EMBLEM K3	Necessary	55.00 F	*55.00 FL
5	2		*BOOTLID REFLECTOR	Cracked	1,190.00 F	*624.60 FL
6	2		*SET BOOTLID REFLECTOR CIPS	Not Necessary	40.00 F	*- FL
7	1		*BOOTLID LOCK	Distorted	139.00 F	*139.00 FL
8	1		*BOOTLID LOCK STRIKER	Distorted	61.00 F	*61.00 FL
9	1		*BOOTLID LOCK SWITCH	Not Necessary	119.00 F	*- FL
10	1		*BOOTLID LOCK SENSOR	Not Necessary	108.00 F	*- FL
11	1		*BOOTLID WEATHERSTRIP	Cut	198.00 F	*198.00 FL
12	2		*BOOTLID HINGE	Not Necessary	198.00 F	*- FL
13	2		*BOOTLID HINGE GARNISH	Not Necessary	184.00 F	*- FL
14	1		*BOOTLID INNER TRIM	Torn	361.00 F	*361.00 FL
15	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	35.00 F	*35.00 FL
16	2		*REAR NUMBER PLATE LAMP	Not Necessary	158.00 F	*- FL
17	1		*REAR BUMPER	Deformed	798.00 F	*698.10 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Cracked	128.00 F	*128.00 FL
20	1		*REAR BUMPER LOWER	Deformed	447.00 F	*447.00 FL
21	2		*REAR BUMPER REFLECTOR	Not Necessary	288.00 F	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Cracked	394.00 F	*394.00 FL
23	2		*REINFORCEMENT BRACKET	Distorted	198.00 F	*198.00 FL
24	3		*REAR BUMPER LOWER BRACKET	Not Necessary	82.00 F	*- FL
25	1		*REAR BUMPER LOWER COVER	Deformed	122.00 F	*122.00 FL
26	1		*REAR END PANEL	Dented	428.00 F	*428.00 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	121.00 F	*121.00 FL
28	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	35.00 F	*35.00 FL
29	1		*SPARE TYRE PANEL	Buckled	1,255.00 F	*607.00 FL
30	1		*SPARE TYRE PANEL INSULATOR PADDING	Necessary	339.00 F	*339.00 FL
31	1		*SPARE TYRE FASTENER	Bent	35.00 F	*35.00 FL
32	2		*TAILLAMP	Cracked	1,704.00 F	*1,126.40 FL
33	2		*SET TAILLAMP CLIPS	Not Necessary	70.00 F	*- FL
34	2		*TAILLAMP LOWER BRACKET	Not Necessary	258.00 F	*- FL
35	2		*TAILLAMP BASE PANEL	Repair	385.00 F	*- FL
36	2		*REAR FENDER	Repair	2,866.00 F	*- FL
37	2		*REAR FENDER INNER TRIM	Not Necessary	722.00 F	*- FL
38	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
39	2		*REAR FENDER INNER SHIELD	Not Necessary	174.00 F	*- FL
40	2		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 F	*- FL
41	2		*REAR FENDER AIR VENT	Not Necessary	122.00 F	*- FL
42	1		*REAR WINDSCREEN MOULDING	Not Necessary	89.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*EXHAUST MUFFLER	Not Necessary	1,263.00 F	*-FL
44	3		*EXHAUST MOUNTING	Not Necessary	156.00 F	*-FL
45	1		*SUNDRIES	Not Necessary	50.00 FS	*-FS
46	2		*BOOTLID REFLECTOR SEAL	Not Necessary	80.00 FS	*-FS
47	2		*TAILLAMP SEAL	Not Necessary	100.00 FS	*-FS
48	1		*SPARE TYRE PANEL SEALANT }	Necessary	80.00 FS	*40.00 FS
49	1		*REAR END PANEL SEALANT }		80.00 FS	*-FS
50	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*-FS
51	1		*REAR WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*-FS
52	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*-FS
53	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*-FS
54	1		*REVERSE CAMERA	Not Necessary	400.00 FS	*-FS
55	1		*REVERSE SENSOR WITH CONTROL MODULE	Shorted	300.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,472.00	7,435.10
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,435.02
Total Parts (S\$)	18,472.00	6,000.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.	New	1,600.00	1,200.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.	New	80.00	30.00
3	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.	New	200.00	120.00
4	TO REMOVE AND REFIT BOOTLID COMPONENT TO REPLACE BOOTLID, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.	New	100.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE THE REPAIR.	New	150.00	0.00
6	TO REMOVE AND REFIT FUEL TANK ASSY TO FACILITATE REPAIR.	New	280.00	0.00
7	TO REMOVE AND REFIT, STRAIGHTEN AND READJUST EXHAUST PIPE AND REPLACE EXHAUST SILENCER.	New	180.00	60.00
8	TO MEASURE, DRILL HOLES ON REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS.	New	80.00	40.00
9	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION.	New	200.00	80.00
10	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BOOTLID, REAR BUMPER, REAR END PANEL, SPARE TYRE PANEL, TAILLAMP BASE PANELS, REAR FENDERS AND OTHER AFFECTED AREA / PANEL.	New	1,400.00	1,000.00
Gross Labour Cost (S\$)			4,270.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >