Surveyor REF: Col	/LPC 19001256 / Daddez	Special Instruction:
	Date/Time: 21012019	US: \$ 20000.00 Third Parties: Claimant:
OD/TP Re-inspection / Evaluation)	F	Surveyor: Profige Appriser
To Inspect Vehicle No: SLC 30.	36C Insured: # 5 77	
of 160 Sin Ming Driv		•
Policy No:	Claim No: 17/18/18/	YELL / YELGOL
	,	VI 02/204700
Sum Insured:	D.O.A. 08.08.30	18
		H.O.D. Endorsement/Date:
Date/Time:Person Contact		
Date/Time: Confirmed with Date/Time: Submit Final Fig	Final Fig,days (1920)	Red \$/%; Original 4 days) 1 54 %; Original 4 days)
Date/Time Action/Instruction		
Market value of the vehicle	ct the muterial time of acci	dent
	•	
91C 3836C - X		
STC 382PC - V		
STC 382PC - V	Proces chedal browny	on 3LU 5283 surage
31C 3836C - X	Pries chedal browny	on SLU 5283 Shraye
08 22 19 - PaA	Prices chedal brown ne with demayer sin orbinat 2/5 9200/- wit	
108 02 19 - P-A by m 10 - 70 A	15 9200 - wit	10 days of support its conte
108 22 19 - P-A by m - 70 A	rbmit 2/5 92001 - wit	10 days of support ill conte
108 32 19 - P-A by m 1 - 70 A	15 9200 - wit	nulo to support or conte
108 32 19 - P-A by m - 70 A	nA culved estray no pl domage seen from 71	nulo to support or conte
	nA ellowed estrey no 71 demand seen from 71 (To highlight R or UB,	nAo to 2 mg/r/t UV conte
Para(2): Comments on consistency of	nA ellowed estray no 71 demand seen from 74 (To highlight R or UB,	nAo to support or conte
Para(2): Comments on consistency of MV 60 C	nA ellow estray no 71 demand seen from 71 (To highlight R or UB,	nuto to support ov contents. LR, (Elc) stent: NC)
10 10 19 - P = A 19 19 19 19 19 19 19	nA ellowed estrey no 71 demand seen from 71 (To highlight R or UB,	nAo to support or conte
10 19 - 19 - 19 19 19 19 19	nA ellow ather no ple demand seen from the (To highlight R or UB, end and the consistence of damages (Parts Not Consistence of the consistence of	nAo to Buggert ov canton
10 3836C - K 19 - P-A 19 m 19	nA elloch estrey no 71 demaps seen from 74 (To highlight R or UB, of damages (Parts Not Consistence)	n. 10 olay: J My. n.A. to 2 my ret ov contents. LR, (Elc) stent: NC)
10 38360 - K 19 - P-A 19 19 19 19 19 19 19 1	nA ellow ather no ple demand seen from the (To highlight R or UB, end and the consistence of damages (Parts Not Consistence of the consistence of	n. 10 olay: J My. n.A. to 2 my ret ov contents. LR, (Elc) stent: NC)
108 32 19 - P-A 29 m 19 m	nA eliver estrey rs 71 demand seen from 71 (To highlight R or UB, of damages (Parts Not Consistence) RECEIVED New Lord of Many was valued to 12 JPS 2238	The stent: NC) Fee Charged: Date: Basic & Add
108 32 19 - P-A 29 m 19 m	nA eural entry no 71 deman seen from 71 (To highlight R or UB, of damages (Parts Not Consistence No. 2 JPS 2238 Mens up very the can	Tee Charged: Date: Basic & Add Transport
19 19 - P-A 19 19 19 19 19 19 19 1	nA eliver estrey rs 71 demand seen from 71 (To highlight R or UB, of damages (Parts Not Consistence) RECEIVED New Lord of Many was valued to 12 JPS 2238	The stent: NC) Fee Charged: Date: Basic & Add
Para(1): Parts found not replaced Para(2): Comments on consistency of MV 60 C LTA 43.7 HL 16.3 TO ASL - In Insural Para(3): Nett Value Market Value: 60000 LTA Salvage Value: 43740 Nett Value: 16760 Nett Value: 16760 Nett Value: 16760 Para(1): Date/Time 11/21/9 File Pass to 14	nA eliver estrey rs 71 demand seen from 71 (To highlight R or UB, of damages (Parts Not Consistence) RECEIVED New Lord of Many was valued to 12 JPS 2238	Fee Charged: Date: Basic & Add Transport Photos Others Total
10 19 - 19 - 19 19 19 19 19	That IS 9200 - sit nA elimit 25 9200 - sit nA elimit estrey rs 71 demays seen from 71 (To highlight R or UB, of damages (Parts Not Consistence) RECEIVED NEW Cle no, 2 JPS 2238 MAND who work the case Inspected/ Evaluated by: 1) Date/Time 4) Date/Time	Fee Charged: Date: Basic & Add Transport Photos Others Total File Return to

Denise Tay (LKKAuto)

From:

Mei Kwan (LKKAuto)

Sent:

Wednesday, 13 February 2019 10:11 AM

To:

Admin-D (LKKAuto)

Subject:

FW: Second opinion - SLC 3836 C; DOL: 08/08/2018; OUR REF:

17/18/18/VP02/264906 [External Confidential]

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Tuesday, 12 February, 2019 4:14 PM To: Admin A <admin-a@lkkauto.com>


Subject: FW: Second opinion - SLC 3836 C; DOL: 08/08/2018; OUR REF: 17/18/18/VP02/264906 [External

Confidential]

Best Regards Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: LILLIAN SIM BEE LIAN

Sent: Tuesday, 12 February, 2019 4:07 PM

To: LKK Ms Ang

Cc: GERALD POH WEE BIN

Subject: RE: Second opinion - SLC 3836 C; DOL: 08/08/2018; OUR REF: 17/18/18/VP02/264906 [External

Confidential]

Lonpac External - Confidential WITHOUT PREJUDICE

Dear Sir,

Refer to the above.

Please note that our insured's vehicle is JPS 2238.

Thanks and regards,

LILLIAN SIM

CLAIMS DEPARTMENT I LONPAC INSURANCE BHD

T: 03-27237716 F: 03-20342654 EMAIL: lilliansim@lonpac.com

Lonpac External - Confidential data is for use by authorised external parties only.



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 17/18/18/VP02/264906

Date: 11th Feb 2019

Our Ref: CS1/LPC19001256/Dqd3e2

M/s Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLC 3836C INSURED VEHICLE: JPS 2238 ACCIDENT DATE: 08/08/2018

We thank you for your instruction on 21/01/2019.

We acknowledge receipt of the following documents:-

a) Automobile Inspection Report of SLC 3836C from M/s Prestige Appraiser Services.

b) Colour damaged vehicle photographs of SLC 3836C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SLC 3836C

Make & Model

: Honda Vezel 1.5X A

Year of Registration

: 2016

Chassis Number

: RU11115309

Engine Capacity

: 1496 cc

- We recommend that the repairs of the entire damage require about ______ 10 (Ten) _____ working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 3836C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	1,626.00	858.10
2	REAR BUMPER SIDE	DENTED	778.00	357.60
2	REAR BUMPER BRACKET	SERVICEABLE	162.00	
2	REAR BUMPER SIDE RETAINER	SERVICEABLE	124.00	
1	L/H REAR BUMPER REFLECTOR	BROKEN	155.00	155.00
1	R/H REAR BUMPER REFLECTOR	SERVICEABLE	155.00	
10	REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR END PANEL	DENTED	820.00	467.50
1	REAR END PANEL TOP GARNISH	DENTED	535.00	86.80
6	REAR END PANEL TOP GARNISH CLIP	NECESSARY	42.00	42.00
1	L/H REAR WHEEL HOUSE	TO REPAIR SEE LABOUR	798.00	-
1	TAILGATE	DENTED / DISTORTED	1,850.00	1,072.50
2	TAILGATE ABSORBER	SERVICEABLE	460.00	-
2	TAILGATE HINGE	TO REPAIR SEE LABOUR	220.00	-
1	TAILGATE TOP LOCK	DENTED	380.00	221.40
1	TAILGATE LOWER LOCK	DENTED	198.00	198.00
1	TAILGATE WEATHERSTRIP	DISTORTED	325.00	123.80
1	R/H TAILGATE REFLECTOR	NOT NECESSARY	490.00	-
1	L/H TAILGATE REFLECTOR	CRACKED	490.00	490.00
1	TAILGATE INNER TRIMBOARD	DENTED / CRACKED	725.00	725.00
1	TAILGATE EMBLEM 'LOGO'	NECESSARY	79.00	79.00
1	TAILGATE EMBLEM 'VEZEL'	NECESSARY	85.00	85.00
1	TAILGATE OUTER GARNISH	DENTED / CRACKED	498.00	267.50
1	TAILGATE OPENING SWITCH	NOT NECESSARY	298.00	:-
1	REAR NUMBER PLATE LAMP	SERVICEABLE	210.00	-
1	REAR WIPER MOTOR	NOT NECESSARY	525.00	
1	R/H TAILLAMP	NOT NECESSARY	750.00	-

Report Ref No. CS1/LPC19001256/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	L/H TAILLAMP	CRACKED	750.00	503.30
1	R/H TAILLAMP PANEL	NOT NECESSARY	260.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	285.00	74.10
1	SPARE WHEEL PANEL	DENTED	1,420.00	863.50
1	SPARE WHEEL TOP COVER	DENTED	398.00	398.00
1	SPARE WHEEL SPONGE	SERVICEABLE	268.00	-
1	SPARE WHEEL PANEL LOWER DUST COVER	DENTED / DISTORTED	485.00	157.30
1	L/H SPARE WHEEL SIDE PANEL	DENTED	195.00	195.00
1	L/H REAR FENDER	DENTED / DISTORTED	1,565.00	770.00
1	L/H REAR FENDER DUST COVER	TORN	325.00	134.80
1	L/H REAR FENDER INNER GARNISH	DENTED / DISTORTED	798.00	798.00
1	L/H REAR FENDER ARCH GARNISH	HOLDER FRACTURED	584.00	220.20
1	L/H REAR DOOR	DENTED / DISTORTED	1,568.00	900.10
1	L/H REAR DOOR LOCK	NOT NECESSARY	498.00	-
1	L/H REAR DOOR WEATHERSTRIP	SERVICEABLE	265.00	-
1	REVERSE SENSOR BUZZER	NOT NECESSARY	198.00	-
1	EXHAUST MUFFLER	REFIT	1,050.00	1=
	LESS 20% DISCOUNT		1-	-2,058.70
			23,740.00	8,234.80
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	DAMAGED	500.00	220.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	240.00	40.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	700.00	-
			1,440.00	260.00
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF L/H REAR WHEEL HOUSE AND TAILGATE HINGE.		2,800.00	1,400.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		2,100.00	1,200.00

Report Ref No. CS1/LPC19001256/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.		220.00	60.00
	TO REMOVE / REFIT REAR WINDSCREEN GLASS TO FACILITATE REPAIRS.		240.00	120.00
	TO REMOVE / REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.		240.00	120.00
	TO REMOVE / TRANSFER TAILGATE MECHANISMS.		140.00	60.00
	TO REMOVE / TRANSFER L/H REAR DOOR MECHANISMS.		100.00	60.00
	TO CHECK WIRING FUNCTIONS.		120.00	30.00
			5,960.00	3,050.00
	GRAND TOTAL		31,140.00	11,544.80

RECOMMENDED COST OF LUMP SUM REPAIRS		9,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS1/LPC19001256/Dqd3e2

MARKET VALUE: \$60,000.00(EST)-LTA REIMBURSEMENT VALUE: \$43,700.00=NETT VALUE: \$16,300.00

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.