

ASS. REC. BY:

REF:

CS/SPF19001278/Kvd3.12

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Frankie Thuy

of

SPF

Date/Time:

21/11/19 @ 9.56am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS1369M

Insured:

GBC 3022A

at Workshop m/s

Complete VMS

Tel:

6455 0012

of

176 Sir Ming Drive #03-14

Policy No:

Claim No:

AEMD/105/009/2019/003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17012019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10.16am @ 21/11/19

Person Contacted:

Li Hui

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS1369M-NS/INC18007464/KLrbn2 DOA: 21/4/18
28/2/19	B12672-72 Cashmere (Red 32TH.98, 219) upper Range \$13K - \$14K (EST)
28/2/19	@ 9415m Explint to Li Hui, SPF may reduce the repair cost

***Nivitha (LKK Auto)**

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Monday, 21 January 2019 9:56 AM
To: Catherine Chong; assignments
Cc: Olivia Lau (LKKAuto)
Subject: RE : Pre-Repair Inspection for SLS1369M

Your reference: SLS1369M
Our reference: AEMD/105/009/2019/003

Catherine,
Please conduct a Pre-Repair Inspection for vehicle SLS1369M at address: Complete VMS Pte Ltd, 176, Sin Ming Drive, #03-14, Singapore 575721.
Please contact M/s Lily/Li Hui at Tel: 64550012 for appointment.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



WARNING This e-mail contains Confidential information. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this e-mail to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive such an error.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/01/2019 15:25
Date Of Accident	17/01/2019 21:25
Exact Location Of Accident	T-JUNCTION OF AMK AVE 2 / AMK STREET 11
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLS1369M
Insured/Policyholder	
Name Of Registered Owner	THONG HSI
NRIC No	S6932179H
Email Address	THONGH69@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90225293
Alternative Phone No	OTHERS-90225293
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ELANTRA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094430631-01
Cover Note Number	
Driver	
Name of Driver	THONG HSI
NRIC No	S6932179H
Date Of Birth	18/09/1969
Occupation	INDOOR
Date Of Driving Pass	19/06/1989
Driving Experience	29 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90225293
Fax Number	
Contact Number	OTHERS-90225293
EMail Address	THONGH69@GMAIL.COM

Address	80 JALAN LEBAN
Postcode	577617
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC3023A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

THONG HSI
 80 JALAN LEBAN
 SINGAPORE 577617

Attention : THE OWNER
 Contact : 90225293

Not Notarized
Resurvey By paint
6 das

Estimate : ES006577

Date : 18/01/2019
 Vehicle Num. : SLS1369M
 Make/Model : HYUNDAI ELANTRA 1.6G-2017
 Chassis/Eng# : KMHD841CMJU537475/G4FGHU6908
 Accident Date : 17/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$	
LIST ITEMS :					
1.	1	FRONT BONNET		1,780.70	✓
2.	2	BONNET HINGE	49.10	98.20	✓
3.	1	BONNET LOCK		139.10	✓
4.	1	FRONT FENDER R/H		966.80	✓
5.	1	FRONT FENDER L/H		966.80	✓
6.	2	HEADLAMP	1,198.00	2,396.00	✓
7.	4	HEADLAMP CLIP	8.50	34.00	✓
8.	2	HEADLAMP TOP RUBBER	34.00	68.00	✓
9.	1	FRONT SUPPORT PANEL		969.00	✓
10.	1	FRONT SUPPORT PANEL TOP GARNISH		74.00	✓
11.	8	TOP GARNISH CLIP	6.00	48.00	✓
12.	1	FRONT BUMPER		494.40	✓
13.	1	FRONT BUMPER TOP RUBBER		61.00	✓
14.	1	FRONT BUMPER REINFORCEMENT		695.80	✓
15.	1	FRONT BUMPER SPONGE		118.70	✓
16.	8	FRONT BUMPER CLIP	6.00	48.00	✓
17.	2	FRONT BUMPER BRACKET	41.00	82.00	✓
18.	2	FRONT BUMPER SIDE RETAINER	51.00	102.00	✓
19.	1	RADIATOR GRILLE		490.20	✓
20.	1	GRILLE LOGO		34.00	✓
21.	1	FRONT FOG LAMP L/H		269.00	✓
22.	1	FRONT FOG LAMP GARNISH L/H		148.40	✓
23.	1	FRONT BUMPER LAMP L/H		174.10	✓
24.	1	FRONT BUMPER LAMP GRILLE L/H		131.00	✓
25.	1	FRONT ENGINE UNDER COVER L/H		121.00	✓
26.	10	ENGINE UNDER COVER CLIP	4.50	45.00	✓
27.	1	SUPPORT PANEL TOP AIR DUCT		167.00	✓
28.	1	AIR CLEANER BOX		219.90	✓
29.	1	AIR CLEANER BOX HOSE		121.00	✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

THONG HSI
 80 JALAN LEBAN
 SINGAPORE 577617

Attention : THE OWNER
 Contact : 90225293

Estimate : ES006577

Date : 18/01/2019
 Vehicle Num. : SLS1369M
 Make/Model : HYUNDAI ELANTRA 1.6G-2017
 Chassis/Eng# : KMHD841CMJU537475/G4FGHU6908
 Accident Date : 17/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	AIR CLEANER BOX AIR DUCT		149.00 ?
31.	1	AIR CON CONDENSER		785.00 ?
32.	1	RADIATOR ASSY		621.00 ?
33.	1	AIR CON CONDENSER SIDE COVER L/H		86.00 ?
34.	1	RADIATOR TOP HOSE	34.90	X
35.	1	BUMPER LAMP BRACKET L/H		169.00 ?
36.	1	AIR RESONATOR BOX L/H		129.00 ?
37.	1	RADIATOR FAN MOTOR	699.00	? <i>pc form</i>
38.	1	BONNET INSULATOR		221.00 ✓
39.	1	FRONT FENDER INNER SHIELD L/H		128.00 ?
40.	6	FRONT FENDER INNER SHIELD CLIP L/H	4.50	27.00 ?
List TotalS\$:				14,112.00
15.00% Discount S\$:				2,116.80
				<hr/>
				11,995.20
LABOUR :				
TOW VEHICLE				65.00 <i>30l</i>
RUST PROOFING TREATMENT				150.00 <i>90l</i>
CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION				90.00 <i>20l</i>
REMOVE & REINSTALL AIRCON CONDENSER & REFILL GAS				180.00 <i>100l</i>
SPRAY PAINT DAMAGED AREA AFFECTED				1,100.00 <i>80l</i>
COMPUTER WHEEL ALIGNMENT				120.00 <i>x</i>
TO CUT OFF FRONT SUPPORT PANEL,KNOCK AND STRAIGHTEN				
FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS				1,100.00 <i>700l</i>
Labour Total S\$:				<hr/> 2,805.00

SingDollars : Fourteen Thousand Eight Hundred & Cents Twenty Only

Total S\$: 14,800.20

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



KV

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

THONG HSI
 80 JALAN LEBAN
 SINGAPORE 577617

Attention : THE OWNER
 Contact : 90225293

Not Notarised
Recovery B4 paint
6 days
@ 12,672.72

Estimate : ES006577

Date : 18/01/2019
 Vehicle Num. : SLS1369M
 Make/Model : HYUNDAI ELANTRA 1.6G-2017
 Chassis/Eng# : KMHD841CMJU537475/G4FGHU6908
 Accident Date : 17/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$	Remarks
1.	1	LIST ITEMS :			
2.	2	FRONT BONNET	1740.70	3481.40	
3.	1	BONNET HINGE			
4.	1	BONNET LOCK			
5.	1	FRONT FENDER R/H	617.10	617.10	
6.	1	FRONT FENDER L/H	617.10	617.10	
7.	2	HEADLAMP	1150.00	2300.00	
8.	4	HEADLAMP CLIP			
9.	2	HEADLAMP TOP RUBBER			
10.	1	FRONT SUPPORT PANEL	949.30	949.30	
11.	1	FRONT SUPPORT PANEL TOP GARNISH			
12.	8	TOP GARNISH CLIP			
13.	1	FRONT BUMPER			
14.	1	FRONT BUMPER TOP RUBBER			
15.	1	FRONT BUMPER REINFORCEMENT			
16.	1	FRONT BUMPER SPONGE			
17.	8	FRONT BUMPER CLIP			
18.	2	FRONT BUMPER BRACKET			
19.	2	FRONT BUMPER SIDE RETAINER			
20.	1	RADIATOR GRILLE			
21.	1	GRILLE LOGO			
22.	1	FRONT FOG LAMP L/H			
23.	1	FRONT FOG LAMP GARNISH L/H			
24.	1	FRONT BUMPER LAMP L/H			
25.	1	FRONT BUMPER LAMP GRILLE L/H			
26.	1	FRONT ENGINE UNDER COVER L/H			
27.	10	ENGINE UNDER COVER CLIP			
28.	1	SUPPORT PANEL TOP AIR DUCT			
29.	1	AIR CLEANER BOX			
30.	1	AIR CLEANER BOX HOSE			

CONTINUE / ...



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

THONG HSI
 80 JALAN LEBAN
 SINGAPORE 577617

Attention : THE OWNER
 Contact : 90225293

Estimate : ES006577

Date : 18/01/2019
 Vehicle Num. : SLS1369M
 Make/Model : HYUNDAI ELANTRA 1.6G-2017
 Chassis/Eng# : KMHD841CMJU537475/G4FGHU6908
 Accident Date : 17/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

30.	1	AIR CLEANER BOX AIR DUCT	CMH Part 77	149.00 2
31.	1	AIR CON CONDENSER	M1	785.00 2
32.	1	RADIATOR ASSY	SM	621.00 2
33.	1	AIR CON CONDENSER SIDE COVER L/H	SM	86.00 X
34.	1	RADIATOR TOP HOSE	SM	34.90 X
35.	1	BUMPER LAMP BRACKET L/H	SM	169.00 X
36.	1	AIR RESONATOR BOX L/H	CMH	129.00 2
37.	1	RADIATOR FAN MOTOR <i>589.</i>	CMH	699.00 2
38.	1	BONNET INSULATOR	De form	221.00 2
39.	1	FRONT FENDER INNER SHIELD L/H	SM	128.00 X
40.	6	FRONT FENDER INNER SHIELD CLIP L/H	4.50 nn	27.00 X

List Total S\$: 14,112.00
 15.00% Discount S\$: 2,116.80
20%
 11,995.20

LABOUR :

TOW VEHICLE	65.00	301
RUST PROOFING TREATMENT	150.00	901
CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION	90.00	201
REMOVE & REINSTALL AIRCON CONDENSER & REFILL GAS	180.00	1001
SPRAY PAINT DAMAGED AREA AFFECTED	1,100.00	8801
COMPUTER WHEEL ALIGNMENT	120.00	X 601
TO CUT OFF FRONT SUPPORT PANEL, KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	1,100.00	700

Labour Total S\$: 2,805.00

SingDollars : Fourteen Thousand Eight Hundred & Cents Twenty Only

Total S\$: 14,800.20

=====

15,947.70

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

- LKK Auto Consultancy hence notify
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



COMPLETE VMS PTE LTD *The Premier One-Stop Vehicle Accident Claims Centre*
 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

THONG HSI
 80 JALAN LEBAN
 SINGAPORE 577617

Supplementary Estimate : ES006582

Attention : THE OWNER
 Contact : 90225293

Date : 22/01/2019
 Vehicle Num. : SLS1369M
 Make/Model : HYUNDAI ELANTRA 1.6G-2017
 Chassis/Eng# : KMHD841CMJU537475/G4FGHU6908
 Accident Date : 17/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|---------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | AIR BAG FRONT SENSOR | | |
| 3. | 1 | FRONT SENSOR | | |
| 4. | 1 | FUSE BOX ASSY | | |
| 5. | 1 | FOG LAMP BRACKET L/H | | |
| | | FRONT BUMPER LOWER RUBBER | | |

CM	185.00	✓
CM	215.00	✓
MSJCM	656.00	✓
NIP	169.00	X
TN	125.00	✓

List TotalS\$:
~~15.00%~~ Discount S\$:
 2070

1,350.00
 202.50

 1,147.50

SingDollars : One Thousand One Hundred Forty-Seven & Cents Fifty Only

Total S\$: 1,147.50
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 28 February 2019 10:08 AM
To: 'lihui@completevms.com.sg'; SUR
Subject: SLS 1369M-DOA: 17/1/2019
Attachments: MARK EST.pdf

Dear Li Hui,

For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19001278/Kvd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 04-03-2019	
ATTN : FRANKIE THAY		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 3023A	Veh. Inspected	SLS 1369M
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/003	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	21/01/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHD841CMJU537475	Colour	METALLIC PEARL BEIGE
Odometer	23767	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R16	NEXEN	7 mm
L/H Front Tyre	195/65 R16	NEXEN	7 mm
R/H Rear Tyre	195/65 R16	NEXEN	7 mm
L/H Rear Tyre	195/65 R16	NEXEN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/01/2019	Inspection Date	21/01/2019
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 1369M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	BENT	1,780.70	1,740.70
2	BONNET HINGE @\$49.10	N/S DISTORTED	98.20	49.10
1	BONNET LOCK	DISTORTED	139.10	139.10
1	FRONT FENDER R/H	BUCKLED	966.80	617.10
1	FRONT FENDER L/H	BENT	966.80	617.10
2	HEADLAMP @\$1198.00	O/S MTG CRACKED / N/S BROKEN	2,396.00	2,396.00
4	HEADLAMP CLIP @\$8.50	NECESSARY	34.00	34.00
2	HEADLAMP TOP RUBBER @\$34.00	NECESSARY	68.00	68.00
1	FRONT SUPPORT PANEL	BUCKLED	969.00	949.30
1	FRONT SUPPORT PANEL TOP GARNISH	CRACKED	74.00	74.00
8	TOP GARNISH CLIP @\$6.00	NECESSARY	48.00	48.00
1	FRONT BUMPER	BENT	494.40	494.40
1	FRONT BUMPER TOP RUBBER	NECESSARY	61.00	61.00
1	FRONT BUMPER REINFORCEMENT	BUCKLED	695.80	695.80
1	FRONT BUMPER SPONGE	CRACKED	118.70	118.70
8	FRONT BUMPER CLIP @\$6.00	NECESSARY	48.00	48.00
2	FRONT BUMPER BRACKET @\$41.00	N/S BENT	82.00	41.00
2	FRONT BUMPER SIDE RETAINER @\$51.00	N/S CRACKED	102.00	51.00
1	RADIATOR GRILLE	CRACKED	490.20	490.20
1	GRILLE LOGO	NECESSARY	34.00	34.00
1	FRONT FOG LAMP L/H	MTG CRACKED	269.00	269.00
1	FRONT FOG LAMP GARNISH L/H	DISTORTED	148.40	148.40
1	FRONT BUMPER LAMP L/H	MTG CRACKED	174.10	174.10
1	FRONT BUMPER LAMP GRILLE L/H	SERVICEABLE	131.00	-
1	FRONT ENGINE UNDER COVER L/H	SERVICEABLE	121.00	-
10	ENGINE UNDER COVER CLIP @\$4.50	NOT NECESSARY	45.00	-
1	SUPPORT PANEL TOP AIR DUCT	CRACKED	167.00	167.00
1	AIR CLEANER BOX	CRACKED	219.90	219.90
1	AIR CLEANER BOX HOSE	CRACKED	121.00	121.00
1	AIR CLEANER BOX AIR DUCT	CRACKED	149.00	149.00
1	AIR CON CONDENSER	PUNCTURE / TWISTED	785.00	785.00
1	RADIATOR ASSY	BENT	621.00	621.00

Report Ref No. CS/SPF19001278/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON CONDENSER SIDE COVER L/H	SERVICEABLE	86.00	-
1	RADIATOR TOP HOSE	SERVICEABLE	34.90	-
1	BUMPER LAMP BRACKET L/H	SERVICEABLE	169.00	-
1	AIR RESONATOR BOX L/H	CRACKED	129.00	129.00
1	RADIATOR FAN MOTOR	CRACKED	699.00	589.00
1	BONNET INSULATOR	DEFORMED	221.00	221.00
1	FRONT FENDER INNER SHIELD L/H	SERVICEABLE	128.00	-
6	FRONT FENDER INNER SHIELD CLIP L/H @\$4.50	NOT NECESSARY	27.00	-
1	AIR BAG FRONT SENSOR (ADDITIONAL)	CRACKED	185.00	185.00
1	FRONT SENSOR (ADDITIONAL)	CRACKED	215.00	215.00
1	FUSE BOX ASSY (ADDITIONAL)	MTG CRACKED	656.00	656.00
1	FOG LAMP BRACKET L/H (ADDITIONAL)	NO SUCH PARTS	169.00	-
1	FRONT BUMPER LOWER RUBBER (ADDITIONAL)	TORN	125.00	125.00
	LESS 15% DISCOUNT		-2,319.30	-
	LESS 20% DISCOUNT		-	-2,708.18
			13,142.70	10,832.72
	LABOUR			
	TOW VEHICLE.		65.00	50.00
	RUST PROOFING TREATMENT.		150.00	90.00
	CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION.		90.00	20.00
	REMOVE & REINSTALL AIRCON CONDENSER & REFILL GAS.		180.00	100.00
	SPRAY PAINT DAMAGED AREA AFFECTED.		1,100.00	880.00
	COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO CUT OFF FRONT SUPPORT PANEL, KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS.		1,100.00	700.00
			2,805.00	1,840.00
	GRAND TOTAL		15,947.70	12,672.72
RECOMMENDED COST OF REPAIRS				12,672.72

Report Ref No. CS/SPF19001278/Kvd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$13,000-\$14,000

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.