22/03/2002 ASS, REC, BY	REF: CS3/AIG19001288/GCd3CDescrial Lestruction:
Surveyor:	ASSIGNMENT (Office)
From (Person	thin le ying of AlG Date/Time 31/11198 10:45 cm
Estimated Co.	
OD (TP)W:	STTP RES / OD RES / EVA / INV / MV 7 CS
To Inspect Ve at Workshop of	m/s A.S. Auto Tel: 97388183
200	1 Kaki Bukit Are 6 # 01-106 2100H95384 Claim No: 088880762256
Sum Insured:	Excess:
Make of Veh: (Client's Record	DATE I I I I I I
CA / REV	/ REP. / REV 24 HRS H.O.D. Endorsement:
Date/Time;	11-15am B 21/119 Person Contacted: Mr.5000 Vehicle IN OUT
Date/Time	Action/Instruction ( × ) Estimate
	8Dx 2318x-cc3/A1G17004894/Ahb3g2 Dun: 8/3/17
	181 K 1452 V - X 1
	Diamantle: 22/1/209
	After repair: 23/1/2019.

REF:	72936
ASS	IGNMENT
rom: Date:	Veh No: SDX 2318 Y Yr Regn: 20 cot 2019
estimated Cost:	Type: M.Cas M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD THE WS ! TP RES ! OD RES ! EVA ! INV ! MV	Truck / Trailer or
o Inspect Vehicle No:	Make: Audi Al c.c 999
it Workshop m/s A.S. Awto	Colour Grey A/C: Insured / Std / NI / NA
of San Figure 1	Sp.Reading 32737 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: WAUZZ 8X 8G B 028 353
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Ino@er / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Indrder / Jammed / Leaked / Burnt or
Make of Veh:	Modi : Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 215/45 RH6
(Policy Condition)	R: U
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF Continuator
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 21-01-19
Lum Sum: % 3 Val.: Yes or No	Survey held at W/S
CA / REV / REP. / 24 HRS  Vehicle: IN / OU	Des. of Damages : Frt / Roar / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Carlotte Control of the Control of t	

	7.				
Date/Time, File Pass to?	: Preli. Report	Day	s Of Repair: 5		
1)	: Final Report	Res	urvey No. of Trip:	Survey Fee:	180
Date/Time, File Return to?				Transportation:	
2)		Add Fee:	: Site Insp (\$	S+RS,SI	
2			: Interview (\$	) Photos	
Report Format :	DAR.		: Tech. Invs (\$	) Others	10
Lump Sum / I.B.I: (\$		) . [	: Weekend (\$	, )	
		2		TOTAL	190

# - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 21/1/2019 10:45:26 AM

Attachments:

19012019113738.pdf

Hi LKK.

Kindly assist to survey after 2pm today.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# Centro-Legal Law Corporation

151 Chin Swee Road #02-21 Manhattan House Singapore 169876 Tel: 6235 0633

Tel: 6235 0633 Fax: 6235 6939

ADVOCATES AND SOLICITORS

Your ref

SLK1452Y

Our ref

CLLC.PD.20.2019 LI

19 JANUARY 2019

AIG ASIA PACIFIC INSURANCE PTE LTD 78 Shenton Way #07-16 AIG Building Singapore 079120

BY FAX & EMAIL

Fax: 6835 7416

Attn: Officer-In-Charge

Dear Sirs,

# NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASE

We act for YEOH LAY, the owner of motor vehicle **SDX2318Y**, who has appointed us to act on his behalf to claim against your insured's vehicle no **SLK1452Y** in regards to the road traffic accident on 17.01.2019

Please be informed that the said motor vehicle can be inspected at:-

#### A S AUTO

1 KAKI BUKIT AVENUE 6 #01-106 AUTOBAY@KAKI BUKIT SINGAPORE 417883 Tel: 9738 8183

Kindly contact: Mr Soon Tel: 9738 8183

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

CENTRO-LEGAL LAW CORPORATION
Cc Mr Soon

# Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Owner ID Type:	Singapore NRIC
Owner ID:	7293E
Vehicle Details	
Vehicle No.:	SDX2318Y
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	AUDI
Vehicle Model:	A1 SB 1.0 TFSI (PI)
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	CHZ030453
Chassis No.:	WAUZZZ8X8GB028353
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$21,230.00
Original Registration Date:	20 Oct 2015
First Registration Date:	20 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$6,722.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Oct 2025
PARF Rebate Amount:	\$5,041.00
Intended COE Rebate Details	。
COE Expiry Date:	19 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$37,744.00
Total Rebate Amount:	\$42,785.00

The information contained herein is correct as at 22 Jan 2019

ОК

Rear Portion NAC INC Item CON AC Qty 1137 993626 Rear Number Plate 1138 | 993627 Rear Number Plate Base 1139 993630 Rear Number Plate Garnish 1140 993632 Rear Number Plate Lamp 1141 992958 Rear Bumper 1142 993085 Rear Bumper Upper 1143 993017 Rear Bumper Lower 1144 | 993054 Rear Bumper Side 1145 993103 Rear Bumper Tow Cover 1146 992341 Rear Bumper Clips 1147 | 992976 | Rear Bumper Bracket 1148 993068 Rear Bumper Side Retainer 993045 Rear Bumper Reinforcement 1149 1150 992970 Rear Bumper Beam 1151 993077 Rear Bumper Sponge 1152 992999 Rear Bumper Damper 1153 993040 Rear Bumper Protector 1154 993036 Rear Bumper Pad 1155 993026 Rear Bumper Moulding 1156 993044 Rear Bumper Reflector 1157 993023 Rear Bumper Lower Spoiler 1158 | 994023 | Reverse Sensor 1159 993327 Rear End Panel 1160 993339 Rear End Panel Top Garnish RU 1161 993333 Rear End Panel Inner Trim 1162 | 990333 | Boot Compartment Inner Trim 1163 993851 Rear LH Taillamp 1164 993853 Rear LH Taillamp Garnish 1165 993859 Rear LH Taillamp Panel 1166 995116 Rear RH Taillamp 1167 993853 Rear RH Taillamp Garnish 1168 993859 Rear RH Taillamp Panel 1169 993554 Rear Apron Panel 1170 992895 Bootlid 991328 Bootlid Emblem 1171 1172 990356 Bootlid Handle 1173 995250 Bootlid Moulding 990376 Bootlid Reflector 1174 995222 Bootlid Lamp LH 1175 992899 Bootlid Lamp RH 1176 1177 995243 Bootlid Lock 1178 990377 Bootlid Rubber 1179 990382 Bootlid Hinge 1180 | 993877 | Bootlid Spoiler 1181 994543 Tailgate 991328 Tailgate Emblem 1182 1183 994643 Tailgate Outer Handle 994640 Tailgate Moulding 1184 994545 Tailgate Garnish 1185 994648 Tailgate Reflector 1186 994549 Tailgate Lamp 1187 994646 Tailgate Protector 1188 994676 Tailgate Wiper Arm 1189 994677 Tailgate Wiper Blade 1190 1191 994679 Tailgate Wiper Nozzle 1192 994555 Tailgate Wiper Motor 1193 994602 Tailgate Glass 1194 994606 Tailgate Glass Rubber 1195 994604 Tailgate Glass Moulding 994607 Tailgate Glass Sealant 1196 994629 Tailgate Lock 1197 994651 Tailgate Rubber 1198

1199

1200

994611 Tailgate Hinge

994594 Tailgate Damper

R (Re:	ar)	(4)Not Consider NC)  Vehicle No: SOX 2	718	Y	
NAC	INC				
NAC 1202		Item .	CON	AC	Qt
	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	993063	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209		Antenna			
1210	990534	Centre Exhaust Pipe Assy			-
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe		_	
1213	993357	Rear Exhaust Chrome Pipe		_	_
1214	993361	Rear Exhaust Mounting		_	
1215	993358	Rear Exhaust Heat Shield		_	-
1216	995223	Rear LH Chassis Member		_	
1217	993165	Rear RH Chassis Member		-	-
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector		-	
1220	993420	Rear LH Fender Inner Panel		_	_
1221	003/131	Rear LH Fender Inner Trim		_	_
1222	003/15	Rear LH Fender Inner Trim			
1222	993413	Rear LH Fender Inner Garnish.			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
		Rear LH Wheel Rim			
		Rear LH Rim Cover			
		Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel		_	
1231	993431	Rear RH Fender Inner Trim		_	_
1232	993415	Rear RH Fender Inner Garnish		_	-
1233	993425	Rear RH Fender Inner Shield		_	_
1234	993622	Rear RH Mudflap		_	_
1235	993934	Rear RH Wheel Rim		_	
1236	994025	Rear RH Rim Cover	-	_	_
1237	995065	Rear RH Tyre		_	-
1238	995162	Rear Fender Extension Panel LH		_	_
1239	993401	Rear Fender Extension Panel RH			_
1240		Rear Fender Extension Panel RH			
1241					_
1241	993452	Rear Fender 1/4 Glass			
1242	993453	Rear Fendér 1/4 Glass Rubber			
1244	993949	Rear Fender 1/4 Glass Sealant Rear Windscreen Glass		_	
1245					
1245	993976				
	993961	Rear Windscreen Moulding			_
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille	218	/	
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			_
1252		Fuel Tank			
1253	992184	Fuel Tank Bracket			-
1254		Fuel Tank Float		-	-
11136¥				-	-
- 1.11 · 174				-	-
			-	<del> </del> —	-
				-	-
				_	_
					-
					_
					_
					_
					_
				_	

# ...CLAIM SUBFOLDER...(Pending for Survey Report) $_{\text{PRI}}$

CLAIM SUB	FOLDER TRA	CKING									
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj S	Submitted	Ins Auth'ed	5	Status	
Main	21 Jan 2019 Edit Reg		21 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estin	nates	S\$0.	<b>00</b> w Rpt			Pending for Survey Report Cancel Case	
	Main	R	eference	Cla	aim Det	ails		Docume	ents		Show All
CLAIM SU	BFOLDER DI	TAILS					[Created	by adjuster]			
Insured: KOH SWEE YONG, ID: S1214487C											
Main Claimant:	YEOH LA	1									
Vehicle Reg No.:	SDX231	SDX2318Y Date of Loss: 17/01/2019 21:00 - :59 [38 Months and 28 Days From LTA Reg Date (Man Yr)]						(Man Yr)]			
Claim Type	: <b>TP</b> / 088	8807622SG			Policy/Co Note No.			4 (Compreher 06/01/2019 -		020	
Vehicle Reg No. (Insured):	SLK1452	Y			Policy No (Claiman						
					Excess:						
Repairer:	As Auto S	Service (HQ) Blk	1 Kaki Bukit Avenue	6 #01-106	Autobay	@Kaki	Bukit, 4178	83 Kaki Bukit	- Tel:		
Handling Insurer:	WZ.Tan@a	aig.com	e Pte. Ltd. (Expres				151				
Adjuster:	LKK Auto	<b>Consultants Pte</b>	Ltd (HQ) - Tel: 62	56-3561 [	Handled	by X	ING GUO Q	IANG] [Fi	nal Rp	<b>t</b> due 30/0	1/2019]
Insurer's Solicitor:	CENTRO-	LEGAL LAW COR	PORATION (HQ) -	Tel: 6235 06	533 Ir	ncomir	ng Assignme	ent			
ASSOCIA	TED MAIL RE	CEIVED							View All	Compos	se Case Mail
AIG_SG (22/01/2019): TP GIA REPORT											
ALL ASSO	CIATED TAS	sks∃				V	iew All   5	Search Tasks	Create	New Task	Complete
Due Dat	e Priority	Type Task	Group Subjec	t Handle	er A	_	ed By	Completed		Created Or	
						FR ( FEE					

### **Claim Documents**

Ass	essment Reports		1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Prin
1	22/01/19 14:59	Accident Statement From:OD - Reg. No: SLK1452Y, Claimant: KOH SWEE YONG	1 Load HTM	
Pho	otos/Images		3 per page	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/19 10:30	General View	1 Load JPG	✓
2	23/01/19 10:30	General View	1 Load JPG	✓
3	23/01/19 10:30	General View	Load JPG	✓
4	23/01/19 10:30	General View	1 Load JPG	✓
5	23/01/19 10:30	General View	1 Load JPG	<b>✓</b>
6	23/01/19 10:30	General View	1 Load JPG	<b>✓</b>
7	23/01/19 10:30	General View	Load JPG	<b>✓</b>
8	23/01/19 10:30	General View	1 Load JPG	<b>✓</b>
9	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
10	23/01/19 10:30	General View	1 Load JPG	<b>✓</b>
11	23/01/19 10:30	General View	1 Load JPG	V
12	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
13	23/01/19 10:30	General View	Load JPG	V
14	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
15	23/01/19 10:30	General View	1 Load JPG	~
16	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
17	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
18	23/01/19 10:30	General View	1 Load JPG	V
19	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
20	23/01/19 10:30	General View	1 Load JPG	~
21	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
22	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
23	23/01/19 10:30	General View	1 Load JPG	V
24	23/01/19 10:30	General View	1 Load JPG	<b>V</b>
25	23/01/19 10:30	General View	1 Load JPG	<b>▼</b>
26	23/01/19 10:30	General View	1 Load JPG	<b>▼</b>
27	23/01/19 10:30	General View	Load JPG	<b>▼</b>
			1 Load JPG	
28	23/01/19 10:30	General View	Load JPG     Load JPG	
29	23/01/19 10:30	General View		
30	23/01/19 10:30	General View		_
31	23/01/19 10:30	General View	Load JPG	_
32	23/01/19 10:31	Photographs of Damaged Parts	Load JPG	_
33	23/01/19 10:31	Photographs of Damaged Parts	1 Load JPG	4

Ass	essment Reports		1 per pa	ge 🗸	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Prin
34	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	✓
35	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	V
36	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	~
37	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	<b>V</b>
38	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	V
39	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	~
		Photographs of Damaged Parts	0	Load JPG	<b>√</b>
40	23/01/19 10:31		0	Load JPG	V
11	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	₹ ¥
12	23/01/19 10:31	Photographs of Damaged Parts			
13	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	V
14	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	~
15	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	<b>∀</b>
16	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	~
47	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	4
18	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	V
19	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	~
50	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	V
51	23/01/19 10:31	Photographs of Damaged Parts	Ð	Load JPG	V
52	23/01/19 10:31	Photographs of Damaged Parts	O	Load JPG	V
3	23/01/19 10:31	Photographs of Damaged Parts	Ð	Load JPG	V
54	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	V
55	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	V
56	23/01/19 10:31	Photographs of Damaged Parts	0	Load JPG	V
57		Parconia Service Control of the Cont	0	Load JPG	V
	28/01/19 13:28	Photo After Spray	0	Load JPG	V
58	28/01/19 13:28	Photo After Spray			
59	28/01/19 13:28	Photo After Spray	0	Load JPG	<u>~</u>
50	28/01/19 13:28	Photo After Spray	0	Load JPG	<u>-</u>
51	28/01/19 13:28	Photo After Spray	0	Load JPG	~
52	28/01/19 13:28	Photo After Spray	0	Load JPG	4
53	28/01/19 13:28	Photo After Spray	0	Load JPG	~
54	28/01/19 13:28	Photo After Spray	Ð	Load JPG	~
55	28/01/19 13:28	Photo After Spray	0	Load JPG	V
56	28/01/19 13:28	Photo After Spray	0	Load JPG	~
57	28/01/19 13:28	Photo After Spray	0	Load JPG	V
58	28/01/19 13:28	Photo After Spray	0	Load JPG	V
59	28/01/19 13:28	Photo After Spray	0	Load JPG	2
70	28/01/19 13:28	Photo After Spray	0	Load JPG	V
71	28/01/19 13:28	Photo After Spray	0	Load JPG	<u></u>
72		Photo After Spray	0	Load JPG	<u>-</u>
	28/01/19 13:28	21 (100-100 100 100 100 100 100 100 100 100	0	Load JPG	2
73	28/01/19 13:28	Photo After Spray		W TO STATE OF STATE OF	-
74	28/01/19 13:28	Photo After Spray	0	Load JPG	<u> </u>
75	28/01/19 13:28	Photo After Spray	0	Load JPG	~
76	28/01/19 13:28	Photo After Spray	0	Load JPG	
77	28/01/19 13:28	Photo After Spray	0	Load JPG	~
78	28/01/19 13:28	Photo After Spray	0	Load JPG	~

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print

Merimen e-Claims Page 3 of 3

There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Insurer's Solicitor Note: Remarks are private unless you show it to other parties.	

#### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19001288/GCD3E2

Date:

29/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100495384

Claimant Vehicle SDX2318Y No:

Insured Vehicle No:

**SLK1452Y** 

Date of Loss:

17/01/2019

Nature of Claim:

TP

Claim No: 0888807622SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**SDX2318Y** 

Make & Model:

AUDI A1, 999cc SB 1.0 TFSI (PI) (A)

Engine No:

CHZ030453

Reg. Date: Colour:

20/10/2015 (Man. Year: 2015)

Grey

Chassis No: Odometer:

WAUZZZ8X8GB028353 32737 km

**Engine Capacity:** 

999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Engine Modification: 215/45 R16

Rear Tyre Size:

215/45 R16

Front Tyre Size: Front Left Side:

Continental 6 mm

Rear Left Side: Rear Right Side: Continental 6 mm Continental 6 mm

Front Right Side: Continental 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

21/01/2019

Date Inspected:

21/01/2019 Inspected At:

As Auto Service (HQ)

Blk 1 Kaki Bukit Avenue 6 #01-106

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair:

5.0 days

Adjuster: XING GUO QIANG

Manager:

**CELINE FONG** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_... 29/1/2019

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
3	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
6	1		*REAR BUMPER LOWER SPOILER	Broken	0.00 F	*- F
7	2		*REVERSE SENSOR	Broken	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Crumpled	0.00 F	*- F
10	1		*TAILGATE	Repair	0.00 F	*-F
11	1		*REAR PANEL AIR GRILLE	Distorted	0.00 F	*- F
F=Fra	anchise	part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >