



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/07/2019

Survey Details:

Date of loss	15-Jan-19
Date of appointment	21-Jan-19
Date of survey	21-Jan-19
Location of survey	KAI MOTOR TRADING

Vehicle Details:

Claim Type:	Third party
Vehicle number	SGM 159A
Make and Model	TOYOTA WISH 1.8A
Date of registration	5/7/2006 till 2026
Excess	
Market Value	\$45,000
Parf Rebate	\$33,879
Nett Loss	\$11,121

Repair details:

Initial Estimate	\$ 16,412.08
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 4,875.13	list price-25%
Check items (estimate)	\$ -	
Labour	\$ 2,640.00	
Total	\$ 7,515.13	
Lump Sum(if applicable)	\$ 6,000.00	after -20%

Number of days for repair	8
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: The said chain collision involved 3 vehicles whereby our insured was the last vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%. We have send letter to OI to notify TP claim and excess amount on 20th June 2019.

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 6,420.00	(\$6,000.00+7%gst)
Loss of use	\$ -	
Loss of rental	\$ 1,200.00	(\$12days x \$100.00)
Loss of income	\$ -	
GIA search fees	\$ 7.45	
Others	\$ -	
Proposed Total	\$ 7,627.45	



Pls offer global-sum settlement

Type

🔗 Question

Message

Pls start offering at \$7200 for global-sum settlement. You have settlement mandate up to \$7400.

Reply


AUTHORISATION TO ACT


I/We, Tan Ah Hae (the third party claimant") of SGM 59A
(address), owner of SGM 159A (vehicle no.) hereby
authorize KAI MOTOR TRADING ("the workshop") to act for me with respect
to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no.
SGM 159A that was damaged pursuant to the accident which occurred on _____ (date)
along SLE/BKE Near Nee Soon Flyover (location) involving
vehicle no/s SJP 9412 H ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 20 (day) of 08 (month) 2017 (year)


Signed by "the third party claimant"
(with company stamp if applicable)


Signed by "the workshop"
(with company stamp)



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 12/04/2019

Attn: The Motor Claims Department

Your Insured veh no : SJP 9412 H

AXA Insurance S'pore Pte Ltd

8 Shenton way

27-01 AXA Tower

Singapore 068811

WITHOUT PREJUDICE

(By Email Only)

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NO SGM 159 A & SJP 9412 H on 15/01/2019@07:10:00

We have been authorised by Mr Tan Ah Hee, the owner of vehicle claim against the party / parties responsible for the damages arising from number SGM 159 A, to the above mentioned accident.

Our records show that you are the insurers of vehicle number (SJP 9412 H) at the material time of the accident with the driver of our client's vehicle, (Mr Tan Ah Hee).

As a result of the accident caused by your insured driver's negligent driving and/or management of your insured's vehicle number (SJP 9412 H), our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 6,420.00
(2) Dawn Enterprises	\$ 1,920.00
(3) PIR 2days	\$ 160.00
(4) LTA	\$ 7,480.00
	\$ 7.45
	<u>\$ 8,507.45</u>

A cope of each of the following supporting documents is enclosed:

- (a) Final repair bill
- (b) GIA report with sketch plan of (our client's veh number)
- (c) LTA Search





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001303/Awb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: PETER WANG

Date : 09-09-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 9412H	Veh. Inspected	SGM 159A
Policy No.	P2170497	Coverage (\$)	0.00
Claim No.	S9M01B5Q	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	21/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100316396	Colour	SILVER
Odometer	210251	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	6 mm
L/H Front Tyre	195/65 R15	MICHELIN	6 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/01/2019	Inspection Date	21/01/2019
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGM 159A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	799.80	-
1	REAR BOOT COVER (CONSISTENT)	DENTED	1,460.30	1,270.00
1	REAR BOOT INNER BOX (CONSISTENT)	CRACKED	302.50	302.50
12	REAR BOOT INNER BOX CLIPS (CONSISTENT)	NECESSARY	87.60	30.00
1	REAR BOOT MOULDING (CONSISTENT)	NOT NECESSARY	315.00	-
1	REAR BOOT COVER WINDSCREEN GLASS SEALANT (CONSISTENT)	NECESSARY	85.00	85.00
1	REAR BOOT COVER OUTER HOLDER MLD (CONSISTENT)	NOT NECESSARY	165.00	-
1	REAR BOOT COVER INNER LOCK (CONSISTENT)	DAMAGED	480.00	395.00
2	REAR BOOT COVER ABSORBER @ \$250.00 (CONSISTENT)	NOT NECESSARY	500.00	-
2	REAR BOOT COVER RUBBER (CONSISTENT)	CUT	330.00	330.00
2	REAR LAMP @ \$530.00 (CONSISTENT)	NOT NECESSARY	1,060.00	-
1	REAR END PANEL (CONSISTENT)	DENTED	398.00	398.00
1	REAR INNER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	198.00	-
1	REAR PANEL GARNISH (CONSISTENT)	DEFORMED	450.00	374.00
1	REAR MEMBER (CONSISTENT)	TO REPAIR SEE LABOUR	220.00	-
1	REAR TRIM BOARD (CONSISTENT)	DEFORMED	785.10	690.50
2	REAR FENDER INNER AIR DUCT RH/LH @ \$135.00 (CONSISTENT)	NOT NECESSARY	270.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,240.30	483.00
6	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	42.00	42.00
2	REAR BUMPER SIDE RETAINER @ \$65.00 (CONSISTENT)	NECESSARY	130.00	130.00
2	REAR LAMP LOWER BRACKET @\$30.00 (CONSISTENT)	DENTED	60.00	60.00
2	REAR BUMPER REFLECTORS @ \$60.00 (CONSISTENT)	CRACKED	120.00	120.00
1	REAR EXHAUST PIPE (CONSISTENT)	BENT	3,380.00	981.00
1	REAR INSULATOR HEAT (CONSISTENT)	CRUMPLED	187.50	187.50
1	REAR SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	580.00	-

Report Ref No. CC4/ASM19001303/Awb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT COVER LOGO (CONSISTENT)	NECESSARY	75.00	75.00
	REAR BUMPER BRACKET @ \$60.00 (CONSISTENT)	DENTED	120.00	120.00
1	SET REAR AIR CON (CONSISTENT)	NOT NECESSARY	900.00	-
	LESS 25% DISCOUNT		-3,685.27	-1,518.37
			11,055.83	4,555.13
1	REAR BOOT COVER WINDSCREEN GLASS SEAL (SN) (CONSISTENT)	NECESSARY	75.00	60.00
	LESS 25% DISCOUNT		-18.75	-
			56.25	60.00
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	BENT	55.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN) (CONSISTENT)	DEFORMED	65.00	30.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	55.00	-
1	REAR NUMBER PLATE HOLDER (SN) (CONSISTENT)	NOT NECESSARY	65.00	-
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	350.00	200.00
			590.00	260.00
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, REAR INNER PANEL, REAR MEMBER AND REAR SPARE TYRE PANEL.		2,200.00	1,200.00
	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION.		2,000.00	1,100.00
	TO CHECK WIRING FUNCTIONS.		120.00	30.00
	LABOUR CHARGE TO REMOVE & REFIX WINDSCREEN.		150.00	120.00
	TO REMOVE EXHAUST PIPE.		100.00	80.00
	TO REMOVE REVERSE SENSOR.		80.00	50.00
	TO TOWING CHARGE.		60.00	60.00
			4,710.00	2,640.00
	GRAND TOTAL		16,412.08	7,515.13
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,000.00



Report Ref No. CC4/ASM19001303/Awb3s2

A handwritten signature in black ink, appearing to read 'A.L.P.' or similar, with a stylized flourish.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.