



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV191000101
 Date : 08.10.2019
 Vehicle No. : SHC4752B
 Your Ref No. : TAX/01/19/2072
 Our Ref No. : 24099690
 Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
PIXEL STICKER	2.00	\$ 60.00	0.00	\$ 0.00	\$ 120.00
BUMPER LIP COVER RR/LH	1.00	\$ 72.20	(25.00)	\$ 18.05	\$ 54.15
BUMPER LIP COVER RR/RH	0.00	\$ 118.10	0.00	\$ 0.00	\$ 0.00
BUMPER LIP REAR	1.00	\$ 228.90	(25.00)	\$ 57.22	\$ 171.68
BUMPER SEAL, RR LH	1.00	\$ 88.90	(25.00)	\$ 22.22	\$ 66.68
BUMPER SEAL, RR RH	1.00	\$ 65.70	(25.00)	\$ 16.42	\$ 49.28
BUMPER SIDE RETAINER RR/LH	1.00	\$ 94.80	(25.00)	\$ 23.70	\$ 71.10
BUMPER SIDE RETAINER RR/RH	0.00	\$ 94.80	0.00	\$ 0.00	\$ 0.00
UNDER COVER SUBASSY, RR FLOOR	1.00	\$ 514.50	(25.00)	\$ 128.62	\$ 385.88
EXHAUST HEAT SHIELD, REAR	0.00	\$ 107.40	0.00	\$ 0.00	\$ 0.00
EXHAUST TAIL PIPE	0.00	\$ 656.20	0.00	\$ 0.00	\$ 0.00
EXHAUST PIPE FRT	0.00	\$4184.70	0.00	\$ 0.00	\$ 0.00
SUPPORT EXHAUST PIPE, NO.4	0.00	\$ 40.30	0.00	\$ 0.00	\$ 0.00
SUPPORT, EXHAUST REAR	0.00	\$ 33.60	0.00	\$ 0.00	\$ 0.00
TAILGATE ASY	1.00	\$1007.90	(25.00)	\$ 251.97	\$ 755.93
TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$ 29.40	(25.00)	\$ 7.35	\$ 22.05
TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$ 29.40	(25.00)	\$ 7.35	\$ 22.05
TAILGATE DOOR GLASS	1.00	\$1090.90	(25.00)	\$ 272.72	\$ 818.18
MOULDING BACK WINDOW, LOWER NO.1	1.00	\$ 29.40	(25.00)	\$ 7.35	\$ 22.05
TAILGATE LOWER WINDOW GLASS	1.00	\$ 721.30	(25.00)	\$ 180.32	\$ 540.98
SEALANT W/SCREEN	3.00	\$ 37.00	0.00	\$ 0.00	\$ 111.00
TAILGATE DOOR HINGE LH/RH	0.00	\$ 58.30	0.00	\$ 0.00	\$ 0.00
TAILGATE DOOR LOCK	0.00	\$ 444.10	0.00	\$ 0.00	\$ 0.00
TAILGATE DOOR STAY LH	0.00	\$ 241.50	0.00	\$ 0.00	\$ 0.00
TAILGATE DOOR STAY RH	0.00	\$ 241.50	0.00	\$ 0.00	\$ 0.00
TAILGATE DOOR WEATHER STRIP	0.00	\$ 353.40	0.00	\$ 0.00	\$ 0.00
TAILGATE LOCK, COVER	0.00	\$ 15.70	0.00	\$ 0.00	\$ 0.00

Authorized Signature
 for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV191000101
 Date : 08.10.2019
 Vehicle No. : SHC4752B
 Your Ref No. : TAX/01/19/2072
 Our Ref No. : 24099690
 Terms : 30 Days

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

Description	Qty	Unit Cost	Add / (Discount) %	(Discount) Amount	Amount
TAILGATE OUTSIDE GARNISH STRIKER, BACK DOOR	1.00	\$ 504.90	(25.00)	\$ 126.22	\$ 378.68
TAILGATE TRIM, LH	0.00	\$ 85.90	0.00	\$ 0.00	\$ 0.00
TAILGATE TRIM, LOWER	0.00	\$ 180.70	0.00	\$ 0.00	\$ 0.00
TAILGATE TRIM, RH	0.00	\$ 88.30	0.00	\$ 0.00	\$ 0.00
TAILGATE TRIM, UPPER	0.00	\$ 49.60	0.00	\$ 0.00	\$ 0.00
TAILGATE, BOARD ASSY	0.00	\$ 246.90	0.00	\$ 0.00	\$ 0.00
WIRE, BACK DOOR, NO.1	0.00	\$ 582.40	0.00	\$ 0.00	\$ 0.00
MOTOR ASSY, RR WIPER	0.00	\$ 734.60	0.00	\$ 0.00	\$ 0.00
ARM, RR WIPER	0.00	\$ 84.70	0.00	\$ 0.00	\$ 0.00
BLADE ASSY, REAR WIPER	0.00	\$ 55.00	0.00	\$ 0.00	\$ 0.00
CAMERA ASSY, TELEVISION, RR	0.00	\$1436.60	0.00	\$ 0.00	\$ 0.00
SWITCH ASSY, BACK DOOR OPENER	0.00	\$ 146.10	0.00	\$ 0.00	\$ 0.00
FENDER RR/LH	1.00	\$ 766.80	(25.00)	\$ 191.70	\$ 575.10
SMRT LOGO	1.00	\$ 7.80	0.00	\$ 0.00	\$ 7.80
STICKER DECAL 6555 8888	1.00	\$ 21.60	0.00	\$ 0.00	\$ 21.60
FENDER LINER RR/LH	0.00	\$ 141.30	0.00	\$ 0.00	\$ 0.00
LID ASSY, FUEL	0.00	\$ 102.00	0.00	\$ 0.00	\$ 0.00
CABLE SUB-ASSY, FUEL LID	0.00	\$ 63.90	0.00	\$ 0.00	\$ 0.00
RETAINER, FUEL LID CABLE	0.00	\$ 5.90	0.00	\$ 0.00	\$ 0.00
CAP ASSY, FUEL TANK	0.00	\$ 68.10	0.00	\$ 0.00	\$ 0.00
PIPE SUB-ASSY, FUEL NECK	0.00	\$ 230.80	0.00	\$ 0.00	\$ 0.00
TUBE, FUEL TANK	0.00	\$ 36.10	0.00	\$ 0.00	\$ 0.00
TANK SUB-ASSY, FUEL	0.00	\$ 745.10	0.00	\$ 0.00	\$ 0.00
QUARTER GLASS RR/LH	1.00	\$ 168.10	(25.00)	\$ 42.02	\$ 126.08
SEALANT W/SCREEN	1.00	\$ 37.00	0.00	\$ 0.00	\$ 37.00
TYRE	0.00	\$ 126.74	0.00	\$ 0.00	\$ 0.00

Authorized Signature
 for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063
 SMRT TAXIS PTE LTD
 Block Unit
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV191000101
 Date : 08.10.2019
 Vehicle No. : SHC4752B
 Your Ref No. : TAX/01/19/2072
 Our Ref No. : 24099690
 Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
WHEEL, DISC	0.00	\$1490.20	0.00	\$ 0.00	\$ 0.00
REINFORCEMENT, ROOF SIDE INNER LH	0.00	\$ 60.30	0.00	\$ 0.00	\$ 0.00
REINFORCE, ROOF SIDE OUTER LH	0.00	\$ 91.90	0.00	\$ 0.00	\$ 0.00
REINFORCEMENT, BACK DOOR SIDE LH	0.00	\$ 89.50	0.00	\$ 0.00	\$ 0.00
EXTENSION, QUARTER PANEL FRONT LH	0.00	\$ 83.50	0.00	\$ 0.00	\$ 0.00
EXTENSION, QUARTER PANEL REAR LH	0.00	\$ 108.50	0.00	\$ 0.00	\$ 0.00
PANEL, ROOF SIDE, INNER LH	0.00	\$ 134.80	0.00	\$ 0.00	\$ 0.00
EMBLEM REAR	1.00	\$ 60.30	(25.00)	\$ 15.07	\$ 45.23
LICENSE PLATE LAMP	0.00	\$ 35.70	0.00	\$ 0.00	\$ 0.00
NUMBER PLATE	1.00	\$ 15.00	0.00	\$ 0.00	\$ 15.00
NUMBER PLATE FRAME	1.00	\$ 12.00	0.00	\$ 0.00	\$ 12.00
NAME PLATE (HYBRID)	1.00	\$ 51.90	(25.00)	\$ 12.97	\$ 38.93
NAME PLATE (PRIUS)	1.00	\$ 60.80	(25.00)	\$ 15.20	\$ 45.60
NAME PLATE (TOYOTA)	1.00	\$ 51.90	(25.00)	\$ 12.97	\$ 38.93
SPOILER REAR	1.00	\$ 953.70	(100.00)	\$ 953.70	\$ 0.00
3RD BRAKE LAMP	0.00	\$ 231.30	0.00	\$ 0.00	\$ 0.00
SMRT LOGO	1.00	\$ 7.80	0.00	\$ 0.00	\$ 7.80
STICKER DECAL 6555 8888	1.00	\$ 21.60	0.00	\$ 0.00	\$ 21.60
END PANEL	0.00	\$ 602.10	0.00	\$ 0.00	\$ 0.00
END PANEL COVER, DECK TRIM HOLE	0.00	\$ 46.10	0.00	\$ 0.00	\$ 0.00
END PANEL COVER, DECK TRIM, RR	0.00	\$ 121.10	0.00	\$ 0.00	\$ 0.00
REINFORCEMENT, RR	0.00	\$ 34.60	0.00	\$ 0.00	\$ 0.00
SEALANT SIKAFLEX	0.00	\$ 37.00	0.00	\$ 0.00	\$ 0.00
SPARE TYRE PANEL	0.00	\$ 667.70	0.00	\$ 0.00	\$ 0.00
MEMBER SUB-ASSY, RR LH	0.00	\$ 174.10	0.00	\$ 0.00	\$ 0.00
MEMBER SUB-ASSY, RR RH	0.00	\$ 174.10	0.00	\$ 0.00	\$ 0.00
MEMBER SUB ASSY, REAR FLOOR CROSS	0.00	\$ 436.40	0.00	\$ 0.00	\$ 0.00

Authorized Signature
 for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063
 SMRT TAXIS PTE LTD
 Block Unit
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV191000101
 Date : 08.10.2019
 Vehicle No. : SHC4752B
 Your Ref No. : TAX/01/19/2072
 Our Ref No. : 24099690
 Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
NO.1					
MEMBER SUB ASSY, REAR FLOOR CROSS	0.00	\$ 655.70	0.00	\$ 0.00	\$ 0.00
NO.2					
FLOOR PANEL RR/LH	0.00	\$ 102.00	0.00	\$ 0.00	\$ 0.00
FLOOR PANEL RR/RH	0.00	\$ 209.90	0.00	\$ 0.00	\$ 0.00
BOX, DECK FLOOR, RR	0.00	\$ 649.70	0.00	\$ 0.00	\$ 0.00
BOX, RR FLOOR, BOARD	0.00	\$ 679.60	0.00	\$ 0.00	\$ 0.00
BOARD, RR FLOOR	0.00	\$ 392.30	0.00	\$ 0.00	\$ 0.00
BOARD ASSY, RR RH	0.00	\$ 379.20	0.00	\$ 0.00	\$ 0.00
SPACER, RR FLOOR	0.00	\$ 130.60	0.00	\$ 0.00	\$ 0.00
BOX, DECK FLOOR, COVER LH	0.00	\$ 230.10	0.00	\$ 0.00	\$ 0.00
BOX, DECK FLOOR, LH	0.00	\$ 196.80	0.00	\$ 0.00	\$ 0.00
COVER ASSY, TONNEAU	0.00	\$ 602.10	0.00	\$ 0.00	\$ 0.00
CUSHION, SPARE WHEEL	0.00	\$ 230.80	0.00	\$ 0.00	\$ 0.00
PROTECTOR, SPARE	0.00	\$ 143.70	0.00	\$ 0.00	\$ 0.00
CARRIER, SPARE	0.00	\$ 19.70	0.00	\$ 0.00	\$ 0.00
TYRE	0.00	\$ 126.74	0.00	\$ 0.00	\$ 0.00
WHEEL, DISC	0.00	\$1490.20	0.00	\$ 0.00	\$ 0.00
BREAKDOWN SIGN	0.00	\$ 35.00	0.00	\$ 0.00	\$ 0.00
PANEL ASSY, DECK LH	0.00	\$ 307.00	0.00	\$ 0.00	\$ 0.00
PANEL ASSY, DECK RH	0.00	\$ 307.00	0.00	\$ 0.00	\$ 0.00
GARNISH SIDE UPPER, LHR	0.00	\$ 261.70	0.00	\$ 0.00	\$ 0.00
BATTERY	0.00	\$ 278.00	0.00	\$ 0.00	\$ 0.00
BATTERY ASSY, HV	0.00	\$5544.40	0.00	\$ 0.00	\$ 0.00
BATTERY CLAMP	0.00	\$ 16.10	0.00	\$ 0.00	\$ 0.00
BATTERY TRAY	0.00	\$ 42.80	0.00	\$ 0.00	\$ 0.00
WIRE, FRAME	0.00	\$1680.90	0.00	\$ 0.00	\$ 0.00

Authorized Signature
 for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063
 SMRT TAXIS PTE LTD
 Block Unit
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV191000101
 Date : 08.10.2019
 Vehicle No. : SHC4752B
 Your Ref No. : TAX/01/19/2072
 Our Ref No. : 24099690
 Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
WIRE, ENGINE, NO.3	0.00	\$ 74.00	0.00	\$ 0.00	\$ 0.00
WIRE, FLOOR	0.00	\$1675.00	0.00	\$ 0.00	\$ 0.00
WIRE, FLOOR, NO.2	0.00	\$1305.40	0.00	\$ 0.00	\$ 0.00
RECEIVER, DOOR CONTROL	0.00	\$ 239.70	0.00	\$ 0.00	\$ 0.00
PANEL SUB-ASSY, QTR	0.00	\$ 326.70	0.00	\$ 0.00	\$ 0.00
PANEL SUB-ASSY, QTR	0.00	\$ 588.40	0.00	\$ 0.00	\$ 0.00
PANEL SUB-ASSY, QTR WHEEL HOUSE	0.00	\$ 588.40	0.00	\$ 0.00	\$ 0.00
PANEL, QUARTER WHEEL HOUSE, OUTER LH	0.00	\$ 326.70	0.00	\$ 0.00	\$ 0.00
TAIL LAMP BRACKET, LH	0.00	\$ 30.70	0.00	\$ 0.00	\$ 0.00
TAIL LAMP LH	1.00	\$ 548.40	(10.00)	\$ 54.84	\$ 493.56
TROUGH, BACK DOOR LH	0.00	\$ 110.90	0.00	\$ 0.00	\$ 0.00
Sub-Total					\$ 18030.81

Labour

TO REPAIR MEMBER SUB ASSY RR RH	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO REPAIR REAR FENDER RH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO REPAIR REAR WHEELHOUSE	1.00	\$ 400.00	0.00	\$ 0.00	\$ 400.00
TO REPAIR & REPLACE END PANEL, SPARE TYRE PANEL & MEMBER SUB ASSY	1.00	\$ 400.00	0.00	\$ 0.00	\$ 400.00
TO REPAIR FRONT LH PORTION	1.00	\$ 400.00	0.00	\$ 0.00	\$ 400.00
TO REPAIR REAR PORTION	1.00	\$ 800.00	0.00	\$ 0.00	\$ 800.00

Others

TO RESPRAY REAR FENDER RH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY REAR SPARE TYRE PANEL	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO RESPRAY REAR BOTH MEMBERS	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO RESPRAY REAR WHEELHOUSE	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00

Authorised Signature
 for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063
 SMRT TAXIS PTE LTD
 Block Unit
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV191000101
 Date : 08.10.2019
 Vehicle No. : SHC4752B
 Your Ref No. : TAX/01/19/2072
 Our Ref No. : 24099690
 Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
TO RESPRAY REAR PANEL	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO RESPRAY REAR DOOR RH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO REPSRAY FRONT BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY FRONT SUPPORT PANEL	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY FRONT FENDER LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY RIM	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO RESPRAY FRONT PILLAR LH	1.00	\$ 80.00	0.00	\$ 0.00	\$ 80.00
TO RESPRAY FRONT DOOR LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY REAR BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY TAIL GATE	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO RESPRAY REAR SPOILER	1.00	\$ 80.00	0.00	\$ 0.00	\$ 80.00
TO RESPRAY REAR PANEL	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY REAR SPARE TYRE PANEL	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY BATTERY PANEL	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY REAR MEMBER, RH	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY REAR MEMBER, LH	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY RH REAR WHEEL HOUSE	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY REAR LH WHEEL HOUSE	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY FUEL LID COVER	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY RH RAIL ROOF SIDE	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY LH RAIL ROOF SIDE	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO RESPRAY MEMBER SUB-ASSY, CENTER	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00

Authorised Signature
 for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063
 SMRT TAXIS PTE LTD
 Block Unit
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV191000101
 Date : 08.10.2019
 Vehicle No. : SHC4752B
 Your Ref No. : TAX/01/19/2072
 Our Ref No. : 24099690
 Terms : 30 Days

Description	Qty	Unit Cost	Add / (Discount) %	Amount	Amount
FLOOR CROSS , NO.2					
TO RESPRAY TROUGH BACK DOOR RH	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY TROUGH BACK DOOR LH	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY REAR FENDER LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY REAR FENDER RH	0.00	\$ 378.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY RH REAR DOOR	0.00	\$ 378.00	0.00	\$ 0.00	\$ 0.00
TO RESRAY REAR DOOR LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO REMOVE & REFIT BATTERY ASSY HV	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TOWING CHARGE	1.00	\$ 90.00	0.00	\$ 0.00	\$ 90.00
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 20.00	0.00	\$ 0.00	\$ 20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	1.00	\$ 60.00	0.00	\$ 0.00	\$ 60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	1.00	\$ 30.00	0.00	\$ 0.00	\$ 30.00
TO TOP UP A/C GAS	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE / REFIT SEAT	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO ALIGN CHASSIS	0.00	\$ 350.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE & REFIT FUEL TANK	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE & REFIT EXHAUST	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO TRANSFER DOOR MECHANISM	0.00	\$ 240.00	0.00	\$ 0.00	\$ 0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	1.00	\$ 600.00	0.00	\$ 0.00	\$ 600.00
TO TRANSFER REAR TAILGATE MECHANISM	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00

Authorised Signature
 for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063
 SMRT TAXIS PTE LTD
 Block Unit
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV191000101
 Date : 08.10.2019
 Vehicle No. : SHC4752B
 Your Ref No. : TAX/01/19/2072
 Our Ref No. : 24099690
 Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
TO TEST AND REFIX REVERSE SENSOR SYSTEM	1.00	\$ 30.00	0.00	\$ 0.00	\$ 30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	1.00	\$ 40.00	0.00	\$ 0.00	\$ 40.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO CHECK & RESET SYSTEM FUNCTION	0.00	\$ 350.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$ 120.00	0.00	\$ 0.00	\$ 120.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE AND REFIT WIRE HARDESS	0.00	\$ 250.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE AND REFIT BATTERY ASSY HV	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REPLACE SUNDRY PARTS	0.00	\$ 100.00	0.00	\$ 0.00	\$ 0.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$ 0.00	\$ 0.00

GRAND TOTAL \$ 24,380.81

Remark :

Make/Model : TOYOTA PRIUS
 Accident Date : 14.01.2019

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.
 No receipt will be issued unless requested.

Authorised Signature
 for SMRT Automotive Services Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19001355/Jga3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG		Date : 10-02-2020	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLL 1969T	Veh. Inspected	SHC 4752B
Policy No.	VPA/P1925681	Coverage (\$)	0.00
Claim No.	S9M01AOJ	Excess (\$)	0.00
Assign From	LYNN KHONG	Assign Date	21/01/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKN36U505767755	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/01/2019	Inspection Date	21/01/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 9

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4752B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	DUCT ASSY, QUARTER @ \$70.40 (DISC 25%) (CONSISTENT)	BUCKLED	140.80	105.60
1	BUMPER FRT (DISC 25%) (CONSISTENT)	BROKEN	482.00	361.50
10	BUMPER CLIPS @ \$1.61 (DISC 25%) (CONSISTENT)	NECESSARY	16.10	12.08
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%) (CONSISTENT)	SCRATCHED	311.10	233.33
1	COVER, FR BUMPER HOLE LH (DISC 25%) (CONSISTENT)	SCRATCHED	18.50	13.88
1	BUMPER SUPPORT F/LH (DISC 25%) (CONSISTENT)	CRACKED	76.40	57.30
1	FENDER FRT/LH (DISC 25%) (CONSISTENT)	DEFORMED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%) (CONSISTENT)	NECESSARY	51.90	38.93
1	SEAL, FRONT FENDER TO COWL SIDE, LH (DISC 25%) (CONSISTENT)	NECESSARY	15.20	11.40
1	BUMPER REAR (DISC 25%) (CONSISTENT)	DEFORMED	458.60	343.95
10	BUMPER CLIPS @ \$1.61 (DISC 25%) (CONSISTENT)	NECESSARY	16.10	12.08
1	BUMPER REINFORCEMENT REAR (DISC 25%) (CONSISTENT)	DENTED	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%) (CONSISTENT)	DENTED	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%) (CONSISTENT)	DENTED	139.60	104.70
1	BUMPER LIP COVER RR/LH (DISC 25%) (CONSISTENT)	DEFORMED	72.20	54.15
1	BUMPER LIP REAR (DISC 25%) (CONSISTENT)	DEFORMED	228.90	171.68
1	BUMPER SEAL, RR LH (DISC 25%) (CONSISTENT)	NECESSARY	88.90	66.68
1	BUMPER SEAL, RR RH (DISC 25%) (CONSISTENT)	NECESSARY	65.70	49.28
1	BUMPER SIDE RETAINER RR/LH (DISC 25%) (CONSISTENT)	CRACKED	94.80	71.10
1	UNDER COVER SUBASSY, RR FLOOR (DISC 25%) (CONSISTENT)	DEFORMED	514.50	385.88
1	TAILGATE ASY (DISC 25%) (CONSISTENT)	DENTED	1,007.90	755.93
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%) (CONSISTENT)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%) (CONSISTENT)	NECESSARY	29.40	22.05
1	TAILGATE DOOR GLASS (DISC 25%) (CONSISTENT)	CRACKED	1,090.90	818.18

Report Ref No. CC4/ASM19001355/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%) (CONSISTENT)	NECESSARY	29.40	22.05
1	TAILGATE LOWER WINDOW GLASS (DISC 25%) (CONSISTENT)	CRACKED	721.30	540.98
1	TAILGATE OUTSIDE GARNISH (DISC 25%) (CONSISTENT)	DEFORMED	504.90	378.68
1	FENDER RR/LH (DISC 25%) (CONSISTENT)	BUCKLED	766.80	575.10
1	QUARTER GLASS RR/LH (DISC 25%) (CONSISTENT)	NECESSARY	168.10	126.08
1	EMBLEM REAR (DISC 25%) (CONSISTENT)	NECESSARY	60.30	45.23
1	NAME PLATE (HYBRID) (DISC 25%) (CONSISTENT)	NECESSARY	51.90	38.93
1	NAME PLATE (PRIUS) (DISC 25%) (CONSISTENT)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%) (CONSISTENT)	NECESSARY	51.90	38.93
1	FOG LAMP LH (DISC 10%) (CONSISTENT)	SCRATCHED	280.10	252.09
1	LENS & BODY, FR TURN LH (DISC 10%) (CONSISTENT)	SCRATCHED	511.80	460.62
1	HEAD LAMP LH (DISC 10%) (CONSISTENT)	CRACKED	945.20	850.68
1	TAIL LAMP LH (DISC 10%) (CONSISTENT)	CRACKED	548.40	493.56
1	STICKER DECAL SMRT (DOOR) (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	SENSOR REVERSE (SN) (CONSISTENT)	SHORTED	180.00	180.00
2	PIXEL STICKER @ \$60.00 (SN) (CONSISTENT)	NECESSARY	120.00	120.00
3	SEALANT W/SCREEN @ \$37.00 (SN) (CONSISTENT)	NECESSARY	111.00	111.00
1	SMRT LOGO (SN) (CONSISTENT)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN) (CONSISTENT)	NECESSARY	21.60	21.60
1	SEALANT W/SCREEN (SN) (CONSISTENT)	NECESSARY	37.00	37.00
1	NUMBER PLATE (SN) (CONSISTENT)	BUCKLED	15.00	15.00
1	NUMBER PLATE FRAME (SN) (CONSISTENT)	BUCKLED	12.00	12.00
1	SMRT LOGO (SN) (CONSISTENT)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN) (CONSISTENT)	NECESSARY	21.60	21.60
1	PANEL, ROOF SIDE, / LH SIDE (CONSISTENT)	NOT NECESSARY	134.80	-
1	PANEL, ROOF SIDE OUTER LH (CONSISTENT)	NOT NECESSARY	134.80	-
1	DOOR LOCK RR/LH (CONSISTENT)	NOT NECESSARY	709.30	-
1	HINGE LOWER LHR, DOOR (CONSISTENT)	NOT NECESSARY	72.20	-
1	HINGE UPPER LHR, DOOR (CONSISTENT)	NOT NECESSARY	81.70	-
1	CHECK ASSY, FR DOOR, (CONSISTENT)	NOT NECESSARY	150.30	-
1	TAIL LAMP BRACKET, RH (CONSISTENT)	NOT NECESSARY	30.70	-
1	TAIL LAMP RH (CONSISTENT)	NOT NECESSARY	557.80	-

Report Ref No. CC4/ASM19001355/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TROUGH, BACK DOOR (CONSISTENT)	NOT NECESSARY	110.90	-
1	FENDER RR/RH (CONSISTENT)	NOT NECESSARY	766.80	-
1	SMRT LOGO (CONSISTENT)	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888 (CONSISTENT)	NOT NECESSARY	21.60	-
1	FENDER LINER RR/RH (CONSISTENT)	NOT NECESSARY	141.30	-
1	BACK ASSY, REAR SIDE SEAT, RH (CONSISTENT)	NOT NECESSARY	643.80	-
1	QUARTER GLASS RR/RH (CONSISTENT)	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN (CONSISTENT)	NOT NECESSARY	37.00	-
1	DOOR LOCK RR/RH (CONSISTENT)	NOT NECESSARY	709.30	-
1	HINGE LOWER RHR, DOOR (CONSISTENT)	NOT NECESSARY	52.00	-
1	HINGE UPPER RHR, DOOR (CONSISTENT)	NOT NECESSARY	81.70	-
1	DOOR LOCK STRIKER (CONSISTENT)	NOT NECESSARY	40.50	-
1	BUMPER ENERGY ABSORBER FRT (CONSISTENT)	NOT NECESSARY	78.80	-
1	BUMPER REINFORCEMENT FRT (CONSISTENT)	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH (CONSISTENT)	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH (CONSISTENT)	NOT NECESSARY	250.40	-
1	BUMPER FRT ABSORBER LOWER (CONSISTENT)	NOT NECESSARY	127.70	-
1	BRACKET, FR TURN CENTER LH (CONSISTENT)	NOT NECESSARY	58.20	-
1	BRACKET, FR TURN UPPER LH (CONSISTENT)	NOT NECESSARY	24.40	-
1	BRACKET, FR TURN LOWER LH (CONSISTENT)	NOT NECESSARY	26.00	-
1	GRILLE, RADIATOR (CONSISTENT)	NOT NECESSARY	310.60	-
1	SUPPORT SUB-ASSY (CONSISTENT)	NOT NECESSARY	1,460.40	-
1	FENDER LINER FRT/LH (CONSISTENT)	NOT NECESSARY	171.70	-
1	FENDER LINER PAD, FR WHEEL LH (CONSISTENT)	NOT NECESSARY	49.30	-
1	PROTECTOR, FRONT FENDER SIDE PANEL LH (CONSISTENT)	NOT NECESSARY	114.50	-
1	TYRE (CONSISTENT)	NOT NECESSARY	126.74	-
1	COOLANT (CONSISTENT)	NOT NECESSARY	12.32	-
1	QUARTER GLASS FRT/LH (CONSISTENT)	NOT NECESSARY	234.90	-
1	SEALANT W/SCREEN (CONSISTENT)	NOT NECESSARY	37.00	-
1	ANTENNA, ELECTRICAL LOWER REAR (CONSISTENT)	NOT NECESSARY	157.40	-
1	BUMPER LIP COVER RR/RH (CONSISTENT)	NOT NECESSARY	118.10	-
1	BUMPER SIDE RETAINER RR/RH (CONSISTENT)	NOT NECESSARY	94.80	-

Report Ref No. CC4/ASM19001355/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST HEAT SHIELD, REAR (CONSISTENT)	NOT NECESSARY	107.40	-
1	EXHAUST TAIL PIPE (CONSISTENT)	NOT NECESSARY	656.20	-
1	EXHAUST PIPE FRT (CONSISTENT)	NOT NECESSARY	4,184.70	-
2	SUPPORT EXHAUST PIPE, NO.4 @ \$40.30 (CONSISTENT)	NOT NECESSARY	80.60	-
2	SUPPORT, EXHAUST REAR @ \$33.60 (CONSISTENT)	NOT NECESSARY	67.20	-
2	TAILGATE DOOR HINGE LH/RH @ \$58.30 (CONSISTENT)	NOT NECESSARY	116.60	-
1	TAILGATE DOOR LOCK (CONSISTENT)	NOT NECESSARY	444.10	-
1	TAILGATE DOOR STAY LH (CONSISTENT)	NOT NECESSARY	241.50	-
1	TAILGATE DOOR STAY RH (CONSISTENT)	NOT NECESSARY	241.50	-
1	TAILGATE DOOR WEATHER STRIP (CONSISTENT)	NOT NECESSARY	353.40	-
1	TAILGATE LOCK, COVER (CONSISTENT)	NOT NECESSARY	15.70	-
1	STRIKER, BACK DOOR (CONSISTENT)	NOT NECESSARY	48.90	-
1	TAILGATE TRIM, LH (CONSISTENT)	NOT NECESSARY	85.90	-
1	TAILGATE TRIM, LOWER (CONSISTENT)	NOT NECESSARY	180.70	-
1	TAILGATE TRIM, RH (CONSISTENT)	NOT NECESSARY	88.30	-
1	TAILGATE TRIM, UPPER (CONSISTENT)	NOT NECESSARY	49.60	-
1	TAILGATE, BOARD ASSY (CONSISTENT)	NOT NECESSARY	246.90	-
1	WIER, BACK DOOR, NO.1 (CONSISTENT)	NOT NECESSARY	582.40	-
1	MOTOR ASSY, RR WIPER (CONSISTENT)	NOT NECESSARY	734.60	-
1	ARM, RR WIPER (CONSISTENT)	NOT NECESSARY	84.70	-
1	BLADE ASSY, REAR WIPER (CONSISTENT)	NOT NECESSARY	55.00	-
1	CAMERA ASSY, TELEVISION, RR (CONSISTENT)	NOT NECESSARY	1,436.60	-
1	SWITCH ASSY, BACK DOOR OPENER (CONSISTENT)	NOT NECESSARY	146.10	-
1	FENDER LINER RR/LH (CONSISTENT)	NOT NECESSARY	141.30	-
1	LID ASSY, FUEL (CONSISTENT)	NOT NECESSARY	102.00	-
1	CABLE SUB-ASSY, FUEL LID (CONSISTENT)	NOT NECESSARY	63.90	-
1	RETAINER, FUEL LID CABLE (CONSISTENT)	NOT NECESSARY	5.90	-
1	CAP ASSY, FUEL TANK (CONSISTENT)	NOT NECESSARY	68.10	-
1	PIPE SUB-ASSY, FUEL NECK (CONSISTENT)	NOT NECESSARY	230.80	-
1	TUBE, FUEL TANK (CONSISTENT)	NOT NECESSARY	36.10	-
1	TANK SUB-ASSY, FUEL (CONSISTENT)	NOT NECESSARY	745.10	-
1	TYRE (CONSISTENT)	NOT NECESSARY	126.74	-
1	WHEEL, DISC (CONSISTENT)	NOT NECESSARY	1,490.20	-

Report Ref No. CC4/ASM19001355/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REINFORCEMENT, ROOF SIDE INNER LH (CONSISTENT)	NOT NECESSARY	60.30	-
1	REINFORCE, ROOF SIDE OUTER LH (CONSISTENT)	NOT NECESSARY	91.90	-
1	REINFORCEMENT, BACK DOOR SIDE LH (CONSISTENT)	NOT NECESSARY	89.50	-
1	EXTENSION, QUARTER PANEL FRONT LH (CONSISTENT)	NOT NECESSARY	83.50	-
1	EXTENSION, QUARTER PANEL REAR LH (CONSISTENT)	NOT NECESSARY	108.50	-
1	PANEL, ROOF SIDE, INNER LH (CONSISTENT)	NOT NECESSARY	134.80	-
2	LICENSE PLATE LAMP @ \$35.70 (CONSISTENT)	NOT NECESSARY	71.40	-
1	3RD BRAKE LAMP (CONSISTENT)	NOT NECESSARY	231.30	-
1	END PANEL (CONSISTENT)	NOT NECESSARY	602.10	-
1	END PANEL COVER, DECK TRIM HOLE (CONSISTENT)	NOT NECESSARY	46.10	-
1	END PANEL COVER, DECK TRIM, RR (CONSISTENT)	NOT NECESSARY	121.10	-
2	REINFORCEMENT, RR @ \$34.60 (CONSISTENT)	NOT NECESSARY	69.20	-
1	SEALANT SIKAFLEX (CONSISTENT)	NOT NECESSARY	37.00	-
1	SPARE TYRE PANEL (CONSISTENT)	NOT NECESSARY	667.70	-
1	MEMBER SUB-ASSY, RR LH (CONSISTENT)	NOT NECESSARY	174.10	-
1	MEMBER SUB-ASSY, RR RH (CONSISTENT)	NOT NECESSARY	174.10	-
1	MEMBER SUB ASSY, REAR FLOOR CROSS NO.1 (CONSISTENT)	NOT NECESSARY	436.40	-
1	MEMBER SUB ASSY, REAR FLOOR CROSS NO.2 (CONSISTENT)	NOT NECESSARY	655.70	-
1	FLOOR PANEL RR/LH (CONSISTENT)	NOT NECESSARY	102.00	-
1	FLOOR PANEL RR/RH (CONSISTENT)	NOT NECESSARY	209.90	-
1	BOX, DECK FLOOR, RR (CONSISTENT)	NOT NECESSARY	649.70	-
1	BOX, RR FLOOR, BOARD (CONSISTENT)	NOT NECESSARY	679.60	-
1	BOARD, RR FLOOR (CONSISTENT)	NOT NECESSARY	392.30	-
1	BOARD ASSY, RR RH (CONSISTENT)	NOT NECESSARY	379.20	-
1	SPACER, RR FLOOR (CONSISTENT)	NOT NECESSARY	130.60	-
1	BOX, DECK FLOOR, COVER LH (CONSISTENT)	NOT NECESSARY	230.10	-
1	BOX, DECK FLOOR, LH (CONSISTENT)	NOT NECESSARY	196.80	-
1	COVER ASSY, TONNEAU (CONSISTENT)	NOT NECESSARY	602.10	-
1	CUSHION, SPARE WHEEL (CONSISTENT)	NOT NECESSARY	230.80	-
1	PROTECTOR, SPARE (CONSISTENT)	NOT NECESSARY	143.70	-
1	CARRIER, SPARE (CONSISTENT)	NOT NECESSARY	19.70	-
1	TYRE (CONSISTENT)	NOT NECESSARY	126.74	-

Report Ref No. CC4/ASM19001355/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEEL, DISC (CONSISTENT)	NOT NECESSARY	1,490.20	-
1	BREAKDOWN SIGN (CONSISTENT)	NOT NECESSARY	35.00	-
1	PANEL ASSY, DECK LH (CONSISTENT)	NOT NECESSARY	307.00	-
1	PANEL ASSY, DECK RH (CONSISTENT)	NOT NECESSARY	307.00	-
1	GARNISH SIDE UPPER, LHR (CONSISTENT)	NOT NECESSARY	261.70	-
1	BATTERY (CONSISTENT)	NOT NECESSARY	278.00	-
1	BATTERY ASSY, HV (CONSISTENT)	NOT NECESSARY	5,544.40	-
1	BATTERY CLAMP (CONSISTENT)	NOT NECESSARY	16.10	-
1	BATTERY TRAY (CONSISTENT)	NOT NECESSARY	42.80	-
1	WIRE, FRAME (CONSISTENT)	NOT NECESSARY	1,680.90	-
1	WIRE, ENGINE, NO.3 (CONSISTENT)	NOT NECESSARY	74.00	-
1	WIRE, FLOOR (CONSISTENT)	NOT NECESSARY	1,675.00	-
1	WIRE, FLOOR, NO.2 (CONSISTENT)	NOT NECESSARY	1,305.40	-
1	RECEIVER, DOOR CONTROL (CONSISTENT)	NOT NECESSARY	239.70	-
1	PANEL SUB-ASSY, QTR (CONSISTENT)	NOT NECESSARY	326.70	-
1	PANEL SUB-ASSY, QTR (CONSISTENT)	NOT NECESSARY	588.40	-
1	PANEL SUB-ASSY, QTR WHEEL HOUSE (CONSISTENT)	NOT NECESSARY	588.40	-
1	PANEL, QUARTER WHEEL HOUSE, OUTER LH (CONSISTENT)	NOT NECESSARY	326.70	-
1	TAIL LAMP BRACKET, LH (CONSISTENT)	NOT NECESSARY	30.70	-
1	TROUGH, BACK DOOR LH (CONSISTENT)	NOT NECESSARY	110.90	-
1	RAIL, ROOF SIDE LH (CONSISTENT)	TO REPAIR SEE LABOUR	273.60	-
1	DOOR RR/LH (CONSISTENT)	TO REPAIR SEE LABOUR	954.50	-
1	DOOR RR/RH (CONSISTENT)	TO REPAIR SEE LABOUR	954.50	-
1	WHEEL DISC, FRONT (CONSISTENT)	TO REPAIR SEE LABOUR	1,484.20	-
1	DOOR FRT/LH (CONSISTENT)	TO REPAIR SEE LABOUR	894.40	-
1	PILLAR, FR BODY, LH (CONSISTENT)	TO REPAIR SEE LABOUR	363.10	-
1	SPOILER REAR (CONSISTENT)	TO REPAIR SEE LABOUR	953.70	-
1	SOLAR FILM (SN) (CONSISTENT)	NECESSARY	850.00	600.00

Report Ref No. CC4/ASM19001355/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BATTERY ASSY, HV (DISC 10%) (CONSISTENT) (ADDITIONAL)	DENTED	5,544.40	4,989.96
1	BUMPER ENERGY ABSORBER FRT (DISC 25%) (CONSISTENT) (ADDITIONAL)	BROKEN	78.80	59.10
1	SUPPORT SUB-ASSY (DISC 25%) (CONSISTENT) (ADDITIONAL)	DENTED	1,460.40	1,095.30
1	TAILGATE DOOR LOCK (DISC 25%) (CONSISTENT) (ADDITIONAL)	BENT	444.10	333.08
1	TAILGATE DOOR WEATHER STRIP (DISC 25%) (CONSISTENT) (ADDITIONAL)	TORN	353.40	265.05
1	TAILGATE, BOARD ASSY (DISC 25%) (CONSISTENT) (ADDITIONAL)	CRUSHED	246.90	185.18
1	FENDER LINER RR/LH (DISC 25%) (CONSISTENT) (ADDITIONAL)	CRUSHED	141.30	105.98
1	END PANEL (DISC 25%) (CONSISTENT) (ADDITIONAL)	DENTED	602.10	451.58
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%) (CONSISTENT) (ADDITIONAL)	CRUSHED	46.10	34.58
1	END PANEL COVER, DECK TRIM, RR (DISC 25%) (CONSISTENT) (ADDITIONAL)	CRUSHED	121.10	90.83
1	SPARE TYRE PANEL (DISC 25%) (CONSISTENT) (ADDITIONAL)	DENTED	667.70	500.78
1	MEMBER SUB-ASSY, RR LH (DISC 25%) (CONSISTENT) (ADDITIONAL)	DENTED	174.10	130.58
1	FLOOR PANEL RR/LH (DISC 25%) (CONSISTENT) (ADDITIONAL)	DENTED	102.00	76.50
1	BOX, DECK FLOOR, RR (DISC 25%) (CONSISTENT) (ADDITIONAL)	BROKEN	649.70	487.28
1	PROTECTOR, SPARE (DISC 25%) (CONSISTENT) (ADDITIONAL)	BROKEN	143.70	107.78
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%) (CONSISTENT) (ADDITIONAL)	BROKEN	157.40	141.66
			74,942.04	18,630.81
LABOUR				
TO REMOVE & REFIT BATTERY ASSY HV. (ADDITIONAL)			250.00	200.00
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF RAIL, ROOF SIDE LH; DOOR RR/LH; DOOR RR/RH; WHEEL DISC, FRONT; DOOR FRT/LH; PILLAR, FR BODY, LH AND SPOILER REAR.			4,723.00	2,300.00
SPRAY PAINT.			9,158.00	2,610.00

Report Ref No. CC4/ASM19001355/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGE.		126.00	90.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		300.00	100.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	30.00
	TO TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.	NOT NECESSARY	120.00	-
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO ALIGN CHASSIS.	NOT NECESSARY	350.00	-
	TO REMOVE & REFIT FUEL TANK.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT EXHAUST.	NOT NECESSARY	120.00	-
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	240.00	-
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	50.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	40.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	50.00
	TO CHECK & RESET SYSTEM FUNCTION.	NOT NECESSARY	350.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN.		240.00	120.00
	TO REMOVE & REFIT REAR QUARTER GLASS RH.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS LH.		120.00	50.00
	TO REMOVE & REFIX FRONT LHS/RHS QUARTER GLASS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIT BATTERY ASSY HV.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			-	-
			-	-
			-	-
			18,027.00	5,750.00



GRAND TOTAL		92,969.04	24,380.81
RECOMMENDED COST OF REPAIRS			24,380.81

Report Ref No. CC4/ASM19001355/Jga3s2

ONG HWEE JIE
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.