

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III19001416/KGA3Q2
Date: 20/08/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHF651U	Insured Vehicle No :	SHA1214T
Date of Loss:	17/01/2019	Nature of Claim:	TP
		Claim No:	MCT19010503

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF651U		
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Engine No:	M9R8839C001645
Reg. Date:	30/06/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC278388
Colour:	Metallic White/Red	Odometer:	562763 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,945.91	18,171.48	17,774.43	49.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,480.00	4,910.00	7,570.00	60.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,425.91	23,081.48	25,344.43	52.34
Approved Total (Overridden) (S\$)		15,200.00		

(S\$)	48,425.91	15,200.00	33,225.91	68.61
+ GST 7.00/7.00% (S\$)	3,389.81	1,064.00	2,325.81	68.61
Nett Amount (S\$)	51,815.72	16,264.00	35,551.72	68.61
+ Loss of Use (26.0 x S\$40.00/day) (S\$)		1,040.00		
+ Car Rental (26.0 x S\$99.32/day) (S\$)		2,582.32		
Nett Liability (S\$)		19,886.32		

INSPECTION

Date of Assignment: 21/01/2019

Date Inspected: 21/01/2019

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111

Estimated Period of Repair: 20.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2019)
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF651U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Cracked	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Cracked	135.97 FL	*135.97 FL
8	1		*BUMPER RETAINER LH REAR	Cracked	44.99 FL	*44.99 FL
9	1		*BUMPER REFLECTOR LH	Broken	43.61 FL	*43.61 FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Distorted	225.95 FL	*225.95 FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Warped	470.06 FL	*470.06 FL
15	1		*BOOT REFLECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
16	1		*BOOT REFLECTOR LAMP RH	Broken	493.35 FL	*493.35 FL
17	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
18	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
20	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
21	1		*BOOT HINGE LH	Bent	367.84 FL	*367.84 FL
22	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
23	1		*BOOT INNER TRIM	Cracked	586.45 FL	*586.45 FL
24	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
25	1		*BOOT LOCK	Dented	202.67 FL	*202.67 FL
26	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
27	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
29	1		*FENDER PANEL REAR LH	Broken	3,299.13 FL	*3,299.13 FL
30	1		*WHEELARCH REAR LH	Cracked	543.47 FL	*543.47 FL
31	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
32	1		*WHEEL HOUSING PANEL REAR LH	Repair	4,682.09 FL	*- FL
33	1		*TAILLAMP LH	Cracked	552.55 FL	*552.55 FL
34	1		*TAILLAMP PANEL LH	Bent	986.70 FL	*986.70 FL
35	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
36	1		*OUTER PANEL REAR (END PANEL) TRIM	Distorted	404.56 FL	*404.56 FL
37	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Bent / Buckled	2,189.88 FL	*2,189.88 FL
38	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
39	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
40	1		*KNUCKLE ARM REAR LH L70Y	Serviceable	736.67 FL	*- FL
41	1		*BRAKE DISC REAR L70Y	Serviceable	525.91 FL	*- FL
42	1		*ABS SENSOR REAR LH L70Y	Serviceable	375.93 FL	*- FL
43	1		*REAR AXLE L70Y	Serviceable	4,167.03 FL	*- FL
44	1		*LOWER ARM REAR LH L70Y	Serviceable	905.99 FL	*- FL
45	2		*ABSORBER REAR	Serviceable	389.75 FL	*- FL
46	1		*STABILIZER BAR REAR L70Y	Serviceable	604.65 FL	*- FL
47	1		*BOOT WEATHERSTRIP (50%)	Cut	290.75 FS	*161.53 FS
48	1		*SET PARKING AID	Torn	700.00 FS	*600.00 FS
49	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
50	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
51	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
52	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
53	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
54	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
55	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
56	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
57	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
58	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
59	1		*REAR BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
60	1		*REAR BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
61	1		*REAR DOOR STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
62	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
63	1		*SET FENDER WHEELARCH REAR LH CLIP	Necessary	35.00 FS	*35.00 FS
64	1		*FENDER INNER TRIM CLIP LH	Necessary	28.00 FS	*28.00 FS
65	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
66	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
67	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
68	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
69	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
70	1		*LEFT REAR TYRE	Serviceable	330.00 FS	*- FS
71	1		*LEFT REAR TYRE RIM	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)**39,646.48****20,054.47****- List Item Discount on L Items 10.00/10.00% (\$)**

3,700.57

1,882.99

Total Parts (\$)**35,945.91****18,171.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF AFFECTED PORTION.	New	4,500.00	1,760.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	4,500.00	2,200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	120.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }	New	170.00	80.00
7	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }	New	170.00	0.00
10	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }	New	380.00	120.00
11	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	New	380.00	80.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	120.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	60.00
14	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
15	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
16	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	250.00
Gross Labour Cost (\$\$)			12,480.00	4,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >