

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19001417/KPS3Q2

**Date:** 02/06/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SBM5555R	<b>Insured Vehicle No :</b>	SH7702U
Date of Loss: 17/01/2019	Nature of Claim: TP	Claim No: MCT19010489

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBM5555R		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	1ZRY316965
Reg. Date:	02/11/2016 (Man. Year: 2016)	Chassis No:	MR053REH104554810
Colour:	Metallic Blue	Odometer:	24891 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,653.69	3,130.79	2,522.90	44.62
Miscellaneous Items	10.00	11.00	-1.00	-10.00
Labour	2,370.00	1,690.00	680.00	28.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>8,033.69</b>	<b>4,831.79</b>	<b>3,201.90</b>	<b>39.86</b>
<b>Approved Total (Overridden) (\$)</b>		<b>4,830.79</b>		
<b>(\$)</b>	8,033.69	4,830.79	3,202.90	39.87
<b>+ GST 7.00/7.00% (\$)</b>	562.36	338.16	224.20	39.87
<b>Nett Amount (\$)</b>	<b>8,596.05</b>	<b>5,168.95</b>	<b>3,427.10</b>	<b>39.87</b>
<b>+ Medical Costs (\$)</b>		120.00		
<b>+ Car Rental (8.0 x \$100.00/day) (\$)</b>		800.00		
<b>+ Doc/Search Fee (\$)</b>		7.45		
<b>Nett Liability (\$)</b>		<b>6,096.40</b>		

### INSPECTION

Date of Assignment:	22/01/2019 Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	22/01/2019 Inspected At:	K Kim Hin Auto Pte Ltd (HQ)
		160 Sin Ming Drive #02-20, Sin Ming
		AutoCity
		Singapore 575722
Estimated Period of Repair:	6.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jun 2020)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBM5555R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	486.50 F	*486.50 F
2	2		*REAR BUMPER SIDE RETAINER-LONG LH/RH	Distorted	240.00 F	*240.00 F
3	2		*REAR BUMPER SIDE RETAINER-SHORT LH/RH	Distorted	160.00 F	*160.00 F
4	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 F
5	2		*REAR BUMPER REFLECTOR	Serviceable	134.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 F	*395.00 F
7	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Repair	136.00 F	*- F
8	1		*REAR BUMPER PARKING SENSOR SET	Shorted	421.70 F	*421.70 F
9	1		*SMART KEY ANTENNA	Serviceable	165.00 F	*- F
10	2		*TAILLAMP ASSY LH/RH	Serviceable	790.00 F	*- F
11	1		*REAR END PANEL	Bent	649.20 F	*649.20 F
12	1		*REAR END PANEL TOP GARNISH	Mtg Distorted	240.00 F	*240.00 F
13	2		*REAR END PANEL TOP GARNISH CLIPS	Necessary	5.00 F	*5.00 F
14	1		*SPARE TYRE PANEL TOP BOARD	Serviceable	334.87 F	*- F
15	1		*SPARE TYRE LOCK SCREW	Serviceable	65.00 F	*- F
16	2		*REAR FENDER INNER TRIM LH/RH	Serviceable	1,518.00 F	*- F
17	1		*BOOTLID	Buckled	758.00 F	*758.00 F
18	1		*BOOTLID LOGO	Necessary	52.15 F	*52.15 F
19	1		*BOOTLID COROLLA EMBLEM	Necessary	48.00 F	*48.00 F
20	1		*BOOTLID ALTIS EMBLEM	Necessary	48.00 F	*48.00 F
21	2		*BOOTLID HINGES LH/RH	Repair	136.00 F	*- F
22	1		*BOOTLID LOCK	Dented	382.50 F	*382.50 F
23	1		*BOOTLID LOCK CATCH	Repair	35.00 F	*- F
24	1		*BOOTLID WEATHERSTRIP	Dented / Distorted	185.00 F	*185.00 F
25	10		*BOOTLID INSULATOR CLIPS	Not Necessary	50.00 F	*- F
26	1		*REAR NUMBER PLATE	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>7,524.92</b>	<b>4,161.05</b>
<b>- Add. Disc. on L,N Items 25.00/25.00% (\$\$)</b>	<b>1,871.23</b>	<b>1,030.26</b>
<b>Total Parts (\$\$)</b>	<b>5,653.69</b>	<b>3,130.79</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	11.00
<b>Sub Total (\$\$)</b>			<b>10.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	900.00	700.00
2	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	50.00	20.00
3	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	120.00	60.00
4	TO APPLY UNDERSEALING.	New	120.00	60.00
5	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	New	80.00	50.00
6	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,100.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,370.00</b>	<b>1,690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >