



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)  
NIL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/01/2019
Vehicle Reg. No.:	<b>SBM5555R</b>	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHOW WEE JIA, ANASTACIA	Driver (Insured):	CHENG POH KHUAN
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	02/11/2016
Vehicle Colour:	GREY		
Engine No:	1ZRY316965	Chassis No:	MR053REH104554810
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	6 ✓		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN AND ARRANGE FOR SURVEY. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

*Not Authorised  
Resurvey & Repair*

### COST OF CLAIMS

	Amount
Parts	5,653.69
Miscellaneous Items	10.00
Labour	2,370.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>8,033.69</b>
<b>+ GST 7.00% (\$\$)</b>	<b>562.36</b>
<b>Nett Amount (\$\$)</b>	<b>8,596.05</b>

This claim is handled by: WONG SHU MAN

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Jan 2019)

**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SBM5555R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*REAR BUMPER	R	0.00	0.00	*486.50 F	✓
2	2		*REAR BUMPER SIDE RETAINER-LONG LH/RH	D.Y	0.00	0.00	*240.00 F	✓
3	2		*REAR BUMPER SIDE RETAINER-SHORT LH/RH	D.Y	0.00	0.00	*160.00 F	✓
4	10		*REAR BUMPER CLIPS	R	0.00	0.00	*50.00 F	✓
5	2		*REAR BUMPER REFLECTOR	R	0.00	0.00	*134.00 F	X
6	1		*REAR BUMPER REINFORCEMENT	R	0.00	0.00	*395.00 F	✓
7	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	R	0.00	0.00	*136.00 F	X
8	1		*REAR BUMPER PARKING SENSOR SET	Short	0.00	0.00	*421.70 F	✓
9	1		*SMART KEY ANTENNA	SVC	0.00	0.00	*165.00 F	X
10	2		*TAILLAMP ASSY LH/RH	R	0.00	0.00	*790.00 F	X
11	1		*REAR END PANEL	R	0.00	0.00	*649.20 F	✓
12	1		*REAR END PANEL TOP GARNISH	M/D 1	0.00	0.00	*240.00 F	✓
13	2		*REAR END PANEL TOP GARNISH CLIPS	R	0.00	0.00	*5.00 F	✓
14	1		*SPARE TYRE PANEL TOP BOARD	R	0.00	0.00	*334.87 F	X
15	1		*SPARE TYRE LOCK SCREW	SVC	0.00	0.00	*65.00 F	X
16	2		*REAR FENDER INNER TRIM LH/RH	R	0.00	0.00	*1,518.00 F	X
17	1		*BOOTLID	R	0.00	0.00	*758.00 F	✓
18	1		*BOOTLID LOGO	R	0.00	0.00	*52.15 F	✓
19	1		*BOOTLID COROLLA EMBLEM	R	0.00	0.00	*48.00 F	✓
20	1		*BOOTLID ALTIS EMBLEM	R	0.00	0.00	*48.00 F	✓
21	2		*BOOTLID HINGES LH/RH	R	0.00	0.00	*136.00 F	X
22	1		*BOOTLID LOCK	R	0.00	0.00	*382.50 F	✓
23	1		*BOOTLID LOCK CATCH	R	0.00	0.00	*35.00 F	X
24	1		*BOOTLID WEATHERSTRIP	Ref 1011	0.00	0.00	*185.00 F	✓
25	10		*BOOTLID INSULATOR CLIPS	R	0.00	0.00	*50.00 F	X
26	1		*REAR NUMBER PLATE	R	0	0.00	*40.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	7,524.92
- Add. Disc. on L,N Items 25.00% (\$\$)	1,871.23
<b>Total Parts (\$\$)</b>	<b>5,653.69</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	700 900.00
2	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	201 50.00
3	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	601 120.00
4	TO APPLY UNDERSEALING.	New	601 120.00
5	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	New	501 80.00
6	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	800 1,100.00
Gross Labour Cost (\$\$)			2,370.00

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: