



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 37Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	11,800.00	-
1	REAR BUMPER CHROME TIP LH (CONSISTENT)	SERVICEABLE	1,750.00	-
1	REAR BUMPER CHROME TIP RH (CONSISTENT)	SERVICEABLE	1,750.00	-
1	REAR BUMPER TOWING COVER (CONSISTENT)	SERVICEABLE	325.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	3,680.00	-
	LESS 10% DISCOUNT		-1,930.50	-
			17,374.50	-
	<u>SPECIAL NETT ITEMS</u>			
2	REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	680.00	-
			680.00	-
	<u>LABOUR</u>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTENING ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER REINFORCEMENT.	NOT NECESSARY	1,500.00	-
	TO REMOVE & REFIT REAR BUMPER SENSORS.	NOT NECESSARY	150.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.	NOT NECESSARY	100.00	-
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	400.00
			2,750.00	400.00
	GRAND TOTAL		20,804.50	400.00
	RECOMMENDED COST OF REPAIRS			400.00

Report Ref No. CC4/ASM19001445/Kps3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.