

ASS. REC. BY:

REF

CS/MSG19001472/Dx03^{SV}

Special Instruction:

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

Jwyn Tay

of

M81G

Date/Time:

22/11/19 @ 5:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 3508S

Insured:

SLE 3871P

at Workshop m/s

Chunni Motor

Tel:

65425119

of

Blk 10 # 01-05/06 AMIC Autopoint

Policy No:

MSD/vpcp/18-000756-00

Claim No:

MSC/v/19-000092

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/1/19

(Client's Record)

CA / REV / REP. / REV 24 HRS lup

23/1/19
H.O.D. Endorsement:

Date/Time:

5:44pm @ 22/11/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (→) Estimate

SHD 3508S - NS/INC 17007738/H/vbn2

D.O.A: 16/4/17

SLE 3871P - X

29/1/19

Send preli revised via merimen

REF:

ASSIGNMENT

COE 2024 Dec

From: _____ Date: _____
 Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No SHD 3508 8 Yr Regn: Dec 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C. Insured / Std / NI / NA

Sp. Reading: 387000 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU700043

C/No: KMHLB41UMHU097712

Gen. Cond: Good Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Ni / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 21/01/2019 D.O.I. 23/01/2019

Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSG ALF 3871P

19/02/19 jnana 2/5 15000/- with 8 days of rev (Red 9332.66, 3870)

RECEIVED 19 FEB 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 19/2- typist

Report Format: merimen

Lump Sum / I.B.F. (\$) 15,000/-

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

1) S + RS \$

2) Photos

3) Other

4) ...

TOTAL

250

10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2019		22 Jan 2019 17:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N, Email: JUNTAIYO@HCSPL.COM.SG			
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R			
Vehicle Reg. No.:	SHD3508S	Date of Loss:	21/01/2019 12:00 - :59 [24 Months and 23 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MSC/V/19-000092	Policy/Cover Note No.:	MSD/VPCP/18-000756-00 (Comprehensive) Coverage: 01/06/2018 - 31/05/2019	
Vehicle Reg. No. (Insured):	SLE3871P	Policy No. (Claimant):		
		Excess:	S\$2,000.00	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2019]			
Driver/Custodian (Insured):	CHUA CHOON LOK (64 / Male), NRIC: S1024474I, Tel: +6583892336			
Adj Asg. Remarks:	on WP, SJE AGREED / LIABILITY 100% Workshop Location : SOON HOCK MOTOR #01-05/06 AMK AUTOPOINT Please contact MS LYNN 6542 5119 or MS IRENE 6542 7162 to arrange for survey .			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jowyn Tay Mei Ling	Date: 29 Jan 2019

Preliminary Advice

Insured Vehicle No	: SLE3871P		
TP Vehicle No	: SHD3508S	Accident Date	: 21/01/2019
Make	: HYUNDAI I40	Assignment Date	: 22/01/2019
Date of Inspection	: 23/01/2019	Est. Duration of Repair	: 8.00
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,332.66
Revised Amount	:S\$	19,485.18
Check Items (Estimated)	:S\$	0.00
Total	:S\$	19,485.18
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MCD619009853 / ComfortDelGro Engineering Pte Ltd - Loyal
ENTRY DATE & TIME: 21/01/2019 15:31
SUBMITTED BY: Janet Lim Siong Gek

SINGAPORE ACCIDENT STATEMENT**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2019 15:31
Date Of Accident	21/01/2019 12:45
Exact Location Of Accident	ECP >CHANGI B4 BEDOK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3508S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	ONG SENG YAP
NRIC No	S1355366A
Date Of Birth	29/09/1959
Occupation	OUTDOOR
Date Of Driving Pass	08/08/1978
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93805938
Fax Number	
Contact Number	
Email Address	DHSSDELIGHT@HOTMAIL.COM

Address BLK 485 DUNMAN ROAD
#02-01
Postcode 439190
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 4
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLE3871P
Vehicle Make/Model/Colour TOYOTA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHUA CHOON LOK
NRIC/Passport Number S1024474I
Contact Number
Address
Postcode
Insurance Company Name

Nature Of Damage FRONT AND REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJM5108D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver KINGSLEY JAY LOH YI MIN
NRIC/Passport Number S7835456I
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHD2035X
Vehicle Make/Model/Colour PRIME TAXI
Details Of Properties
Vehicle Category TAXI
Name of Driver LIEW PEI CHIN
NRIC/Passport Number S7102565I
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT
No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21.01.2019@1500HRS

Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.: June Tan

SKETCH PLAN



A- SHD 3508S
 B- SLE 3871P
 C- SJM 5108D
 D- SHD 2035X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21.01.2019@ 1245HRS I was travelling along ECP twds Changi before Bedok Exit with one female passenger onboard.

I was travelling straight and suddenly Veh(B) SLE 3871P from my back hit onto my vehicle rear portion and caused my vehicle to surge forward and hit onto veh(C) SJM 5108D.

As the accident took place too fast I could not take evasive action to prevent the accident.

I have company video and photos at scene to support my claims.

Veh(B) SLE 3871P MR Chua Choon Lok S 1024474I

Veh(C) SJM 5108D MR Kingsley Jay Loh Yi Min S 7835456I

Veh(D) SHD 2035X MR Liew Pei Chin 7102565I

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 21.01.2019@1500HRS

Reporting Centre Personnel's Signature
 Name: June Tan
 NRIC/FIN No.:

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3508S

DATE : 21.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 5039


MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>CYANK</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>hlu</i>			\$ 120.30	✓
	Front Bumper Cover <i>distorted / mounting broken</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>turn</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>Dead</i>			\$ 402.10	✓
	Front Bumper Bracket Top (LH/RH) <i>HL</i>		\$ 22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>HL</i>		\$ 24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>HL</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>CYANK / 1st</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>mounting broken</i>		\$ 1,388.00	\$ 2,776.00	✓
	Radiator <i>2 1st / punctured</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>HL</i>			\$ 792.95	X
	Radiator Bracket (RH/LH) <i>HL</i>		\$ 6.50	\$ 13.00	X
	Radiator Guard <i>broken</i>		\$ 20.00	\$ 40.00	✓
	Horn Unit (LH/RH) <i>broken</i>		\$ 73.80	\$ 147.60	✓
	Aircon Condenser <i>2 1st</i>			\$ 927.50	✓
	Inter Cooler <i>2 1st / punctured</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>HL</i>			\$ 25.90	X
			9313.20		
			7450.56		
	SUB TOTAL			\$ 10,461.65	
	LESS 20%			\$ 2,092.33	
	DISCOUNTED TOTAL			\$ 8,369.32	
	Front Number Plate <i>CYANK</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>broken</i>			\$ 30.00	Nett ✓
	Front Fender Advertisement Logo (RH) <i>HL HL</i>			\$ 100.00	Nett <i>X</i>
			155.00		
			55.00		
				\$ 155.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 500.00	360/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charge			\$ 50.00	HL
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	HL
			970.00		
	TOTAL LABOUR			\$ 2,230.00	

SHD 3508S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid St			\$ 2,174.90 ✓
	Boot Lid Rubber deformed			\$ 96.50 ✓
	Boot Lid Hinge (LH/RH) NW	S	142.30	\$ 284.60 X
	Boot Lid Lock Upper St			\$ 102.60 ✓
	Boot Lid Lock Lower St			\$ 31.70 ✓
	Boot Lid 'H' Emblem hlc			\$ 28.70 ✓
	Boot Lid CRDI Plate hlc			\$ 27.90 ✓
	Boot Lid Lamp (LH/RH) CWK	S	565.60	\$ 1,131.20 ✓
	Boot Lid Trimboard torn			\$ 116.40 ✓
	Boot Lid Trimboard Clips (10pcs) hlc			\$ 11.00 ✓
	Bootlid Moulding HW			\$ 85.00 X
	Bootlid i40 Emblem HW hlc			\$ 27.90 ✓
	Bootlid Lower Garnish rgyr			\$ 227.90 X
	Rear Bumper distorted			\$ 553.00 ✓
	Rear Bumper Reinforcement CWK			\$ 428.40 ✓
	Rear Bumper Reinforcement Bracket (LH/RH) HW	S	80.30	\$ 160.60 X
	Rear Bumper Clip 10 pcs hlc			\$ 22.00 ✓
	Rear Bumper Bracket HW	S	35.60	\$ 71.20 X
	Rear Bumper Sponge torn			\$ 118.40 ✓
	Rear Bumper Under Cover distorted			\$ 228.00 ✓
	Tail Lamp (LH/RH) CWK	S	697.80	\$ 1,395.60 ✓
	Rear Panel Dented			\$ 526.70 ✓
	Rear Panel Garnish deformed mounting			\$ 57.70 ✓
	Rear Panel Lower Panel Dented			\$ 495.50 ✓
	Exhaust Pipe Insulator HW	S	58.55	\$ 117.10 X
	Exhaust Silencer St dentee	S	967.70	\$ 1,935.40 Z ✓
	Exhaust Pipe Hanger HW	S	58.55	\$ 117.10 X
	Exhaust Pipe Centre HW distorted HW			\$ 730.10 X ✗ X
	Spare Tyre Panel Dented			\$ 852.80 ✓
	Spare Tyre Panel Cushion HW			\$ 209.05 X
	Rear Towing Hook HW			\$ 94.60 X
		10362.30		
		8289.84		
	SUB TOTAL			\$ 12,459.55
	LESS 20%			\$ 2,491.91
	DISCOUNTED TOTAL			\$ 9,967.64
	Boot Lid Comfort Logo & Tel No. Sticker hlc			\$ 30.00 Nett ✓
	Boot Lid Advertisement Logo hlc			\$ 100.00 Nett ✓
	Rear No.Plates HW			\$ 25.00 Nett X
	Rear Bumper Reverse Sensor Dmm			\$ 135.70 Nett ✓
	Rear Bumper Advertisement Logo hlc			\$ 50.00 Nett ✓
	Rear Bumper Rubber Mat hlc			\$ 50.00 Nett ✓
	Rear Fender Advertisement Logo (LH/RH) hlc	S	100.00	\$ 200.00 Nett ✓
		565.70		
				\$ 590.70

SHD 3508S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,500.00 700/-
	Spray Painting Charge			S 1,000.00 600/-
	Wiring Charge			S 50.00 30/-
	Tuff Kote			S 50.00 40/-
	Remove/Refix Reverse Sensor			S 120.00 40/-
	Remove/Refix Exhaust Pipe		1470.00	S 300.00 60/-
	 TOTAL LABOUR			S 3,020.00
	ESTIMATE TOTAL			S 24,332.66
	23/01/2019 @ 1000hrs		18801.10	
	N/A Antenna		4/5 15000/-	
	2/Sum			
	 8 days.			
	2kt Auto			
				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2019		22 Jan 2019 17:15 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N, Email: JUNTAIYO@HCSPL.COM.SG		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD3508S	Date of Loss:	21/01/2019 12:00 - :59 [24 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/19-000092	Policy/Cover Note No.:	MSD/VPCP/18-000756-00 (Comprehensive) Coverage: 01/06/2018 - 31/05/2019
Vehicle Reg. No. (Insured):	SLE3871P	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 21/02/2019]		
Driver/Custodian (Insured):	CHUA CHOON LOK (64 / Male), NRIC: S1024474I, Tel: +6583892336		
Adj Asg. Remarks:	on WP, SJE AGREED / LIABILITY 100% Workshop Location : SOON HOCK MOTOR #01-05/06 AMK AUTOPOINT Please contact MS LYNN 6542 5119 or MS IRENE 6542 7162 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD3508S (MSC/V/19-000092)**
[SLE3871P]
TP
COMFORT TRANSPORTATION PTE LTD
Jan 21 2019 12:00PM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Chunni Motor Work Pte Ltd - Amk

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports

No	Finalized On		1 per page	Thumbnail	Print
1	22/01/19 11:44	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement From: SC - Reg. No: SLE3871P, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD		Load HTM	
1	29/01/19 08:46	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice		Load HTM	

Photos/Images

No	Relabel/Reorder		3 per page	Thumbnail	Print
1	17/02/19 13:53	LKK Auto Consultants Pte Ltd (HQ) Rear View Right		Load JPG	☒
2	17/02/19 13:53	Rear View Left		Load JPG	☒
3	17/02/19 13:54	General View		Load JPG	☒
4	17/02/19 13:54	General View		Load JPG	☒
5	17/02/19 13:54	General View		Load JPG	☒
6	17/02/19 13:54	General View		Load JPG	☒
7	17/02/19 13:54	General View		Load JPG	☒
8	17/02/19 13:54	General View		Load JPG	☒
9	17/02/19 13:54	General View		Load JPG	☒
10	17/02/19 13:54	General View		Load JPG	☒
11	17/02/19 13:54	General View		Load JPG	☒
12	17/02/19 13:54	General View		Load JPG	☒
13	17/02/19 13:54	General View		Load JPG	☒
14	17/02/19 13:54	General View		Load JPG	☒
15	17/02/19 13:54	General View		Load JPG	☒
16	17/02/19 13:54	General View		Load JPG	☒
17	17/02/19 13:54	General View		Load JPG	☒
18	17/02/19 13:54	General View		Load JPG	☒
19	17/02/19 13:54	General View		Load JPG	☒
20	17/02/19 13:54	General View		Load JPG	☒
21	17/02/19 13:54	General View		Load JPG	☒
22	17/02/19 13:54	General View		Load JPG	☒
23	17/02/19 13:54	General View		Load JPG	☒
24	17/02/19 13:54	General View		Load JPG	☒
25	17/02/19 13:54	General View		Load JPG	☒
26	17/02/19 13:54	General View		Load JPG	☒
27	17/02/19 13:54	General View		Load JPG	☒
28	17/02/19 13:54	General View		Load JPG	☒
29	17/02/19 13:54	General View		Load JPG	☒
30	17/02/19 13:54	General View		Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	17/02/19 13:54	General View	 Load JPG	☒
32	17/02/19 13:54	General View	 Load JPG	☒
33	17/02/19 13:54	General View	 Load JPG	☒
34	17/02/19 13:54	General View	 Load JPG	☒
35	17/02/19 13:54	General View	 Load JPG	☒
36	17/02/19 13:54	General View	 Load JPG	☒
37	17/02/19 13:54	General View	 Load JPG	☒
38	17/02/19 13:54	General View	 Load JPG	☒
39	17/02/19 13:54	General View	 Load JPG	☒
40	17/02/19 13:54	General View	 Load JPG	☒
41	17/02/19 13:54	General View	 Load JPG	☒
42	17/02/19 13:54	General View	 Load JPG	☒
43	17/02/19 13:54	General View	 Load JPG	☒
44	17/02/19 13:54	General View	 Load JPG	☒
45	17/02/19 13:54	General View	 Load JPG	☒
46	17/02/19 13:54	General View	 Load JPG	☒
47	17/02/19 13:54	General View	 Load JPG	☒
48	17/02/19 13:54	General View	 Load JPG	☒
49	17/02/19 13:54	General View	 Load JPG	☒
50	17/02/19 13:54	General View	 Load JPG	☒
51	17/02/19 13:54	General View	 Load JPG	☒
52	17/02/19 13:54	General View	 Load JPG	☒
53	17/02/19 13:54	General View	 Load JPG	☒
54	17/02/19 13:54	General View	 Load JPG	☒
55	17/02/19 13:54	General View	 Load JPG	☒
56	17/02/19 13:54	General View	 Load JPG	☒
57	17/02/19 13:54	General View	 Load JPG	☒
58	17/02/19 13:54	General View	 Load JPG	☒
59	17/02/19 13:54	General View	 Load JPG	☒
60	17/02/19 13:54	General View	 Load JPG	☒
61	17/02/19 13:54	General View	 Load JPG	☒
62	17/02/19 13:54	General View	 Load JPG	☒
63	17/02/19 13:54	General View	 Load JPG	☒
64	17/02/19 13:54	General View	 Load JPG	☒
65	17/02/19 13:54	General View	 Load JPG	☒
66	17/02/19 13:54	General View	 Load JPG	☒
67	17/02/19 13:54	General View	 Load JPG	☒
68	17/02/19 13:54	General View	 Load JPG	☒
69	17/02/19 13:54	General View	 Load JPG	☒
70	17/02/19 13:54	General View	 Load JPG	☒
71	17/02/19 13:54	General View	 Load JPG	☒
72	17/02/19 13:54	General View	 Load JPG	☒
73	17/02/19 13:54	General View	 Load JPG	☒
74	17/02/19 13:54	General View	 Load JPG	☒
75	17/02/19 13:54	General View	 Load JPG	☒
76	17/02/19 13:54	General View	 Load JPG	☒
77	17/02/19 13:54	General View	 Load JPG	☒
78	17/02/19 13:54	General View	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
79	17/02/19 13:54	General View	 Load JPG	✓
80	17/02/19 13:54	General View	 Load JPG	✓
81	17/02/19 13:54	General View	 Load JPG	✓
82	17/02/19 13:54	General View	 Load JPG	✓
83	17/02/19 13:54	General View	 Load JPG	✓
84	17/02/19 13:54	General View	 Load JPG	✓
85	17/02/19 13:54	General View	 Load JPG	✓
86	17/02/19 13:55	Front View Left	 Load JPG	✓
87	17/02/19 13:55	Front View Right	 Load JPG	✓
88	17/02/19 13:56	General View	 Load JPG	✓
89	17/02/19 13:56	General View	 Load JPG	✓
90	17/02/19 13:56	General View	 Load JPG	✓
91	17/02/19 13:56	General View	 Load JPG	✓
92	17/02/19 13:56	General View	 Load JPG	✓
93	17/02/19 13:56	General View	 Load JPG	✓
94	17/02/19 13:56	General View	 Load JPG	✓
95	17/02/19 13:56	General View	 Load JPG	✓
96	17/02/19 13:56	General View	 Load JPG	✓
97	17/02/19 13:56	General View	 Load JPG	✓
98	17/02/19 13:56	General View	 Load JPG	✓
99	17/02/19 13:56	General View	 Load JPG	✓
100	17/02/19 13:56	General View	 Load JPG	✓
101	17/02/19 13:56	General View	 Load JPG	✓
102	17/02/19 13:56	General View	 Load JPG	✓
103	17/02/19 13:56	General View	 Load JPG	✓
104	17/02/19 13:56	General View	 Load JPG	✓
105	17/02/19 13:56	General View	 Load JPG	✓
106	17/02/19 13:56	General View	 Load JPG	✓
107	17/02/19 13:56	General View	 Load JPG	✓
108	17/02/19 13:56	General View	 Load JPG	✓
109	17/02/19 13:56	General View	 Load JPG	✓
110	17/02/19 13:56	General View	 Load JPG	✓
111	17/02/19 13:56	General View	 Load JPG	✓
112	17/02/19 13:56	General View	 Load JPG	✓
113	17/02/19 13:56	General View	 Load JPG	✓
114	17/02/19 13:56	General View	 Load JPG	✓
115	17/02/19 13:56	General View	 Load JPG	✓
116	17/02/19 13:56	General View	 Load JPG	✓
117	17/02/19 13:56	General View	 Load JPG	✓
118	17/02/19 13:56	General View	 Load JPG	✓
119	17/02/19 13:56	General View	 Load JPG	✓
120	17/02/19 13:56	General View	 Load JPG	✓
121	17/02/19 13:56	General View	 Load JPG	✓
122	17/02/19 13:56	General View	 Load JPG	✓
123	17/02/19 13:56	General View	 Load JPG	✓
124	17/02/19 13:56	General View	 Load JPG	✓
125	17/02/19 13:56	General View	 Load JPG	✓
126	17/02/19 13:56	General View	Load JPG	✓

Assessment Reports			1 per page ▾	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
127	17/02/19 13:56	General View	 Load JPG	☒
128	17/02/19 13:56	General View	 Load JPG	☒
129	17/02/19 13:56	General View	 Load JPG	☒
130	17/02/19 13:56	General View	 Load JPG	☒
131	17/02/19 13:56	General View	 Load JPG	☒
132	17/02/19 13:56	General View	 Load JPG	☒
133	17/02/19 13:56	General View	 Load JPG	☒
134	17/02/19 13:56	General View	 Load JPG	☒
135	17/02/19 13:56	General View	 Load JPG	☒
136	17/02/19 13:56	General View	 Load JPG	☒
137	17/02/19 13:56	General View	 Load JPG	☒
138	17/02/19 13:56	General View	 Load JPG	☒
139	17/02/19 13:56	General View	 Load JPG	☒
140	17/02/19 13:56	General View	 Load JPG	☒
141	17/02/19 13:56	General View	 Load JPG	☒
142	17/02/19 13:56	General View	 Load JPG	☒
143	17/02/19 13:56	General View	 Load JPG	☒
144	17/02/19 13:56	General View	 Load JPG	☒
145	17/02/19 13:56	General View	 Load JPG	☒
146	17/02/19 13:56	General View	 Load JPG	☒
147	17/02/19 13:56	General View	 Load JPG	☒
148	17/02/19 13:56	General View	 Load JPG	☒
149	17/02/19 13:56	General View	 Load JPG	☒
150	17/02/19 13:56	General View	 Load JPG	☒
151	17/02/19 13:56	Odometer Reading	 Load JPG	☒
152	17/02/19 13:56	Chassis Number	 Load JPG	☒
153	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
154	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
155	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
156	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
157	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
158	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
159	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
160	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
161	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
162	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
163	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
164	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
165	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
166	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
167	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
168	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
169	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
170	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
171	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
172	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
173	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
174	17/02/19 13:58	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
175	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
176	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
177	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
178	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
179	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
180	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
181	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
182	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
183	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
184	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
185	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
186	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
187	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
188	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
189	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
190	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
191	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
192	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
193	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
194	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
195	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
196	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
197	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
198	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
199	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
200	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
201	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
202	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
203	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
204	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
205	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
206	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
207	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
208	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
209	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
210	17/02/19 13:58	Reinspection Photo	 Load JPG	☒
211	17/02/19 13:58	Finishing Photo	 Load JPG	☒
212	17/02/19 13:58	Finishing Photo	 Load JPG	☒
213	17/02/19 13:58	Finishing Photo	 Load JPG	☒
214	17/02/19 13:58	Finishing Photo	 Load JPG	☒
215	17/02/19 13:58	Finishing Photo	 Load JPG	☒
216	17/02/19 13:58	Finishing Photo	 Load JPG	☒
217	17/02/19 13:58	Finishing Photo	 Load JPG	☒
218	17/02/19 13:58	Finishing Photo	 Load JPG	☒
219	17/02/19 13:58	Finishing Photo	 Load JPG	☒
220	17/02/19 13:58	Finishing Photo	 Load JPG	☒
221	17/02/19 13:58	Finishing Photo	 Load JPG	☒
222	17/02/19 13:58	Finishing Photo	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
223	17/02/19 13:58	Finishing Photo	 Load JPG	✓
224	17/02/19 13:58	Finishing Photo	 Load JPG	✓
225	17/02/19 13:58	Finishing Photo	 Load JPG	✓
226	17/02/19 13:58	Finishing Photo	 Load JPG	✓
227	17/02/19 13:58	Finishing Photo	 Load JPG	✓
228	17/02/19 13:58	Finishing Photo	 Load JPG	✓
229	17/02/19 13:58	Finishing Photo	 Load JPG	✓
230	17/02/19 13:58	Finishing Photo	 Load JPG	✓
231	17/02/19 13:58	Finishing Photo	 Load JPG	✓
232	17/02/19 13:58	Finishing Photo	 Load JPG	✓
233	17/02/19 13:58	Finishing Photo	 Load JPG	✓
234	17/02/19 13:58	Finishing Photo	 Load JPG	✓
235	17/02/19 13:58	Finishing Photo	 Load JPG	✓
236	17/02/19 13:58	Finishing Photo	 Load JPG	✓
237	17/02/19 13:58	Finishing Photo	 Load JPG	✓
238	17/02/19 13:58	Finishing Photo	 Load JPG	✓
239	17/02/19 13:58	Finishing Photo	 Load JPG	✓
240	17/02/19 13:58	Finishing Photo	 Load JPG	✓
241	17/02/19 13:58	Finishing Photo	 Load JPG	✓
242	17/02/19 13:58	Finishing Photo	 Load JPG	✓
243	17/02/19 13:58	Finishing Photo	 Load JPG	✓
244	17/02/19 13:58	Finishing Photo	 Load JPG	✓
245	17/02/19 13:58	Finishing Photo	 Load JPG	✓
246	17/02/19 13:58	Finishing Photo	 Load JPG	✓
247	17/02/19 13:58	Finishing Photo	 Load JPG	✓
248	17/02/19 13:58	Finishing Photo	 Load JPG	✓
249	17/02/19 13:58	Finishing Photo	 Load JPG	✓
250	17/02/19 13:58	Finishing Photo	 Load JPG	✓
251	17/02/19 13:58	Finishing Photo	 Load JPG	✓
252	17/02/19 13:58	Finishing Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/01/19 11:44	TPD SHD3508S GIA REPORT (2/4) From:SC - Reg. No: SLE3871P, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD	 Load PDF	
2	22/01/19 11:50	TPD SHD3508S - ESTIMATE REPAIR & PRI	 Load PDF	
3	22/01/19 15:23	Reply email from TP Workshop & appoint INHOUSE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19001472/DVD3S2

Date: 19/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/18-000756-00

Claimant Vehicle No : SHD3508S Insured Vehicle No : SLE3871P

Date of Loss: 21/01/2019 Nature of Claim: TP Claim No: MSC/V/19-000092

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD3508S**
 Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU700043
 Reg. Date: 29/12/2016 (Man. Year: 2016) Chassis No: KMHLB41UMHU097712
 Colour: Blue Odometer: 387000 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50R16 Rear Tyre Size: 205/50R16
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,082.66	16,361.10	2,721.56	14.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	2,440.00	2,810.00	53.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,332.66	18,801.10	5,531.56	22.73
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	24,332.66	15,000.00	9,332.66	38.35
+ GST 7.00/7.00% (S\$)	1,703.29	1,050.00	653.29	38.35
Nett Amount (S\$)	26,035.95	16,050.00	9,985.95	38.35

INSPECTION

Date of Assignment: 22/01/2019

Date Inspected: 23/01/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)
 Blk 10 #01-05/06, AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 19 Feb 2019)

Parts: 143 **HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD3508S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	120.30 FL	*120.30 FL
3	1		*FRONT BUMPER COVER	Distorted / Mtg Broken	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	402.10 FL	*402.10 FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked / Bent	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mtg Broken	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Bent / Punctured	698.30 FL	*698.30 FL
12	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Not Necessary	792.95 FL	*- FL
13	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
14	2		*RADIATOR GUARD	Broken	40.00 FL	*40.00 FL
15	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
16	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
17	1		*INTER COOLER	Bent / Punctured	1,032.50 FL	*1,032.50 FL
18	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*- FL
19	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
20	1		*FRONT NO. PLATE TRIM COVER	Broken	30.00 FS	*30.00 FS
21	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Not Necessary	100.00 FS	*- FS
22	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
23	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
24	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
25	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
26	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
27	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
28	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
29	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
30	1		*BOOT LID TRIMBOARD	Torn	116.40 FL	*116.40 FL
31	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
32	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
33	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
34	1		*BOOTLID LOWER GARNISH	Repair	227.90 FL	*- FL
35	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
36	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
37	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	160.60 FL	*- FL
38	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
39	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
40	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
41	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
42	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
44	1		*REAR PANEL GARNISH	Mtg Deformed	57.70 FL	*57.70 FL
45	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
46	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
47	2		*EXHAUST SILENCER	Bent / Dented	1,935.40 FL	*1,935.40 FL
48	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
49	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
50	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
51	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
52	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
53	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
54	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
55	1		*REAR NO. PLATE	Not Necessary	25.00 FS	*- FS
56	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
57	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
58	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
59	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	23,666.90	20,296.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,584.24	3,935.10
Total Parts (\$\$)	19,082.66	16,361.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING.	New	2,500.00	1,200.00
2	SPRAY PAINTING CHARGE.	New	1,500.00	960.00
3	WIRING CHARGE.	New	100.00	60.00
4	TOWING CHARGE.	New	50.00	0.00
5	REMOVE / REFIX AIRCON & REFILL GAS.	New	150.00	80.00
6	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	New	480.00	0.00
7	TUFF KOTE.	New	50.00	40.00
8	REMOVE / REFIX REVERSE SENSOR.	New	120.00	40.00
9	REMOVE / REFIX EXHAUST PIPE.	New	300.00	60.00
Gross Labour Cost (S\$)			5,250.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >