

ASS. REC. BY:

REF:

CS / TP19001453 / ASD3m2

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____Veh No: SMG7523X Yr Regn: 28 / 12 / 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2 c.c. 1496Colour: White A/C: Insured / Std / Nil / NASp. Reading: 1738 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MM6DL28AA KW401935Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R15R: 185/55R15BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 21/01/19Survey held at Hua MengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Malaysia Vehicle Independent.14/03/19 Confirmed 215 @ 8,800/- @ 9 days with Adrian
(\$6,902.88 Red 44%)

MV:

PV:

Nett:

RECEIVED 15 MAR 2019

Resurvey No. of TP - 1

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1) 7/4/19

2)

IN

OUT

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

170 + 75505014980574

Prel. Report:

Final Report:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5709E
Vehicle Details	
Vehicle No.:	SMG7523X
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5 AT STANDARD PLUS EU6
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	P520533031
Chassis No.:	MM6DL25AAKW401935
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$14,549.00
Original Registration Date:	28 Dec 2018
First Registration Date:	28 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,549.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2028
PARF Rebate Amount:	\$10,911.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,501.00
COE Rebate Amount:	\$24,952.00
Total Rebate Amount:	\$35,863.00

The information contained herein is correct as at 14 Mar 2019

OK

Shirley Hiew (LKK Auto)

From: Hua Meng <huameng@live.com.sg>
Sent: Thursday, 14 March 2019 7:02 PM
To: Shirley Hiew (LKK Auto)
Subject: Re: REQUEST SMG 7523X GIA REPORT DOA -17/01/2019
Attachments: img-314185751.pdf

Dear Shirley

Client claim against malaysia car. He did not lodge GIA.

Enclosed attachment for client's police report.

Thanks & Regards

June

Hua Meng Spray Painting Workshop

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, March 14, 2019 11:43 AM
To: 'Hua Meng'
Subject: REQUEST SMG 7523X GIA REPORT DOA -17/01/2019

Dear Sir/Madam,

Kindly send us your client's GIA report.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Please see our list of surveyors below and liaise with LKK Auto Consultants Pte Ltd for survey.

Dear Catherine/Nivitha

FYA

No.	Name	Please tick <input checked="" type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	



SINGAPORE POLICE FORCE



T/20190118/2013

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

1 of 4

Report No. T/20190118/2013

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/01/2019 01:10	Vide Report No.: L/20190117/0170	Station Diary No.: 39
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: NG JIAJIE			Address: APT BLK 873 YISHUN STREET 81 #01-153 SINGAPORE 760873	
ID Type / ID No.: NRIC NO / S9315709E			Contact No.: Home/Office: Mobile: 93885383	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 25	Date of Birth: 21/04/1993	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Horticulturist/Arborist			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/01/2019 22:55	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY				
Woodlands Crossing proceeding to BKE.				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SMG7523X	Car	MAZDA	MAZDA2 SEDAN 1.5 AT STANDARD PLUS EU6	White	Slightly Damaged	1
VD3891	Car	PROTON		Red	Slightly Damaged	2



**SINGAPORE
POLICE FORCE**



T/20190118/2013

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

2 of 4

Report No. T/20190118/2013

CONTINUATION OF REPORT

Details of Person Involved:			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger:			
Name	ANGIE ONG	ID No.	S8937345Z
Related Vehicle	SMG7523X (Car)	Contact No.	94553237
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	NG JIAJIE	ID No.	S9315709E
Related Vehicle	SMG7523X (Car)	Contact No.	93885383
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	SYED ABDUL RAHMAN BIN SYED SALLEH	ID No.	970424015247
Related Vehicle	VD3891 (Car)	Contact No.	0104072404
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/01/2019 at about 2255hrs, I was driving my personal vehicle (SMG7523X) with a passenger (Angie Ong) heading back home as we just came back from Malaysia. I was stationary on the most left lane of a 3 lane road, when suddenly I felt an impact from the rear. After collision, I alighted and immediately called for the police. The opposite driver admitted that he was using his phone to check for navigation thus waited for the traffic police to arrive. Shortly later, traffic police arrived and issued a case card to me and the opposite party to proceed to the near post to lodge a police report. Traffic police also seized my SD card from my vehicle and a NP323 was issued to me. My vehicle suffered from dents and cracks at the rear bumper area and my car-boot was unable to close due to the damage sustained.



**SINGAPORE
POLICE FORCE**



T/20190118/2013

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

3 of 4

Report No. T/20190118/2013

CONTINUATION OF REPORT

Nobody was injured due to the accident and no government property was involved. IO in-charge is Esmond (65472077).



**SINGAPORE
POLICE FORCE**



T/20190118/2013

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

4 of 4

Report No. T/20190118/2013

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Staff Sgt MUHAMMAD HIDAYAT BIN
MOHAMED FADIAH

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt SHAIFUL NEEZAM BIN ABDUL
SAMAD

Contact No.: 65476180

Authentication Stamp

NP168



Signature: _____

Singapore Police Force

Signature Of Informant:

Date/Time:

18/01/2019 01:10

Classification Of Case:

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MM6DL2SAAKW401935

NG JIAJIE

BLK 873 YISHUN ST 81

#01-153

S 760873

TP Malaysia

Shirley

Date

:31.01.2019

Vehicle no

:SMG 7523 X

Make/Model

:MAZDA 2

Accident date

:17.01.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear boot lid <i>Dented</i>	1	\$ 1079.9 ✓
2	Rear boot lid insulation <i>New</i>	1	\$ 362.7 ✓
3	Rear boot lid hinges @ \$156.00 <i>Bent</i>	2	\$ 312 ✓
4	Rear boot lid upper lock <i>Damaged</i>	1	\$ 218.4 ✓
5	Rear boot lid lower lock <i>New</i>	1	\$ 71.5 ✓
6	Rear boot lid reflector @ \$270.50 <i>Cracked</i>	2	\$ 541 ✓
7	Rear boot lid weather strip <i>LT</i>	1	\$ 141 ✓
8	Rear boot lid MAZDA emblem	1	\$ 72.9 ✓
9	Rear boot lid centre emblem <i>New</i>	1	\$ 75.9 ✓
10	Rear boot lid SKYACTIV emblem	1	\$ 86.2 ✓
11	Rear boot lid insulation clips <i>New</i>	1	\$ 70 30
12	Rear number plate lamp @ \$97.50 <i>New</i>	2	\$ 195 ✓
13	Rear lamp @ \$489.30 <i>cracked</i>	2	\$ 978.6 ✓
14	Rear lamp housing @ \$769.10 <i>LH Backed</i>	2	\$ 1538.2 <i>178</i>
15	Rear end panel <i>Dented</i>	1	\$ 812.2 ✓
16	Rear end panel inner top garnish <i>Deformed</i>	1	\$ 72.5 ✓
17	Rear bumper <i>Distorted</i>	1	\$ 1181.7 ✓
18	Rear bumper side holder @ \$35.00 <i>New</i>	2	\$ 70 ✓
19	Rear bumper reverse sensor @ \$214.50 <i>Damaged</i>	2	\$ 429 ✓
20	Rear bumper reflector @ \$65.50 <i>cracked</i>	2	\$ 131 ✓
21	Rear bumper clips (1set) <i>New</i>	1	\$ 70 50
22	Rear exhaust pipe <i>Bent</i>	1	\$ 1222.3 ✓
23	Rear exhaust pipe mounting <i>New</i>	1	\$ 44.2 ✓
24	Rear spare tyre top board <i>Deformed</i>	1	\$ 362.7 ✓
25	Rear spare tyre well <i>Repair</i>	1	\$ 97.5 ✓
26	Rear spare tyre well insulation @ \$111.30 <i>Not new</i>	3	\$ 333.9 ✓
27	Rear spare tyre tool spore <i>Deformed</i>	1	\$ 123.5 ✓
28	Rear fender inner garnish @ \$224.90 <i>Deformed</i>	2	\$ 449.8 ✓
29	Rear fender inner shield @ \$97.50 <i>New</i>	2	\$ 195 ✓
30	Rear LH fender <i>Repair</i>	1	\$ 1092 ✓
31	Jack <i>New</i>	1	\$ 143 ✓
			\$ 12573.6
			\$ 2514.72
			\$ 10058.88

8618.60

6894.88

Less 20% Disc

Total

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NG JIAJIE

BLK 873 YISHUN ST 81

#01-153

S 760873

Date

:31.01.2019

Vehicle no

:SMG 7523 X

Make/Model

:MAZDA 2

Accident date

:17.01.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Labour Cost

- 1 To supply rear end panel inner sealant
- 2 Remove & reinstall reverse sensor
- 3 Remove & reinstall exhaust pipe
- 4 Remove & reinstall boot lid inner garnish
- 5 Remove & reinstall petrol tank
- 6 Remove, replace & repair consistent to the accident
- 7 Respray Painting
- 8 Tuff kote

2910

\$ 200 60 neu
\$ 200 50
\$ 200 80
\$ 200 60
\$ 200 X
\$ 2500 1400
\$ 2000 1200
\$ 150 60

Total

\$ 5650

Grand Total

\$ 15708.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5804.88
H/S (10%) : 8.8K
09 Days.

H/S 8.8K
09 Days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HUA MENG SPRAY PAINTING WORKSHOP

Ref : CS/TP19001483/Asd3n2

1 KAKI BUKIT AVE 6

#01-61 AUTOBAYSINGAPORE 417883

ON BEHALF OF NG JIAJIE

Date : 18-03-2019

Code : TP127



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SMG 7523X
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	21/01/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 2	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MM6DL2SAAKW401935	Colour	WHITE
Odometer	1738	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R15	DUNLOP	6 mm
L/H Front Tyre	185/55 R15	DUNLOP	6 mm
R/H Rear Tyre	185/55 R15	DUNLOP	6 mm
L/H Rear Tyre	185/55 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/01/2019	Inspection Date	21/01/2019
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 7523X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	DENTED	1,079.90	1,079.90
1	REAR BOOT LID INSULATION	NOT NECESSARY	362.70	-
2	REAR BOOT LID HINGES @\$156.00	BENT	312.00	312.00
1	REAR BOOT LID UPPER LOCK	DAMAGED	218.40	218.40
1	REAR BOOT LID LOWER LOCK	NOT NECESSARY	71.50	-
2	REAR BOOT LID REFLECTOR @\$270.50	CRACKED	541.00	541.00
1	REAR BOOT LID WEATHER STRIP	CUT	141.00	141.00
1	REAR BOOT LID MAZDA EMBLEM	NECESSARY	72.90	72.90
1	REAR BOOT LID CENTRE EMBLEM	NECESSARY	75.90	75.90
1	REAR BOOT LID SKYACTIV EMBLEM	BROKEN	86.20	86.20
1	REAR BOOT LID INSULATION CLIPS	NECESSARY	70.00	30.00
2	REAR NUMBER PLATE LAMP @\$97.50	NOT NECESSARY	195.00	-
2	REAR LAMP @\$489.30	CRACKED	978.60	978.60
2	REAR LAMP HOUSING @\$769.10	N/S BUCKLED	1,538.20	178.00
1	REAR END PANEL	DENTED	812.20	812.20
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	72.50	72.50
1	REAR BUMPER	DISTORTED	1,181.70	1,181.70
2	REAR BUMPER SIDE HOLDER @\$35.00	NECESSARY	70.00	70.00
2	REAR BUMPER REVERSE SENSOR @\$214.50	DAMAGED	429.00	429.00
2	REAR BUMPER REFLECTOR @\$65.50	CRACKED	131.00	131.00
1	SET REAR BUMPER CLIPS	NECESSARY	70.00	50.00
1	REAR EXHAUST PIPE	BENT	1,222.30	1,222.30
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	44.20	-
1	REAR SPARE TYRE TOP BOARD	DEFORMED	362.70	362.70
1	REAR SPARE TYRE WELL	TO REPAIR SEE LABOUR	97.50	-
3	REAR SPARE TYRE WELL INSULATION @\$111.30	NOT NECESSARY	333.90	-
1	REAR SPARE TYRE TOOL SPONGE	DEFORMED	123.50	123.50
2	REAR FENDER INNER GARNISH @\$224.90	DEFORMED	449.80	449.80
2	REAR FENDER INNER SHIELD @\$97.50	NOT NECESSARY	195.00	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	1,092.00	-
1	JACK	NOT NECESSARY	143.00	-

Report Ref No. CS/TP19001483/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,514.72	-1,723.72
			10,058.88	6,894.88
	<u>SPECIAL NETT ITEMS</u>			
1	REAR END PANEL INNER SEALANT (SN)	NECESSARY	200.00	60.00
			200.00	60.00
	<u>LABOUR</u>			
	REMOVE & REINSTALL REVERSE SENSOR.		200.00	50.00
	REMOVE & REINSTALL EXHAUST PIPE.		200.00	80.00
	REMOVE & REINSTALL BOOT LID INNER GARNISH.		200.00	60.00
	REMOVE & REINSTALL PETROL TANK.	NOT NECESSARY	200.00	-
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE WELL AND REAR LH FENDER.		2,500.00	1,400.00
	RESPRAY PAINTING.		2,000.00	1,200.00
	TUFF KOTE.		150.00	60.00
			5,450.00	2,850.00
	GRAND TOTAL		15,708.88	9,804.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,800.00

Report Ref No. CS/TP19001483/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.