



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2003629  
INV Date 04/05/2020  
Reference CC3/EQI19001484/Jpa3q2  
Code EQI



### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 708L  
Insured Veh. GBB 6584H  
Claim No. DM19HO00204-JG  
Policy No.  
Accident Date 19/01/2019  
Inspection Date 21/01/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI19001484/Jpa3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 04-05-2020		
		Code : EQI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	GBB 6584H	<b>Veh. Inspected</b>	SHB 708L
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	DM19HO00204-JG	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	21/01/2019
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA PRIUS	<b>c.c</b>	1798
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	JTDKN36U005768411	<b>Colour</b>	MAROON
	<b>Odometer</b>	151700	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/65 R15	WEST LAKE	6 mm
	<b>L/H Front Tyre</b>	195/65 R15	WEST LAKE	6 mm
	<b>R/H Rear Tyre</b>	195/65 R15	WEST LAKE	6 mm
	<b>L/H Rear Tyre</b>	195/65 R15	WEST LAKE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS			
<b>5. General Information</b>				
	<b>Accident Date</b>	19/01/2019	<b>Inspection Date</b>	21/01/2019
	<b>Survey held at</b>	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 708L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FENDER FRT/LH (DISC 25%)	BUCKLED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	DOOR RR/LH (DISC 25%)	BUCKLED	954.50	715.88
1	MIRROR LAMP LH (DISC 10%)	SCRATCHED	65.30	58.77
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	FENDER LINER FRT/LH	NOT NECESSARY	171.70	-
1	TAPE OUT WIN FRAME LHF ,DOOR	NOT NECESSARY	45.60	-
1	DOOR LOCK FRT/LH	NOT NECESSARY	575.80	-
1	HINGE UPPER LHF,DOOR	NOT NECESSARY	80.50	-
1	HINGE LOWER LHF ,DOOR	NOT NECESSARY	90.10	-
1	CHECK ASSY ,FR DOOR	NOT NECESSARY	150.30	-
1	MIRROR ASSY LH	NOT NECESSARY	1,224.90	-
1	HINGE LOWER LHR DOOR	NOT NECESSARY	72.20	-
1	HINGE UPPER LHR ,DOOR	NOT NECESSARY	81.70	-
1	CHECK ASSY ,RR DOOR	NOT NECESSARY	150.30	-
1	TAPE OUT WIN FRAME LHR DOOR	NOT NECESSARY	32.30	-
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	WHEEL DISC ,FRONT	TO REPAIR SEE LABOUR	1,484.20	-
1	DOOR FRT/LH	TO REPAIR SEE LABOUR	894.40	-
1	DOOR OUTER HANDLE FRT/LH	TO REPAIR SEE LABOUR	370.80	-
1	COVER OUTER MIRROR LH	TO REPAIR SEE LABOUR	107.40	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
			8,801.90	1,505.53

Report Ref No. CC3/EQ19001484/Jpa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF WHEEL DISC ,FRONT,DOOR FRT/LH ,DOOR OUTER HANDLE FRT/LH ,COVER OUTER MIRROR LH ,FENDER RR/LH AND BUMPER FRT .		1,014.00	750.00
	SPRAY PAINT.		2,250.00	1,100.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	20.00
	TO TRANSFER DOOR MECHANISM.		240.00	50.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	40.00
	TO DO WHEEL ALIGNMENT /TYRE BALANCING.		120.00	60.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	120.00	-
			4,304.00	2,050.00
<b>GRAND TOTAL</b>			<b>13,105.90</b>	<b>3,555.53</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,555.53</b>

Report Ref No. CC3/EQ19001484/Jpa3q2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 708L

INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 708L

RE-INSPECTION

