

ASS. REC. BY:

REP: C93/12118022023 / Avel³⁻¹¹ Special Instruction

Surveyor Adrian ASSIGNMENT (Office)

From (Person): Bernard Lee of Ali Date/Time: 23012019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN 4704 X Insured: SIB 4470 Y

at Workshop m/s: V.Z. Automotiv Tel: 9174 5434

of 8 Kuki Bukit Ave 4 #D5-02

Policy No: 2100459919 Claim No: 0351541101SG-007

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 04-12-018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp H.O.D. Endorsement: _____

Date/Time: 07122018 939am Person Contacted: Merina Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJN 4704 X (R/P) 12021505 / 400305</u>
	<u>SIB 4470 Y</u>
	<u>Disassemble: 7/12/2018</u>
	<u>After repair: 13/12/2018</u>
<u>8/3/19</u>	<u>Submit LS \$ 7300, 12 days (Reel 3700, 34M)</u> <u>↓</u> <u>Informed Adrian</u>

RECEIVED 06 MAR 2019

VIN: SJN4709X - Page: 2009 Feb
 Type: Car / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer
 Make: Honda Civic Year: 1999
 Color: Black A/C: Insured / Std / NI / NA
 No. of Seats: 148406 T.R. Insured / Std / NI / NA
 Engine: _____
 O/M: JHMF016309S201545
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In Order / Jammed / Leaked / Burnt or
 Brake: In Order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F. 205/55R16
 R. 205/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front: _____ Rear: _____
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A. _____ D.O.I: 07/12/18
 Survey held at: V.Z.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision: _____
 CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT _____



Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$16K
 IDAC Accident Report Consistent? Yes or No
 GSA / RR / Sec Consistent? Yes or No
 Est. Repair: 8 days Res: Yes or No
 Loss Sett: Yes or No
 Date: _____ Time: _____ Action / Instruction: TP ALG PRS.

Pending COE Renewal.

Report Format: DAR
 Lump Sum / L.B / _____
 Add Fee: Side Ins. - \$
 Information - \$
 _____ - \$
 _____ - \$

Days Of Repair: 8
 Resurvey No. of Trip: 2
 Survey Fee: _____
 Transport: _____

Catherine Chong (LKK Auto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Wednesday, 23 January, 2019 9:40 AM
To: Admin A; Admin-D (LKKAuto)
Subject: Paper Adjustment for 0351541101SG-007
Attachments: 0351541101SG.PDF

Dear LKK,

Understand that PRS has been done for this case, appreciate if you could assist to conduct paper adjustment as well.

Thank you.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6528D
Vehicle Details	
Vehicle No.:	SJN4709X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	HONDA CIVIC 1.8L 5AT
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R18A14008905
Chassis No.:	JHMFD16309S201545
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$26,671.00
Original Registration Date:	17 Feb 2009
First Registration Date:	17 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$26,671.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$15,777.00
COE Rebate Amount:	\$15,183.00
Total Rebate Amount:	\$15,183.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Mar 2019

OK

Condition Codes

(0) Item (1) Deleted (2) Damaged (3) Corroded (4) Cut (5) Scratched
 (6) Perfected (8) Shilled (9) Ducked (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION IAC

(1) Replace (✓) (2) Repair (0) (3) Check (0)
 (4) Not Considered (NC)

Aug 2005

2 of 2

Vehicle No: SJN 4709X

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	05	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC	✓	
1147	992976	Rear Bumper Bracket	LH	✓	
1148	993068	Rear Bumper Side Retainer	LH	✓	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	TR	✓	
1159	993327	Rear End Panel	TR	✓	
1160	993339	Rear End Panel Top Garnish	TR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	TR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	CU	✓	
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber	BT	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

19/12/2008

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	BS	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1256	990247	Sticker			

Stew 18/12/18

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com,assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022023/ACBS2
Date: 26/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100459919
Claimant Vehicle No : SJN4709X **Insured Vehicle No :** SLB4470Y
 Date of Loss: 04/12/2018 Nature of Claim: TP Claim No: 0351541101SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN4709X**
 Make & Model: HONDA CIVIC, 1.8 L 5AT (A) Engine No: R18A14008905
 Reg. Date: 17/02/2009 (Man. Year: 2008) Chassis No: JHMFD16309S201545
 Colour: Black Odometer: 148406 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/12/2018
 Date Inspected: 07/12/2018 Inspected At: 8 Kaki Bukit Ave 4 #05-02
 Estimated Period of Repair: 8.0 days Repairer: V.Z. Automotive Pte Ltd

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*-F
2	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*-F
3	1		*FRT NUMBER PLATE GARNISH	Cracked	0.00 F	*-F
4	1		*FRT BUMPER	Crushed	0.00 F	*-F
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
6	1		*FRT BUMPER SIDE RETAINER LH	Broken	0.00 F	*-F
7	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*-F
8	1		*FRT GRILLE	Cracked	0.00 F	*-F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
10	1		*FRT SUPPORT PANEL	Repair	0.00 F	*-F
11	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Distorted	0.00 F	*-F
12	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*-F
13	1		*LH HEADLAMP LOWER BRACKET	Cracked	0.00 F	*-F
14	1		*REAR BUMPER	Dented	0.00 F	*-F
15	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
16	1		*REAR BUMPER BRACKET LH	Dented	0.00 F	*-F
17	1		*REAR BUMPER SIDE RETAINER LH	Broken	0.00 F	*-F
18	1		*REVERSE SENSOR	Broken	0.00 F	*-F
19	1		*REAR END PANEL	Dented	0.00 F	*-F
20	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*-F
21	1		*REAR RH TAILLAMP	Broken	0.00 F	*-F
22	1		*BOOTLID	Dented	0.00 F	*-F
23	3		*BOOTLID EMBLEM	Necessary	0.00 F	*-F
24	1		*BOOTLID LAMP LH	Cut	0.00 F	*-F
25	1		*BOOTLID LOCK	Bent	0.00 F	*-F
26	1		*BOOTLID RUBBER	Bent	0.00 F	*-F
27	1		*SPARE TYRE PANEL	Buckled	0.00 F	*-F
28	1		*REAR LH FENDER INNER TRIM	Torn	0.00 F	*-F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S YANTO ANG
C O V Z AUTOMOTIVE PTE LTD
Blk 1, Kaki Bukit 6, #02-02
SINGAPORE 417887

Date: 17 December 2018
Our Ref: WG TP 2018-422

REFERENCE PARTICULARS

Date of Accident : 04 December 2018
Date of Inspection : 05 December 2018

Type of Inspection : Third Party Claim
Date of Re-Inspr : 07 December 2018

VEHICLE PARTICULARS

Registration No : SJN4709X
Make : HONDA
Model : HONDA CIVIC 1.8L 5A1
Year : 2008

Engine No : R18A14008905
Chassis No : JHMFD16309S201545
Odometer : 148406km
Colour : Black

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size	Thread Balance
Front Near Side	Westlake	215 55R16	5mm
Front Off side	Westlake	215 55R16	5mm
Rear Near side	Westlake	215 55R16	5mm
Rear Off side	Westlake	215 55R16	5mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front and rear portion
For details, refer to assessment for repairs and photographs attached

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$11,000.00** nett at lump sum basis (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Fifteen (15) working days.

Enclosed Sixty-two (62) photographs depicting damage to the vehicle

Inspection conducted at : V.Z. AUTOMOTIVE PTE LTD
Blk 1, Kaki Bukit 6, #02-02, SINGAPORE 417887

In accordance to your instruction, we have **not authorise** repairs and inspection
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : SJN4709X
 MODEL : HONDA CIVIC 1.8L 5AT

Our Ref : WG/TP/2018-422

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

	QTY	ASSESSED	ORIGINAL	REVISED
SPARE PARTS	PC/SET	CONDITION	QUOTATION	QUOTATION
1 FRONT BUMPER	1	CRACKED	\$ 737.10	\$ 737.10 638
2 FRONT BUMPER RETAINER	2	NECESSARY	\$ 49.90	\$ 49.90
3 FRONT BUMPER REINFORCEMENT	1	DENTED	\$ 395.10	\$ 395.10 295
4 FRONT GRILLE	1	NECESSARY	\$ 259.94	\$ 259.94
5 FRONT LH HEADLAMP	1	CRACKED	\$ 1,182.90	\$ 1,182.90 912
6 FRONT LH HEADLAMP LOWER BRACKET	1	NECESSARY	\$ 44.52	\$ 44.52
7 FRONT LH FOG LAMP	1	NOT NECESSARY	\$ 290.50	\$ -
8 REAR BUMPER	1	DEFORMED	\$ 738.92	\$ 738.92 638
9 REAR BUMPER LOWER BRACKET	2	NECESSARY	\$ 47.40	\$ 47.40
10 REAR BUMPER SIDE RETAINER	2	NECESSARY	\$ 39.50	\$ 39.50
11 REAR END PANEL	1	DENTED	\$ 531.93	\$ 531.93
12 REAR END PANEL TOP GARNISH	1	DEFORMED	\$ 160.40	\$ 160.40
13 REAR LH TAILLAMP	1	CRACKED	\$ 326.50	\$ 326.50
14 REAR LH TAILLAMP PANEL	1	DENTED	\$ 165.70	\$ 165.70
15 REAR LH FENDER	1	DENTED	\$ 958.50	\$ 958.50
16 REAR LH FENDER INNER TRIM	1	TORN	\$ 195.63	\$ 195.63
17 REAR WINDSCREEN MOULDING	1	NECESSARY	\$ 96.00	\$ 96.00
18 BOOTLID	1	DENTED	\$ 710.70	\$ 710.70
19 BOOTLID WEATHERSTRIP	1	DEFORMED	\$ 115.04	\$ 115.04
20 BOOTLID EMBLEM LOGO	1	NECESSARY	\$ 45.00	\$ 45.00
21 BOOTLID EMBLEM - CIVIC	1	NECESSARY	\$ 41.00	\$ 41.00
22 BOOTLID EMBLEM - 1.8	1	NECESSARY	\$ 45.90	\$ 45.90
23 BOOTLID NUMBER PLATE LAMP	1	NOT NECESSARY	\$ 35.00	\$ -
24 BOOTLID GARNISH STRIP	1	NOT NECESSARY	\$ 121.90	\$ -
25 BOOTLID LAMP LH	1	CRACKED	\$ 245.90	\$ 245.90
26 BOOTLID LOCK	1	JAMMED	\$ 295.90	\$ 295.90 115
27 BOOTLID LOCK STRIKER	1	BENT	\$ 65.00	\$ 65.00
28 BOOTLID HINGE	2	BENT	\$ 110.50	\$ 110.50
29 BOOTLID STOPPER	2	NECESSARY	\$ 30.00	\$ 30.00
30 SPARE TYRE TOP BOARD	1	DEFORMED	\$ 397.80	\$ 397.80 316
31 SPARE TYRE COMPARTMENT PANEL	1	DENTED	\$ 1,421.40	\$ 1,421.40 952
			\$ 9,901.48	\$ 9,454.10
			\$ 1,980.29	\$ 1,890.82
			\$ 7,921.19	\$ 7,563.28

B) NET ITEM

32 REAR BUMPER CLIP	1 SET	NECESSARY	\$ 50.00	\$ 40.00
33 REAR FENDER INNER TRIM CLIP	1 SET	NECESSARY	\$ 30.00	\$ 20.00
34 WINDSCREEN SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00
35 JOINT SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00
36 REVERSE SENSOR	1 SET	MALFUNCTION	\$ 400.00	\$ 400.00 370
37 FLOOR INSULATOR	1	NECESSARY	\$ 150.00	\$ 130.00
38 REVERSE CAMERA	1	MALFUNCTION	\$ 500.00	\$ 400.00
39 FRONT BUMPER CLIP	1 SET	NECESSARY	\$ 40.00	\$ 20.00
40 FRONT GRILLE CLIP	1 SET	NECESSARY	\$ 30.00	\$ 20.00
			\$ 1,500.00	\$ 1,200.00

Parts Total :

\$ 9,421.19 \$ 8,763.28

C) LABOUR CHARGES & MIS

41 CHECK FRONT, REAR WIRING AND LIGHTNING SYSTEM			\$ 80.00	\$ 70.00
42 REMOVE AND REFIT REAR LINING, TRIM AND GARNISH			\$ 200.00	\$ 150
43 REMOVE AND REFIT REAR REVERSE SENSOR			\$ 100.00	\$ 50
44 REMOVE AND REFIT FUEL TANK			\$ 150.00	\$ 130.00
45 REMOVE AND RENEW FLOOR INSULATOR			\$ 150.00	\$ 60
46 REMOVE AND REFIT REAR BATTERY ASSY			\$ 500.00	\$ 400.00
47 REMOVE AND REFIT REAR WINDSCREEN			\$ 150.00	\$ 130.00
48 TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW			\$ 200.00	\$ 80
49 PANEL BEATING ON AFFECTED AREAS			\$ 2,400.00	\$ 1,500
50 SPRAY PAINTING ON AFFECTED AREAS			\$ 1,800.00	\$ 1,300
51 APPLY ANTI-RUST ON AFFECTED AREAS			\$ 200.00	\$ 100
			\$ 5,930.00	\$ 4,880.00

Labour Total :

\$ 5,930.00 \$ 4,880.00

Total Parts and Labour :

\$ 15,351.19 \$ 13,643.28

FINAL LUMP SUM ADJUSTMENT

\$ 11,000.00

total : 9021.58
 4/5 : 7.2k
 12 Days

POINT OF IMPACT

The impact was confined to the front and rear portion of the vehicle
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$11,000.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully,
WG APPRAISAL SERVICE


Winston Goh
Automotive Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18022023/Avd3s2-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 08-03-2019



ATTN: BERNARD LER

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 4470Y	Veh. Inspected	SJN 4709X
Policy No.	2100459919	Coverage (\$)	0.00
Claim No.	0351541101SG	Excess (\$)	0.00
Assign From	BERNARD LER	Assign Date	23/01/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JHMF16309S201545	Colour	BLACK
Odometer	148406	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	WEST LAKE	6 mm
L/H Front Tyre	205/55R16	WEST LAKE	6 mm
R/H Rear Tyre	205/55R16	WEST LAKE	6 mm
L/H Rear Tyre	205/55R16	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/12/2018	Inspection Date	07/12/2018
Survey held at	V.Z AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-02 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
--	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 4709X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CRACKED	737.10	638.00
2	FRONT BUMPER RETAINER	NECESSARY	49.90	49.90
1	FRONT BUMPER REINFORCEMENT	DENTED	395.10	295.00
1	FRONT GRILLE	NECESSARY	259.94	259.94
1	FRONT LH HEADLAMP	CRACKED	1,182.90	912.00
1	FRONT LH HEADLAMP LOWER BRACKET	NECESSARY	44.52	44.52
1	FRONT LH FOG LAMP	NOT NECESSARY	290.50	-
1	REAR BUMPER	DEFORMED	738.92	638.00
2	REAR BUMPER LOWER BRACKET	NOT NECESSARY	47.40	-
2	REAR BUMPER SIDE RETAINER	NECESSARY	39.50	39.50
1	REAR END PANEL	DENTED	531.93	531.93
1	REAR END PANEL TOP GARNISH	DEFORMED	160.40	160.40
1	REAR LH TAILLAMP	CRACKED	326.50	326.50
1	REAR LH TAILLAMP PANEL	TO REPAIR SEE LABOUR	165.70	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	958.50	-
1	REAR LH FENDER INNER TRIM	TORN	195.63	195.63
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	96.00	-
1	BOOTLID	DENTED	710.70	710.70
1	BOOTLID WEATHERSTRIP	DEFORMED	115.04	115.04
1	BOOTLID EMBLEM LOGO	NECESSARY	45.00	45.00
1	BOOTLID EMBLEM - CIVIC	NECESSARY	41.00	41.00
1	BOOTLID EMBLEM - 1.8	NECESSARY	45.90	45.90
1	BOOTLID NUMBER PLATE LAMP	NOT NECESSARY	35.00	-
1	BOOTLID GARNISH STRIP	NOT NECESSARY	121.90	-
1	BOOTLID LAMP LH	CRACKED	245.90	245.90
1	BOOTLID LOCK	JAMMED	295.90	115.00
1	BOOTLID LOCK STRIKER	NOT NECESSARY	65.00	-
2	BOOTLID HINGE	NOT NECESSARY	110.50	-
2	BOOTLID STOPPER	NOT NECESSARY	30.00	-

Report Ref No. CS3/AIG18022023/Avd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE TOP BOARD	DEFORMED	397.80	316.00
1	SPARE TYRE COMPARTMENT PANEL	DENTED	1,421.40	952.00
	LESS 20% DISCOUNT		-1,980.29	-1,335.56
			7,921.19	5,342.30
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	40.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	30.00	20.00
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	150.00	-
1	JOINT SEALANT (SN)	NECESSARY	150.00	60.00
1	SET REVERSE SENSOR (SN)	MALFUNCTION	400.00	200.00
1	FLOOR INSULATOR (SN)	NECESSARY	150.00	130.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	500.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	30.00	20.00
			1,500.00	500.00
	LABOUR			
	CHECK FRONT, REAR WIRING AND LIGHTING SYSTEM.		80.00	70.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		200.00	150.00
	REMOVE AND REFIT REAR REVERSE SENSOR.		100.00	50.00
	REMOVE AND REFIT FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE AND RENEW FLOOR INSULATOR.		150.00	60.00
	REMOVE AND REFIT REAR BATTERY ASSY.	NOT NECESSARY	500.00	-
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW.		200.00	80.00
	PANEL BEATING AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR LH TAILLAMP PANEL AND REAR LH FENDER.		2,400.00	1,500.00
	SPRAY PAINTING AFFECTED AREAS.		1,800.00	1,300.00
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	100.00
			5,930.00	3,310.00
GRAND TOTAL			15,351.19	9,152.30



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,300.00
---	--	--	----------

Report Ref No. CS3/AIG18022023/Avd3s2-1

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.