

Tanfer

REF: INC CS/INC19000503/71+13e2


ASSIGNMENT

WE 2019 Oct.

From: Date: 23/10/2019
Estimated Cost:
OL / IT / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SJT 6991B
at Workshop n/s Torque 5
of 8 Kaki Bukit Ave 4 #01-49
insured
Policy No.
Claims No.
Sum Insured: Excess:
(Client's Record)
Make of Veh:

Veh No: SJT 6991B Yr Regn: 2009 Oct.
Type: M/Lor / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: 1614 Caparo C/G 1998
Colour: B/ack A/C Insured / Std / NI / NA
Sp. Reading: 149062 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: KNAF 6521397294365
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$10,500
IDAC Accident Report: Consistent? Yes or No
GIA / PR Seen: Consistent? Yes or No
Est. Repairs: days Res: Yes or No
Lum Sum: % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: Person Contacted: Vehicle: IN / OUT

Tyre Size: F: 25/65R17 R:
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hunko
Front: 6 mm Rear: 6 mm
R/Bal: 6 mm L/Bal: 6 mm
D.O.A. 23/1/19 1208PM
Survey held at Torque 5
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
26/4/19 confirm repair limit of \$4000
20/11/19 1st DOZ 26/4/19, reopen ref only
REOPEN submit front & rear report. 1600, 2 days
Rear- 2400, 6 days
RECEIVED 23 APR 2019
25/11

Date/Time, File Pass to: 0314 Typist
Date/Time, File Return to:
Report Format: TP
Lump Sum / LBT: \$4000
Days Of Repair: 8
Resurvey No. of Trip:
Add Fee: Site Insp \$ Interview \$ Tech insp \$ Weekend \$
Survey Fee: Transportation: Photos: Other:
TOTAL

Denise Tay (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Monday, 16 September 2019 5:03 PM
To: 'Lim Serene (MT)'; SUR
Cc: assignments
Subject: FW: TP CASE FARMED OUT TO LKK ON 23/1/2019
Attachments: Survey+Report+(for+Tablet)+2019-4-29.pdf.pdf

Dear Serene,

Thank you for the email.

Dear Shiau Chan,

Kindly assist

FYNA Our Ref : CS/INC19001503/T1td3e2

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Serene (MT) [mailto:lim.serene@income.com.sg]
Sent: Monday, 16 September 2019 4:58 PM
To: assignments@lkkauto.com
Subject: FW: TP CASE FARMED OUT TO LKK ON 23/1/2019

Hi,

SJT6991B	SFN7776D	TORQUE 5 PTE LTD / Lucas 81316318	18-1-2019 / MT-1028659-001	11:00-1
----------	----------	--------------------------------------	----------------------------	---------

We refer to the above case.

We understood that there is no evidence that this is a three car chain collision, whereby our Insured> TP> Unknown vehicle.

Kindly assist to split out the Cost of Repair/Labour for the front and rear damages.

Thank you



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 6991B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,205.20	723.00
1	REAR BUMPER LOWER GARNISH	DEFORMED	415.80	249.48
1	REAR BUMPER RETAINER (LH)	NECESSARY	121.50	72.90
1	REAR BUMPER RETAINER (RH)	NECESSARY	121.50	72.90
1	REAR BUMPER SPONGE	DEFORMED	385.50	90.00
1	REAR BUMPER REINFORCEMENT	BENT	599.00	359.40
1	REAR BUMPER BRACKET (LH)	NECESSARY	198.00	118.80
1	REAR BUMPER BRACKET (RH)	NECESSARY	198.00	118.80
1	TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE LOCK (NPA)	NOT NECESSARY	-	-
1	TAILGATE LOCK GARNISH (NPA)	NOT NECESSARY	-	-
1	TAILGATE EMBLEM - KIA	NECESSARY	98.00	98.00
1	TAILGATE EMBLEM - CARENS	NECESSARY	98.00	98.00
1	TAILGATE EMBLEM - CVVT	NECESSARY	98.00	98.00
1	TAILGATE EMBLEM - 2.0	NECESSARY	98.00	98.00
1	TAILGATE EMBLEM - ELITE	NECESSARY	98.00	98.00
1	LICENSE LAMP GARNISH (NPA)	NOT NECESSARY	-	-
1	LICENSE LAMP (LH) (NPA)	NOT NECESSARY	-	-
1	LICENSE LAMP (RH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE LOCK SWICTH (NPA)	NOT NECESSARY	-	-
1	REAR WINDSCREEN (NPA)	NOT NECESSARY	-	-
1	REAR WINDSCREEN MOULDING (NPA)	NOT NECESSARY	-	-
1	TAILGATE INNER TRIM BOARD (NPA)	NOT NECESSARY	-	-
1	TAILGATE DAMPER (LH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE DAMPER (RH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE HINGE (LH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE HINGE (RH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE RUBBER BEADING (NPA)	NOT NECESSARY	-	-
1	TAILGATE WIPER MOTOR (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP (LH) (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP (RH) (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP GASKET (LH) (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP GASKET (RH) (NPA)	NOT NECESSARY	-	-

Report Ref No. CS/INC19001503/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL (NPA) <i>rear</i>	TO REPAIR SEE LABOUR	-	-
1	END PANEL TOP GARNISH (NPA) <i>rear</i>	NOT NECESSARY	-	-
1	FRONT BUMPER	DEFORMED	1,446.20	867.72
1	FRONT BUMPER LOWER GARNISH	CUT	590.00	354.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	420.00	252.00
1	RADIATOR GRILLE	CRACKED	638.00	382.80
1	RADIATOR GRILLE EMBLEM - LOGO	NECESSARY	140.00	84.00
1	FRONT BUMPER RETAINER (LH)	NECESSARY	102.00	61.20
1	FRONT BUMPER RETAINER (RH)	NECESSARY	102.00	61.20
1	FRONT BUMPER BRACKET (LH) (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER BRACKET (RH) (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER SPONGE	DEFORMED	120.00	120.00
1	FRONT BUMPER REINFORCEMENT	BENT	280.00	280.00
1	FOG LAMP GARNISH (LH) (NPA)	NOT NECESSARY	-	-
1	FOG LAMP GARNISH (RH) (NPA)	NOT NECESSARY	-	-
1	FOG LAMP (LH) (NPA)	NOT NECESSARY	-	-
1	FOG LAMP (RH) (NPA)	NOT NECESSARY	-	-
1	HEAD LAMP (LH) (NPA)	NOT NECESSARY	-	-
1	HEAD LAMP (RH) (NPA)	NOT NECESSARY	-	-
1	BONNET (NPA)	NOT NECESSARY	-	-
1	BONNET LOCK (NPA)	NOT NECESSARY	-	-
1	BONNET INSULATOR (NPA)	NOT NECESSARY	-	-
1	FRONT SUPPORT PANEL (NPA)	NOT NECESSARY	-	-
1	A/C CONDENSER (NPA)	NOT NECESSARY	-	-
1	RADIATOR (NPA)	NOT NECESSARY	-	-
1	REAR EXHAUST MUFFLER (NPA)	NOT NECESSARY	-	-
1	EXHAUST MID PIPE (NPA)	NOT NECESSARY	-	-
1	REAR EXHAUST HEAT SHIELD (NPA) <i>rear</i>	NOT NECESSARY	-	-
1	REAR FLOOR PANEL TOP BOARD (NPA) <i>rear</i>	NOT NECESSARY	-	-
1	FRT BUMPER UNDER COVER	CRACKED	128.30	128.30
1	FRT SUPPORT PANEL	TO REPAIR SEE LABOUR	687.50	-
	LESS 20% DISCOUNT		-	-977.30
			8,388.50	3,909.20

Report Ref No. CS/INC19001503/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	500.00	-
1	REAR NUMBER PLATE & CASING (SN)	NOT NECESSARY	45.00	-
1	SET REAR BUPMER CLIP (SN)	NECESSARY	45.00	30.00
1	SET TAILGATE INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	45.00	-
1	REAR WINDSCREEN TINTED (SN)	NECESSARY	180.00	180.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	DECAL (SN)	NOT NECESSARY	30.00	-
1	SET END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	30.00	-
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	30.00	-
1	END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET EXHAUST MOUNTING (SN)	NOT NECESSARY	160.00	-
1	FRONT NUMBER PLATE & CASING (SN) Fvt	CRACKED	45.00	45.00
1	SET FRONT BUMPER CLIP (SN) Fvt	NECESSARY	50.00	30.00
1	SET BONNET INSULATOR CLIP (SN) Fvt	NOT NECESSARY	45.00	-
1	ENGINE COOLANT (SN) Fvt	NOT NECESSARY	80.00	-
1	SET A/C CONDENSER O'RING (SN) Fvt	NOT NECESSARY	20.00	-
1	AUTO TRANSMISSION FLUID 1 LITRE (SN) Fvt	NOT NECESSARY	50.00	-
1	SUNDRIES (SN) Rear.	NECESSARY	50.00	20.00
			1,755.00	555.00
	LABOUR			
	TO R&R REAR BUMPER REVERSE SENSOR.		60.00	30.00
	TO CHECK WIRING & LIGHTING SYSTEM.		80.00	30.00
	TO PERFORM, ANTI RUST TREATMENT ON AFFECTED AREAS.		60.00	30.00
	TO SUPPLY UNDERCOATING / PUTTY ON PARTS REPLACED.		80.00	30.00
	TO R&R REAR WINDSCREEN.	NOT NECESSARY	220.00	-
	TO R&R REAR TRIMS, GARNISH & SEATS ASSY.		200.00	60.00
	TO R&R REAR EXHAUST ASSY.	NOT NECESSARY	250.00	-
	TO CONDUCT HEAD LAMP FOCUS.	NOT NECESSARY	60.00	-
	TO R&R A/C CONDENSER, RADIATOR ASSY. Fvt	NOT NECESSARY	300.00	-
	TO TOP UP 134A REFRIGERANT.	NOT NECESSARY	100.00	-
	TO REPAIR, REPLACE AND REALIGN DAMAGED AREAS. Fvt - 200		1,600.00	900.00
	INCLUSIVE OF THE REPAIR OF TAILGATE, END PANEL AND FRT SUPPORT PANEL. Rear - 700.			

Report Ref No. CS/INC19001503/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON AFFECTED AREAS. Frt - \$200		1,400.00	800.00
	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR. Rear - \$600		120.00	30.00
			4,530.00	1,910.00
GRAND TOTAL			14,673.50	6,374.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,000.00

Report Ref No. CS/INC19001503/T1td3e2

Frt - 02 days
Rear - 06 days

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC19001503/T1td3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date : 26-04-2019	
ATTN: SERENE LIM			Code : INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFN 7776D	Veh. Inspected	SJT 6991B	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT-1028659-001	Excess (\$)	0.00	
Assign From	DANIEL KOH	Assign Date	23/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA CARENS	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KNAFG521397294363	Colour	BLACK	
Odometer	149062	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R17	HANKOOK	6 mm	
L/H Front Tyre	205/65 R17	HANKOOK	6 mm	
R/H Rear Tyre	205/65 R17	HANKOOK	6 mm	
L/H Rear Tyre	205/65 R17	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/01/2019	Inspection Date	23/01/2019	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR (FRONT):		2 Working Days		
ESTIMATED NORMAL PERIOD FOR REPAIR (REAR):		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 6991B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,446.20	867.72
1	FRONT BUMPER LOWER GARNISH	CUT	590.00	354.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	420.00	252.00
1	RADIATOR GRILLE	CRACKED	638.00	382.80
1	RADIATOR GRILLE EMBLEM - LOGO	NECESSARY	140.00	84.00
1	FRONT BUMPER RETAINER (LH)	NECESSARY	102.00	61.20
1	FRONT BUMPER RETAINER (RH)	NECESSARY	102.00	61.20
1	FRONT BUMPER BRACKET (LH) (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER BRACKET (RH) (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER SPONGE	DEFORMED	120.00	120.00
1	FRONT BUMPER REINFORCEMENT	BENT	280.00	280.00
1	FOG LAMP GARNISH (LH) (NPA)	NOT NECESSARY	-	-
1	FOG LAMP GARNISH (RH) (NPA)	NOT NECESSARY	-	-
1	FOG LAMP (LH) (NPA)	NOT NECESSARY	-	-
1	FOG LAMP (RH) (NPA)	NOT NECESSARY	-	-
1	HEAD LAMP (LH) (NPA)	NOT NECESSARY	-	-
1	HEAD LAMP (RH) (NPA)	NOT NECESSARY	-	-
1	BONNET (NPA)	NOT NECESSARY	-	-
1	BONNET LOCK (NPA)	NOT NECESSARY	-	-
1	BONNET INSULATOR (NPA)	NOT NECESSARY	-	-
1	FRONT SUPPORT PANEL (NPA)	NOT NECESSARY	-	-
1	A/C CONDENSER (NPA)	NOT NECESSARY	-	-
1	RADIATOR (NPA)	NOT NECESSARY	-	-
1	REAR EXHAUST MUFFLER (NPA)	NOT NECESSARY	-	-
1	EXHAUST MID PIPE (NPA)	NOT NECESSARY	-	-
1	FRT BUMPER UNDER COVER	CRACKED	128.30	128.30
1	FRT SUPPORT PANEL	TO REPAIR SEE LABOUR	687.50	-
	LESS 20% DISCOUNT		-	-518.24
			4,654.00	2,072.98

Report Ref No. CS/INC19001503/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE & CASING (SN)	CRACKED	45.00	45.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	45.00	-
1	ENGINE COOLANT (SN)	NOT NECESSARY	80.00	-
1	SET A/C CONDENSER O'RING (SN)	NOT NECESSARY	20.00	-
1	AUTO TRANSMISSION FLUID 1 LITRE (SN)	NOT NECESSARY	50.00	-
			290.00	75.00
	<u>LABOUR</u>			
	TO CONDUCT HEAD LAMP FOCUS.	NOT NECESSARY	60.00	-
	TO R&R A/C CONDENSER, RADIATOR ASSY.	NOT NECESSARY	300.00	-
	TO TOP UP 134A REFRIGERANT.	NOT NECESSARY	100.00	-
	TO REPAIR, REPLACE AND REALIGN DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF FRT SUPPORT PANEL.		800.00	200.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		700.00	200.00
			1,960.00	400.00
	GRAND TOTAL		6,904.00	2,547.98
	RECOMMENDED COST OF LUMP SUM REPAIRS (FRONT PORTION) (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,600.00

Report Ref No. CS/INC19001503/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this R



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 6991B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF REAR PARTS				
1	REAR BUMPER	DEFORMED	1,205.20	723.00
1	REAR BUMPER LOWER GARNISH	DEFORMED	415.80	249.48
1	REAR BUMPER RETAINER (LH)	NECESSARY	121.50	72.90
1	REAR BUMPER RETAINER (RH)	NECESSARY	121.50	72.90
1	REAR BUMPER SPONGE	DEFORMED	385.50	90.00
1	REAR BUMPER REINFORCEMENT	BENT	599.00	359.40
1	REAR BUMPER BRACKET (LH)	NECESSARY	198.00	118.80
1	REAR BUMPER BRACKET (RH)	NECESSARY	198.00	118.80
1	TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE LOCK (NPA)	NOT NECESSARY	-	-
1	TAILGATE LOCK GARNISH (NPA)	NOT NECESSARY	-	-
1	TAILGATE EMBLEM - KIA	NECESSARY	98.00	98.00
1	TAILGATE EMBLEM - CARENS	NECESSARY	98.00	98.00
1	TAILGATE EMBLEM - CVVT	NECESSARY	98.00	98.00
1	TAILGATE EMBLEM - 2.0	NECESSARY	98.00	98.00
1	TAILGATE EMBLEM - ELITE	NECESSARY	98.00	98.00
1	LICENSE LAMP GARNISH (NPA)	NOT NECESSARY	-	-
1	LICENSE LAMP (LH) (NPA)	NOT NECESSARY	-	-
1	LICENSE LAMP (RH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE LOCK SWICTH (NPA)	NOT NECESSARY	-	-
1	REAR WINDSCREEN (NPA)	NOT NECESSARY	-	-
1	REAR WINDSCREEN MOULDING (NPA)	NOT NECESSARY	-	-
1	TAILGATE INNER TRIM BOARD (NPA)	NOT NECESSARY	-	-
1	TAILGATE DAMPER (LH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE DAMPER (RH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE HINGE (LH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE HINGE (RH) (NPA)	NOT NECESSARY	-	-
1	TAILGATE RUBBER BEADING (NPA)	NOT NECESSARY	-	-
1	TAILGATE WIPER MOTOR (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP (LH) (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP (RH) (NPA)	NOT NECESSARY	-	-

Report Ref No. CS/INC19001503/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP GASKET (LH) (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP GASKET (RH) (NPA)	NOT NECESSARY	-	-
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	END PANEL TOP GARNISH (NPA)	NOT NECESSARY	-	-
1	REAR EXHAUST HEAT SHIELD (NPA)	NOT NECESSARY	-	-
1	REAR FLOOR PANEL TOP BOARD (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-	-459.06
			3,734.50	1,836.22
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	500.00	-
1	REAR NUMBER PLATE & CASING (SN)	NOT NECESSARY	45.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	SET TAILGATE INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	45.00	-
1	REAR WINDSCREEN TINTED (SN)	NECESSARY	180.00	180.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	DECAL (SN)	NOT NECESSARY	30.00	-
1	SET END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	30.00	-
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	30.00	-
1	END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET EXHAUST MOUNTING (SN)	NOT NECESSARY	160.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			1,465.00	480.00
	<u>LABOUR</u>			
	TO R&R REAR BUMPER REVERSE SENSOR.		60.00	30.00
	TO CHECK WIRING & LIGHTING SYSTEM.		80.00	30.00
	TO PERFORM, ANTI RUST TREATMENT ON AFFECTED AREAS.		60.00	30.00
	TO SUPPLY UNDERCOATING / PUTTY ON PARTS REPLACED.		80.00	30.00
	TO R&R REAR WINDSCREEN.	NOT NECESSARY	220.00	-
	TO R&R REAR TRIMS, GARNISH & SEATS ASSY.		200.00	60.00
	TO R&R REAR EXHAUST ASSY.	NOT NECESSARY	250.00	-

Report Ref No. CS/INC19001503/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR.		120.00	30.00
	TO REPAIR, REPLACE AND REALIGN DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF TAILGATE AND END PANEL.		800.00	700.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		700.00	600.00
			2,570.00	1,510.00
GRAND TOTAL			7,769.50	3,826.22
RECOMMENDED COST OF LUMP SUM REPAIRS (REAR PORTION) (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,400.00

Report Ref No. CS/INC19001503/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this R