12/13/21, 12:33 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG19001522/KEA3Q2

Date:

13/12/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100510550

Claimant Vehicle No :

SHC5216B 18/01/2019 Insured Vehicle No:
Nature of Claim:

SLM6166E TP

Claim No:

0524238982SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5216B

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C000701

Reg. Date: 19/02/2014 (Man. Year: 2013)

Odometer:

Chassis No:

VF1ABL15AUC276169 754819 km

Colour: Metallic White/Red

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Fo

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engi

Engine Modification:

No

Pre-accident Condition:

165

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size: Rear Left Side: 215/60 R16 Sailun 8 mm

Front Left Side: Front Right Side:

Sailun 8 mm Sailun 8 mm

Rear Right Side:

Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,694.89	0.00	9,694.89	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		8,250.00	300.00	7,950.00	96.36
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	17,944.89	300.00	17,644.89	98.33
	+ GST 7.00/7.00% (S\$)	1,256.14	21.00	1,235.14	98.33

Nett Amount (S\$)	19,201.03	321.00	18,880.03	98.33
+ Car Rental (3.0 x S\$83.46/day) (S\$)		250.38		
	+ Doc/Search Fee (S\$)	7.49		
	Nett Liability (S\$)	578.87		
Global Sum Settlement (S\$)		570.00		

INSPECTION

Date of Assignment: 22/01/2019

Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111 Date Inspected: 22/01/2019 Inspected At:

Estimated Period of Repair: 1.0 days

KENNETH KONG Adjuster: Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*-FL
2 1	*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
3 1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
1	*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
5 1	*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
3 1	*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
7 1	*BUMPER COVER REAR	Repair	1,108.46 FL	*- FL
3 1	*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
9 1	*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
10 1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
1 1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
12 1	*REAR TAILLAMP RH	Serviceable	552.55 FL	*- FL
13 1	*SET PARKING AID	Serviceable	700.00 FS	*-FS
14 1	*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*-FS
15 1	*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*-FS
16 1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
17 1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
18 1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
9 1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
20 1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
21 1	*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*-FS
=Franchise part. S=SpcNett.	L=ListItemDisc.			
		Sub Total (S\$)	10,666.88	0.00
		- List Item Discount on L Items 10.00/10.00% (S\$)	971.99	0.00
		Total Parts (S\$)	9,694.89	0.00
	Report was	s unsubmitted during this print-out.		

12/13/21, 12:33 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARADJUST AND REALIGN THE SAME	TS New	3,000.00	80.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
8	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
10	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
	Gi	ross Labour Cost (S\$)	8,250.00	300.00
		-		

Report was unsubmitted during this print-out.

< END OF ESTIMATES >