

REPAIR ESTIMATE*

VEHICLE NO : SHA7534E

DATE 22/1/2019 16:47

MAKE :

MODEL : HYUNDAI i40

L/Sun
AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 544.50
	Front Bumper Bracket Top (LH) <i>con</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>con</i>			\$ 24.60
	<i>Front Fender (LH) x repair</i>			
	SUB TOTAL			\$ 591.50
	LESS 20%			\$ 118.30
	DISCOUNTED TOTAL			\$ 473.20
	Labour Charge			
	Panel Beating			\$ 400.00 <i>200</i>
	Spray Painting Charge			\$ 400.00 <i>500.00</i>
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,050.00
	ESTIMATE TOTAL			\$ 1,523.20
<i>Kahir (LKS)</i> <i>23/1/19 1620hr</i> <i>2 hrs</i> <i>U/s</i> <i>After Repair p.d.</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				