




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19001537/R1ps3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date : 06-08-2020	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKF 228Z	Veh. Inspected	SJJ 4613J	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M01BKD	Excess (\$)	0.00	
Assign From		Assign Date	27/02/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA CARENS 1.7 A	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KNAHU815VJ7208648	Colour	GREY	
Odometer	10793	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	215/50 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/50 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/50 R17	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/01/2019	Inspection Date	27/02/2019	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		