

22/03/2002

ASS. REC. BY:

REF:

08/FCI19001541/Asd3

N2

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

CWS

Karen Tan

of

FCI

Date/Time:

307pm @ 23/1/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 3875S

Insured:

SHA 4396G.

at Workshop m/s

Kang Car Repairs

Tel:

67477636

of

1 Kalei Bukit Ave G # 02-06

Policy No:

Claim No:

D19000616 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A:

21/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

IDS

H.O.D. Endorsement:

Date/Time:

4:17pm @ 23/1/19

Person Contacted:

sharon

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKS 3875S - CCB / AIG / 18008635 / Ahg3s2

DOR: 4/5/2018

SHA 4396G - CCB / CIL / 18002006 / klhg3n2

DOR: 31/1/18

24/1/19

Informed for pending workshop est by email

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____

Veh No: SKS 381SS Yr Regn: 2015 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios c.c. 1497

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 80723 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHFBT9F3006028307

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 23/01/19.

Survey held at Kang.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Des. O/S.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPM Corp.
30/01/19	Confirmed L/S \$ 2,100/- @ 5 days with Adrian. (\$ 2,779.87 Red - 57%)
	Resurvey NO. of Tap: 1
	MV:
	PV:
	Nett:

RECEIVED 31 JAN 2019

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1) 3/01/19 Typ: st	2)	IN OUT	Basic & Add.	135
3)	4)		S + RS, SI	50
5)	6)		Photos	50
Preli. Report:			Others	20
Final Report: 45 \$ 2,100/-			TOTAL	255

MOTOR SURVEY ASSIGNMENT

Date	22-01-2019	Our Ref No. D19000616MFSH
Accident Date	21-01-2019	Claim Type. Third Party
Insured Vehicle	SHA4396G	Third Party Vehicle. SKS3875S
Survey Location	1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT	
Contact Person.	SHARON	
Contact No.	67477636/ 0	Fax No. 67485071
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KANG CAR REPAIRERS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 24 January 2019 9:39 AM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000616MFSH/1, SKS 3875S

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKS 3875S on 23/1/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 23 January 2019 4:37 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000616MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 23 January 2019 3:07 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000616MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1882C
Vehicle Details	
Vehicle No.:	SK538755
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J GRADE MT
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1NZZ095187
Chassis No.:	MHFBT9F3006028307
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,288.00
Original Registration Date:	13 Apr 2015
First Registration Date:	13 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$9,288.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2025
PARF Rebate Amount:	\$6,966.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,900.00
COE Rebate Amount:	\$40,238.00
Total Rebate Amount:	\$47,204.00

The information contained herein is correct as at 31 Jan 2019

OK

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 21/01/2019
TP Veh Reg No: SHA4396G

Estimate No: EST1900025
Date: 22 Jan 2019

Veh Reg No: SKS3875S
Make/Model: TOYOTA VIOSJGRADEMT
Chasis No: MHFBT9F3006028307
Reg. Date: 13/04/2015
Your Ref No: SHA4396G

Shirley.

Estimate Repair Cost to Vehicle No :SKS3875S

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC REAR BUMPER <i>reband</i>	482.70 ✓	
2	1 PC REAR BUMPER SIDE RETAINER RH <i>3 pc</i>	113.90 ✓	
3	1 PC REAR BUMPER RETAINER (SMALL) RH	36.70 ✓	
4	1 PC REAR BUMPER REFLECTOR - RH <i>let</i>	179.80 ✓	
5	1 PC REAR BUMPER MUDFLAP RH <i>not den</i>	67.40 ✓	
6	1 PC REAR FENDER RH <i>eye</i>	872.10 ✓	
7	1 PC TAIL LAMP - RH <i>cracked</i>	367.20 ✓	
		2,119.80	
	Less 25%	529.95	1,589.87
	Special Net		
8	2 PCS "L" PLATE BRACKET <i>den</i>	70.00 ✓	
9	1 SET REAR BUMPER CLIPS <i>pc</i>	60.00 30 ✓	
10	1 PC REAR FENDER STICKER <i>3 pc</i>	195.00 ✓	
11	1 SET REAR BUMPER STICKER <i>3 pc</i>	195.00 ✓	
12	1 PC REAR WINDSCREEN SEALANT <i>3 pc</i>	60.00 ✓	
13	1 PC REAR WINDSCREEN RUBBER	60.00 ✓	
		640.00	640.00
	Labour		
14	1 TO CHECK WIRING	50.00 30 ✓	
15	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	
16	1 TO REMOVE AND REFIT SEAT CUSHION & TRIM	180.00 50 ✓	
17	1 TO SPRAY UNDERSEAL	100.00 ✓	
18	1 (REAR) TO SPRAY PAINTING	1,000.00 600 ✓	
19	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 600 ✓	
		2,650.00	2,650.00

1180.3

885.22

490

1280

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 21/01/2019
TP Veh Reg No: SHA4396G

Estimate No: EST1900025
Date: 22 Jan 2019

Veh Reg No: SKS3875S
Make/Model: TOYOTA
VIOSJGRADEMT
Chasis No: MHFBT9F3006028307
Reg. Date: 13/04/2015
Your Ref No: SHA4396G

Estimate Repair Cost to Vehicle No :SKS3875S

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	Total		SS 4,879.87 85
	Add GST @ 7%		341.59
	Total Amount Payable		<u>SS 5,221.46</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND TWO HUNDRED TWENTY ONE AND CENTS FORTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj total: 2655.22
L/S 23/01/19. A/S: 2.1K
05 Rys



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19001541/Asd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4396G	Veh. Inspected	SKS 3875S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000616MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	23/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MHFBT9F3006028307	Colour	SILVER	
Odometer	80723	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DUNLOP	6 mm	
L/H Front Tyre	185/60 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/60 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/60 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/01/2019	Inspection Date	23/01/2019	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 3875S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	482.70	482.70
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	113.90	113.90
1	REAR BUMPER RETAINER (SMALL) RH	NECESSARY	36.70	36.70
1	REAR BUMPER REFLECTOR-RH	CUT	179.80	179.80
1	REAR BUMPER MUDFLAP RH	NOT NECESSARY	67.40	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	872.10	-
1	TAIL LAMP-RH	CRACKED	367.20	367.20
	LESS 25% DISCOUNT		-529.95	-295.08
			1,589.85	885.22
<u>SPECIAL NETT ITEMS</u>				
2	"L" PLATE BRACKET (SN)	NECESSARY	70.00	70.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR FENDER STICKER (SN)	NECESSARY	195.00	195.00
1	SET REAR BUMPER STICKER (SN)	NECESSARY	195.00	195.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR WINDSCREEN RUBBER (SN)	NOT NECESSARY	60.00	-
			640.00	490.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT SEAT CUSHION & TRIM.		180.00	50.00
	TO SPRAY UNDERSEAL.	NOT NECESSARY	100.00	-
	(REAR) TO SPRAY PAINTING.		1,000.00	600.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS,AND FOR CUTTING/WELDING WORKS.INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,200.00	600.00
			2,650.00	1,280.00
GRAND TOTAL			4,879.85	2,655.22



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	----------

Report Ref No. CS/FCI19001541/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.