



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2010 BMW 740 LI (SJM7733K)
Date of Loss	19 January 2019
Time of Loss	22.00
Loss Description	SJM7733K (INSD) > SHC6648G (TP) > SHC5005T > SHD6661L
Comment	

Workshop Details

Total Rebate Amount	48446
Nett Loss Amount	\$20,554.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJM7733K

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

30/07/2010



Mileage

155875

Age of Vehicle

8

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2010

2010

Make

BMW

B.M.W.

Model

740 LI

740LI 3.0L A/T A

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

CHUA TIONG KEE

Date of Birth

15 August 1971

dd/mm/yy



Age

48

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	WBAKB42040CY83247	WBAKB42040CY
Engine No	09427456N54B30A	09427456N54B30A
Engine Capacity		2979
Sum Insured	0	0
Market Value	0	69000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	27	
Driver License #		
License Type		
License Issue Date		dd/mm/yy 
License Expiration Date		dd/mm/yy 
Address	BLK 33 MARSILING DRIVE, #05-363, 730033, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S7173600H	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

24/01/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

275/40R19

Rear Tyre Size

275/40R19

Front left side

PIRELLI6mm

Rear left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear right side

PIRELLI6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMARKS
☐		0	1		BONNET (WCP) (10%)	Bent	0	3190	No		0			3190	Reviewing	
☐		0	1		BONNET LOCK - 2PCS (WCP) (10%)	Bent	0	209	No		0			209	Reviewing	
☐		0	1		BONNET LOCK CATCH - 2PCS (WCP) (10%)	Bent	0	88	No		0			88	Reviewing	
☐		0	1		BONNET CENTER LOCK CATCH	Serviceable	0	0	No		0			0	Deny	
☐		0	1		BONNET INSULATION (WCP) (10%)	Necessary	0	330	No		0			330	Reviewing	
☐		0	25		BONNET INSULATOR CLIPS (WCP) (10%)	Necessary	0	5.5	No		0			137.5	Reviewing	
☐		0	1		BONNET RUBBERSTRIP (WCP) (10%)	Necessary	0	55	No		0			55	Reviewing	
☐		0	1		BONNET CENTER RUBBERSTRIP (WCP) (10%)	Necessary	0	49.5	No		0			49.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMARKS
		0	2		BONNET HINGES (LH&RH)	Serviceable	0	0	No		0			0	Deny	
		0	1		FRONT BUMPER (WCP) (10%)	Damaged	0	1650	No		0			1650	Reviewing	
		0	10		FRONT BUMPER CLIPS (WCP) (10%)	Necessary	0	5.5	No		0			55	Reviewing	
		0	2		FRONT BUMPER CHROME MOULDING LH & RH (WCP) (10%)	Cracked	0	52.8	No		0			105.6	Reviewing	
		0	1		FRONT BUMPER LOWER GRILLE LH	Serviceable	0	0	No		0			0	Deny	
		0	1		FRONT BUMPER LOWER GRILLE RH (WCP) (10%)	Deformed	0	38.5	No		0			38.5	Reviewing	
		0	1		FRONT BUMPER CENTER GRILLE (WCP) (10%)	Missing	0	74.8	No		0			74.8	Reviewing	
		0	1		FRONT BUMPER INNER SPONGE (WCP) (10%)	Cracked	0	77	No		0			77	Reviewing	
		0	1		FRONT BUMPER REINFORCEMENT (WCP) (10%)	Bent	0	880	No		0			880	Reviewing	
		0	2		FRONT BUMPER BRACKET (WCP) (10%)	Necessary	0	16.5	No		0			33	Reviewing	
		0	2		FRONT BUMPER INNER V-BAR (WCP) (10%)	Bent	0	24.2	No		0			48.4	Reviewing	
		0	1		HEADLAMP NOZZLE LH	Serviceable	0	0	No		0			0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REN
		0	1		HEADLAMP NOZZLE RH (WCP) (10%)	Cracked	0	198	No		0			198	Reviewing	
		0	1		HEADLAMP NOZZLE COVER LH	Serviceable	0	0	No		0			0	Deny	
		0	1		HEADLAMP NOZZLE COVER RH (WCP) (10%)	Deformed	0	55	No		0			55	Reviewing	
		0	1		HEADLAMP NOZZLE HOSE (WCP) (10%)	Cut	0	52.8	No		0			52.8	Reviewing	
		0	2		HEADLAMP TOP RUBBER (LH&RH)	Serviceable	0	0	No		0			0	Deny	
		0	1		HEADLAMP LH (HID) (WCP) (10%)	Cracked	0	3080	No		0			3080	Reviewing	
		0	1		HEADLAMP RH (HID) (WCP) (10%)	Broken	0	3080	No		0			3080	Reviewing	
		0	1		HEADLAMP RH BALLAST (WCP) (10%)	Broken	0	880	No		0			880	Reviewing	
		0	1		HEADLAMP RH BULB - 2PCS (WCP) (10%)	Cracked	0	418	No		0			418	Reviewing	
		0	1		HEADLAMP PANEL RH	Repair	0	0	No		0			0	Deny	
		0	2		FRONT GRILLE (LH&RH) (WCP) (10%)	Cracked	0	192.5	No		0			385	Reviewing	
		0	1		FRONT GRILLE INNER BRACKET (WCP) (10%)	Cracked	0	264	No		0			264	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMARKS
		0	4		SUPPORT PANEL (WCP) (10%)	Buckled	0	173.25	No		0			693	Reviewing	
		0	1		FOG LAMP RH (WCP) (10%)	Cracked	0	297	No		0			297	Reviewing	
		0	1		FRONT SPLASH SHIELD LH	Serviceable	0	0	No		0			0	Deny	
		0	1		FRONT SPLASH SHIELD RH (WCP) (10%)	Damaged	0	363	No		0			363	Reviewing	
		0	10		FRONT SPLASH SHIELD CLIPS - 20PCS (WCP) (10%)	Necessary	0	5.5	No		0			55	Reviewing	
		0	1		OIL COOLER RH (WCP) (10%)	Dented	0	814	No		0			814	Reviewing	
		0	1		BRAKE AIR DUCT RH (WCP) (10%)	Cracked	0	71.5	No		0			71.5	Reviewing	
		0	1		FRONT FENDER RH (WCP) (10%)	Buckled	0	1353	No		0			1353	Reviewing	
		0	1		FRONT FENDER LH	Repair	0	0	No		0			0	Deny	
		0	1		FRONT FENDER UPPER GARNISH LH	Serviceable	0	0	No		0			0	Deny	
		0	1		FRONT FENDER UPPER GARNISH RH (WCP) (10%)	Damaged	0	165	No		0			165	Reviewing	
		0	10		FRONT FENDER UPPER GARNISH CLIPS LH	Serviceable	0	0	No		0			0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMARKS
		0	10		FRONT FENDER UPPER GARNISH CLIPS RH (WCP) (10%)	Necessary	0	5.5	No		0			55	Reviewing	
		0	1		AIRCON SUCTION PIPE (WCP) (10%)	Bent	0	385	No		0			385	Reviewing	
		0	1		AIRCON PRESSURE PIPE (WCP) (10%)	Bent	0	341	No		0			341	Reviewing	
		0	1		AIRCON DISCHARGE PIPE (WCP) (10%)	Bent	0	341	No		0			341	Reviewing	
		0	1		ENGINE UNDER COVER (WCP) (10%)	Cut	0	220	No		0			220	Reviewing	
		0	20		ENGINE UNDER COVER CLIPS (WCP) (10%)	Necessary	0	5.5	No		0			110	Reviewing	
		0	1		CHASSIS MEMBER RH	Repair	0	0	No		0			0	Deny	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMARKS
		0		LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO STRAIGHTEN & REPAIRS RH HEADLAMP PANEL, FRONT LH & RH FENDER AND FRONT SUPPORT PANEL; TO REMOVE & REPLACE FRONT DAMAGED PARTS AS LISTED ABOVE	0	1600	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REN
 	0		TO SPRAY PAINTING ON : BONNET (INNER, OUTER), FRONT BUMPER, FRONT SUPPORT PANEL AND FRONT BOTH FENDER, FRONT RH DOOR	0	1500	0	0	Reviewing		
 	0		TO REMOVE & INSTALL A/C CONDENSER, A/C PIPINGS & FITTINGS TO ENABLE REPAIRS; TO VACUUM & CHARGES UP GAS	0	120	0	0	Reviewing		
 	0		TO REMOVE & INSTALL RADIATOR & HOSES & ELECTRICAL FANS TO ENABLE REPAIRS; INCLUDING PRESSURIZE COOLING	0	80	0	0	Reviewing		
 	0		TO REMOVE & REPLACE HEADLAMP, CHECK LIGHTING & FOCUS HEADLIGHTS	0	50	0	0	Reviewing		
 	0		TO DRILL 7 PCS SENSORS HOLES AND REPLACE SENSORS	0	60	0	0	Reviewing		
 	0		TO REMOVE & REPLACE HEADLAMP WIPER JET C/W MOTOR, RE-ALIGN & TEST FUNCTION	0	0	0	0	Deny		
 	0		TO CARRY OUT E.C.U CHECK, REMOVE & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS	0	150	0	0	Reviewing		
 	0		LABOUR CHARGE FOR TOP UP ENGINE COOLANT					Deny		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 12 DAYS	Reviewing		0		
	0	FRONT BUMPER DISTANCE SENSOR - 7PCS	Reviewing		460	NOT WORKING - 2PCS ONLY	
	0	FRONT BUMPER DISTANCE SENSOR HOLDER- 7PCS	Reviewing		420	NECESSARY	

EDIT		SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	FRONT BUMPER DISTANCE SENSOR SEAL- 7PCS	Reviewing		42	NECESSARY	
		0	SET FRONT NUMBER PLATE WITH HOLDER	Reviewing		50	CRACKED	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$25,229.60

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$20,697.60

Labour

\$0.00

\$3,560.00

Miscellaneous

\$0.00

\$972.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

20000





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$20,000.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$20,000.00

[Submit for Review](#)