

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

03/08/09.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SLW974BYr Regn: 2009Augst.Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lancerc.c. 1998Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 111365

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSTCY4A84002410Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 21/01/19.Survey held at RHT.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Cont Pac

LI \$ 4900 (Reel \$ 9576 / 66%)MV: 151KPV: 9.3KNett: 5.7K

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

**Cheap Car Insurance Renewal**

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

► **SEARCH** Price Range Depreciation 2010 Vehicle Type

► Used Car Comparison

--- Comparing 3 Vehicles ---

Mitsubishi Lancer EX 2.0A GLS



Clear All

[Back to search result](#)

Mitsubishi Lancer EX 1.5A Sports



Mitsubishi Lancer EX 1.5A Sports



NO IMAGE AV

Use search bar above to search to compare.

CAR DETAILS

Price	\$17,800	\$20,800	\$19,000	-
Instalment	\$1,164	\$1,249	\$1,242	-
Registration Date	29-Dec-2009	29-Jan-2010	07-Jan-2010	-
Manufactured	2009	2009	2009	-
Mileage	-	-	150,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,998 cc	1,499 cc	1,499 cc	-
Road Tax	\$1,210 /yr	\$684 /yr	\$684 /yr	-
Power	114.0 kW (152 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)	-
Curb Weight	1,427 kg	1,313 kg	1,313 kg	-
Features	-	Smooth, Powerful, Responsive 1.5 16 Valves DOHC MIVEC Engine With 107BHP, Dual SRS Airbags, Climatic Aircon, 4 Speed Auto Transmission, ABS.	1.5L 16 Valves DOHC Engine, Dual SRS Airbags, ABS, Auto Climatic Aircon, 4 Speed Auto Transmissions.	-
Accessories	-	16" Sport Rims, Original Leather Seats, Factory Audio System, Multi Function Steering Wheel Control, Knockdown Seats, Auto Retractable Mirrors.	Sports Rims, Leather Seats, Factory Fitted Audio System, Retractable Side Mirrors With Indicators, Solar Film.	-
Description	S Pass, EP Or LTV Pass Welcome To Loan! In-House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Viewing And Test Drive Available Daily From 10.30 A.M. To 6.30 P.M.! All Our Vehicles Has Undergone A 120 Points Check By Our In-House Workshop!	Don't Miss Out Best Unit In Town! Original Condition Since Day 1 And Fully Maintain By Agent C&C With One Lady Owner. Low Maintenance And Reliable Sedan, Ample Boot Space. Loan Application Available! Wait No More And Call Now To Make An Appointment Today!	Balloon Scheme Available. Regular Servicing. Well Maintained.	-
COE	\$20,200	\$20,501	\$15,792	-
OMV	\$21,096	\$18,868	\$19,039	-
ARF	\$21,096	\$18,868	\$19,039	-
Depreciation	\$7,790 /yr	\$11,180 /yr	\$9,910 /yr	-
No. of Owners	2	1	3	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car, Premium Ad Car	PARF Car	PARF Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 4540N

Vehicle Details

Vehicle No.: SLW974B
Vehicle to be Exported: No
Intended Deregistration Date: 21 Jan 2019
Vehicle Make: MITSUBISHI
Vehicle Model: LANCER 2.0L MIVEC GLS
6-CVT

Primary Colour: Blue
Manufacturing Year: 2007
Engine No.: 4B11BA0114
Chassis No.: JMYSTCY4A8U002410
Maximum Power Output: 114.0 kW (152 bhp)
Open Market Value: \$16,903.00
Original Registration Date: 03 Aug 2009
First Registration Date: 03 Aug 2009
Transfer Count: 1
Actual ARF Paid: \$16,903.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Aug 2019
PARF Rebate Amount: \$8,451.00

Intended COE Rebate Details

COE Expiry Date: 02 Aug 2019
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$16,801.00
COE Rebate Amount: \$894.00

Total Rebate Amount: \$9,345.00

The information contained herein is correct as at 21 Jan 2019

OK



Adrian Loo
新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

22/01/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Con Pac.

Xiao Tony

Accident date: 21/01/2019

Estimated repair cost for vehicle no: SLW974B MITSUBISHI LANCER 2.0 A '09

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Rehanded</i>		\$758.00 ✓
2	10	Front Bumper Clip <i>re</i>	\$6.50	\$65.00 30
3	1	Front L/H Bumper Side Retainer <i>re</i>		\$38.00 ✓
4	1	Front L/H Head Lamp <i>cracked</i>		\$652.00 ✓
5	1	Front L/H Head Lamp Lower Bracket <i>re</i>		\$23.00 +
6	1	Front L/H Fender <i>Dented</i>		\$486.00 ✓
7	1	Front L/H Fender Signal Lamp <i>re</i>		\$68.00 +
8	1	Front L/H Fender Cowling <i>Rehanded</i>		\$107.00 ✓
9	8	Front L/H Fender Cowling Clip <i>re</i>	\$6.50	\$52.00 30
10	1	Front L/H Door <i>Dented</i>		\$1,065.00 ✓
11	2	Front L/H Door Frame Sticker <i>re</i>	\$36.00	\$72.00 ✓
12	1	Front L/H Rim <i>lt</i>		\$680.00 450(w)
13	1	Front L/H Tyre <i>re</i>		\$350.00 +
14	1	Front L/H Lower Arm <i>Bent</i>		\$292.00 ✓
15	1	Front L/H Knuckle Arm <i>Bent</i>		\$358.00 ✓
16	1	Front L/H Knuckle Arm Bearing <i>re</i>		\$259.00 ✓
17	1	Front L/H Stabilizer Bar <i>re</i>		\$309.00 +
18	1	Front L/H Shock Absorber <i>Bent</i>		\$387.00 ✓
19	1	Front L/H Drive Shaft <i>re</i>		\$1,386.00 +
20	1	Front Steering Rack <i>re</i>		\$1,833.00 +
21	1	Front Crossmember <i>re</i>		\$956.00 +

4534

Subtotal :- \$10,196.00

4080.60

S/V 450

Labour charges

To remove & refit front L/H undercarriage	\$380.00 220
To remove & refit L/H drive shaft, steering rack & crossmember	\$450.00 x
To remove & refit front L/H door, glass, lock, rubber, gear motor, frame sticker & trim board	\$150.00 80
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
Towing fee	\$100.00 x
Tuff kote	\$150.00 x
Panel beating	\$1,400.00 800
Spray painting	\$1,400.00 600

Subtotal :- \$4,280.00

Total:- \$14,476.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

total : 6140.60
x/s : 4.9k.

05 Pays.

4.9k

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 24 January, 2019 10:06 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving SKD9733H (OI : LPC - TBA) AND SLW974B (TP : LKK REF - CC6/LPC19001558/Apa3) on 21/01/2019
Attachments: 24012019100229.pdf
Categories: HMK

Our Ref : 18/19/19/VP05/021349

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

The premium for the policy has been settled.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

Sent: Wednesday, 23 January, 2019 6:53 PM

To: MT_Claim_SG

Cc: ONG LI LI; GERALD POH WEE BIN; Hsiao Tong (LKKAUTO); CS A Team; Admin A

Subject: Direct Settlement - Accident Involving SKD9733H (OI : LPC - TBA) AND SLW974B (TP : LKK REF - CC6/LPC19001558/Apa3) on 21/01/2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SLW 974B at M/s New Hock Teck Motor Pte Ltd - Kaki Bukit.

Enclosed here with a copy of TP's GIA report for your perusal.

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Friday, 29 March 2019 4:44 PM
To: MT_Claim_SG
Cc: 'GERALD POH WEE BIN'; Hsiao Tong (LKKAuto); Admin A
Subject: <SEEK MANDATE> YOUR REF: 18/19/19VP05/021349 **(OUR REF: CC6/LPC19001558/Apa3) ** ACCIDENT INVOLVING SKD 9733H & SLW 974B ON 21/01/2019 **

Attachments: ADJUSTMENT REPORT.pdf; INSPECTION REPORT.pdf; LKK RESURVEY PHOTO.pdf; LKK SURVEY PHOTO.pdf; LOD AND OTHER DOCUMENTS.pdf

Lonpac Ref: **18/19/19VP05/021349**

LKK Ref: CC6/LPC19001558/Apa3

Dear Sirs/Madam,

We refer to the above matter.

We have highlighted to your good office on 23/01/2019 of Third-Party's request to do Direct Settlement with our Principal, Lonpac Insurance Bhd.

This is a T-Junction collision. Liability is not in our driver's favour.

Summary to offer to third party repairer, "**NEW HOCK TECK MOTOR PTE LTD**" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 15,489.32	\$ 5,243.00
2. Loss of Use (05days x \$120.00)	\$ 600.00	\$ 600.00 (05days x \$120.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 16,096.77	\$ 5,850.45

**05days recommendation for repair

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC19001558/Aga3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 16-04-2019

Code : LPC2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 9733H	Veh. Inspected	SLW 974B
Policy No.	Z18VP05020175	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021349	Excess (\$)	0.00
Assign From		Assign Date	21/01/2019

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JMYSTCY4A8U002410	Colour	BLUE
Odometer	111365	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/01/2019	Inspection Date	21/01/2019
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 974B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	758.00	758.00
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
1	FRONT L/H BUMPER SIDE RETAINER	NECESSARY	38.00	38.00
1	FRONT L/H HEAD LAMP	CRACKED	652.00	652.00
1	FRONT L/H HEAD LAMP LOWER BRACKET	NOT NECESSARY	23.00	-
1	FRONT L/H FENDER	DENTED	486.00	486.00
1	FRONT L/H FENDER SIGNAL LAMP	NOT NECESSARY	68.00	-
1	FRONT L/H FENDER COWLING	DEFORMED	107.00	107.00
8	FRONT L/H FENDER COWLING CLIP @\$6.50	NECESSARY	52.00	30.00
1	FRONT L/H DOOR	DENTED	1,065.00	1,065.00
2	FRONT L/H DOOR FRAME STICKER @\$36.00	NECESSARY	72.00	72.00
1	FRONT L/H TYRE	NOT NECESSARY	350.00	-
1	FRONT L/H LOWER ARM	BENT	292.00	292.00
1	FRONT L/H KNUCKLE ARM	BENT	358.00	358.00
1	FRONT L/H KNUCKLE ARM BEARING	NECESSARY	259.00	259.00
1	FRONT L/H STABILIZER BAR	NOT NECESSARY	309.00	-
1	FRONT L/H SHOCK ABSORBER	BENT	387.00	387.00
1	FRONT L/H DRIVE SHAFT	NOT NECESSARY	1,386.00	-
1	FRONT STEERING RACK	NOT NECESSARY	1,833.00	-
1	FRONT CROSSMEMBER	NOT NECESSARY	956.00	-
	LESS 10% DISCOUNT		-	-453.40
			9,516.00	4,080.60
<u>SPECIAL NETT ITEMS</u>				
1	FRONT L/H RIM (SN)	CUT	680.00	450.00
			680.00	450.00
<u>LABOUR</u>				
	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE.		380.00	220.00
	TO REMOVE & REFIT L/H DRIVE SHAFT, STEERING RACK & CROSSMEMBER.	NOT NECESSARY	450.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT FRONT L/H DOOR, GLASS, LOCK , RUBBER, GEAR MOTOR, FRAME STICKER & TRIM BOARD,		150.00	80.00
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING.		1,400.00	600.00
	SPRAY PAINTING.		1,400.00	600.00
			4,280.00	1,610.00
GRAND TOTAL			14,476.00	6,140.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CC6/LPC19001558/Aga3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.