

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001562/AEA3Q2

Date: 09/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100398788

Claimant
Vehicle No : SLV3174D **Insured Vehicle No :** SJW6979Y

Date of Loss: 18/01/2019 Nature of Claim: TP Claim No: 0200246932SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3174D		
Make & Model:	KIA CARENS, 1.7 DCT (A)	Engine No:	D4FDHH547292
Reg. Date:	28/12/2017 (Man. Year: 2017)	Chassis No:	KNAHU815VJ7195581
Colour:	Red	Odometer:	96076 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,315.90	7,944.30	12,371.60	60.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,620.00	3,210.00	4,410.00	57.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	27,935.90	11,154.30	16,781.60	60.07
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,338.75		

INSPECTION

Date of Assignment: 22/01/2019

Date Inspected: 22/01/2019 Inspected At: Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT FENDER LH	Dented	445.00 FL	*445.00 FL
2	1	*FRT FENDER INNERSHIELD LH	Not Necessary	268.00 FL	*- FL
3	1	*FRT FENDER ENCLOSURE LH	Deformed	134.00 FL	*134.00 FL
4	1	*FRT DOOR LH	Distorted	1,056.00 FL	*1,056.00 FL
5	1	*FRT DOOR HINGE UPP LH	Not Necessary	38.00 FL	*- FL
6	1	*FRT DOOR HINGE LOW LH	Not Necessary	38.00 FL	*- FL
7	1	*FRT DOOR CHECK LH -LINK CHECK	Not Necessary	74.00 FL	*- FL
8	1	*FRT DOOR LOCK LH	Damaged	294.00 FL	*294.00 FL
9	1	*FRT DOOR LOCK CATCHER LH -STRIKER	Not Necessary	21.00 FL	*- FL
10	1	*FRT DOOR INNER TRIM LH	Cracked	959.00 FL	*959.00 FL
11	1	*FRT DOOR RUBBER BEADING LH-BODY SIDE	Not Necessary	166.00 FL	*- FL
12	1	*FRT DOOR WEATHERSTRIP LH	Cut	126.00 FL	*126.00 FL
13	1	*FRT DOOR OUTER HANDLE LH	Not Necessary	235.00 FL	*- FL
14	1	*FRT DOOR OUTER HANDLE KNOB LH	Not Necessary	31.00 FL	*- FL
15	1	*FRT DOOR BLACK STICKER LH	Necessary	18.00 FL	*18.00 FL
16	1	*FRT DOOR GLASS LH	Not Necessary	230.00 FL	*- FL
17	1	*FRT DOOR GLASS OUTER MLDG LH	Not Necessary	57.00 FL	*- FL
18	1	*FRT DOOR POWER WINDOW REGULATOR ASSY LH	Damaged	274.00 FL	*274.00 FL
19	1	*RR DOOR LH	Dented	926.00 FL	*926.00 FL
20	1	*RR DOOR HINGE UPP LH	Not Necessary	38.00 FL	*- FL
21	1	*RR DOOR HINGE LOW LH	Not Necessary	38.00 FL	*- FL
22	1	*RR DOOR CHECKER LH-LINK CHECK	Not Necessary	74.00 FL	*- FL
23	1	*RR DOOR LOCK LH	Not Necessary	294.00 FL	*- FL
24	1	*RR DOOR LOCK CATCHER LH -STRIKER	Not Necessary	21.00 FL	*- FL
25	1	*RR DOOR RUBBER BEADING LH-BODY SIDE	Not Necessary	166.00 FL	*- FL
26	1	*RR DOOR WEATHER STRIP LH	Not Necessary	126.00 FL	*- FL
27	1	*RR DOOR OUTER HANDLE LH	Not Necessary	235.00 FL	*- FL
28	1	*RR DOOR OUTER HANDLE KNOB LH -COVER	Not Necessary	31.00 FL	*- FL
29	1	*RR DOOR BLACK STICKER LH	Necessary	18.00 FL	*18.00 FL
30	1	*RR DOOR GLASS OUTER MLDG LH	Not Necessary	57.00 FL	*- FL
31	1	*RR DOOR POWER WINDOW REGULATOR ASSY LH	Not Necessary	274.00 FL	*- FL
32	1	*FRT DOOR PILLAR PANEL LH	Repair	1,833.00 FL	*- FL
33	1	*LH CENTER PILLAR PANEL	Repair	2,077.00 FL	*- FL
34	1	*LH ROCKER PANEL	Dented	1,582.00 FL	*1,582.00 FL
35	1	*FRT LH ROCKER PANEL STEP GARNISH	Not Necessary	52.00 FL	*- FL
36	1	*RR LH ROCKER PANEL STEP GARNISH	Not Necessary	52.00 FL	*- FL
37	1	*RR FENDER LH	Dented	1,345.00 FL	*1,345.00 FL
38	1	*RR FENDER INNERSHIELD LH	Not Necessary	268.00 FL	*- FL
39	1	*RR FENDER OUTER QUARTER GLASS LH	Not Necessary	441.00 FL	*- FL
40	1	*FRT RIM LH	Not Necessary	774.00 FL	*- FL
41	1	*FRT WHEEL BEARING LH	Not Necessary	284.00 FL	*- FL
42	1	*FRT KNUCKLE ARM LH	Not Necessary	412.00 FL	*- FL
43	1	*FRT LOW ARM LH	Not Necessary	514.00 FL	*- FL
44	1	*FRT SHOCK ABSORBER LH	Not Necessary	402.00 FL	*- FL
45	1	*FRT STABILIZER LINK LH	Not Necessary	112.00 FL	*- FL
46	1	*RR RIM LH	Cut	774.00 FL	*774.00 FL
47	1	*RR WHEEL BEARING LH	Not Necessary	456.00 FL	*- FL
48	1	*RR SHOCK ABSORBER LH	Not Necessary	266.00 FL	*- FL
49	1	*RR AXLE BEAM ASSY	Not Necessary	1,276.00 FL	*- FL
50	1	*RR BUMPER	Cracked	576.00 FL	*576.00 FL
51	1	*RR BUMPER LOW	Not Necessary	226.00 FL	*- FL
52	1	*RR BUMPER SIDE RETAINER LH	Not Necessary	31.00 FL	*- FL
53	1	*RR BUMPER REFLECTOR LH	Not Necessary	139.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*RR TAILLAMP LH	Not Necessary	428.00 FL	*- FL
55	1		*RR FUEL LID COVER	Not Necessary	69.00 FL	*- FL
56	1		*FRT TYRE RH	Not Necessary	300.00 FS	*- FS
57	1		*RR TYRE LH	Cut	300.00 FS	*180.00 FS
58	10		*FRT BUMPER CLIP	Not Necessary	80.00 FS	*- FS
59	10		*FENDER INNERSHIELD CLIP	Not Necessary	80.00 FS	*- FS
60	10		*RR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
61	1		*FRT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
62	1		*FRT QUARTER GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
63	1		*FRT QUARTER GLASS SOLAR FILM	Not Necessary	100.00 FS	*- FS
64	1		*RR QUARTER GLASS SEALANT	Necessary	80.00 FS	*30.00 FS
65	1		*RR QUARTER GLASS INNER SEAL	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,431.00	8,797.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,115.10	852.70
Total Parts (\$\$)	20,315.90	7,944.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,400.00	1,400.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA,FRT BUMPER ,FRT FENDER LH,FRT DOOR LH ,FRT DOOR PILLAR PANEL LH ,LH ROCKER PANEL ,LH CENTRE PILLAR ,DOOR LH ,RR FENDER LH ,RR BUMPER	New	2,200.00	1,200.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	180.00	30.00
4	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	160.00	80.00
5	TO REMOVE AND REPLACE LHF UNDER CARRIAGE PARTS	New	200.00	0.00
6	TO CONDUCT 4 WHEEL ALIGNMENT	New	180.00	80.00
7	TO REMOVE AND REPLACE DASHBOARD SYSTEM AND INTERNAL WIRING FOR ASSIST REPAIR FRT DOOR PILLAR PANEL	New	600.00	0.00
8	TO CONDUCT RESET OF AIR BAG LIGHT ON	New	300.00	0.00
9	TO CONDUCT TRANSFER FRONT DOOR MECHANISM TO NEW DOOR PANEL	New	200.00	80.00
10	TO CONDUCT TRANSFER REAR DOOR MECHANISM TO NEW DOOR PANEL	New	200.00	80.00
11	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	400.00	120.00
12	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	0.00
13	REMOVE AND REPLACE LHR UNDER CARRIAGE PARTS	New	200.00	0.00
14	TO REMOVE AND REFIT FUEL TANK TO FACILITATE ACCIDENT REPAIR	New	200.00	80.00
15	TO REMOVE AND REFIX REAR QUARTER GLASS	New	120.00	60.00
Gross Labour Cost (\$\$)			7,620.00	3,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >