

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT**Vehicle No** : GBF6329H**Estimation No.** : E19010029**Make & Model** : TOYOTA,DYNA 150 5MT,JTFAT35Y30K207246**DOA** : 23/01/2019**Year of** : 2016**Manufacture**

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Diesel tank	1.00	1,298.60	1,298.60 DD✓
2	Diesel tank lock	1.00	192.00	192.00 JM✓
3	Diesel tank bracket set front	1.00	340.00	340.00 } BT✓
4	Diesel tank bracket set rear	1.00	370.00	370.00 }
5	Rear mud flap panel (RH)	1.00	640.00	640.00 BT✓
6	Rear RH wheel bearing	1.00	270.00	270.00 JM✓
7	Rear RH axle shaft	1.00	0.00	0.00 }
8	Rear RH absorber	1.00	320.00	320.00 } NNA
9	Rear axle	1.00	0.00	0.00 }
10	Diesel tank fuel level sensor	1.00	0.00	0.00 BT✓ 0.00 ? 218.60
3329.2 = 2496.9				Amt S\$ 3,430.60
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,430.60
<u>Section: Special Nett Items</u>				
11	Rear body fender (RH)	1.00	3,400.00	3,400.00 DD✓
12	Rear body fender hinge	4.00	180.00 400.00	1,600.00 NEC ✓
13	Rear wheel rim (RH)	2.00	800.00	1,600.00 NR X
14	Rear tyre (RH)	2.00	250.00	500.00 BR✓
15	Gear oil 3 Litre (1 litre)	1.00	180.00	180.00 60.00
16	Rear mud flap (RH)	1.00	120.00	120.00 NN X
4430				Amt S\$ 7,400.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 7,400.00
<u>Section: Labour Items</u>				
17	To support undercoating / putty on parts replaced	1.00	100.00	100.00 50.00

Continue on next page...

Maray
25/1/19



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBF6329H

Make & Model : TOYOTA,DYNA 150 5MT,JTFAT35Y30K207246

Year of : 2016

Manufacture

Estimation No. : E19010029

DOA : 23/01/2019

No	Description	Qty	U/P	Amt
18	To perform anti rust treatment on affected	1.00	80.00	80.00 40.00
19	To R&R rear wheel rim, tyre and balacing	1.00	80.00	80.00 30.00
20	To R&R diesel tank assy	1.00	350.00	350.00 150.00
21	To R&R rear ^{undercarriage} undercoating damaged parts	1.00	450.00	450.00 120.00
22	To repair,replace and realign damaged areas	1.00	900.00	900.00 300.00
23	To spray painting on affected areas	1.00	800.00	800.00 80.00

parts = 3329.20 - 25% AAA
= 2496.90

990

Amt S\$ 2,760.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 2,760.00

S/N = 4430

Labour = 990

7806.9 - 20%

#6200

ptstl = 7916.90 - 20% L/S
= 6333.52

= #6300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

? photo

TGGM 24/1/19 1550

Lumpsum repair

Repair days 4

List Items Subtotal S\$ 3,430.60

Special Nett Items S\$ 7,400.00

Subtotal

Labour Items Subtotal S\$ 2,760.00

Total S\$

13,590.60