

A.S. REC. BY:

REF:

es/CTI1900162/Dsd3

n2

Special Instruction:

Surveyor

meinen

ASSIGNMENT (Office)

From (Person):

Ong Chin Kiat

of

CTI

Date/Time:

24/1/19 @ 2:13pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 3355B

Insured:

GY 4730K

at Workshop m/s

Chunni Motor

Tel:

65425119

of

Blk 10 # 01-05/06 Ark Autopoint

Policy No:

BMCVSN30313618022

Claim No:

SNM19D200421'002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/01/2019

CA / REV / REP. / REV 24 HRS

lap

25/01/19

H.O.D. Endorsement:

Date/Time:

3:09pm 24/1/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHB 3355B - CC3 / AIG 09025254 / En 11

DOA: 7/11/2019

GY 4730K - CS / CTI 18021624 / R / vd3n2

DOA: 19/11/2018

REF:

ASSIGNMENT

COR OctobN 2022

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 108 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8HB 33553 Yr Regn: 2014 Oct

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 643021 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDEU411153

C/No: KMHLB41UMEU061635

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 22/01/2019 D.O.I: 25/01/2019

Survey held at Churni AMC

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

H/S Front

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Chun Taping GY 4730 K

01/03/19 Insure L/S 12000/- with 10 days. of 19

(\$7,797.68 Red - 39%)

RECEIVED 01 MAR 2019.

Date/Time, File Pass to?

01/03/19

1) Typist

Date/Time, File Return to?

(2)

☐: Preli. Report☒: Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

) TOTAL

Add Fee: ☐ Site Insp: (\$☐ Interview: (\$☐ Tech. Invs: (\$☐ Weekend: (\$

Report Format:

Lump Sum / I.B.L: (\$ 12,000/- H/S

220

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2019		24 Jan 2019 14:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIN SOON HING POULTRY, Co. Reg. No.: 53040422B		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHB3355B	Date of Loss:	22/01/2019 01:00 - :59 [50 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200421C02	Policy/Cover Note No.:	DMCVSN30313618022 (TP, Fire & Theft) Coverage: 20/04/2018 - 19/04/2019
Vehicle Reg. No. (Insured):	GY4730K	Policy No. (Claimant):	D-18088937MFSH
		Excess:	S\$0.00
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/02/2019]		
Driver/Custodian (Insured):	NG PENG HONG (/ Male), NRIC: S0179833B		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD619010537 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 22/01/2019 14:38
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2019 14:38
Date Of Accident	22/01/2019 01:45
Exact Location Of Accident	MARSILING MARKET (BLK 21 CARPARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB3355B
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	
Driver	
Name of Driver	TAN CHIN SON
NRIC No	S2019455C
Date Of Birth	31/08/1947
Occupation	OUTDOOR
Date Of Driving Pass	25/11/1968
Driving Experience	50 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81225185
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 301 WOODLANDS STREET 31 #02-229
 Postcode 730301
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : -
 GENDER: : MALE
 Passenger 2 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident: HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GY4730K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver NG PENG HONG
 NRIC/Passport Number S0179833B
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

FRT RIGHT

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that;

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 22.01.2019@1150HRS


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22.01.2019 @ 0145HRS I was travelling along Marsiling Market Blk 21 Carpark with 1 male and 1 female passenger onboard .

As I was entering the carpark veh (B) GY 4730K suddenly dashed out from my front left and hit onto my vehicle front left portion.

As the accident took place too fast I could not take evasive action to prevent the accident.

I have company photos and video to support my claims.

No injury in this accident .

Veh(B) GY 4730K MR Ng Peng Hong S 0179833B

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

22.01.2019@1150HRS

June Tan

to survey by UCK
DATE : 22.01.2019

DATE : 22.01.2019


TEL : 6542 5119

FAX : 6542 6039

ChinaTaiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet Dented			\$ 2,265.90 ✓
	Bonnet Hinge (LH/RH) HH		\$ 41.00	\$ 82.00 X
	Bonnet Insulator HH			\$ 196.50 X
	Bonnet Insulator Clips HH			\$ 8.40 X
	Radiator Grille HH			\$ 251.00 X
	Radiator Grille H Emblem HH			\$ 27.50 X
	Front Bumper Cover distorted			\$ 544.50 ✓
	Front Bumper Sponge HH			\$ 99.20 X
	Front Bumper Reinforcement HH			\$ 402.10 Y
	Front Bumper Grille (LH) cut			\$ 41.60 ✓
	Front Bumper Bracket Top (LH) HH			\$ 22.40 X
	Front Bumper Bracket (LH) broken			\$ 24.60 ✓
	Headlamp Support Top Cover HH			\$ 222.60 X
	Headlamp Support Panel Assy broken			\$ 907.40 ✓
	Headlamp (LH) broken			\$ 1,388.00 ✓
	Headlamp Halogen Bulb (LH) HH			\$ 14.40 X
	Front Fender (LH) Dented			\$ 566.30 ✓
	Front Fender Apron Panel (LH) Dented			\$ 637.00 ✓
	Front Fender Shield (LH) deformed / torn			\$ 174.90 ✓
	Air Cleaner Assy broken			\$ 118.60 ✓ photo
	Air Cleaner Bottom Assy HH			\$ 325.00 X
	Front Wheel Rim (LH) & distorted			\$ 325.30 A-✓
	Front Wheel Hub Cap (LH) cut			\$ 107.10 ✓
	Front Wheel Bearing & Dam			\$ 540.50 Z-✓
	Front Shock Absorber (Assy) (LH) & distorted			\$ 342.20 Z-✓
	Front Shock Absorber Mounting (LH) HH			\$ 108.80 X
	Front Drive Shaft (LH) & distorted			\$ 1,030.80 Z-✓
	Rack & Pinion Assy & Dam			\$ 969.60 Z-✓
	STG Tie End & distorted			\$ 62.60 Z-✓
	Front Suspension Lower Arm (LH) & distorted			\$ 529.30 Z-✓
	Knuckle Arm (LH) & distorted			\$ 552.00 Z-✓
	Engine Under Cover HH			\$ 334.60 Z-✓ X
	Engine Crossmember & distorted			\$ 2,094.40 X ✓
	ABS Sensor HH			\$ 234.00 Z-✓ X
	Wiring-Engine & wiring broken			\$ 3,326.00 Z-✓
	SUB TOTAL			\$ 18,877.10
	LESS 20%			\$ 3,775.42
	DISCOUNTED TOTAL			\$ 15,101.68
	Front Tyre (LH) S/VL			\$ 216.00 Nett

SHB 3355B

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 700/-
	Spray Painting Charge			\$ 1,000.00 500/- 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 HW
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 HW
	Remove/Refix Dashboard		1960.00	\$ 450.00 150/-
	Remove/Refix Fuse Box			\$ 180.00 50/-
	Re-set Frt ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 180/-
	TOTAL LABOUR			\$ 4,480.00
	ESTIMATE TOTAL			\$ 19,797.68
	25/01/2019 e 0945hr			
	LKA Antenna			
	1/5mm 10 days.			
	1 year			
	LKK Auto			
				
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHB 3355 B

Technician:

Mileage: 643021

Time Printed 25.1.19 10:05 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
4°54'		-3°00' 3°00'
3°28'		-0°19' 5°41'
6°56'		-1°30' 1°30'
8°53'		
13°47'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°21'		-3°00' 3°00'
4°23'		-0°19' 5°41'
-0°22'		-1°30' 1°30'
10°28'		
12°48'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
2°33'		-3°00' 3°00'
-0°55'		-3°00' 3°00'
-1°35'		-3°00' 3°00'
6°33'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°30'		-3°30' 2°30'
0°36'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°16'		-3°30' 2°30'
-0°48'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°15'		-3°00' 3°00'
-0°12'		-3°00' 3°00'
0°42'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19001622/DSD3N2

Date: 04/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30313618022
Claimant Vehicle No :	SHB3355B	Insured Vehicle No :	GY4730K
Date of Loss:	22/01/2019	Nature of Claim:	TP
		Claim No:	SNM19D200421C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3355B	Engine No:	D4FDEU411153
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMEU061635
Reg. Date:	30/10/2014 (Man. Year: 2014)	Odometer:	643021 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,317.68	13,238.88	2,078.80	13.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	1,960.00	2,520.00	56.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,797.68	15,198.88	4,598.80	23.23
Approved Total (Overridden) (\$\$)		12,000.00		
(\$\$)	19,797.68	12,000.00	7,797.68	39.39
+ GST 7.00/7.00% (\$\$)	1,385.84	840.00	545.84	39.39
Nett Amount (\$\$)	21,183.52	12,840.00	8,343.52	39.39

INSPECTION

Date of Assignment:	24/01/2019	
Date Inspected:	25/01/2019 Inspected At:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	10.0 days	

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2019)
Parts: 143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3355B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	82.00 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	196.50 FL	*- FL
4	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
5	1		*RADIATOR GRILLE	Not Necessary	251.00 FL	*- FL
6	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	27.50 FL	*- FL
7	1		*FRONT BUMPER COVER	Distorted	544.50 FL	*544.50 FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	402.10 FL	*- FL
10	1		*FRONT BUMPER GRILLE (LH)	Cut	41.60 FL	*41.60 FL
11	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	22.40 FL	*- FL
12	1		*FRONT BUMPER BRACKET (LH)	Broken	24.60 FL	*24.60 FL
13	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
14	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
15	1		*HEADLAMP (LH)	Broken	1,388.00 FL	*1,388.00 FL
16	1		*HEADLAMP HALOGEN BULB (LH)	Not Necessary	14.40 FL	*- FL
17	1		*FRONT FENDER (LH)	Dented	566.30 FL	*566.30 FL
18	1		*FRONT FENDER APRON PANEL (LH)	Dented	637.00 FL	*637.00 FL
19	1		*FRONT FENDER SHIELD (LH)	Deformed/Torn	174.90 FL	*174.90 FL
20	1		*AIR CLEANER ASSY	Broken	118.60 FL	*118.60 FL
21	1		*AIR CLEANER BOTTOM ASSY	Not Necessary	325.00 FL	*- FL
22	1		*FRONT WHEEL RIM (LH)	Distorted	325.30 FL	*325.30 FL
23	1		*FRONT WHEEL HUB CAP (LH)	Cut	107.10 FL	*107.10 FL
24	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
25	1		*FRONT SHOCK ABSORBER (ASSY)(LH)	Distorted	342.20 FL	*342.20 FL
26	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
27	1		*FRONT DRIVE SHAFT (LH)	Distorted	1,030.80 FL	*1,030.80 FL
28	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
29	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
30	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	529.30 FL	*529.30 FL
31	1		*KNUCKLE ARM (LH)	Distorted	552.00 FL	*552.00 FL
32	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
33	1		*ABS SENSOR	Not Necessary	234.00 FL	*- FL
34	1		*WIRING-ENGINE	Housing broken	3,326.00 FL	*3,326.00 FL
35	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS
36	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,093.10	16,548.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,775.42	3,309.72
Total Parts (\$\$)	15,317.68	13,238.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,500.00	700.00
2	SPRAY PAINTING CHARGE	New	1,000.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
9	REMOVE/REFIX DASHBOARD	New	450.00	150.00
10	REMOVE/REFIX FUSE BOX	New	180.00	50.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	180.00
12	RE-SET FRT ABS SYSTEM }	New	200.00	0.00
Gross Labour Cost (S\$)			4,480.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >