

11/03/2001

ASS. REC. BY:

REF:

08/FCI 19001627/Dt d302

Special Instruction

Surveyor

CWS

ASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time:

3:20pm @ 24/1/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 3550J

Insured:

SHA 1148B

at Workshop m/s

chunni motor

Tel:

65425119

of

Amk Autopoint #01-05/06

Policy No:

Claim No:

D19000611MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/1/2019

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

3:20pm @ 24/1/19

Person Contacted:

lynn

Vehicle: IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHA 3550J - CS/FCI 19001588/d3

DUA: 19/1/19

SHA 1148B - CS/FCI 17004322/Girbe2

DUA: 23/2/17

24/1@10:54am

- revised via preli advise. sent email.

REF:


ASSIGNMENT

CORRECTION 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 14 ~~18~~ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHA 35503** Yr Regn: **2016 March**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / **Truck** / Prime Mover /

Truck / Trailer or

Make: **Hyundai I40** C.C. **1685**
 Colour: **Blue** A/C: Insured / Std / NI / NA
 Sp. Reading: **N.A.** T/Radio: Insured / Std / NI / NA
 Eng/No: **D4FDFU595957**
 C/No: **KMHCB41UMGU085541**

Gen. Cond: **Good** / Fair / Poor / BurntSteering: **In order** / Jammed / Leaked / Burnt orBrake: **In order** / Jammed / Leaked / Burnt orModi: **Nil** / S/Rim / STD A/Rim orTyre Size: F: **205/60 R16**R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Hankook**

Front

Rear

R/Bal. **S** mmR/Bal. **S** mmL/Bal. **S** mmL/Bal. **S** mmD.O.A. **19/01/2019**D.O.I. **25/01/2019**Survey held at **Chunni AMK**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SHA 11483

14/03/19 **Payment 2/5 30,000/- with 14 days of rev**
(Red: 40668.38! 570%)

RECEIVED 15 MAR 2019

Date/Time, File Pass to?

1) **15/3 Typist**

Date/Time, File Return to?

12)

Report Format :

Lump **Sum** / L.B.I. (\$**TP****30,000/-**Days Of Repair: **14**Resurvey No. of Trip: **2**Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

) **580**) **580**

TOTAL

15/3/19**60x15= 90****170 + 900****50****50+50****304****1524**

MOTOR SURVEY ASSIGNMENT

Date	22-01-2019	Our Ref No. D19000611MFSH
Accident Date	19-01-2019	Claim Type. Third Party
Insured Vehicle	SHA1148B	Third Party Vehicle. SHA3550J
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06.	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65427162	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000611MFSH

Date: 29/01/2018

Our Ref: CS/FCI19001627/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 3550J

Please be informed that we had conducted the inspection of the abovementioned vehicle 25/01/2019 at the premises of M/s Chun Ni have the following to report: -

Workshop Estimate Amount	: S\$	<u>70,668.38</u>
Revised Estimate Amount	: S\$	<u>40,891.94</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 29 January 2019 10:59 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000611MFSH/1
Attachments: PRELI ADVISED SHA 3550J.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHA 3550J**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 24 January 2019 3:20 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000611MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 25/01/2019.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 24 January 2019 3:12 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000611MFSH/1

Dear Sir/Mdm,

MCD619009273-01 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 21/01/2019 07:23
 SUBMITTED BY: Catherine Por May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2019 07:23
Date Of Accident	19/01/2019 19:30
Exact Location Of Accident	CTE TOWARDS AYE AFTER BUKIT TIMAH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3550J
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	NG PENG SOON
NRIC No	S1629173J
Date Of Birth	08/04/1964
Occupation	OUTDOOR
Date Of Driving Pass	11/02/1983
Driving Experience	35 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97549518
Fax Number	
Contact Number	
EMail Address	FSG61137@YAHOO.COM.SG

Address 403D #25-149 FERNVALE LANE
Postcode 794403
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 4
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4

Passenger 1
NAME: : -
GENDER: : FEMALE

Passenger 2
NAME: : -
GENDER: : FEMALE

Passenger 3
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
POLICE STATION NAME [OTHER] SENGKANG NPC
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA1148B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver TAN ENG

NRIC/Passport Number
Contact Number 96368832
Address
Postcode
Insurance Company Name
Nature Of Damage FRT
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHD6560U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRT & REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLP3079C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage REAR
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GRACE NG
Approximate Age
Injuries Sustain FOREHEAD
Injured person in which vehicle? SHA3550J
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name JOYCE NG
Approximate Age
Injuries Sustain KNEE,CHIN
Injured person in which vehicle? SHA3550J
Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 3

Name LIM CHENG MUI

Approximate Age

Injuries Sustain CHEST, KNEE

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 4

Name NG PENG SOON

Approximate Age 55

Injuries Sustain CHEST

Injured person in which vehicle? SHA3550J

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *Fanny*
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DOA : 19-01-2019 @ 1930hr,

Refer Police Report T/20190120/2022

[The remaining lines of the form are crossed out with diagonal lines.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: *Fauzy*
NRIC/FIN No.:

CTE towards AYE AFTER
Bukit Timah Exit

DOA: 19-01-2019

Time: 1930hr.

4 3 2 1





SINGAPORE POLICE FORCE



T/20190120/2022

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

1 of 4

Report No. T/20190120/2022

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/01/2019 08:58		Vide Report No.:		Station Diary No.: 37	
Informant's Particulars					
Name of Informant: NG PENG SOON			Address: APT BLK 322D SUMANG WALK #08-855 SINGAPORE 824322		
ID Type / ID No.: NRIC NO / S1629173J			Contact No.: Home/Office: Mobile: 97549518		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 08/04/1964	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 19/01/2019 19:30	Type of Location: Expressway
Location: Along Road 1 CENTRAL EXPRESSWAY				
Along CTE towards AYE after Bukit Timah Exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Chain Collision				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA1148B	Taxi					0
SHA3550J	Taxi					3
SHD6560U	Taxi					0
SLP3079C	Car					0

B.
A
C
D

T/20190120/2022

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 4

Report No. T/20190120/2022

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	JOYCE NG MING HUI	ID No.	T0205407D
Related Vehicle	SHA3550J (Taxi)	Contact No.	97549518
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/01/2019	Date Discharge	19/01/2019
No. of Days granted Medical Leave	02	Degree of Injury	NIL
Passenger			
Name	GRACE NG EN HUI	ID No.	S9831158J
Related Vehicle	SHA3550J (Taxi)	Contact No.	97549518
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/01/2019	Date Discharge	19/01/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	NG PENG SOON	ID No.	S1629173J
Related Vehicle	NIL	Contact No.	97549518
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/01/2018 at about 1930hrs, I was driving my taxi (SHA 3550J) along CTE towards AYE and heading straight on the first lane. The traffic was heavy and everything was normal.

All of a sudden , there was a vehicle (SLP 3079C) who suddenly applied his emergency brake as he wanted to filter to the left towards the exit. As a result, the second vehicle (SHD 6560U) which was directly in front of me also applied its brake.

Upon seeing it, I immediately applied my emergency brake but could not stop in time. The front of my



**SINGAPORE
POLICE FORCE**



T/20190120/2022

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 4

Report No. T/20190120/2022

CONTINUATION OF REPORT

vehicle then knocked onto the rear of the second vehicle (SHD 6560U). There was also a fourth vehicle SHA 1148B who also knocked onto the rear of my vehicle resulting in a chain collision.

Traffic police and ambulance came to scene and both my daughters (Grace Ng En Hui, S9831158J and Joyce Ng Ming Hui, T0205407D) was conveyed to Tan Tock Seng hospital and given 3 days and 2 days Medical Certificate respectively.

I had an in car camera and I believed the whole accident was captured.

**SINGAPORE
POLICE FORCE**

T/20190120/2022

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

4 of 4

Report No. T/20190120/2022

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt CHEE SI WEI, FELIX
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sgt 3 MOHAMED RIZWAN BIN BRAHIM Contact No: 93265045
Authentication Stamp NP168

Signature Of Informant:
Date/Time: 20/01/2019 08:58
Classification Of Case:

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 3550J

DATE : 23.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>bnc</i>			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) <i>bst</i>	\$	41.00	\$ 82.00	✓
	Bonnet Lock <i>bst</i>			\$ 36.90	✓
	Bonnet Absorber <i>hwl</i>	\$	58.10	\$ 116.20	X
	Bonnet Insulator <i>bst</i>			\$ 196.50	✓
	Bonnet Insulator Clips <i>hlc</i>			\$ 8.40	✓
	Radiator Grille <i>broken</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>broken</i>			\$ 120.30	✓
	Front Bumper Cover <i>broken</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>broken</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>tend / Dented</i>			\$ 402.10	✓
	Front Bumper Grille (RH) <i>cnt</i>			\$ 93.60	✓
	Front Bumper Grille Airduct (RH) <i>hwl</i>			\$ 26.20	X
	Front Bumper Lip <i>hwl</i>			\$ 54.90	X
	Front Bumper Bracket Top (LH/RH) <i>hwl</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>hwl</i>	\$	24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>broken</i>			\$ 222.60	✓
	Headlamp Support Panel Assy <i>broken / bnc</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>broken / mount y broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Headlamp Halogen Bulb (RH) <i>hwl</i>			\$ 14.40	X
	Radiator <i>bst / punctured</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95	✓
	Radiator Bracket (RH/LH) <i>hwl</i>	\$	6.50	\$ 13.00	X
	Radiator Hose Upper <i>deformed</i>			\$ 105.80	✓
	Radiator Hose Lower <i>hwl</i>			\$ 52.70	X
	Radiator Expansion Tank <i>hwl</i>			\$ 28.30	X
	Radiator Guard <i>broken</i>	\$	20.00	\$ 40.00	✓
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60	✓
	Horn Wire <i>broken</i>			\$ 156.50	✓
	Front Fender (LH/RH) <i>Dented</i>	\$	566.30	\$ 1,132.60	✓
	Front Fender Apron Panel (RH) <i>Dented</i>			\$ 637.00	✓
	Front Fender Shield (LH/RH) <i>hwl</i>	\$	174.90	\$ 349.80	X
	Air Cleaner Assy <i>hwl</i>			\$ 118.60	X
	Air Duct <i>broken</i>			\$ 134.60	✓
	Air Flow Sensor <i>hwl</i>			\$ 502.20	X
	Air Cleaner Bottom Assy <i>broken / hwl</i>			\$ 325.00	✓
	Aircon Condenser <i>punctured / bst</i>			\$ 927.50	✓
	Aircon Suction & Liquid Hose <i>broken / bst</i>			\$ 624.00	✓
	Aircon Discharge Hose <i>broken / bst</i>			\$ 162.60	✓
	Aircon Compressor <i>bad disto A.S.D</i>			\$ 2,578.00	✓
	Frt Safety Belt (Assy) (LH/RH) <i>activated</i>	\$	475.40	\$ 950.80	✓
	Wiper Container <i>deformed</i>			\$ 61.90	✓
	Wiper Container Motor <i>Don</i>			\$ 75.00	✓
	Engine Mounting <i>hwl</i>			\$ 456.30	X
	Engine Mtg (Rear) <i>hwl</i>			\$ 279.60	X

SHA 3550J

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Gearbox Mounting HH			\$ 215.40 X
	Starter Motor Assy HH			\$ 790.60 X
	Steering Wheel Horn Button Assy HH			\$ 864.00 X
	Inter Cooler <i>functional</i> 1 BT			\$ 1,032.50 ✓
	Inter Cooler Mounting (2 PCS) HH			\$ 25.90 X
	Hose B To Inter Cooler HH			\$ 229.70 X
	Hose C To Inter Cooler Inlet <i>detached</i>			\$ 294.50 ✓
	Pipe To Inter Cooler HH			\$ 167.05 X
	Pipe To Inter Cooler Outlet HH			\$ 244.55 X
	Wiring-Engine <i>wiring broken</i>			\$ 3,326.00 ? ✓
	Wiring-FEM, RH <i>X HH</i>			\$ 168.00 ? X
	Actuator - Swirl Control <i>broken</i>			\$ 814.60 ✓
	Engine Top Cover <i>broken</i> HH			\$ 386.00 X
	Throttle Body Assy HH			\$ 1,096.60 X
	Intake Manifold Assy <i>HH Dam</i>			\$ 1,141.10 ✗ ✓
	Airbag Complete <i>activated</i>			\$ 2,948.50 ✓
	Airbag Control Module <i>activated</i>			\$ 1,140.40 ✓
	Steering Angle Assy HH			\$ 1,150.60 X
	Sensor Assy Impact -Frt Impact HH			\$ 198.30 X
	Airbag Sensor <i>activated</i>		\$ 580.00	\$ 1,160.00 ? ✓
	Electric Power Steering HH			\$ 4,880.50 X
	EGR Valve & Pipe Assy HH			\$ 2,480.50 X
			30455.95	
			24364.76	
	SUB TOTAL			\$ 45,784.85
	LESS 20%			\$ 9,156.97
	DISCOUNTED TOTAL			\$ 36,627.88
	Front Number Plate <i>dislodged</i>			\$ 25.00 Nett ✓
	Front No Plate Trim Cover <i>broken</i>			\$ 30.00 Nett ✓
			55.00	
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,600.00 1000/-
	Spray Painting Charge			\$ 1,250.00 800/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 HH
	Front Chassis Alignment Charge			\$ 400.00 150/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Remove/Refix Engine/Gearbox			\$ 650.00 HH
	Remove/Refix Dashboard			\$ 450.00 ? 150/-
	Remove/Refix Fuse Box			\$ 180.00 ? 50/-
	R/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$ 550.00 200/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 180/-
			2680.00	
	TOTAL LABOUR			\$ 5,910.00

SHA 3550J

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid St			\$ 2,174.90	✓
	Boot Lid Rubber defunct / h/c			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) LH	\$	142.30	\$ 284.60	X
	Boot Lid Lock Upper St			\$ 102.60	✓
	Boot Lid Lock Lower van			\$ 31.70	X
	Boot Lid 'H' Emblem h/c			\$ 28.70	✓
	Boot Lid CRDI Plate h/c			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) crack / broken	\$	565.60	\$ 1,131.20	✓
	Boot Lid Trimboard turn			\$ 116.40	✓
	Boot Lid Trimboard Clips (10pcs) h/c			\$ 11.00	✓
	Bootlid Moulding HH			\$ 85.00	X
	Bootlid i40 Emblem HH			\$ 27.90	X
	Bootlid Lower Garnish HH			\$ 227.90	X
	Rear Bumper Detent			\$ 553.00	✓
	Rear Bumper Reinforcement crack			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) HH	\$	80.30	\$ 160.60	X
	Rear Bumper Clip 10 pcs h/c			\$ 22.00	✓
	Rear Bumper Bracket HH	\$	35.60	\$ 71.20	X
	Rear Bumper Sponge turn			\$ 118.40	✓
	Rear Bumper Under Cover defunct / distorted			\$ 228.00	✓
	Tail Lamp (LH/RH) crack	\$	697.80	\$ 1,395.60	✓
	Rear Panel Detent			\$ 526.70	✓
	Rear Panel Garnish mounting detent			\$ 57.70	✓
	Rear Panel Lower Panel Detent			\$ 495.50	✓
	Spare Tyre Holder HH			\$ 248.00	X
	Spare Tyre Panel HH			\$ 852.80	X
	Spare Tyre Panel Cushion HH			\$ 209.05	X
	Rear Towing Hook HH			\$ 94.60	X
	Member Assy- Rear Floor Centre HH			\$ 570.40	X
	Exhaust Pipe Insulator HH	\$	58.55	\$ 117.10	X
	Exhaust Silencer distorted	\$	967.70	\$ 1,935.40	✓
	Exhaust Pipe Hanger HH	\$	58.55	\$ 117.10	X
	Exhaust Pipe Centre HH			\$ 730.10	X
	Rear Fender With Housing (LH/RH) 0/3 Detent / N/S HH	\$	4,736.80	\$ 9,473.60	2020.1
	Rear Windscreen Moulding h/c			\$ 28.30	✓
	Rear Door (RH) HH			\$ 2,201.10	X
	Rocker Panel Outer Garnish (RH) HH			\$ 341.40	X
			11498.20		
			9198.56		
	SUB TOTAL			\$ 25,322.35	
	LESS 20%			\$ 5,064.47	
	DISCOUNTED TOTAL			\$ 20,257.88	
	Boot Lid Comfort Logo & Tel No. Sticker h/c			\$ 30.00	Nett ✓
	Rear Bumper Reverse Sensor Detent			\$ 135.70	Nett ✓
	Rear Bumper Rubber Mat h/c			\$ 50.00	Nett ✓
	Rear Windscreen Sealant h/c			\$ 46.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) h/c			\$ 80.00	Nett ✓
			341.70		
				\$ 341.70	

SHA 3550J

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,400.00 800/-
	Spray Painting Charge			\$ 1,500.00 800/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Exhaust Pipe			\$ 300.00 60/-
	Transfer of Door			\$ 120.00 H4
	Re-set Rear Power Window System		1930.00	\$ 200.00 H4
	TOTAL LABOUR			\$ 5,010.00
	ESTIMATE TOTAL			\$ 68,202.46
	25/01/2019 @ 1400w NA Androm L/S me 14 18 days. gn LKK Auto	Supp	38570.02 2321.92 40891.94 L/S 30000/-	70668.38
<div style="border: 1px solid black; padding: 5px;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 3550J (Supplementary)

DATE : 28.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Engine Crossmember <i>distorted</i>			\$ 2,094.40 ✓
	Engine Oil Filter Housing <i>Down</i>			\$ 688.00 ✓
	Engine Oil - 6 Litres <i>Leaky / new</i>			\$ 200.00 120.00 <i>120.00</i>
			2902.40	\$ 3,082.40
	SUB TOTAL		2321.92	\$ 616.48
	LESS 20%			\$ 2,465.92
	DISCOUNTED TOTAL			
	<i>28/01/2019</i>			
	<i>[Signature]</i>			
	<i>L Kk And</i>			
	<i>8</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19001627/Dtd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1148B	Veh. Inspected	SHA 3550J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000611MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	24/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU085541	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/01/2019	Inspection Date	25/01/2019	
Survey held at	AMK AUTOPOINT #01-05/06			
Repairer	CHUNNI MOTOR WORK PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3550J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	2,265.90	2,265.90
2	BONNET HINGE (LH/RH) @\$41.00	BENT	82.00	82.00
1	BONNET LOCK	BENT	36.90	36.90
2	BONNET ABSORBER @\$58.10	NOT NECESSARY	116.20	-
1	BONNET INSULATOR	BENT	196.50	196.50
1	BONNET INSULATOR CLIPS	NECESSARY	8.40	8.40
1	RADIATOR GRILLE	BROKEN	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	BROKEN	120.30	120.30
1	FRONT BUMPER COVER	BROKEN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	BROKEN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	BENT / DENTED	402.10	402.10
1	FRONT BUMPER GRILLE (RH)	CUT	93.60	93.60
1	FRONT BUMPER GRILLE AIRDUCT (RH)	NOT NECESSARY	26.20	-
1	FRONT BUMPER LIP	NOT NECESSARY	54.90	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	NOT NECESSARY	49.20	-
1	HEADLAMP SUPPORT TOP COVER	BROKEN	222.60	222.60
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN / BUCKLED	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	BROKEN / MTG BROKEN	2,776.00	2,776.00
1	HEADLAMP HALOGEN BULB (RH)	NOT NECESSARY	14.40	-
1	RADIATOR	BENT / PUNCTURE	698.30	698.30
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY	BROKEN	792.95	792.95
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
1	RADIATOR HOSE UPPER	DEFORMED	105.80	105.80
1	RADIATOR HOSE LOWER	NOT NECESSARY	52.70	-
1	RADIATOR EXPANSION TANK	NOT NECESSARY	28.30	-
2	RADIATOR GUARD @\$20.00	BROKEN	40.00	40.00
2	HORN UNIT (LH/RH) @\$73.80	BROKEN	147.60	147.60
1	HORN WIRE	TORN	156.50	156.50

Report Ref No. CS/FCI19001627/Dtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FENDER (LH/RH) @\$566.30	DENTED	1,132.60	1,132.60
1	FRONT FENDER APRON PANEL (RH)	DENTED	637.00	637.00
2	FRONT FENDER SHIELD (LH/RH) @\$174.90	NOT NECESSARY	349.80	-
1	AIR CLEANER ASSY	NOT NECESSARY	118.60	-
1	AIR DUCT	BROKEN	134.60	134.60
1	AIR FLOW SENSOR	NOT NECESSARY	502.20	-
1	AIR CLEANER BOTTOM ASSY	NOT NECESSARY	325.00	-
1	AIRCON CONDENSER	BENT / PUNCTURE	927.50	927.50
1	AIRCON SUCTION & LIQUID HOSE	BENT	624.00	624.00
1	AIRCON DISCHARGE HOSE	BENT	162.60	162.60
1	AIRCON COMPRESSOR	DISTORTED	2,578.00	2,578.00
2	FRT SAFETY BELT (ASSY) (LH/RH) @\$475.40	ACTIVATED	950.80	950.80
1	WIPER CONTAINER	DEFORMED	61.90	61.90
1	WIPER CONTAINER MOTOR	DAMAGED	75.00	75.00
1	ENGINE MOUNTING	NOT NECESSARY	456.30	-
1	ENGINE MTG (REAR)	NOT NECESSARY	279.60	-
1	GEARBOX MOUNTING	NOT NECESSARY	215.40	-
1	STARTER MOTOR ASSY	NOT NECESSARY	790.60	-
1	STEERING WHEEL HORN BUTTON ASSY	NOT NECESSARY	864.00	-
1	INTER COOLER	PUNCTURE / BENT	1,032.50	1,032.50
2	INTER COOLER MOUNTING	NOT NECESSARY	25.90	-
1	HOSE B TO INTER COOLER	NOT NECESSARY	229.70	-
1	HOSE C TO INTER COOLER INLET	DEFORMED	294.50	294.50
1	PIPE TO INTER COOLER	NOT NECESSARY	167.05	-
1	PIPE TO INTER COOLER OUTLET	NOT NECESSARY	244.55	-
1	WIRING-ENGINE	HOUSING BROKEN	3,326.00	3,326.00
1	WIRING-FEM, RH	NOT NECESSARY	168.00	-
1	ACTUATOR-SWIRL CONTROL	BROKEN	814.60	814.60
1	ENGINE TOP COVER	NOT NECESSARY	386.00	-
1	THROTTLE BODY ASSY	NOT NECESSARY	1,096.60	-
1	INTAKE MANIFOLD ASSY	DAMAGED	1,141.10	1,141.10
1	AIRBAG COMPLETE	ACTIVATED	2,948.50	2,948.50
1	AIRBAG CONTROL MODULE	ACTIVATED	1,140.40	1,140.40

Report Ref No. CS/FCI19001627/Dtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING ANGLE ASSY	NOT NECESSARY	1,150.60	-
1	SENSOR ASSY IMPACT - FRT IMPACT	NOT NECESSARY	198.30	-
2	AIRBAG SENSOR @\$580.00	ACTIVATED	1,160.00	1,160.00
1	ELECTRIC POWER STEERING	NOT NECESSARY	4,880.50	-
1	EGR VALVE & PIPE ASSY	NOT NECESSARY	2,480.50	-
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID RUBBER	DEFORMED / NECESSARY	96.50	96.50
2	BOOT LID HINGE (LH/RH) @\$142.30	NOT NECESSARY	284.60	-
1	BOOT LID LOCK UPPER	BENT	102.60	102.60
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
2	BOOT LID LAMP (LH/RH) @\$565.60	CRACKED / BROKEN	1,131.20	1,131.20
1	BOOT LID TRIMBOARD	TORN	116.40	116.40
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	BOOTLID MOULDING	NOT NECESSARY	85.00	-
1	BOOTLID I40 EMBLEM	NOT NECESSARY	27.90	-
1	BOOTLID LOWER GARNISH	NOT NECESSARY	227.90	-
1	REAR BUMPER	DENTED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	NOT NECESSARY	160.60	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	NOT NECESSARY	71.20	-
1	REAR BUMPER SPONGE	TORN	118.40	118.40
1	REAR BUMPER UNDER COVER	DEFORMED / DISTORTED	228.00	228.00
2	TAIL LAMP (LH/RH) @\$697.80	CRACKED	1,395.60	1,395.60
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL GARNISH	MTG DEFORMED	57.70	57.70
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
1	SPARE TYRE HOLDER	NOT NECESSARY	248.00	-

Report Ref No. CS/FCI19001627/Dtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE PANEL	NOT NECESSARY	852.80	-
1	SPARE TYRE PANEL CUSHION	NOT NECESSARY	209.05	-
1	REAR TOWING HOOK	NOT NECESSARY	94.60	-
1	MEMBER ASSY-REAR FLOOR CENTRE	NOT NECESSARY	570.40	-
2	EXHAUST PIPE INSULATOR @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$967.70	DISTORTED	1,935.40	1,935.40
2	EXHAUST PIPE HANGER @\$58.55	NOT NECESSARY	117.10	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	730.10	-
2	REAR FENDER WITH HOUSING (LH/RH) @\$4736.80	O/S DENTED / N/S NOT NECESSARY	9,473.60	2,020.00
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (RH)	NOT NECESSARY	2,201.10	-
1	ROCKER PANEL OUTER GARNISH (RH)	NOT NECESSARY	341.40	-
1	ENGINE CROSSMEMBER (ADDITIONAL)	DISTORTED	2,094.40	2,094.40
1	ENGINE OIL FILTER HOUSING (ADDITIONAL)	DAMAGED	688.00	688.00
6	LITRES ENGINE OIL (ADDITIONAL)	LEAKING / NECESSARY	300.00	120.00
	LESS 20% DISCOUNT		-14,837.92	-8,971.31
			59,351.68	35,885.24
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DISLODGE	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	BROKEN	30.00	30.00
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
			396.70	396.70
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER.		4,000.00	1,800.00
	SPRAY PAINTING CHARGE.		2,750.00	1,600.00
	WIRING CHARGE.		100.00	60.00

Report Ref No. CS/FCI19001627/Dtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		150.00	80.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	FRONT CHASSIS ALIGNMENT CHARGE.		400.00	150.00
	REMOVE / REFILL AIRCON & REFILL GAS.		150.00	80.00
	REMOVE / REFILL ENGINE / GEARBOX.	NOT NECESSARY	650.00	-
	REMOVE / REFILL DASHBOARD.		450.00	150.00
	REMOVE / REFILL FUSE BOX.		180.00	50.00
	R/REFILL AIR BAG / STEERING WHEEL / DASHBOARD / SEAT.		550.00	200.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		480.00	180.00
	REMOVE / REFILL CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFILL REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE / REFILL REVERSE SENSOR.		120.00	40.00
	REMOVE / REFILL EXHAUST PIPE.		300.00	60.00
	TRANSFER OF DOOR.	NOT NECESSARY	120.00	-
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
			10,920.00	4,610.00
GRAND TOTAL			70,668.38	40,891.94

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			30,000.00
---	--	--	-----------

Report Ref No. CS/FCI19001627/Dtd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.