

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120**Our File No:** CC3/AIG19001693/AVD3E2**Date:** 29/07/2019REFERENCE

Insured/Claimant:	TAN LAY HOON	Policy No:	2100395403-04		
Date of Loss:	24/01/2019	Nature of Claim:	OD	Claim No:	4766483590SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ7394Y		
Make & Model:	AUDI A4, 1.8 T (A)	Engine No:	CJE090117
Reg. Date:	23/12/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ8K5FA045622
Colour:	Bronze	Odometer:	66744 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$74,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	20,769.00	11,737.80	9,031.20	43.48	
Miscellaneous Items	0.00	0.00	0.00		
Labour	12,512.00	7,482.00	5,030.00	40.20	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	33,281.00	19,219.80	14,061.20	42.25	
Approved Total (Overridden) (S\$)		13,400.00			
	(S\$)	33,281.00	13,400.00	19,881.00	59.74
	+ GST 7.00/7.00% (S\$)	2,329.67	938.00	1,391.67	59.74
	Nett Amount (S\$)	35,610.67	14,338.00	21,272.67	59.74

INSPECTION

Date of Assignment:	25/01/2019		
Date Inspected:	25/01/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	15.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,100.00 FS	*1,680.00 FS
2	4		*REAR BUMPER STICKY PAD	Not Necessary	21.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	206.00 FS	*- FS
4	1		*REAR BUMPER SPOILER - LH	Cut	243.00 FS	*194.40 FS
5	1		*REAR BUMPER CARRIER	Bent	587.00 FS	*469.60 FS
6	1		*HOLDER FOR BUMPER BRACKET - LH	Not Necessary	203.00 FS	*- FS
7	1		*HOLDER FOR BUMPER BRACKET - RH	Not Necessary	203.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	40.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION - UPPER LH	Not Necessary	21.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION - UPPER RH	Not Necessary	20.00 FS	*- FS
12	1		*REAR LID SECURING STRIP	Necessary	12.00 FS	*9.52 FS
13	4		*REAR PARKING SENSOR	Damaged	838.00 FS	*670.40 FS
14	4		*REAR PARKING SENSOR SEAL RING	Necessary	5.00 FS	*3.84 FS
15	1		*SET REAR BUMPER WIRING	Not Necessary	472.00 FS	*- FS
16	1		*REAR LID	Dented	2,554.00 FS	*2,043.20 FS
17	1		*REAR LID ATTACHMENT PARTS	Not Necessary	67.00 FS	*- FS
18	1		*REAR LID HINGE - LH	Bent	233.00 FS	*186.40 FS
19	1		*REAR LID HINGE - RH	Bent	233.00 FS	*186.40 FS
20	1		*REAR LID GASKET FOR FLAP	Damaged	185.00 FS	*147.60 FS
21	2		*REAR LID STOP BUFFER - LH / RH	Not Necessary	50.00 FS	*- FS
22	2		*REAR LID COVER	Not Necessary	66.00 FS	*- FS
23	1		*REAR LID CLOSING ELEMENT - LH	Not Necessary	29.00 FS	*- FS
24	1		*REAR LID CLOSING ELEMENT - RH	Not Necessary	29.00 FS	*- FS
25	2		*REAR LID STOP CAP - LH / RH	Not Necessary	6.00 FS	*- FS
26	2		*REAR STOP BUFFER	Not Necessary	51.00 FS	*- FS
27	2		*REAR STOPPER	Not Necessary	14.00 FS	*- FS
28	1		*REAR LID LOCK	Jammed	199.00 FS	*158.80 FS
29	1		*REAR LID LOCK COVER	Damaged	18.00 FS	*14.16 FS
30	1		*PROTECTIVE CAP	Damaged	18.00 FS	*13.68 FS
31	1		*REAR LID LOCK STRIKER	Bent	45.00 FS	*36.00 FS
32	1		*PUSH BOTTON FOR ELECTRIC LOCK LID ACTUATOR	Damaged	167.00 FS	*133.20 FS
33	1		*GUARD PLATE	Damaged	56.00 FS	*44.72 FS
34	1		*SEAL FOR PUSH BUTTON	Not Necessary	14.00 FS	*- FS
35	1		*BOOT DAMPER	Not Necessary	109.00 FS	*- FS
36	1		*BALL STUD	Not Necessary	19.00 FS	*- FS
37	1		*PACKING ADHESIVE	Necessary	18.00 FS	*13.92 FS
38	1		*AUDI EMBLEM	Necessary	113.00 FS	*90.00 FS
39	1		*CHROME INSCRIPTION - A4	Necessary	87.00 FS	*69.28 FS
40	1		*CHROME INSCRIPTION - TFSI	Necessary	87.00 FS	*69.28 FS
41	1		*REAR CROSS PANEL - OUTER	Dented	286.00 FS	*228.40 FS
42	1		*REAR REINFORCEMENT BEAN - INNER	Repair	484.00 FS	*- FS
43	1		*REAR CROSS PANEL - LOWER	Repair	794.00 FS	*- FS
44	1		*REAR LID TRIM PANEL	Not Necessary	240.00 FS	*- FS
45	1		*TRIM FOR REAR CROSS PANEL	Deformed	168.00 FS	*133.60 FS
46	1		*LUGGAGE COMP.FLOOR COVERING	Not Necessary	646.00 FS	*- FS
47	1		*LED TAIL LIGHT - LEFT	Cut	824.00 FS	*658.80 FS
48	1		*LED TAIL LIGHT - RIGHT	Not Necessary	824.00 FS	*- FS
49	1		*LICENSE PLATE LIGHT	O/S Cracked	105.00 FS	*41.68 FS
50	2		*EXHAUST TAIL PIPE	Not Necessary	557.00 FS	*- FS
51	1		*SEAT BELT WITH TENSIONER - LH	Activated	1,005.00 FS	*804.00 FS
52	1		*SEAT BELT WITH TENSIONER - RH	Activated	1,005.00 FS	*804.00 FS
53	2		*TAIL PIPE ADJUSTMENT FITTING	Bent	357.00 FS	*285.60 FS
54	1		*AIRBAG CONTROL UNIT	Activated	1,927.00 FS	*1,541.60 FS
55	1		*CENTRAL PROTECTION	Activated	543.00 FS	*434.40 FS
56	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
57	1		*REAR NO. PLATE	Bent	25.00 FS	*25.00 FS
58	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
59	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS

LKK Auto Consultants Pte Ltd/SKQ7394Y/29/07/2019 08:44

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
60	1		*SUNDRIES	Necessary	1,000.00 FS	*46.32 FS
					Total Parts (S\$)	20,769.00
						11,737.80

F=Franchise part. S=SpcNett.

LKK Auto Consultants Pte Ltd/SKQ7394Y/29/07/2019 08:44
--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
3	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHT	New	280.00	280.00
4	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE, RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS	New	480.00	480.00
5	TO DISMANTLE AND REINSTALL CENTRE CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT	New	1,800.00	1,800.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND REWELD END PANELLING. TO REPAIR SPARE WHEEL HOUSING. TO INSPECT FOR FURTHER DAMAGES. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	2,500.00
7	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDER, HINGES, SPARE WHEEL HOUSING AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	4,400.00	1,950.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (S\$)	12,512.00
				7,482.00

LKK Auto Consultants Pte Ltd/SKQ7394Y/29/07/2019 08:44

< END OF ESTIMATES >