

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5433R

AAD1901-221

*Not Notarised
L1 Imp & 38501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5433R

VF1ABL15AUC279862

RENAULT

LATITUDE

22.1.2019

QBE

19/11/2014

| | PART | | LIST |
|---|--------------------------------------|----|----------------------------|
| 1 | DOOR PANEL FRT RH | \$ | <i>Btl/warp</i> 2,844.66 ✓ |
| 1 | DOOR HINGE UPPER RH | \$ | <i>R</i> 261.28 |
| 1 | DOOR HINGE LOWER RH | \$ | <i>R</i> 300.55 |
| 1 | DOOR CHECK FRT RH | \$ | <i>Sm</i> 194.77 |
| 1 | DOOR LOCK FRT RH | \$ | <i>R</i> 908.75 |
| 1 | DOOR CATCH FRT RH | \$ | <i>Sm</i> 131.23 |
| 1 | DOOR HANDLE OUTER FRT RH | \$ | <i>R</i> 477.76 |
| 1 | DOOR HANDLE COVER FRT RH | \$ | <i>Sm</i> 13.22 |
| 1 | DOOR HANDLE MODULE FRT RH | \$ | <i>Sm</i> 133.60 |
| 1 | DOOR REGULATOR FRT RH | \$ | <i>R</i> 505.19 |
| 1 | DOOR REGULATOR MOTOR FRT RH | \$ | <i>Sm</i> 796.46 |
| 1 | DOOR REGULATOR GUIDE FRT RH | \$ | <i>Sm</i> 120.97 |
| 1 | DOOR PANEL REAR RH | \$ | <i>R</i> 2,844.66 |
| 1 | DOOR GUIDE REAR RH | \$ | <i>Sm</i> 176.82 |
| 1 | DOOR HINGE UPPER RH | \$ | <i>R</i> 274.50 |
| 1 | DOOR HINGE LOWER RH | \$ | <i>R</i> 300.55 |
| 1 | DOOR CHECK REAR LH/RH L70Y | \$ | <i>Sm</i> 203.06 |
| 1 | DOOR LOCK REAR RH | \$ | <i>R</i> 908.75 |
| 1 | DOOR HANDLE OUTER REAR RH | \$ | <i>Sm</i> 126.49 |
| 1 | DOOR HANDLE CAP REAR RH | \$ | <i>Sm</i> 35.52 |
| 1 | DOOR HANDLE SEAL REAR RH | \$ | <i>Sm</i> 7.89 |
| 1 | DOOR HANDLE COVER REAR RH | \$ | <i>Sm</i> 13.22 |
| 1 | DOOR HANDLE MODULE REAR RH | \$ | <i>Sm</i> 133.60 |
| 1 | DOOR REGULATOR REAR RH | \$ | <i>R</i> 1,135.10 |
| 1 | DOOR REGULATOR MOTOR REAR RH | \$ | <i>Sm</i> 893.75 |
| 1 | DOOR REGULATOR NUT REAR L70Y | \$ | <i>Sm</i> 12.43 |
| 1 | DOOR REGULATOR MOTOR SCREW REAR L70Y | \$ | <i>Sm</i> 6.31 |
| 1 | DOOR FINISHER REAR RH | \$ | <i>Sm</i> 423.10 |
| 1 | DOOR MOULDING REAR RH | \$ | <i>Sm</i> 176.82 |

X

Trans-cab Auto Services Pte Ltd

AAD1901-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5433R

| | | | | | |
|---|-----------------------|----|-----------|-------|-----|
| 1 | DOOR HINGE NUT RH | \$ | <i>nn</i> | 14.60 | } X |
| 1 | DOOR CHECK BOLT | \$ | <i>nn</i> | 22.69 | |
| 1 | DOOR CHECK NUT | \$ | <i>nn</i> | 3.75 | |
| 1 | DOOR LOCK SCREW L70Y | \$ | <i>nn</i> | 6.12 | |
| 1 | DOOR CATCH SCREW L70Y | \$ | <i>nn</i> | 10.06 | |

| | | |
|--------------|-----------|---------------|
| TOTAL | \$ | 311.63 |
|--------------|-----------|---------------|

| | | |
|--------------------|-----------|------------------|
| TOTAL PARTS | \$ | 18,396.72 |
|--------------------|-----------|------------------|

LABOUR

| | | | |
|---|----|------------------|-------------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 4,500.00 | <i>300/</i> |
| Putty and spray painting of the affected portion. | \$ | 4,200.00 | <i>500/</i> |
| To rust-proofing of the affected areas. | \$ | 170.00 | <i>30/</i> |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | <i>nn</i> 380.00 | X |
| To check steering geometry and computer wheel alignment | \$ | <i>nn</i> 220.00 | X |
| To transfer of tire, rim and on wheel balancing. | \$ | <i>nn</i> 170.00 | X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | <i>20/</i> |
| To transfer of front door fittings, attachment and perform water seepage test. | \$ | 380.00 | <i>60/</i> |
| To transfer of Rear door fittings, attachment and perform water seepage test. | \$ | <i>nn</i> 380.00 | X |

| | | |
|--------------|-----------|------------------|
| TOTAL | \$ | 10,570.00 |
|--------------|-----------|------------------|

| | | |
|-----------------------|-----------|------------------|
| Over All Total | \$ | 28,966.72 |
|-----------------------|-----------|------------------|

LUMP SUM (REPAIR DAY)**15 DAYS***2 1/2 days*