



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2004475
INV Date 23/06/2020
Reference CC6/CTI19001750/Uba3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SGU 71B
Insured Veh. PA 6215M
Claim No. SNM19D200474
Policy No. DMB1SN1744851801
Accident Date 25/01/2019
Inspection Date 25/01/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19001750/Uba3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 23-06-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 6215M	Veh. Inspected	SGU 71B
Policy No.	DMB1SN1744851801	Coverage (\$)	0.00
Claim No.	SNM19D200474	Excess (\$)	0.00
Assign From		Assign Date	25/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053BK4107006369	Colour	SILVER
Odometer	195976	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45ZR18	HABILEAD	6 mm
L/H Front Tyre	235/45ZR18	HABILEAD	6 mm
R/H Rear Tyre	235/45ZR18	HABILEAD	6 mm
L/H Rear Tyre	235/45ZR18	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/01/2019	Inspection Date	25/01/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 71B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	1,455.10	-
1	BOOTLID REAR LOGO	NECESSARY	68.50	68.50
1	BOOTLID 'CAMRY' EMBLEM	NECESSARY	66.20	66.20
1	BOOTLID 'HYBRID' EMBLEM	NECESSARY	85.90	85.90
1	BOOTLID '2.0' EMBLEM	NECESSARY	58.00	58.00
1	BOOTLID 'HYBRID SYNERGY DRIVE' EMBLEM	NECESSARY	85.00	85.00
2	BOOTLID REFLECTORS @ \$681.10	NOT NECESSARY	1,362.20	-
1	BOOTLID INNER LOCK	NOT NECESSARY	399.50	-
1	BOOTLID WEATHERSTRIP	TWISTED	315.10	315.10
1	REAR BUMPER	DENTED / DEFORMED	898.10	699.10
1	REAR BUMPER REINFORCEMENT	DENTED	415.50	415.50
2	REAR BUMPER SIDE RETAINERS @ \$145.00	BENT	290.00	290.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER SKIRTING	DEFORMED / NECESSARY	850.00	850.00
2	REAR BUMPER REFLECTORS @ \$105.00	NOT NECESSARY	210.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	815.10	-
1	REAR END PANEL TOP GARNISH	TWISTED	499.50	499.50
2	TAILLAMPS @ \$850.00	CRACKED	1,700.00	1,700.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,021.10	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	411.50	-
	LESS 25% DISCOUNT		-	-1,295.70
			11,056.30	3,887.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	380.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	250.00	-
			680.00	200.00

Report Ref No. CC6/CTI19001750/Uba3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX BOOTLID MECHANISM.	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		100.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		120.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID, REAR END PANEL AND REAR EXHAUST.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			3,300.00	1,710.00
GRAND TOTAL			15,036.30	5,797.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,600.00

Report Ref No. CC6/CTI19001750/Uba3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.