

INSURANCE

INS. CASE OWNER:

KC | CCV ASM 1801, E9 J03^{S2}LKK:
IDAC:

Surveyor:

Steve

DOI:

ASSIGNMENT

29/1/19

Date / Time:

28/1/19

Registered in Meriten:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKC 22R

Name of Insured:

SHAW ming tung FRANK

Insured Tel No.:

HP:

D.O.A:

21/1/19

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKC 22R

EG 1004

SDP 18731

INSRS:
WSP:
Tel:
Liability:
RMKS:

01

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
28/1/19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call Of:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice:	☒ ☐
	LTA / GIA:	☒ ☐
	Medical Bill:	☒ ☐
	PIR:	☒ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD:	☒ ☐
	Payment Breakdown Form:	☒ ☐
	Post-Repair Photos:	☒ ☐
	Others:	☒ ☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
12-0-190	400 CALL 01 - NO ANS.	
12/1/19	AXA instruct settlement not exceeding \$18,398.62 (all-in).	
19/1/19	offer as per TP LOD, DV send (pending DV)	
21/1/19	DV in (File pass Admin to close).	

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: R/P	SS 16,143.10	13 days Reduction: %	Steve
FINAL SETTLEMENT	Date/Time: 21/1/19	Confirm with: CAROLINE	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	28
Repair Cost: (W/EST)	SS 17,273.12		
Loss of Rental (LOR):	SS 1123.50	(15 days) x \$74.90 (W/EST)	
Loss of Use (LOU):	SS -	(S x days)	
Loss of Income (LOI):	SS -	(S x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 18,398.62	Global Sum SS:	-
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☒ Call ☐
Payee 1:	SS 18,398.62	Name 1:	Performance Motors Limited
Payee 2: (Strike if N.A.)	SS -	Name 2:	
Payee 3: (Strike if N.A.)	SS -	Name 3:	

Steve

REF ASM(CAXA)

ASSIGNMENT

From:

Date:

25/2/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

EG10014

at Work stoppage

performance

at

303 Alexandra Rd

Insured

Policy No

Claim No

Sum Insured

Excess

(Client's Record)

Make of Veh

Intrien

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

13

days

Res.: Yes or No

Lump Sum

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No

EG10014

V. Reg

8/03/17

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make

BMW X1

c.c. 1998

Colour

white

A/C: Insured / Std / Nil / NA

Sp Reading

36406

I/Radio: Insured / Std / Nil / NA

Eng/No

C/No

WBAHS 7203056 65917

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modt: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

225/50R18

R:

H

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal

7

mm

R/Bal

7

mm

L/Bal

7

mm

L/Bal

7

mm

D.O.A.

21/1/19

D.O.I.

25/2/19

Survey held at

Performance

Des. of Damages: ☒ Front / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

(Red v \$4903.70 / 23%)

10-4-19 P/P- \$16,143.10

* 13 repair days + 2 PRS = 15 days.

Date/Time: File Pass to:

☐

Preli. Report

n

☐

Final Report

Date/Time: File Return to:

n

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) 1st PRS

) Photo

) Collar

) 1st

TOTAL

Report Format:

Lump Sum / LB L/C

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19001801/jb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 28-01-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKC 22R	Veh. Inspected	EG 1001U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/01/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/01/2019	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



FINAL REPORT

Estimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Leslie Lam Kwok Tai
10B Rochalie Drive

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 248244

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace front/rear bumpers and attachments, front air duct, tail end panel, trunk floor, heat insulation include pulling and straightening on accident areas and knocking out dents caused by the accident	6800.00	10.00	6,120.00 ✓
* To spray paint front bumper, rear bumper, tail end panel and trunk floor plate	2847.00	10.00	2,562.30 ✓
* To check electrical wiring systems and lightings at the front and rear section for proper function	251.00	10.00	225.90 ✓
① To supply front emboss number plate	83.00	0.00	83.00 ✓
② To remove and install boot compartment carpet and garnish to facilitate repairs	230.00	10.00	207.00 ✓
③ To replace rear exhaust silencer include alignment of system and conducting checks for leak	451.00	10.00	405.90 ✓
# To replace boot lid smart opener top sensor line include programming and checking control unit, bottom sensor line for proper function *	562.00	10.00	505.80 ✓
⑤ # To carry out body cavity preservation (For cut panel)*	451.00	10.00	405.90 ✓
④ Sundries	150.00	0.00	150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH * NEC	60.60	1.00	3.00	58.78 ✓
① REAR SILENCER DD	1,465.05	1.00	3.00	1,421.10 ✓
# TRUNK FLOOR * DD	452.00	1.00	3.00	438.44 ✓
③ # TAIL PANEL * DD	401.75	1.00	3.00	389.70 ✓
⑤ # FRT BUMPER TOP CARRIER * DD	373.95	1.00	3.00	362.73 ✓
④ FRT BUMPER PANEL LOWER SECTION (PDC DD	281.80	1.00	3.00	273.35 ✓
② RR BUMPER CARRIER DD	493.85	1.00	3.00	479.03 ✓
③ MOUNTING SMART OPENER TA	45.30	1.00	3.00	43.94 ✓

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

5	REAR TRIM UNDERRIDE PROTECTION (X L	105.40	1.00	3.00	102.24 ✓
6	# RR BUMPER LH CORNER MOUNTING *	141.90	1.00	3.00	137.64 ✓
7	RR BUMPER RH CORNER MOUNTING	141.90	1.00	3.00	137.64 ✓
8	REAR BUMPER PANEL PRIMED	770.80	1.00	3.00	747.68 ✓
9	REAR BUMPER MIDDLE TRIM PANEL (PDC)	242.80	1.00	3.00	235.52 ✓
10	REAR BUMPER BOTTOM TRIM PANEL (LINE	231.25	1.00	3.00	224.31 ✓
11	LICENCE PLATE HOLDER ECE	70.65	1.00	3.00	68.53 ✓
12	REAR BUMPER HEAT INSULATION	69.55	1.00	3.00	67.46 ✓
14	# AIR DUCT *	246.00	1.00	3.00	238.62 ✓
	# PLUG BLACK D=5MM *	0.90	8.00	3.00	6.98 ✓
	# PLUG BLACK D=5MM *	0.90	2.00	3.00	1.75 ✓
	# SENSOR WIRE FOR SMART OPENER TOP *	43.15	1.00	3.00	41.86 ✓

SUPPLEMENTARY ITEMS

Total Labour :	10,665.80 ✓
Total Parts :	5,477.30 ✓
Total Labour & Parts :	16,143.10 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	16,143.10
GST @7%:	1,130.02
Grand Total :	17,273.12

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

303, Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Tel. 63190100 (Sales & Admin)

63190111 (AfterSales)

Fax. 64747770

315, Alexandra Road

Sime Darby Business Centre

Singapore 159944

Tel. 63190528 (AfterSales)

63190533/530 (Motorrad)

Fax. 64796601 (AfterSales)

64796624 (Motorrad)

Signature:

Date:

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49905
 Date Estimated : 25/01/2019
 Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Leslie Lam Kwok Tai
 10B Rochalie Drive

Singapore 248244

- ACCOUNT - 238

AXA Insurance Pte Ltd
 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear bumper, attachments, repair front bumper and repair tail panel.

Painting front bumper, rear bumper and tail panel.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

① To supply front emboss number plate.

② To remove and install boot compartment carpet and garnish to facilitate repairs.

③ To replace rear exhaust silencer including alignment system and conduct checks for leak.

④ Sundries.

Total Labour 1: 7,431.00

DESCRIPTION

① REAR SILENCER

TAILPIPE TRIM CHROME

TRIM PANEL AIRDUCT (X LINE)

④ FRT BUMPER PANEL LOWER SECTION (PDC)

② RR BUMPER CARRIER

③ MOUNTING SMART OPENER

⑤ REAR TRIM UNDERRIDE PROTECTION (X L)

REAR TRIM UNDERRIDE PROTECTION (X L)

⑥ RR BUMPER RH CORNER MOUNTING

RR BUMPER RH CORNER MOUNTING

⑧ REAR BUMPER PANEL PRIMED

⑨ REAR BUMPER MIDDLE TRIM PANEL (PDC)

⑩ REAR BUMPER BOTTOM TRIM PANEL (LINE)

⑪ LICENCE PLATE HOLDER ECE

QTY	PRIC	VALUE
1	1,465.05	1,465.05
2	107.85	215.70
1	153.30	153.30
1	281.80	281.80
1	493.85	493.85
1	45.30	45.30
1	105.40	105.40
1	105.40	105.40
1	141.90	141.90
1	141.90	141.90
1	770.80	770.80
1	242.80	242.80
1	231.25	231.25
1	70.65	70.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

No illegal modification(s) is allowed

Supplier of parts must be from Insurance Company

Tel. 63190888 (AfterSales)

Fax. 63449773

Acknowledged by Repairer

Signature:

Date:

GST REG. NO : M2 - 0020081 - X

25 JAN 2019



Survey & repair
 on 25.02 @ 10 am

Store
 83278813
 25/2/19
 12-30pm

13 days

with parking P/P

the 8 days Rec bet & AH spy

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION	QTY	PRIC	VAL
REAR BUMPER HEAT INSULATION ? 00	1	69.55 /	69.
Total Parts :			4,534.

Labour 1	:	7,431.
Parts	:	4,534.00
Labour 2	:	0
Excess	:	0
Total GST @ 7%	:	837
Grand Total	:	12,803.

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Supp. Summary
GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50390
Date Estimated : 05/03/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Leslie Lam Kwok Tai
10B Rochalie Drive

Singapore 248244

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION

To replace air duct(front support),tail panel and trunk floor.

VALUE

nn 5,950.00X

Painting Trunk floor.

nn 572.00X

(S) To carry out body cavity preservation.
(For cut panel).

451 531.00

Total Labour 1: 7,053.00

DESCRIPTION

TRUNK FLOOR

TAIL PANEL

FRT BUMPER TOP CARRIER

AIR DUCT

BLIND RIVET AVIBVLB

SCREW (SF PLUS M5X15)

(DG/SL) BODY ADHESIVE K5B (195ML)

(DG) BODYWORK ADHESIVE K5A (50ML)

(DG) CLEANER R1 (100ML)

PUNCH RIVET N4

(S/L) SEAM SEAL 300ML

QTY

PRIC

VALUE

1

452.00

452.00

1

401.75

401.75

1

373.95

373.95

1

246.00

246.00

60

0.55

33.00

10

0.55

5.50

1

326.80

326.80

1

112.70

112.70

1

26.15

26.15

30

0.55

16.50

1

33.80

33.80

Total Parts : 2,028.15

Labour 1 : 7,053.00

Parts : 2,028.15

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 635.68

Grand Total : 9,716.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

24187.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Supp.

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50390
Date Estimated : 05/03/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Leslie Lam Kwok Tai
10B Rochalie Drive

Singapore 248244

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION

To replace air duct(front support),tail panel and trunk floor.

Painting Trunk floor.

To carry out body cavity preservation.
(For cut panel).

VALUE

5,950.00

572.00

481 531.00

Total Labour 1: 7,053.00

DESCRIPTION

TRUNK FLOOR

TAIL PANEL

FRT BUMPER TOP CARRIER

AIR DUCT

BLIND RIVET AVIBVLB

SCREW (SF PLUS M5X15)

(DG/SL) BODY ADHESIVE K5B (195ML)

(DG) BODYWORK ADHESIVE K5A (50ML)

(DG) CLEANER R1 (100ML)

PUNCH RIVET N4

(S/L) SEAM SEAL 300ML

QTY

PRIC

VALUE

1

452.00

452.00

1

401.75

401.75

1

373.95

373.95

1

246.00

246.00

60

0.55

33.00

10

0.55

5.50

1

326.80

326.80

1

112.70

112.70

1

26.15

26.15

30

0.55

16.50

1

33.80

33.80

Total Parts : 2,028.15

Labour 1 : 7,053.00

Parts : 2,028.15

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 635.68

Grand Total : 9,716.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Leslie Lam Kwok Tai
10B Rochalie Drive

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 248244

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace boot lid smart opener top sensor line include programming and checking control unit, bottom sensor line for proper function *	562.00	10.00	505.80
# To carry out body cavity preservation (For cut panel)*	451.00	10.00	405.90

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH * <i>ALC</i>	60.60	1.00	3.00	58.78
# TRUNK FLOOR *	452.00	1.00	3.00	438.44
# TAIL PANEL *	401.75	1.00	3.00	389.70
# FRT BUMPER TOP CARRIER *	373.95	1.00	3.00	362.73
# RR BUMPER LH CORNER MOUNTING *	141.90	1.00	3.00	137.64
# AIR DUCT *	246.00	1.00	3.00	238.62
# PLUG BLACK D=5MM * <i>ALC</i>	0.90	8.00	3.00	6.98
# PLUG BLACK D=5MM * <i>ALC</i>	0.90	2.00	3.00	1.75
# SENSOR WIRE FOR SMART OPENER TOP * <i>ALC</i>	43.15	1.00	3.00	41.86

Total Labour :	911.70
Total Parts :	1,676.50
Total Labour & Parts :	2,588.20

Main + Supplementary

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Change appointment to 26/02 @ 10am

Survey & repair on 25.02 @ 10am

GST REG. NO : M2 - 0020081 - X

25 JAN 2019

ESTIMATE

Estimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Leslie Lam Kwok Tai
10B Rochalie Drive

Singapore 248244

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear bumper, attachments, repair front bumper and repair tail panel.

1700 3,400.00

Painting front bumper, rear bumper and tail panel.

2537 2,819.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To supply front emboss number plate.

83.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451 531.00

Sundries.

150.00

Total Labour 1: 7,431.00

DESCRIPTION

REAR SILENCER

QTY	PRIC	VALUE
1	1,465.05	1,465.05

TAILPIPE TRIM CHROME

2 107.85 215.70

TRIM PANEL AIRDUCT (X LINE)

1 153.30 153.30

FRT BUMPER PANEL LOWER SECTION (PDC)

1 281.80 281.80

RR BUMPER CARRIER

1 493.85 493.85

MOUNTING SMART OPENER

1 45.30 45.30

REAR TRIM UNDERRIDE PROTECTION (X L)

1 105.40 105.40

REAR TRIM UNDERRIDE PROTECTION (X L)

1 105.40 105.40

RR BUMPER RH CORNER MOUNTING

1 141.90 141.90

RR BUMPER RH CORNER MOUNTING

1 141.90 141.90

REAR BUMPER PANEL PRIMED

1 770.80 770.80

REAR BUMPER MIDDLE TRIM PANEL (PDC)

1 242.80 242.80

REAR BUMPER BOTTOM TRIM PANEL (LINE)

1 231.25 231.25

LICENCE PLATE HOLDER ECE

1 70.65 70.65

◀ Service Request Details

Claim

S9M01BI3

Reference

None 

Loss Date

January 21, 2019

Request Date

January 25, 2019

Due Date

February 1, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

25/01/2019 @ 5:31 pm
Caroline Veh not in

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

EG1001U

Make

TPVD BMW



Service Address

Primary Contact/Insured

SHAW MING JEONG FRANK @ SHAO FRANK
22 CAMBORNE ROAD, 299867, Singapore
96397778

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Friday, 25 January, 2019 2:50 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: REQUEST FOR DIRECT SETTLEMENT - EG1001U & SKC22R ON 21/01.2019
Attachments: SKM_558e19012514470.pdf; EG1001U(JAN).PDF

Categories: Pragati

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

 Re:MANDATE IA- EG 1001U - PERFORMANCE

Type

 Question

Message

PLS CHECK MARKET VALUE, PLS ENSURE THERE IS MARKET VALUE BEFORE SEEKING MANDATE APPROVAL

[Reply](#)



Re:RE: Re:RE: Re:MANDATE IA- EG 1001U - PERFORMANCE

Type

🔗 Question

Message

PLS PROCEED FOR SETTLEMENT NOT EXCEEDING \$18,398.62 ALL IN

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKC 22R (Insd veh)	Model:	B.M.W. X1
	EG 1001U (TP veh)		
Date of Accident:	21/01/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	25,880.16
Final Repair Cost	:	\$	17,273.12
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,123.50 15 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 18,398.62

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ 100 _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LTD	:	\$ 18,398.62

NUR SHAQILAH BTE ABDOL
WAHAB

30/07/2019
Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001801/Egb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: KIAN CHUAN

Date : 30-07-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKC 22R	Veh. Inspected	EG 1001U
Policy No.	VPX/P1168186	Coverage (\$)	0.00
Claim No.	S9M01BI3	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	28/01/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X1	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBAHS720305G65917	Colour	WHITE
Odometer	36406	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50R18	PIRELLI	7 mm
L/H Front Tyre	225/50R18	PIRELLI	7 mm
R/H Rear Tyre	225/50R18	PIRELLI	7 mm
L/H Rear Tyre	225/50R18	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/01/2019	Inspection Date	25/02/2019
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EG 1001U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR SILENCER (SN) (CONSISTENT)	DENTED	1,465.05	1,421.10
2	TAILPIPE TRIM CHROME (SN) (CONSISTENT)	NOT NECESSARY	215.70	-
1	TRIM PANEL AIRDUCT (X LINE) (SN) (CONSISTENT)	NOT NECESSARY	153.30	-
1	FRT BUMPER PANEL LOWER SECTION (PDC) (SN) (CONSISTENT)	DENTED	281.80	273.35
1	RR BUMPER CARRIER (SN) (CONSISTENT)	DENTED	493.85	479.03
1	MOUNTING SMART OPENER (RUBBER) (SN) (CONSISTENT)	TORN	45.30	43.94
1	REAR TRIM UNDERRIDE PROTECTION (X L) (SILVER) (SN) (CONSISTENT)	CRUSHED	105.40	102.24
1	REAR TRIM UNDERRIDE PROTECTION (X L) (SN) (CONSISTENT)	REPEATED	105.40	-
1	RR BUMPER RH CORNER MOUNTING (SN) (CONSISTENT)	CRUSHED	141.90	137.64
1	BUMPER LH CORNER MOUNTING (SN) (CONSISTENT)	BROKEN	141.90	137.64
1	REAR BUMPER PANEL PRIMED (SN) (CONSISTENT)	DENTED	770.80	747.68
1	REAR BUMPER MIDDLE TRIM PANEL (PDC) (SN) (CONSISTENT)	DENTED	242.80	235.52
1	REAR BUMPER BOTTOM TRIM PANEL (LINE) (SN) (CONSISTENT)	DENTED	231.25	224.31
1	LICENCE PLATE HOLDER ECE (FRONT) (SN) (CONSISTENT)	BROKEN	70.65	68.53
1	REAR BUMPER HEAT INSULATION (SN) (CONSISTENT)	DENTED	69.55	67.46
1	FRONT EMBOSS NUMBER PLATE (SN) (CONSISTENT)	BENT	83.00	83.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	150.00
1	TRUNK FLOOR (SN) (CONSISTENT)	DENTED	452.00	438.44
1	TAIL PANEL (SN) (CONSISTENT)	DENTED	401.75	389.70
1	FRT BUMPER TOP CARRIER (SN) (CONSISTENT)	DENTED	373.95	362.73
1	AIR DUCT (SN) (CONSISTENT)	BROKEN	246.00	238.62
60	BLIND RIVET AVIBVLB (SN) (CONSISTENT)	NOT NECESSARY	33.00	-
10	SCREW (SF PLUS M5X15) (SN) (CONSISTENT)	NOT NECESSARY	5.50	-
1	(DG/SL) BODY ADHESIVE K5B (195ML) (SN) (CONSISTENT)	NOT NECESSARY	326.80	-

Report Ref No. CC4/ASM19001801/Egb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	(DG) BODYWORK ADHESIVE K5A (50ML) (SN) (CONSISTENT)	NOT NECESSARY	112.70	-
1	(DG) CLAENER R1 (100ML) (SN) (CONSISTENT)	NOT NECESSARY	26.15	-
30	PUNCH RIVET N4 (SN) (CONSISTENT)	NOT NECESSARY	16.50	-
1	(S/L) SEAM SEAL 300ML (SN) (CONSISTENT)	NOT NECESSARY	33.80	-
1	SENSOR WIRE FOR SMART OPENER TOP (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	41.86	41.86
8	PLUG BLACK D=5MM (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	6.98	6.98
2	PLUG BLACK D=5MM (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	1.75	1.75
1	CLAMPING BUSH (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	58.78	58.78
			6,905.17	5,710.30
	LABOUR			
	TO REPLACE REAR BUMPER, ATTACHMENTS, REPAIR FRONT BUMPER AND REPAIR TAIL PANEL.		6,120.00	6,120.00
	PAINTING FRONT BUMPER, REAR BUMPER AND TAIL PANEL.		2,519.00	2,562.30
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PORPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		225.90	225.90
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	207.00
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.		531.00	405.90
	TO REPLACE AIR DUCT (FRONT SUPPORT), TAIL PANEL AND TRUNK FLOOR.	NOT NECESSARY	5,950.00	-
	PAINTING TRUNK FLOOR.	NOT NECESSARY	572.00	-
	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL).		531.00	405.90
	TO REPLACE BOOT LID SMART OPENER TOP SENSOR LINE INCLUDE PROGRAMMING AND CHECKING CONTROL UNIT, BOTTOM SENSOR LINE FOR PROPER FUNCTION. (ADDITIONAL)		562.00	505.80
			17,281.90	10,432.80
	GRAND TOTAL		24,187.07	16,143.10
	RECOMMENDED COST OF REPAIRS			16,143.10

Report Ref No. CC4/ASM19001801/Egb3s2



Report Ref No. CC4/ASM19001801/Egb3s2

A handwritten signature in black ink, appearing to be 'CHEN TSUE YEE'.

CHEN TSUE YEE

Automotive Assessor

A handwritten signature in black ink, appearing to be 'HO LEONG CHUAN'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.