

## **ESTIMATE FOR EM222Z**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Tang Yong Choo

616 Dunearn Road Singapore 289620

Mobile: 90699222

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

30454

EM222Z / 28/08/2017

EKIDOO: WDD1179422N496702

27091031253009

MB/MB CLA 180 S/B (X117) "FACELIFT"

021 191 Cosmos Blac/ 041 151 Lther ARTIC

Account No	Terms	Date/Time Print	ted	CSE	5	Operator					
CSI00001	Cash	18/02/2019/	15:05	СН		371 / Go Chee Ha	n				
		Description	n of Good	s / Servi	ces		Qty	Unit Price	Disc%	An	nount
Z REQUEST	2 10	NOT	- 6	KT.	01	FELOLA	1 77 6	VII	13.7	01	0 =
	Request	NOI	A	N.	O	FFICIA		XX II	Vν	OH	
M BPNSUN	O /ACC DATE	F1020212F0			-	1 1 0 17 1		40 4 11		-	_
		: 5102921358	// 21-1	1-2019							
DRIVE IN	1	: // SCL15111	L - AXA					2			
	DATE SURVE	Υ:					255	-			
BY/AUTHR	IZED ON					0/	1/1/			01	1680.0
A BPILAB	DIE AND DE	PLACE ATTACHE	D DAMACE	ED DADT	C & DE	FINISH. 966	11 11	-3		960	1000.0
	BLE AND RE	PLACE ATTACHE	D DAMAGE	ED PARI	S & KEI	TINISH.	11 1			60c	960.0
A BPIRES	DEAD DUMBE	-n				0 10	11			000	900.0
	REAR BUMPE	-K			4	11115	1		0.10		380.0
A BPILAB	NITOV DIACA	NOSTIC TO CHECK	V ON COL	NTDOL I	MITT DE	SET MEMORY TO	-		0.10		300.0
		ANDARD. NETT	K ON COI	VIKUL	WEI LIKE	SELL AIDHOUGH IN O					
	CATION STA	ANDAKD. NETT		[	1 1	1110				/	120.0
A BPILAB	AD LICUTIA	G SYSTEM AND	JATED TE	ST FOR	ANY I	EAKAGE. NETT					120.0
M REAR TRI	W DIMBED	IG STSTEPT AND	WHIER IL	21 101	Jul F	EARAGE. NEIT	1.00	1140.97	00 00		1140.9
		FOR BUMPER	7	7)	-		1.00	119.90			119.9
	R BRACKET		. C				1.00	27.62			27.0
	R BRACKET	3 /1/	0				1.00	27.62			27.6
	IM BUMPER	11					1.00	135.86			135.8
CHROME M		- July					1.00	156.78			156.7
	PIPE BRACK	CET - SM'					1.00	57.85			57.8
	PIPE BRACK		)				1.00	57.85			57.8
RIVET	TIL DIACI	1 . /					10.00	1.27			12.7
EXPANSIO	N RIVET	LINEC					8.00	2.07	00.00		16.5
		E COVER	(mis				1.00	295.95	00.00		295.9
	PIPE CHRON		)				1.00	295.95	00.00		295.9
SPRING N		(	11				4.00	3.08	00.00		12.3
TAPPING SCREW							4.00	2.64	00.00		10.5
	WASHER ASS	SEMBLY /					6.00	3.08	00.00		18.4
	SENSOR						2.00	177.22	00.00		354.4
	ING ZO	1					2.00	6 40	00.00		12.8

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





## **ESTIMATE FOR EM222Z**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Tang Yong Choo

616 Dunearn Road Singapore 289620

Mobile: 90699222

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Operator

27091031253009 MB/MB CLA 180 S/B (X117) "FACELIFT"

30454

EM222Z

Vehicle & Document Information

WDD1179422N496702

021 191 Cosmos Blac/ 041 151 Lther ARTIC

Unit Price

/ 28/08/2017

Account No

CSI00001

Terms

Cash

LH/REAR LAMP COMBINATION

REAR CROSS MEMBER

Date/Time Printed CSE 18/02/2019/ 15:05

CH

371 / Go Chee Han

Description of Goods / Services

1.00

Qty

579.21 00.00 45.96 00.00

Disc%

579.21 745.96

Amount

hefar part photos.

Como ai are - 82880282

Como Biany @ Kkanto. com

18/2/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) iş allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer

Signature:

Date:

7% GST dn

Nett 7219.42 7,219.42 505.36

**Total Payable** 

7,724.78

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg