

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 3369J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT N/S HEADLAMP	DAMAGED	1,268.80	✓ 1,268.80
1	FRONT BUMPER	DAMAGED	1,072.00	✓ 1,072.00
1	SET FRONT BUMPER CLIP	NECESSARY	50.00	✓ 50.00
1	FRONT BUMPER FOG LAMP	DAMAGED	232.80	✓ 232.80
1	FRONT BUMPER FOG LAMP COVER	DAMAGED	156.00	✓ 156.00
1	FRONT BUMPER REINFORCEMENT (photo show damaged)	NOT NECESSARY	562.10	562.10
1	FRONT BUMPER SIDE RETAINER	DAMAGED	40.80	✓ 40.80
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR ← not justified.	585.00	\$ 585.00
1	FRONT N/S FENDER BRACKET	NOT NECESSARY	48.00	✓ -
1	FRONT N/S FENDER INNER SHIELD	DAMAGED	163.20	✓ 163.20
1	SET FRONT N/S FENDER INNER SHIELD CLIP	NECESSARY	50.00	✓ 50.00
1	FRONT N/S WHEEL HUB WITH BEARING	NOT NECESSARY	571.20	✓ 571.20
1	FRONT N/S SHOCK ABSORBER	NOT NECESSARY	492.00	✓ 492.00
1	FRONT N/S KNUCKLE ARM WITH BEARING	NOT NECESSARY	751.20	✓ 751.20
1	FRONT N/S LOWER ARM	NOT NECESSARY	417.60	✓ 417.60
1	FRONT N/S BRAKE DISC	NOT NECESSARY	185.00	✓ 185.00
	LESS 10% DISCOUNT		-664.57	-303.36
			5,981.13	2,730.24
<u>SPECIAL NETT ITEMS</u>				
1	FRONT N/S WHEEL RIM (SN)	NOT NECESSARY	1,000.00	800 -
1	FRONT N/S TYRE (SN)	NOT NECESSARY	450.00	450 -
			1,450.00	-
<u>LABOUR</u>				
	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSING.		80.00	30.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	Already dismantle	350.00	350
	TO CONDUCT WHEEL ALIGNMENT. (need alignment once removed)	NOT NECESSARY	150.00	150-
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	90.00	90.-

Report Ref No. CS3/III18022750/Avd3e2-1

↓
 Their surveyor got take
 the dismantled photos.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT N/S FENDER.		1,080.00	300.00 \$ 900
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00 \$ 800
	<i>To dismantle & reassemble front n/s undercarriage</i>	<i>-\$350</i>	2,750.00	730.00
GRAND TOTAL			10,181.13	3,460.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CS3/III18022750/Avd3e2-1

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III18022750/Avd3e2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 26-02-2019		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3572X	Veh. Inspected	SLV 3369J	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT18120443	Excess (\$)	0.00	
Assign From	STANLEY LAI	Assign Date	28/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WVWZZZ16ZCM115117	Colour	BLACK	
Odometer	161147	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/12/2018	Inspection Date	27/12/2018	
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		