

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 13T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER, TOP (CONSISTENT) | DEFORMED | 898.08 | 898.08 |
| 1 | FRONT BUMPER, LOWER (CONSISTENT) | SCRATCHED | 766.08 | 766.08 |
| 1 | BUMPER CROSSRAIL - LWR (CONSISTENT) | * CHECK | 515.98 | - |
| 1 | ORNAMENT, BUMPER RHS (CONSISTENT) | * CHECK | 78.73 | - |
| 1 | PLUG - FRONT BUMPER (CONSISTENT) | * CHECK | 36.93 | - |
| 1 | REINFORCEMENT, BUMPER - TOP (CONSISTENT) | * CHECK | 92.75 | - |
| 1 | WICK. FR BUMPER (CONSISTENT) | * CHECK | 159.66 | - |
| 1 | MAKE MEDALLION (CONSISTENT) | * CHECK | 78.04 | - |
| 1 | RADIATOR GRILLE (CONSISTENT) | * CHECK | 812.00 | - |
| 1 | BONNET (CONSISTENT) | TO REPAIR SEE LABOUR | 983.43 | - |
| 1 | BONNET, HINGE - LH (CONSISTENT) | NOT NECESSARY | 99.82 | - |
| 1 | BONNET, HINGE - RH (CONSISTENT) | NOT NECESSARY | 101.84 | - |
| | LESS 10% DISCOUNT | | -462.32 | -166.42 |
| | | | 4,161.02 | 1,497.74 |
| | SPECIAL NETT ITEMS | | | |
| 1 | NUMBER PLATE (SN) (CONSISTENT) | NOT NECESSARY | 20.00 | - |
| 1 | NUMBER PLATE HOLDER (SN) (CONSISTENT) | NOT NECESSARY | 20.00 | - |
| 1 | SUNDRIES (SN) (CONSISTENT) | * CHECK | 150.00 | - |
| | | | 190.00 | - |
| | <u>LABOUR</u> | | | |
| | TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC. INCLUSIVE OF THE REPAIR OF BONNET. | | 1,800.00 | 300.00 |
| | TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC. | | 1,050.00 | 400.00 |
| | | | 2,850.00 | 700.00 |
| | GRAND TOTAL | | 7,201.02 | 2,197.74 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,750.00 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 1,750.00 |
|--|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |
| (REPAIR COST NOT CONCLUDE) | | |
| (EXCLUDE CHECK ITEMS S\$1,746.68 NETT) | | |

Report Ref No. CC4/ASM19001813/Gbs3s2





Report Ref No. CC4/ASM19001813/Gbs3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

mont

HO LEONG CHUAN
Automotive Assessor