

12/03/2002

ASS. REC. BY:

REF:

CG/FCI19001859/Kqd3

n2

Special Instruction:

Surveyor

LWS

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time: 28/1/19 @ 5:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 8012P

Insured:

SHD 3698B

at Workshop m/s

Hui Yang Motor

Tel:

64515752

of

Blk 176 Sin Ming Drive # 04-02

Policy No:

Claim No:

D19000396 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/01/2019

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

29/1/19 @ 9:31am

Person Contacted:

Belle

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 8012P - x

SHD 3698B - NS/INC160859/H/von2

DN: 30092016

21/2/19 @

5:14pm revised to Eileen Lee by email.

28/1 C1 Log & 22506 email. & C1 from (Red \$6349.19, 74%)

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 8140k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLF 8012P Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Tug Wellfire C.G. 2493

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 146950 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AG1430 0037654

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 10/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 20/2/19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

Date/Time, File Pass to?

1) 01/3/19

Date/Time, File Return to?

2)

☐ : Prell. Report☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Fixings

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

160
50
50
15
275



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000396MFSH

Date: 21 February 2019

Our Ref: CS/FCI19001859/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLF 8012P .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/02/2019 at the premises of M/s HUI YANG MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 8,599.19 .
Revised Estimate Amount	: S\$ 2,195.01 .
"Check" Items Amount	: S\$ 760.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	14-01-2019	Our Ref No. D19000396MFSH
Accident Date	10-01-2019	Claim Type. Third Party
Insured Vehicle	SHD3698B	Third Party Vehicle. SLF8012P
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	MARCUS LOH	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 February 2019 5:14 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000396MFSH/1
Attachments: CSFC19001859Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLF 8012P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 29 January 2019 9:33 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000396MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 28 January 2019 5:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000396MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

10/01/2019

Owner: MKM CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA VELLFIRE 2.5 - SLF8012P

1pc rear tailgate
2pcs rear tailgate reflector @\$591.60
1pc rear tailgate "VELLFIRE" emblem
1pc rear tailgate inner rubber
1pc rear bumper 1575.00
2pcs rear bumper side retainer 1 @\$132.25
2pcs rear bumper side retainer 2 @\$141.45
2pcs rear bumper side reflector @\$174.25
1pc rear end panel

115 Ford Capital (LICK)
20/02/19 (Wednesday)
Not Notified
C/L By @ 2250h
Resurvey After Paint 3 days

11	\$ 1,956.25	X
11	\$ 1,183.20	X
11	\$ 75.58	✓
11	\$ 374.45	✓
11	\$ 1,711.10	✓
11	\$ 264.50	X
11	\$ 282.90	X
11	\$ 348.50	X
11	\$ 781.10	X

less 25%
balance c/f

\$ 6,977.58
\$ 1,744.40
\$ 5,233.19

1set rear windscreen glass moulding
2pcs rear bumper parking sensor @\$380.00
1pc rear end panel outer sensor

11	nett	\$ 100.00	X
11	nett	\$ 760.00	✓
11	nett	\$ 380.00	X
		\$ 1,240.00	
		\$ 124.00	
		\$ 1,116.00	

less 10%

remove & refit rear windscreen glass
sealant
wiring
tuffkote
spray painting
labour charges
Total

11	\$ 120.00	X	
11	\$ 80.00	X	
	\$ 150.00	15%	
11	\$ 100.00	X	
	\$ 900.00	44%	
	\$ 900.00	40%	
		\$ 8,599.19	

8723.19



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19001859/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3698B	Veh. Inspected	SLF 8012P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000396MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	28/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE (A)	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	AGH300037654	Colour	METALLIC BLACK	
Odometer	146950	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	WEST LAKE	7 mm	
L/H Front Tyre	215/60 R17	WEST LAKE	7 mm	
R/H Rear Tyre	215/60 R17	WEST LAKE	7 mm	
L/H Rear Tyre	215/60 R17	WEST LAKE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/01/2019	Inspection Date	20/02/2019	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 8012P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,956.25	-
2	REAR TAILGATE REFECTOR @\$591.60	SERVICEABLE	1,183.20	-
1	REAR TAILGATE "VELLFIRE" EMBLEM	NECESSARY	75.58	75.58
1	REAR TAILGATE INNER RUBBER	SERVICEABLE	374.45	-
1	REAR BUMPER	DENTED / BUCKLED	1,711.10	1,575.00
2	REAR BUMPER SIDE RETAINER 1 @\$132.25	SERVICEABLE	264.50	-
2	REAR BUMPER SIDE RETAINER 2 @\$141.45	SERVICEABLE	282.90	-
2	REAR BUMPER SIDE REFECTOR @\$174.25	SERVICEABLE	348.50	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	781.10	-
	LESS 25% DISCOUNT		-1,744.39	-412.64
			5,233.19	1,237.94
SPECIAL NETT ITEMS				
1	SET REAR WINDSCREEN GLASS MOULDING (SN)	NOT NECESSARY	100.00	-
2	REAR BUMPER PARKING SENSOR @\$380.00 (SN)	SHORTED	760.00	760.00
1	REAR END PANEL OUTER SENSOR (SN)	SERVICEABLE	380.00	-
1	SEALANT (SN)	NOT NECESSARY	80.00	-
			1,320.00	760.00
LABOUR				
	REMOVE & REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	WIRING.		150.00	15.00
	TUFFKOTE.	NOT NECESSARY	100.00	-
	SPRAY PAINTING.		900.00	440.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR END PANEL.		900.00	400.00
			2,170.00	855.00
GRAND TOTAL			8,723.19	2,852.94
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS/FCI19001859/Kqd3n2



Report Ref No. CS/FC119001859/Kqd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.