

AIG
LKK



NG BOON KENG
Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883
Tel: 6509 5545 Fax: 6509 5567
Website: www.chewmotor.com
Registration No.: 201718369R GST Reg No.: 201718369R

23/05/2019

TP416
Asker.

Accident date: 19/05/2019

Estimated repair cost for vehicle no: SMJ7564L HYUNDAI AVANTE 1.6 A '19

CHASSIS: KMHD841CMKU881356

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,853.60 ✓
2	2	Rear Boot Lid Hinge <i>Not nec</i>	\$65.10	\$130.20 +
3	2	Rear Boot Lid Side Reflector <i>ut</i>	\$489.70	\$979.40 ✓
4	1	Rear Boot Lid Emblem Assembly		\$48.90 ✓
5	1	Rear Boot Lid Avante Logo		\$80.30 ✓
6	1	Rear Boot Lid S Logo		\$35.10 ✓
7	1	Rear Boot Lid Reverse Camera <i>amp</i>		\$680.00 ✓
8	1	Rear Boot Lid Inner Lock <i>amp</i>		\$145.70 ✓
9	1	Rear Boot Lid Inner Rubber <i>ut</i>		\$145.60 ✓
10	1	Rear Boot Lid Inner Trim Board <i>2 pcs</i>		\$195.80 +
11	10	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$65.00 +
12	2	Rear Tail Lamp <i>ut</i>	\$545.60	\$1,091.20 ✓
13	4	Rear Tail Lamp Clip <i>ut</i>	\$8.00	\$32.00 ✓
14	2	Rear Tail Lamp Panel <i>Repair</i>	\$245.60	\$491.20 +
15	1	Rear Bumper <i>Dehead</i>		\$654.30 ✓
16	1	Rear Bumper Lower <i>Dehead</i>		\$496.30 ✓
17	10	Rear Bumper Clip <i>ut</i>	\$6.50	\$65.00 30.
18	2	Rear Bumper Side Retainer <i>new</i>	\$85.90	\$171.80 ✓
19	2	Rear Bumper Side Reflector <i>cracked</i>	\$305.70	\$611.40 ✓
20	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00 ✓
21	1	Rear Bumper Number Plate <i>Best</i>		\$50.00 ✓
22	2	Rear Bumper Number Plate Lamp <i>Not nec</i>	\$39.40	\$78.80 +
23	1	Rear Bumper Number Plate Garnish <i>new</i>		\$65.40 +
24	1	Rear Bumper Reinforcement <i>Distorted</i>		\$489.30 ✓
25	2	Rear Bumper Reinforcement Side Bracket <i>Best</i>	\$294.80	\$589.60 ✓
26	3	Rear Bumper Reinforcement Top Bracket Holder <i>Best</i>	\$35.00	\$105.00 ✓
27	2	Rear Fender Inner Trim Board <i>torn</i>	\$285.90	\$571.80 ✓
28	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 +

29	1	Rear End Panel <i>Dented</i>		\$657.80	/
30	1	Rear End Panel Top Garnish <i>deformed</i>		\$175.90	/
31	1	Rear End Panel Buzzer <i>cracked</i>		\$285.70	95
32	1	Rear Spare Tyre Panel <i>rip</i>		\$745.80	+
33	1	Rear Spare Tyre Panel Top Cover <i>deformed</i>		\$385.90	✓
34	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00	+
35	1	Rear Exhaust		\$785.60	+
36	2	Rear Exhaust Mounting	\$35.20	\$70.40	+
37	1	Rear Exhaust Aluminium Cover <i>new</i>		\$155.00	+
38	1	Rear Center Exhaust		\$1,516.80	+

9494.80 Subtotal :- \$15,635.60
7595.92 S.N: 600.

Labour charges

To remove & refit cushion & trim board	\$280.00	80
To remove & refit reverse sensor	\$100.00	60
To remove & refit reverse camera	\$180.00	60
To remove & refit rear & center exhaust	\$380.00	80
To check wiring	\$100.00	30
Tuff kote	\$150.00	60
Towing fee	\$150.00	X
Panel beating	\$1,800.00	80
Spray painting	\$1,600.00	1000

Subtotal :- \$4,740.00

Total:- \$20,375.60

total: 10365.92

H/S: 8.3K

OT Dmp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

8.3K