Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19001891/BKA3Q2

**Date:** 10/11/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800015027

Claimant

SJU4706S

Insured Vehicle No: SDN973X

Vehicle No: SDN973X

Date of Loss: 17/01/2019 Nature of Claim: TP Claim No: 5378420476SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJU4706S

 Make & Model:
 TOYOTA WISH, 1.8 X (A)
 Engine No:
 2ZR0418822

 Reg. Date:
 11/12/2009 (Man. Year: 2009)
 Chassis No:
 ZGE200003330

Colour: White Odometer: 0 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,568.16	2,235.69	2,332.47	51.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,110.00	800.00	41.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,478.16	3,345.69	3,132.47	48.35
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	6,478.16	2,650.00	3,828.16	59.09
+ Loss of Use (7.0 x S\$8	30.00/day) (S\$)	560.00		
+ Doc/S	earch Fee (S\$)	36.45		
Net	tt Liability (S\$)	3,246.45		
Global Sum S	ettlement (S\$)	3,240.00		

**INSPECTION** 

Date of Assignment: 29/01/2019

Date Inspected: 29/01/2019 Inspected At: 385 Sin Ming Drive #01-02

Repairer: Team Autopro Pte Ltd (KAKI

BUKIT)

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan Manager: Khanchna Pothuraj

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Repair	1,220.80 FL	*- FL
2	1		*REAR DOOR RH	Dented	1,579.30 FL	*1,171.00 FL
3	1		*REAR DOOR OUTER HANDLE RH	Broken	212.00 FL	*175.25 FL
4	1		*REAR DOOR EGULATOR MOTOR	Not Necessary	280.70 FL	*- FL
5	1		*REAR DOOR REGULATOR GEAR	Not Necessary	197.40 FL	*- FL
6	1		*REAR DOOR INNER LOCK	Broken	216.00 FL	*216.00 FL
7	1		*REAR DOOR INNER TRIM BOARD	Broken	294.00 FL	*294.00 FL
8	1		*ROCKER PANEL GARNISH RH	Cut	860.00 FL	*738.00 FL
9	1		*REAR DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
10	1		*ROCKER PANEL GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
11	1		*ALLOY RIM 15 (LOCAL REPAIR)	Cut	500.00 FS	*200.00 FS
12	1		*SUNDRIES	Necessary	80.00 FS	*30.00 FS
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	Sub Total (S\$)	5,540.20	2,884.25
	- List Item Discount on L Items 20.00/25.00% (S\$)					648.56
				Total Parts (S\$)	4,568.16	2,235.69
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	R&R REAR WHEEL RH AND BALANCING	New	100.00	0.00
2	R&R REAR DOOR COMPONENT	New	100.00	50.00
3	PANEL BEAT	New	800.00	400.00
4	RUST PROOFING	New	80.00	60.00
5	SPRAY PAINTING	New	800.00	600.00
6	WATER LEAKAGE TEST	New	30.00	0.00
		Gross Labour Cost (S\$)	1,910.00	1,110.00
	Report was u	nsubmitted during this print-out.		

< END OF ESTIMATES >