



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 6237L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	TO REPAIR SEE LABOUR	2,100.80	-
1	BOOTLID EMBLEM LOGO	NECESSARY	150.00	150.00
1	BOOTLID EMBLEM 'MALIBU'	NECESSARY	59.00	59.00
1	BOOTLID EMBLEM 'CHEVROLET'	NECESSARY	49.00	49.00
1	BOOTLID EMBLEM 'LTZ'	NECESSARY	39.00	39.00
1	BOOTLID LOCK	NOT NECESSARY	280.00	-
1	BOOTLID WEATHERSTRIP	CUT	290.00	290.00
2	NUMBER PLATE LAMP @\$65.00	CRACKED	130.00	130.00
1	REAR BUMPER	DEFORMED	1,800.50	1,800.50
1	REAR BUMPER LOWER LIP	DEFORMED	420.00	420.00
2	REAR BUMPER SIDE RETAINER @ \$85.20	NECESSARY	170.40	170.40
2	REAR BUMPER REFLECTOR @ \$111.50	O/S CRACKED	223.00	111.50
1	REAR BUMPER REINFORCEMENT	BENT	890.00	890.00
2	REAR BUMPER REINFORCEMENT BRACKET @ \$80.00	NOT NECESSARY	160.00	-
2	TAILLAMP @ \$923.00	CRACKED	1,846.00	1,846.00
2	TAILLAMP PANEL @ \$820.00	TO REPAIR SEE LABOUR	1,640.00	-
1	END PANEL	DENTED	955.00	955.00
1	END PANEL TOP GARNISH	CRACKED	380.00	380.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,552.80	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	520.00	-
2	TOOLS SIDE SPONGE @ \$80.00	NOT NECESSARY	160.00	-
1	EXHAUST PIPE	NOT NECESSARY	2,992.00	-
1	EXHAUST PIPE INSULATION	NOT NECESSARY	73.00	-
1	SET EXHAUST PIPE MOUNTING	NOT NECESSARY	232.00	-
4	REVERSE SENSOR @ \$262.00	DAMAGED 2PCS ONLY	1,048.00	524.00
1	REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	480.00	-
	LESS 10% DISCOUNT		-1,864.05	-781.44
			16,776.45	7,032.96

Report Ref No. CC6/EQ19001908/Apb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	22.00	22.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	120.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	REVERSE CAMERA (SN)	DAMAGED	220.00	220.00
			432.00	362.00
	<u>LABOUR</u>			
	TO PANEL BEAT, REMOVE AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID, TAILLAMP PANEL AND REAR FLOOR PANEL.		1,600.00	700.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	800.00
	TUFF COAT.		250.00	60.00
	WIRING AND BULB CHECK.		80.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		120.00	50.00
	TRANSFER TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	350.00	-
			4,360.00	1,690.00
GRAND TOTAL			21,568.45	9,084.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,200.00

Report Ref No. CC6/EQ19001908/Apb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.