

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JHMRC 1880HC203499

NG THIAM HUAT
283 BEDOK SOUTH AVE 3
#15-44
S 465460

TPAIG.
Ashes.

Date :14.02.2019
Vehicle no :SLS 518 G
Make/Model :HONDA ODYSSEY
Accident date :27.01.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 110 ✓
2	Rear tailgate <i>Dented</i>	1	\$ 1399.3 1129.40
3	Rear tailgate hinges @ \$44.80	2	\$ 89.6 X
4	Rear tailgate shock absorber @ \$193.20 <i>2 not new</i>	2	\$ 386.4 X
5	Rear tailgate upper lock <i>Damaged</i>	1	\$ 218.5 ✓
6	Rear tailgate lower lock <i>not new</i>	1	\$ 44.9 X
7	Rear tailgate inner board <i>Deformed</i>	1	\$ 241.5 ✓
8	Rear tailgate inner handle <i>not new</i>	1	\$ 41.4 X
9	Rear tailgate weather strip <i>at</i>	1	\$ 135.7 ✓
10	Rear tailgate stopper @ \$24.20 <i>new</i>	2	\$ 48.4 X
11	Rear tailgate H emblem <i>new</i>	1	\$ 37.2 ✓
12	Rear tailgate centre reflector <i>not new</i>	1	\$ 444.2 X
13	Rear tailgate side reflector @ \$963.80 <i>cracked</i>	2	\$ 1927.6 763.20
14	Rear tailgate moulding <i>cracked</i>	1	\$ 189.8 ✓
15	Rear end panel <i>Dented</i>	1	\$ 529.9 ✓
16	Rear end panel top garnish <i>Deformed</i>	1	\$ 126.5 ✓
17	Rear bumper <i>Deformed</i>	1	\$ 653.5 ✓
18	Rear bumper side holder @ \$38.00 <i>new</i>	2	\$ 76 ✓
19	Rear bumper reflector @ \$66.70 <i>not new</i>	2	\$ 133.4 X
20	Rear bumper reverse sensor @ \$207.00 <i>2 pieces damaged</i>	4	\$ 828 414
21	Rear bumper clips (1set) <i>new</i>	1	\$ 70.30
22	Rear bumper side top garnish @ \$103.50 <i>not new</i>	2	\$ 207 X
23	Rear smart buzzer <i>cracked</i>	1	\$ 78.2 ✓
24	Rear antenna assy <i>cracked</i>	1	\$ 86.3 ✓
			\$ 8103.3
Less 20% Disc			\$ 1620.66
Total			\$ 6482.64
<u>Special Nett Items</u>			
1	Rear camera <i>not new</i>	1	\$ 800 X
Total			\$ 800

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NG THIAM HUAT
283 BEDOK SOUTH AVE 3
#15-44
S 465460

Date :14.02.2019
Vehicle no :SL5 518 G
Make/Model :HONDA ODYSSEY
Accident date :27.01.2019

No	DESCRIPTION	Qty	Amount (S\$)
Labour Cost			
1	To supply rear widnscreen sealant		\$ 50 ✓
2	To supply rear end panel inner sealant		\$ 200 ⁶⁰
3	Remove & reinstall rear windscreen		\$ 200 ¹²⁰
4	Remove & reinstall reverse sensor		\$ 200 ⁶⁰
5	Remove & reinstall boot lid inner garnish	2440	\$ 150 ⁸⁰
6	Remove & reinstall rear camera		\$ 100 ⁵⁰
7	Remove, replace & repair consistent to the accident		\$ 1800 ¹⁰⁰⁰
8	Respray Painting		\$ 1500 ⁹⁰⁰
9	Tuff kote		\$ 150 ⁶⁰
10	To remove and reinstall upholstery	150 ⁶⁰	
Total			\$ 4350

Grand Total \$ 11632.64

total 6195.76.
2/s: SK
06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SK