	IGNMENT
S. C.	Veh No. SHE92H Yr Regn: 1 Nov 2017
From: Date:	Veh No. SHF92H Yr Regn: (Nov 2017 Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax)/ Prime Mover /
Estimated Cost:	Truck / Trailer or
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	
To Inspect Vehicle No:	Make: Toyota Prius c.c 1798.
at Workshop m/s	Colour Maroon A/C: Insured / Std / NI / NA
of Old Day	Sp.Reading (67886 T/Radio: Insured / Std / NI / NA
Insured: , SLC 5110X	Eng/No:
Policy No. 5097396339-01 25092018	C/No: JTDKB3FU703573586.
Claims No. M7/1029866-003	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nil / S/Bim / STD A/Rim or
	Tyre Size: F: 195 (65 215
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Falken
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: 4 days Res.: Yes or No	D.O.A. 27/1/19 D.O.I. 29/1/19
Lum Sum: % 3 Val.: Yes or No	Survey held at Surt
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OU	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction SHF 9)H - CC3/ms(a) 7(000830 / Klah	BAZ BUT: 11-UTOUF 01/19/2131
91C 5120X - NA /INC19001835/4	SLC5120 X
19/7/19 Final and \$2,832.73, 4 de	SL25120 X
. Gea & 9019.11. 7 7010.	
PECEIVED	2 2 1111 2019
RECEIVED	1. 104
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
/ /	Resurvey No. of Trip: Survey Fee: 160
W/AVI TIMMAN I I Final Report	Transportation:
1) 2017 TUMA : Final Report Date/Time. File Return to?	Hansportanon.
Date/Time. File Return to?	
Date/Time. File Return to? 2) Add F	ee: : Site Insp (\$)S+PSSI
Date/Time. File Return to? 2) Add F Report Format:	ee: : Site Insp (\$)S+PSSI
Date/Time. File Return to? 2) Add F	ee: : Site Insp (\$)S+PSSI

TP Claims against NTUC Income: Follow-Through Survey

19/07/2019

Date:

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	ш	Estimate
1	MT/1027613-003	SMRT TAXIS PTE LTD	SHD 6202D	SLK 6202U	12/01/2019	20:50	\$	21,795.34
2	MT/1029866-003	SMRT TAXIS PTE LTD	SHF 92H	SLC 5120X	27/01/2019	12:30	\$	12,647.64
ю	MT/1035233-002	SMRT TAXIS PTE LTD	SHB 246C	SMC 8115E	09/03/2019	0:20	s	8,608.74

eBao Tech									0	SeneralC	laim
Hello, NAC_PAYA_UBI_80	0601					-	• Change La	nguage	· Change P	assword	Log Out
My Desktop	Polic	cy Query									
Notice of Loss	Policy N	o.				Date of	Accident	27/01	1/2019 11:40		
	Vehicle	No.(For Motor)	SLC5120	X		Certifica	te Number				
					Se	arch					
	Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
		5097296239- 01		VOULEZ CARS	53350846X	GFT	drivo CLASSIC	SLC5120X	SLC5120X	25/09/2018	
					Cor	ntinue					

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 19 July 2019 11:58 AM

To:

Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); SUR; CS A Team

Cc:

Leong Chee kwong

Subject:

RE: SHF92H

Dear Poh Suan,

WITHOUT PREJUDICE

Confirm final fig \$2,832.73 before GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) < YeoPohsuan@smrt.com.sg>

Sent: Tuesday, 16 July 2019 5:16 PM

To: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Cc: Leong Chee kwong <cheekwongwega@gmail.com>

Subject: SHF92H

Hi All,

Attached herewith the repair estimate of SHF 92H having Case No: TAX/01/19/2131.

There is no change to the approved amount of \$2,832.73 @ 4 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

----Original Message----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Tuesday, 16 July 2019 5:11 PM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 29/01/2019 12:35

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

计中心分别 计多数多数数据	ACCIDENT STATEMENT
Pate Of Report	28/01/2019 11:55
ate Of Accident	27/01/2019 12:30
xact Location Of Accident	LOR 6 TOA PAYOH JUNCTION LOR 8 TOA PAYOH
country/State of Loss	SINGAPORE
在野岛科学科学科学科学科学	DETAILS OF OWN VEHICLE
ehicle Registration Number	SHF92H
nsured/Policyholder	
ame Of Registered Owner	SMRT TAXIS PTE LTD
o Reg No	198905369K
mail Address	NOEMAIL
obile Phone No	
ternative Phone No	OFFICE-80000000
ehicle Particulars	
anufacturer	TOYOTA
odel	PRIUS TAXI-1.8 (A)
kact Purpose for which vehicle was being used a ne of accident	
e you claiming under your own insurance policy r repair to your vehicle?	NO
No, Please state action to be taken	THIRD PARTY
ehicle Category	TAXI
surance Company	
ame of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
pe Of Coverage	THIRD PARTY FIRE AND/OR THEFT
eet Policy	YES
licy Number	D-18090213MFSH
ver Note Number	
iver	
me of Driver	WONG YEW WAH
RIC No	S1607918I
te Of Birth	20/11/1963
cupation	OUTDOOR
te Of Driving Pass	13/05/1988
ving Experience	30 YEARS AND 8 MONTHS
nder	MALE
bile Number	(LOCAL) +65-80000000
	(200/12) ·05-0000000
Number	(200,42) 100-0000000
Number ntact Number	(255/12) 155-55555555

Address

246

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

NO 2

involved in the accident

NO

Was any body injured in the Accident?
Was any injured conveyed to hospital by

NO

ambulance?

...

Was any other material or property damaged?

I have been approached by unknown person(s)

YES

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TURNING LEFT FROM LOR 8 TOA PAYOH INTO THE LEFT MOST LANE OF LOR 6 TOA PAYOH AND HAD STOPPED DUE TO THE FRONT BUS WAS STOPPING. AFTER WHICH, I FELT AN IMPACT FROM THE REAR RIGHT PORTION OF MY TAXI, THE VEHICLE SLC5120X FOLLOWED FROM BEHIND HAD COLLIDED ONTO MY TAXI.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO LARGE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLC5120X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE HIRE

Name of Driver

JONG CHUN CHIAT

NRIC/Passport Number

S7726146Z

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudlate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature ?

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

De 28/1/219

Name:

NRIC/FIN No .:

SKETCH PLAN		
	LOR 6 TUA	2411.41
	20% 6 104	
← .		E
€		←
ا ا	TTX	
Sun Sun	THE PARTY	
N on	7 2 6	
A- SHF92H		
A- SHF92H B- SLC 5120	4 4 /	
ESCRIBE CIRCUMSTANCES OF	and the second s	
The state of the s	THE ACCIDENT LOR & TOA	PAYOH
		
CLARATION		
e declare the pregoing particulars	are true in every respect.	
	Juny 28-1-19	alu 28/1/21
cyholder's Sighāture	Driver Signature	
e & Time:	(If driver is not the policyholder)	Reporting Centre Personnel's Signature Name:
	Date & Time:	2000 120 E. C.

NRIC/FIN No.:

Date & Time:



Case Details

Case Reference Number :

TAX/01/19/2131

Type of Repair : Accident Repair

Vehicle Registration Number : SHF92H

Company Type: SMRT Taxis Pte Ltd

Estimation ID : EST-5533-ID Assigned By : Taxi Claims Manager

Tean

Insurance Company Name : NTUC Income Insurance Co-operative

Accident Date and Time: 27/01/2019 04:30 AM

Vehicle Age(In Months): 14

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

				SMRT Rec	ommen	dation						Su	rveyor Approval	
BOM Type		Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127,13	Replace	0	0	Check ▼	X M
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give ▼	X XMI
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.1	10	2.60	26.00	25.00	19.50	Replace	0	0	Not Give ▼	X MN
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.2	10	3.20	32.00	25.00	24.00	Replace	0	0	Not Give ▼	XIII
One Time Key In	Main			EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	1	137.00	137.00	25.00	102.75	Replace	0	0	Not Give •	X JIMI
One Time Key In	Main			PIPE ASSY, EXHAUST, TAIL	1	1,173.90	1,173.90	25.00	880,43	Replace	1	0	Repair *	R.x
One Time Key In	Main			SUPPORT, EXHAUST PIPE NO.5	2	41.10	82.20	25.00	61.65	Replace	0	0	Not Give +	X I/M
One Time Key In	Main			SUPPORT, EXHAUST PIPE NO.4	1	41.10	41.10	25.00	30.83	Replace	0	0	Not Give ▼)	()///
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB- ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair +	X

1,571.65	Surveyor Total	6,580.57	Total Spare Part Cost
0	Lump Sum Dis (%)	0.00	Lump Sum Discount (%)
	Final Cur Tatal	6 580 57	Final Spare Part Cost

вом	Costing	Doubles		SMRT Rec								Su	rveyor Approval	
Туре	Type	Portion	Material Number	Part Name	Qty	Price Per Unit(S)	List Price(\$)	Dis(%	Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace *	
One Time Key In	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace *	
One Time Key In	Main			EMBLEM SUB- ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace *	> NEC
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace *	
One Time Key n	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace *	
One Time Key	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check +	X MM
One Time Key	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check ▼	X ////
ine ime ey	Main			EXTENSION, REAR FLOOR SIDE PANEL, RH	1	76.20	76.20	25.00	57.15	Replace	0	0	Check *	X AIN/
ine ime ey	Main			BOX, DECK FLOOR, RH	1	304.00	304.00	25.00	228.00	Replace	0	0	Not Give +	(////
ne me ey	Main			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	344.70	25.00	258.52	Replace	0	0	Not Give •	VIVI X
ne me ey	Main		13	LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give ▼	X MM
ne I me iy	Main		- 3	PANEL SUB- ASSY, FENDER REAR RH	1 (824.80	824.80	25.00	618.60	Replace	0	0	Not Give ▼	X MM
ne /	Main			DUCT ASSY, DUARTER VENT , RH & LH	1 (55.00	65.00	25.00	48.75	Replace	0	0	Check +)	1.1/4
ne M	Main			INER, REAR FENDER , RH	1 1	35.80	135.80	25.00	101.85	Replace	0	0	Not Give • X	JIJN
e N ne	fain		1	YRE	1 1	26.74	126.74	0.00	126.74	Replace	0	0	Not Give + X	1////

Total Spare Part Cost	6,580.57	Surveyor Total	1,571.65
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	6,580.57	Final Sur Total	1,571.65

BON	A Costler	Dorting	Metal	SMRT Rec									Surveyor Approval	
Тур		Portion	Material Number	Part Name	Qty	Price Per Unit(\$)	List Price(\$	Dis(%	Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	r Repair/Replac	e Remarks
One Time Key In				COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace *	OEX
One Time Key In	Main			CLIPS PIECE, FR & RR BUMPER	T 10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace *	NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace *	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace •	> NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace *	
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Giv€ ▼	X MM
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace *	MIS
One Time Key n	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check ▼	X MAI
One Time Key	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give ▼	X MMI
One Time Cey	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace *	MEC
ne ime ey	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check *	XIIII
ine Ime ey	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check ▼	X /////
ne ime ey	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace +	DEF
ne me ey	Main		F	COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace *	CUT
ne me ey	Main			PAD, RR BUMPER, CTR	3 :	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace *	NEC
ne me	Main		A	ENS & BODY SSY , RR UMPER , RH	1 4	186.80	486.80	10.00	438.12	Replace	1	438.12/3	Replace *	CRA
						Tot	al Spare Pa	rt Cost	6,580.57		Sup.	eyor Total	1 571 65	
							Sum Disco					ım Dis (%)	0	
											N	1000	U	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	1,014.00	300	
Total:			1,014.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY REAR BUMPER	378.00	200 /	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	50 /	
4	Main	TO RESPRAY REAR PANEL	180.00	0	
5	Main	TO RESPRAY REAR FENDER RH	378.00	0	
6	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100 /	
otal:			1,476.00	350.00	

Other Cost Detail

5.NO.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	126.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20 /	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE & REFIT EXHAUST	120.00	30 /	
6	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40 /	
7	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120,00	30 /	
8	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
9	Main	TO REMOVE AND REFIT WIRE HARDESS	100.00	0	
0	Main	TO REPLACE SUNDRY PARTS	100.00	0	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor	Remarks
11	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,166.00	120.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,580.57	1,571.65
Total Labour Cost	1,014.00	300.00
Total Spray Painting	1,476.00	350.00
Other	1,166.00	120.00
Overall Total	10,236.57	2,341.65
Lump Sum Repair Option		
Lump Sum Total	0.00	2,341.65
Surveyor Approved Amount		2,341.65
No of Repair Days*	7	4
Remarks		P/P REPAIR,PHOTO BEFORE PAINT.
Surveyor Name		Hwee jie
Signature		D Jamento
Survey Date	29/01/2019	Save

12765-44

LKK Auto Consultants hence notify

- the Repairer of the following:

 To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





SMRT Automotive Services Pts L16 60 Weedlands Incustral Park E4, Singspore 757705 FAX Number 63685592

Estimator Telephone Number: \$6667623 Accident Reporting Number: 66962972

Date Generated : 16/01/2019 UserID ; PohSuzn

Registration Number	SHF92H
Case Reference Number	TAX/01/19/2131
Registration Date	1/11/2017
Company Type	SMRT Taxis Ple Ltd
Make	тоуота
Model	PRIUS4
Name of Driver	WONG YEW WAH
Type of Accident	Head to Rear
Accident Date and Time	27/1/2019 12:30 PM
Accident Reported Date and	28/1/2019 11:57 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	27/1/2019 12:33 PM
Replacement Vehicle issued?	No
Job Card Number	24099884
Special Instruction to ARC, if any	TOWED \$90
Prepared Date and Time	28/1/2019 6:48 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	







West Asia	Section B - Summary of Repair Estin	nates
Summary of Repair Estimate:		
为。 1910年(1910年)(1910年)(1910年)(1910年)(1910年)(1910年)	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$500.00
Total Spray Cost	\$1,656.00	\$450.00
Total Spare Part Cost	\$6,771.60	\$1,762.73
Total Other Cost	\$1,166.00	\$120.00
TOTAL COST	\$10,857.60	\$2,832.73 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	29/01/2019 10:21 AM	29/01/2019 5:20 PM
Signature	<u> </u>	
Remarks	Initial estimate = 7 days Request number of days to extend = 1 day	P/P REPAIR, PHOTO BEFORE PAINT.



SMRT Automative Services Pte Ltd
G9 Wacdlands Industrial Park E4, Singapore 7517C5
FAX Number 63685592
Estimator Tolephone Number 68662623
Accided Reporting Number 68662672

Date Generated : 16/07/2019 User ID : PohSuse

H. Friedon	Section C - Quota	ion and Accident invoice Details	
Quotation Number	QN-1907-0257	Invoice Number	
Quotation Date	16.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

S Part 1 - Labour Works	ection D - Details of Repair Estimates	
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$250.00	\$200.00 / (Jyp)
TO REPAIR RH REAR PORTION	\$1,014.00	\$300.00
Total Labour	\$1,264.00	\$500.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$50.00 /
TO RESPRAY REAR PANEL	\$180.00	\$0.00
O RESPRAY REAR PANEL	\$180.00	\$100.00 / (544)
O RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180,00	\$100.00
Total Spray Painting & Panel Beating	\$1,656.00	\$450.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$126.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM	\$120.00	\$40.00
TO FACILITATE REPAIR. TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RE	\$120.00	\$30.00
LIGHTING FOR LEAKAGE TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$100,00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,166.00	\$120.00

Part	Portion	Stock	Part Name	Quantity	List Price	Discount (%)	Final Price (\$)	per made a la l	Surveyor Approved
Number	W Section 7		COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Check X
				0.00	\$222.60	0.00	50.00	Replace	Not Given
***************************************		90467170 26A0	CLIP , FLOOR UNDER COVER , NO.1	0.00	\$2.60	0.00	\$0.00	Replace	Not Given



SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number 63685592

Estimator Telephone Number 68562623 Accident Reporting Number 68562672

Date Generated : 16/07/2019

User ID

: 16/07/2011 : PohSusn

\$0.00 Replace Not Given \$3.20 0.00 90467170 CLIP , FLOOR UNDER 0.00 27C0 COVER, NO.2 \$0.00 Replace Not Given 0.00 \$137.00 0.00 EXHAUST HEAT SHIELD X 58327470 40 INSULATOR, MAIN \$0.00 Replace Repair 100.00 PIPE ASSY, EXHAUST, TAIL 1.00 \$1,173,90 17430377 \$41.10 0.00 \$0.00 Replace Not Given X SUPPORT, EXHAUST PIPE 0.00 17565220 NO.5 \$0.00 Not Given 0.00 Replace SUPPORT, EXHAUST PIPE \$41.10 17565280 0.00 NO.4 100.00 \$0.00 Replace Repair 76801471 TAIL GATE BACK DOOR 1.00 \$891.20 10A1 OUTSIDE GARNISH SUB-Replace \$52.30 25.00 \$39.23 Replace 75441470 NAME PLATE (HYBRID) 1.00 LUGGAGE COMPARTMENT 90 \$39.23 Replace Replace \$52.30 25.00 1.00 75442471 NAME PLATE (PRIUS) , UGGAGE COMPARTMENT 25.00 \$34.73 Replace Replace \$46.30 1.00 75403480 EMBLEM SUB-ASSY REAR 10 Replace Replace 1.00 \$7.80 0.00 \$7.80 SMRTIOGO \$21.60 Replace Replace STICKER DECAL 6555 8888 1.00 0.00 \$21.60 \$0.00 Replace Check \$629.80 0.00 58307470 END PANEL SUBASSY. 0.00 90 BODY LOWER BACK \$0.00 Replace Check \$37.00 0.00 0.00 SEALANT SIKAFLEX X \$0.00 Replace Check \$76.20 0.00 EXTENSION REAR FLOOR 0.00 58315470 X SIDE PANEL, RH 0.00 \$0.00 Replace Not Given \$304.00 BOX, DECK FLOOR, RH 0.00 64995470 50 \$344.70 0.00 \$0.00 Replace Not Given 64730472 PANEL ASSY, DECK TRIM 0.00 SIDE, RH 40C2 LENS & BODY, REAR 0.00 \$0.00 Replace Not Given \$438.10 0.00 81551472 COMBINATION LAMP, RH Replace Not Given 0.00 \$0.00 0.00 \$824.80 61601471 PANEL SUB-ASSY FENDER REAR RH Check \$65.00 0.00 \$0.00 Replace 0.00 62940470 DUCT ASSY, QUARTER X VENT, RH & LH Not Given 0.00 \$0.00 Replace X 65637470 LINER, REAR FENDER, RH 0.00 \$135.80 60 Not Given 0.00 \$0.00 Replace \$126.74 TYRE 0.00 \$317.93 Replace 25.00 Replace \$423.90 52159479 COVER, RR BUMPER ASSY 1.00 Replace \$11.25 Replace \$1.50 25.00 52161160 CLIPS PIECE, FRT & RR 10.00 BUMPER \$5.70 Replace Replace 25.00 PAD, RR BUMPER, RH & 2.00 \$3.80 52462470 \$5.70 Replace Replace 25.00 52462470 PAD, RR BUMPER, RH & 2.00 \$3.80 \$5.70 Replace Replace 25.00 PAD, RR BUMPER, RH & 2.00 \$3.80 52462470 10 LH.3 \$0.00 Replace Not Given SEAL, RR BUMPER ARM, 0.00 \$11.00 0.00 52191470 RH & LH 30 \$89.93 Replace Replace 25.00 \$119.90 52565479 FILLER, RR BUMPER, RH 1.00 00 Replace Check \$0.00 52023470 REAR BUMPER 0.00 \$318.80 0.00 X REINFORCEMENT 30 \$0.00 Replace Not Given 0.00 SENSOR REVERSE 0.00 \$180.00 Replace \$120.00 Replace PIXEL STICKER 2.00 \$60.00 0.00 \$0.00 Replace Check RETAINER, RR BUMPER, 0.00 \$112.70 0.00 52575470 40 Check \$0.00 Replace 52591470 SEAL, RR BUMPER, RH 0.00 \$85.20 0.00 X 50 25.00 \$418.72 Replace Replace GUARD, RR BUMPER, 1.00 \$558.30 52453470 LOWER 10 COVER, GUARD RR Replace \$11.10 Replace 52169470 1.00 \$14.80 25.00 BUMPER LOWER 20 PAD, RR BUMPER, CTR 25.00 \$4.95 Replace Replace 3.00 \$2.20 52461470 10 Replace / Replace 81581470 LENS & BODY ASSY, RR 10.00 \$438.13 1.00 \$486.80 BUMPER, RH 10 \$1,571.70 \$8.231.14 Total



3MRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapere 757705 FAX Number 6358592 Estenstor Telephone Number - 88662623

Accident Reporting Number 68662672

Date Generated: 16/07/2019

User ID : PehSuan

Number Number S8398470 COVER, REAR FLOOR 1.00 \$169.50 25.00 \$127.13 Replace Replace S6398470 UNDER, RH 1.00 \$85.20 25.00 \$63.90 Replace Replace	Part	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor
	Number	18620 - 32	58398470		1.00					
		1	-		1.00	\$85.20	25.00	\$63.90	Replace	Replace /

(SPP) Buc

+ 500.00 + 570.00 + 570.00 + 2832.13

12765.44

ugat.

W to

PRIQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	6809,10,111	Seal RR Bumper RH	63-90/	\$ 85120
2	6812113 -	Cover Rear Floor Under R4	127-13/	# 10950 / 1
3	6806,07,08	To Repair End Panel.		Pt 250.00 \$
4		To perpray Find Panel		8 180 00 A
5				
6				
7				
8				

<<< Please submit photographs for damaged parts>>	Please submi	t photographs	for damaged	parts>>>
---	--------------	---------------	-------------	----------

L (Name)

CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that: - Supplementary Parts are raised for replacement for the aforesald vehicle

Signature of person making this declaration.

Signature of person making this declaration

[To be signed in front of an authorised witness] I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation /
Photo Submitted		Rumber
SMRT Staff		Date of submission



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTU	C INCOME INSUR	RANCE CO-OPERATIVE LTD	Ref:	NS/INC1900195	6/Eqd3e2
		D UNION HOUSESINGAPORE	Date:	25-07-2019 INC4	
1.		Policy Particulars	:- THIR	D PARTY CLAIM	
	Insured Veh.	SLC 5120X	Veh. I	nspected	SHF 92H
	Policy No.	5097296239-01	Cover	age (\$)	0.00
	Claim No.	MT/1029866-003	Exces	s (\$)	0.00
	Assign From		Assig	n Date	29/01/2019
2.		Vehicle Parti	culars &	& Condition	
	Make & Model	TOYOTA PRIUS	c.c		1798
	Engine No.	HIDDEN	Year o	of Reg.	2017
	Chassis No.	JTDKB3FU703573586	Colou	r	MAROON
	Odometer	167886	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modifi	ication	SPORTS RIM
	General	GOOD			
3.		Conditi	ions of	Tyres	福建步级等 高兴等级
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	FALKE	N	6 mm
	L/H Front Tyre	195/65 R15	FALKE	N	6 mm
	R/H Rear Tyre	195/65 R15	FALKE	N	6 mm
	L/H Rear Tyre	195/65 R15	FALKE	N	6 mm
4.		Descripti	on of D	amages	计算程序 (155条) 计
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR POR	TION.	
	DAMAGES SEE D	ETAILS.			
5.	The Part of the Pa	Genera	Inform	nation	
	Accident Date	27/01/2019	Inspe	ction Date	29/01/2019
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a.		R	emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			
5b.		Estimate	Days o	f Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		4 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 92H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.23
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.23
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.73
1	COVER, RR BUMPER ASSY (DISC 25%)	DEFORMED	423.90	317.93
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
1	FILLER, RR BUMPER, RH (DISC 25%)	MISSING	119.90	89.93
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DEFORMED	558.30	418.72
1	COVER, GUARD, RR BUMPER, LOWER (DISC 25%)	CUT	14.80	11.10
3	PAD, RR BUMPER, CTR @\$2.20 (DISC 25%)	NECESSARY	6.60	4.95
1	COVER, REAR FLOOR UNDER, RH (DISC 25%)	BUCKLED	169.50	127.13
1	SEAL, RR BUMPER, RH (DISC 25%)	DEFORMED	85.20	63.90
1	LENS & BODY ASSY, RR BUMPER, RH (DISC 10%)	CRACKED	486.80	438.13
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 6888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	COVER, REAR FLOOR UNDER, RH	NOT NECESSARY	169.50	-
1	COVER, REAR FLOOR UNDER, CENTER	NOT NECESSARY	222.60	-
10	CLIP, FLOOR UNDER COVER, NO. 1 @\$2.60	NOT NECESSARY	26.00	:
10	CLIP, FLOOR UNDER COVER, NO. 2 @\$3.20	NOT NECESSARY	32.00	-
1	EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	NOT NECESSARY	137.00	-
2	SUPPORT, EXHAUST PIPE NO. 5 @\$41.10	NOT NECESSARY	82.20	-
1	SUPPORT, EXHAUST PIPE NO. 4	NOT NECESSARY	41.10	-
1	END PANEL SUBASSY, BODY LOWER BACK	NOT NECESSARY	629.80	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	EXTENSION, REAR FLOOR SIDE PANEL, RH	NOT NECESSARY	76.20	-

Report Ref No. NS/INC19001956/Eqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOX, DECK FLOOR, RH	NOT NECESSARY	304.00	
1	PANEL ASSY, DECK TRIM SIDE, RH	NOT NECESSARY	344.70	2
1	LENS & BODY, REAR COMBINATION LAMP, RH	NOT NECESSARY	438.10	-
1	PANEL SUB-ASSY, FENDER REAR RH	NOT NECESSARY	824.80	
1	DUCT ASSY, QUARTER VENT, RH & LH	NOT NECESSARY	65.00	9
1	LINER, REAR FENDER, RH	NOT NECESSARY	135.80	-
1	TYRE	NOT NECESSARY	126.74	-
2	SEAL, RR BUMPER ARM, RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	112.70	-
1	SEAL, RR BUMPER, RH	NOT NECESSARY	85.20	-
1	PIPE ASSY, EXHAUST, TAIL	TO REPAIR SEE LABOUR	1,173.90	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR SEE LABOUR	891.20	-
			8,679.44	1,762.73
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF PIPE ASSY, EXHAUST, TAIL AND TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY.		1,264.00	500.00
	SPRAY PAINT.		1,656.00	450.00
	TOWING CHARGE.		126.00	9
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT EXHAUST		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	40.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARNESS.	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-

Report Ref No. NS/INC19001956/Eqd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	
			4,086.00	1,070.00
	GRAND TOTAL		12,765.44	2,832.73

RECOMMENDED COST OF REPAIRS	2,832.73
(CONFIRMED)	

Report Ref No. NS/INC19001956/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

M

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.